



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLG 5760 C

Not Authorised
Rummy Bepain

Parts	(a) Cost / List Price Items	\$	3,078.52
	Plus/Less 25%	\$	769.63
	Total of Cost / List	\$	2,308.89
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	2,308.89
Labour		\$	2,320.00
Total		\$	4,628.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 2/5/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 2/5/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLG 5760 C**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU103535416**

Submit By : **SERENCE**
Year Manufacture : **2016**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender <i>B7</i>	1	\$868.70		✓
2	LH front fender undershield <i>D11</i>	1	\$195.60		✓
3	LH front fender undershield clip <i>m</i>	10	\$25.00		✓
4	LHF fender wording "HYBRID" <i>m</i>	1	\$44.17		✓
5	Front bumper <i>Bur</i>	1	\$450.80		✓
6	Front bumper clip <i>m</i>	10	\$40.00		✓
7	Front bumper reinforcement - upper <i>R</i>	1	\$711.50		X
8	Front bumper reinforcement - lower <i>R</i>	1	\$245.30		X
9	Front bumper side retainer RH <i>Sh</i>	1	\$107.20		X
10	Front bumper side retainer LH <i>D11</i>	1	\$107.20		✓
11	LH front hub cab <i>Sh</i>	1	\$195.65		X
12	LH wing mirror (cover) <i>Sh</i>	1	\$87.40		X
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

