

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AXA INSURANCE

Address:

NO 8, SHENTON WAY, #24-01
AXA TOWER, S(068811)

Joy

Telephone:

68804888

Fax:

68804740

Email: motor.survey@axa.com.sg

Make/ Model :

HYUNDAI ELANTRA

Date:

15.04.2019

Chassis No :

KMHD841CMJU727988

Vehicle No:

SDP1991B

Date/Time of Accide

27.04.2019/ 1445

Reg date :

26.07.2018

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT BONNET <i>3 new</i>	1	\$ 1,751.00		\$ + 1,751.00
2	FRONT BONNET LOCK	1	\$ 200.90		\$ + 200.90
3	FRONT HEADLAMP RH <i>at</i>	1	\$ 1,345.60		\$ ✓ 1,345.60
4	FRONT RADIATOR GRILLE <i>new</i>	1	\$ 687.30		\$ + 687.30
5	FRONT RADIATOR GRILLE LOGO <i>new</i>	1	\$ 111.60		\$ + 111.60
6	FRONT RADIATOR GRILLE LOGO <i>new</i>	1	\$ 702.50		\$ ✓ 702.50
7	FRONT BUMPER	1	\$ 72.60		\$ ✓ 72.60
8	FRONT BUMPER RETAINER RH <i>new</i>	1	\$ 695.80		\$ + 695.80
9	FRONT BUMPER REFORCEMENT <i>new</i>	1	\$ 105.60		\$ + 105.60
10	FRONT BUMPER SEAL RUBBER <i>new</i>	1	\$ 195.80		\$ X 195.80
11	FRONT BUMPER FOGLAMP RH <i>Not New</i>	1	\$ 145.80		\$ X 145.80
12	FRONT BUMPER FOGLAMP COVER RH <i>Not New</i>	1	\$ 145.80		\$ X 145.80
13	FRONT FENDER RH <i>new</i>	1	\$ 675.60		\$ + 675.60
14	FRONT FENDER INNER SHIELD RH <i>new</i>	1	\$ 185.50		\$ + 185.50
15	FRONT FENDER INNER SHIELD RH <i>new</i>	1	\$ 1,071.50		\$ + 1,071.50
16	FRONT SUPPORT PANEL <i>new</i>	1	\$ 1,071.50		\$ + 1,071.50
17	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 135.80		\$ + 135.80
18	FRONT WHEELHUB WITH BEARING RH <i>new</i>	1	\$ 456.30		\$ + 456.30
19	FRONT KNUCKLE ARM RH <i>new</i>	1	\$ 563.20		\$ + 563.20
20	FRONT LOWER ARM RH <i>Best</i>	1	\$ 495.60		\$ + 495.60
21	FRONT TIE ROD RH <i>new</i>	1	\$ 135.60		\$ + 135.60
22	FRONT SHOCK ABSORBER RH <i>new</i>	1	\$ 445.90		\$ + 445.90
23	FRONT STABILIZER BAR <i>new</i>	1	\$ 285.00		\$ + 285.00
24	FRONT STABILIZER BAR LINKAGE <i>new</i>	1	\$ 67.80		\$ + 67.80
Total List Price Cost					\$ 10,532.30

PARTS DISCOUNT 20%

\$ 8,425.84

3635.80

2908.64

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00		\$ ✓ 30.00
2	FRONT NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 50.00		\$ + 50.00
3	FRONT RIM RH <i>at</i>	1	\$ 650.00		\$ + 650.00
4	FRONT FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00		\$ + 30.00

5	SUPPORT PANEL TOP GARNISH CLIPS <i>Not</i>	1SET	\$ 30.00	\$ 30.00
Total Special Nett Items				\$ 790.00

430

Labour Works/ Panel Beating Related Works		Quotation
Job Scope		
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN, STRAIGHTENED MEMBER		\$ 1,600.00
		300
Spray Painting		Quotation
Job Scope		
TO RESPRAY AFFECTED AREAS		\$ 1,400.00
		250
Others Cost (Accident Repair Related Expenses)		Quotation
Job Scope		
TO TUFFCOAT AFFECTED AREA		\$ x 150.00
TO REMOVE/ REFIT CONDENSER AND TOP UP GAS		\$ x 100.00
COMPUTERISED WHEEL ALIGNMENT (BEFORE & AFTER)		\$ 80 180.00
TO REMOVE/ REFIT WIRING CHECKS ON AFFECTED AREA		\$ 30 120.00
TO REMOVE/ REFIT / REPLACE HEADLAMPS AND DISTANCE SETTLING		\$ x 150.00
TO REMOVE/ REFIT / REPLACE HEADLAMPS AND DISTANCE SETTLING		\$ 70 120.00
TO REMOVE AND REFIT WEEKEND CAR SEAL		\$ 820.00
Total Others Cost		\$ 13,035.84

GRAND TOTAL

730

CAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allangoh.cas@gmail.com
Fax: 6509 9501
TEL: 64842220

Adrian Lj
H/S 03/05/19.
0588p.

total: 4068-64

H/S: 3.2K.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: CAS GARAGE PTE LTD
VIN: SDP 1991 B
Date: 3.5.19 22:17



SDP 1991 B

Hyundai : Avante/Elantra/Lantra : AD/ADa/ADi (2016-) : AD : Rest of World

Front : Left

Actual	Before	Specified Range
-0°24'	-0°25'	-0°53' 0°07'
4°31'	4°31'	4°00' 5°00'
-0°16'	-0°16'	-0°03' 0°09'
10°03'	10°03'	13°30' 14°30'
9°39'	9°39'	12°37' 14°37'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°53'	-1°53'	-0°53' 0°07'
4°48'	4°48'	4°00' 5°00'
-0°13'	-0°13'	-0°03' 0°09'
12°40'	12°40'	13°30' 14°30'
10°47'	10°47'	12°37' 14°37'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
1°29'	1°28'	
-0°17'	-0°17'	
-2°37'	-2°37'	
-0°30'	-0°29'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°14'	-1°14'	-1°42' -0°42'
-0°01'	-0°01'	-0°02' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°01'	-1°01'	-1°42' -0°42'
0°08'	0°09'	-0°02' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°13'	-0°13'	
0°07'	0°08'	-0°04' 0°32'
-0°05'	-0°05'	