

15/5/2020

INS. CASE OWNER:

CC 4/AIG1900

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20.8.19

FILE PASS TO TYPST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

SS 36,500

(18 days) Reduction:

46 %

Email

Call

FINAL SETTLEMENT

Date/Time: 0-02.20

Confirm with: ANTHONY

Email

Cal

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28. Ass. Lia:

Repair Cost:

SS 36,500.00

DID CHANGED LANE HIT TP.

Loss of Rental (LOR):

SS 2,160.00

(18 days) x 120

Loss of Use (LOU):

SS -

(S x days)

Loss of Income (LOI):

SS -

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

LOR + LO

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 38,660.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 0-02.20

Confirm with: ANTHONY

Email

Cal

Payee 1:

SS 38,660.00

Name 1:

WAN HIER MOTORS

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
13/2/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

P
#330

REF 28/11/19007727/K d3 Special Instruction:
ASSIGNMENT (Office)
ADVISOR Kenneth
From (Person) Mujken of AG Date/Time: 21/11/19 9.36am

Estimated Cost: Bill for:
OD (C) / WS / TP RES / OD RES / EVA / INV / MV / CS
To inspect Vehicle No: SLR 9705D Insured: SLX 72714
at Workshop n/a: Lian Her Motors Tel: 8299 0599
of BLK 5038 AMK Ave 3 # 01 405 AMK hd. park 2
Policy No: Claim No: 963553764459003
Sum Insured: Excess:
Make of Vch: D.O.A. 26/04/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:
Date/Time: 12.25pm 21/11/19 Person Contacted: James Vehicle (IN) / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 9705D - x
	SLX 72714 - cost/ASM 180/0408 Kjb3 Done 2/6/18
<u>26/05/19</u>	@ 13.54 pm checked with Anto Anthony, proceed direct settlement.

REF: A1G

ASSIGNMENT

From:

Date: 2/5/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: STR 9705D
 at Workshop m/s: Lion Her Motor
 of: BLK 6038 AMK Ave 3 #01-405

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

889k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

18 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SUR 9705D

Yr Regn:

08, 17

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy CHR

c.c.

1797

Colour:

M. Gray

A/C: Insured / Std / NI / NA

Sp. Reading:

139977

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

84X10 2015961

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

26/4/19

D.O.I.

2/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR & N/S IR

The U/C / Chassis frame / Body Structure affected due to collision. ✓

Date / Time

Action / Instruction

4s: +36,500 (BEO: +30,816.59 46%)

MV: +89,000

LTA: +46,195

NET: +42,805

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / L.B.I. (\$))

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

LIAN HER MOTORS

BLK 5038 ANG MO KIO IND. PARK 2 #01-405
SINGAPORE 569541
Tel : 82990599 Fax : 64816131
Email : lhcar@hotmail.sg

H.L. CAR RENTAL PTE LTD

BLK 5038 ANG MO KIO IND. PARK 2 #01-405
SINGAPORE 569541

VEHICLE NO. SLR 9705 D
CHASSIS NO. ZYX102015961
MAKE. : TOYOTA C-HR
YEAR. : 2017

Not Authorized
L1M 836,50d.
Running Repair

M: Kenneth

18 days

Paint - 44,034.51
S Nutt - 2,470.00
Labour - 5,530.00
42,034.51

Imp on

41,600.00
40,000.00 Lim repair

QTY	Description	Amount
-----	-------------	--------

ESTIMATE COST OF REPAIR

1	Front bumper fascia	B/C/M \$	1,236.70	✓
2	Front bumper side retainer	CM \$	232.60	✓
2	Front bumper side triangle garnish o/s & n/s	n/s m/s \$	157.20	4 + 78.60
10	Front bumper clip	m \$	129.00	✓
1	Front bumper centre air grille	m \$	154.70	X X
1	Front bumper number plate plinth	m \$	122.80	X
1	Front bumper tow hook cover	m \$	38.00	X
1	Front bumper lower skirt	Dis/Lm \$	499.30	✓
2	Front bumper lower skirt sensor cover o/s & n/s	m \$	55.20	X
1	Front bumper spot lamp cover n/s	Dis \$	177.60	✓
1	Front bumper lower skirt clip	m \$	129.00	✓
1	Front bumper upper reinforcement	\$	461.60	X
1	Front bumper upper reinforcement sponge	\$ m/s	90.20	✓
2	Front bumper upper reinforcement bracket	Dis \$	354.20	X 177.10 4
1	Front bumper lower reinforcement	\$ m	237.60	X
1	Front bumper lower reinforcement sponge	\$ m/s	75.30	✓
2	Front bumper lower reinforcement bracket	Dis \$	144.20	X 72.10 4
2	Front engine lower cover n/s & o/s	CM \$	191.80	4 ✓
8	Front engine lower cover clip	m \$	103.20	✓
1	Front engine mounting n/s	CM \$	335.10	✓
1	Front engine mounting bracket n/s	Dis \$	128.70	✓
1	Front engine mounting rear	CM \$	295.10	✓
1	Front engine mounting bracket rear	Dis \$	125.80	✓

Page 1

Page Total :

\$ 5,474.90

4077.20 ✓

Page 1 balance c/f :

\$ 5,474.90

74X10-2015961

4077.20

1	Front bonnet		\$12 1,260.40 X	
1	Front bonnet lock		\$ 12 92.40 X	
8	Front bonnet insulation clip		\$ un 103.20 X	
3	Front bonnet rear side holder clip o/s		\$ un 38.70 X	
2	Front bonnet rear side holder clip n/s		\$ un 38.70 X	
1	Front grille assy	CM	\$ 434.80	✓
1	Front grille emblem	Sn	\$ 1,654.60 X	
1	Front grille rear sleeve holder		\$ Sn 38.60 X	
5	Front grille clip		\$ un 64.50	✓
1	Headlamp assy o/s	my CM	\$ 1,804.30	✓
1	Headlamp assy n/s	Bn	\$ 1,804.30	✓
1	Headlamp panel n/s		\$ Bn 305.70	✓
3	Headlamp clip n/s	un	\$ 38.70	✓
1	Headlamp panel o/s		\$ un 305.70 X	
3	Headlamp clip o/s		\$ un 38.70 X	
← 1	Headlamp wire harness n/s (complete front wire harness)	Tr	\$ 4,778.68 7	✓
1	Front support top arch panel	Bn	\$ 204.20 7	✓
1	Front support top arch panel cover garnish	CM	\$ 245.60 7	✓
6	Front support top arch panel cover garnish clip	un	\$ 77.40 7	✓
1	Front top support panel	un	\$ 272.60 X	
1	Front top support panel cover garnish	Sn	\$ 214.60 X	
6	Front top support panel cover garnish clip	un	\$ 77.40 X	
1	Front brace panel		\$ un 145.70 X	
1	Front support lower member		\$ Bn 404.70 X	✓
1	Front aircond condenser	Bn Sn	\$ 1,486.20 X	✓
2	Front aircond condenser side garnish n/s & o/s	Sn	\$ 190.40 X	
6	Front aircond condenser side garnish clip n/s & o/s		\$ un 77.40 X	
← 1	Front radiator assy 1841.80	Pu Sn	\$ 2,054.60 X	✓
1	Front radiator cooling fan assy	CM	\$ 958.90 7	✓
1	Front main relay box assy n/s	Sn	\$ 1,375.60 X	
1	Front wiper tank assy o/s	un	\$ 220.90	✓
1	Front wiper tank motor o/s	Sn	\$ 245.71 X	
1	Front wiper tank motor O ring seal o/s	Sn	\$ 25.20 X	
1	Front wheelhouse panel n/s	Bn	\$ 958.00	✓
2	Front fender o/s & n/s	Bn	\$ 1,638.80	✓
2	Front fender emblem o/s & n/s	un	\$ 115.60	✓
2	Front fender bracket o/s & n/s	Bn	\$ 207.80	✓
2	Front fender undershield o/s & n/s	CM	\$ 545.20	✓
16	Front fender undershield clip o/s & n/s	un	\$ 206.40	✓
2	Front fender rear partition garnish o/s & n/s	Sn	\$ 190.40 X	
6	Front fender rear partition garnish clip o/s & n/s	un	\$ 77.40 X	
2	Front fender inner sponge insulation pad o/s & n/s	Sn	\$ 544.80 X	
2	Front fender wheel arch garnish o/s & n/s	Dis / un	\$ 346.40	✓
16	Front fender wheel arch garnish clip o/s & n/s	un	\$ 206.40	✓
2	Front fender wheel arch garnish front retainer o/s & n/s	Dis	\$ 25.00	✓
6	Front fender wheel arch garnish front retainer clip o/s & n/s	un	\$ 77.40	✓

Page 2

Page Total :

\$ 26,218.69

22329.68

Page 2 balance c/f :

\$ 31,693.59

23287.68

22,329.68

1	Front door rear view mirror assy o/s	Br	\$ 1,441.90	✓
1	Front door rear view mirror cover o/s	M/S	\$ 142.70	✓
1	Front door quarter glass o/s	Sn	\$ 111.30	X
1	Front door quarter glass rubber o/s	Sn	\$ 73.80	X
1	Front door quarter glass quarter pillar o/s	nd	\$ 457.80	✓
1	Front door window glass o/s	Butter	\$ 543.60	✓
1	Front door window scrap moulding o/s	Scrt	\$ 125.60	✓
1	Front door assy n/s	n	\$ 1,242.30	X
1	Front door window vertical black garnish n/s	nn	\$ 38.90	X
1	Front door window black sticker n/s	nn	\$ 28.40	X
7	Front door window top black moulding rivert n/s	nn	\$ 90.30	X
1	Front door lower protector n/s <i>* photo</i>	nd	\$ 334.70	✓
8	Front door lower protector clip n/s	nn	\$ 103.20	✓
1	Rocker panel side skirt n/s	CPA	\$ 546.70	✓
8	Rocker panel side skirt clip n/s	nn	\$ 103.20	✓
1	Front suspension crossmember assy	BT	\$ 2,673.20	✓
1	Front suspension crossmember o/s stay <i>Linkage</i>	DIT	\$ 113.40	✓
1	Front suspension crossmember n/s stay <i>Linkage</i>	DIT	\$ 113.40	✓
2	Front knuckle arm o/s & n/s	B ₁	\$ 1,170.40	✓
2	Front lower arm o/s & n/s	B1/DIT	\$ 1,275.00	✓
2	Front lower arm ball joint o/s & n/s	B ₁	\$ 457.00	✓
2	Front shock absorber o/s & n/s	\$ B ₁	\$ 907.20	✓
2	Front shock absorber mounting o/s & n/s	B ₁	\$ 380.20	✓
1	Front driveshaft o/s <i>1535.90</i>	B ₁	\$ 2,272.90	✓
1	Front driveshaft n/s <i>1345.80</i>	B ₁	\$ 2,055.80	✓
2	Front wheel bearing hub o/s & n/s	A1/B ₁	\$ 1,098.40	✓
1	Front stabiliser bar	DIT	\$ 239.50	✓
2	Front stabiliser bar rod o/s & n/s	Sn	\$ 393.40	X
1	Front steering rack and pinion	A1/B ₁	\$ 1,658.20	✓
2	Front steering rack end tie rod	\$ Sn	\$ 257.20	X
1	Front automatic transmission assy <i>C.R</i>	1 hrs CM	\$ 18,385.60	✓ <i>7000sn</i>
TOTAL		\$	70,528.79	58,712.68
LESS		\$	17,632.20	14,678.17
		\$	52,896.59	44,034.51

Special Nett

1	Front radiator coolant
1	Auto transmission fluid
2	Front tyre
2	Front alloy sport rim

\$ M	50.00	✓
\$ M	120.00	✓
Pu	\$46,700.00	<i>5000</i>
nd	\$ 1,900.00	✓
		2470.00

Total Materials Cost : \$ 55,666.59

bond c/f 46,504.51

Labour Cost

To remove all damaged parts with all necessary components/attachments. To apply hot-works where necessary, straighten chassis members, repair/reshape dented body panels, in accordance with factory specifications. Replace damaged parts, refit and align into position. Refit all necessary components/attachments.	\$ 2,800.00	1600
To remove/refit air-con condenser with all necessary pipes and hoses. Vacuum and replenish cooling agent. Check for proper function.	\$ 250.00	100
To remove/refit radiator assembly with all connecting hoses. Replenish cooling agent and check for proper function.	\$ 220.00	50
○ To remove/refit power steering rack assembly with all attachments. Refill power steering fluid, check for proper function.	\$ 350.00	
To dismantle all necessary attachments/components, pipes, hoses, wirings in order to lift engine/gearbox assembly. Refit engine/gearbox with all necessary attachments and components. Reset and test engine for proper function.	\$ 850.00	? 480.00
To conduct engine tests and reset to factory specifications.	\$ 250.00	150
To perform diagnostic checks on control units. Reset to factory specifications	\$ 380.00	? 180.00
To set vehicle on chassis alignment bench, inclusive of all necessary preparatory works.	\$ 380.00	250
○ To remove/refit front undercarriage/suspension assembly with all attachments/components.	\$ 750.00	320
To conduct wheel alignment	\$ 120.00	60

To renew n/s front wheel rim/tyre and conduct wheel balancing.

\$ 150.00 } 401

To renew o/s front wheel rim/tyre and conduct wheel balancing.

\$ 150.00

To transfer door window mechanisms with motor assembly, door glass and all attachments.

nn \$ ~~220.00~~ X

To remove/renew front wire harness, all related connectors. Check proper function. Focus headlights.

\$ 1,200.00 ? 350.00

To remove and refix front dashboard to facilitate the repairs.

nn \$ ~~650.00~~ ? X

To provide towing service using "King Dolly

(Bill) \$ 150.00 750.00

To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials.

\$ 2,500.00 1800

To apply underseal and rust-proofing on the affected areas.

\$ 280.00 1200

15530.00

DURATION OF REPAIR: TWENTY EIGHT (28) WORKING DAY

LIAN HER MOTORS

BLK 5038 ANG MO KIO IND. PARK 2 #01-405

SINGAPORE 569541

Tel : 82990599 Fax : 64816131

Email : lhcar@hotmail.sg

Not Authorized

Running Repair

14 days

H.L. CAR RENTAL PTE LTD

BLK 5038 ANG MO KIO IND. PARK 2 #01-405

SINGAPORE 569541

VEHICLE NO. SLR 9705 D
CHASSIS NO. ZYX102015961
MAKE. : TOYOTA C-HR
YEAR. : 2017

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary survey must be performed and is subject to final settlement from insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

QTY	Description	Amount
-----	-------------	--------

ESTIMATE COST OF REPAIR

1	Front bumper fascia	B/LCM \$ 1,236.70	✓
2	Front bumper side retainer	CM \$ 232.60	✓
2	Front bumper side triangle garnish o/s & n/s	n/s m/s \$ 157.20	✓
10	Front bumper clip	m \$ 129.00	✓
1	Front bumper centre air grille	\$ 154.70	?
1	Front bumper number plate plinth	\$ 122.80	X
1	Front bumper tow hook cover	\$ 38.00	X
1	Front bumper lower skirt	D.I/LM \$ 499.30	✓
2	Front bumper lower skirt sensor cover o/s & n/s	\$ 55.20	X
1	Front bumper spot lamp cover n/s	DC \$ 177.60	✓
1	Front bumper lower skirt clip	m \$ 129.00	✓
1	Front bumper upper reinforcement	\$ 461.60	X
1	Front bumper upper reinforcement sponge	\$ 90.20	?
2	Front bumper upper reinforcement bracket	\$ 354.20	X
1	Front bumper lower reinforcement	\$ 237.60	X
1	Front bumper lower reinforcement sponge	\$ 75.30	?
2	Front bumper lower reinforcement bracket	\$ 144.20	X
2	Front engine lower cover n/s & o/s	CM \$ 191.80	✓
8	Front engine lower cover clip	m \$ 103.20	✓
1	Front engine mounting n/s	\$ 335.10	?
1	Front engine mounting bracket n/s	\$ 128.70	?
1	Front engine mounting rear	\$ 295.10	?
1	Front engine mounting bracket rear	\$ 125.80	?

Page 1

Page Total :

\$ 5,474.90

Page 1 balance c/f :

\$ 5,474.90

1	Front bonnet	\$ 1,260.40	X
1	Front bonnet lock	\$ 92.40	X
8	Front bonnet insulation clip	\$ 103.20	X
3	Front bonnet rear side holder clip o/s	\$ 38.70	X
2	Front bonnet rear side holder clip n/s	\$ 38.70	X
1	Front grille assy	CM \$ 434.80	✓
1	Front grille emblem	Sm \$ 1,654.60	X
1	Front grille rear sleeve holder	\$ 38.60	X
5	Front grille clip	\$ 64.50	✓
1	Headlamp assy o/s	mg CM \$ 1,804.30	✓
1	Headlamp assy n/s	Bn \$ 1,804.30	✓
1	Headlamp panel n/s	\$ Bn 305.70	✓
3	Headlamp clip n/s	ru \$ 38.70	✓
1	Headlamp panel o/s	\$ 305.70	X
3	Headlamp clip o/s	\$ 38.70	X
1	Headlamp wire harness n/s (complete front wire harness)	\$ 4,778.68	?
1	Front support top arch panel	\$ 204.20	?
1	Front support top arch panel cover garnish	\$ 245.60	?
6	Front support top arch panel cover garnish clip	\$ 77.40	?
1	Front top support panel	ru \$ 272.60	X
1	Front top support panel cover garnish	Sm \$ 214.60	X
6	Front top support panel cover garnish clip	ru \$ 77.40	X
1	Front brace panel	\$ 145.70	X
1	Front support lower member	\$ 404.70	X
1	Front aircond condenser	Sm \$ 1,486.20	X
2	Front aircond condenser side garnish n/s & o/s	Sm \$ 190.40	X
6	Front aircond condenser side garnish clip n/s & o/s	\$ 77.40	X
1	Front radiator assy	Sm \$ 2,054.60	X
1	Front radiator cooling fan assy	\$ 958.90	?
1	Front main relay box assy n/s	\$ 1,375.60	?
1	Front wiper tank assy o/s	ru \$ 220.90	✓
1	Front wiper tank motor o/s	Sm \$ 245.71	X
1	Front wiper tank motor O ring seal o/s	\$ 25.20	?
1	Front wheelhouse panel n/s	\$ 958.00	?
2	Front fender o/s & n/s	Bn \$ 1,638.80	✓
2	Front fender emblem o/s & n/s	ru \$ 115.60	✓
2	Front fender bracket o/s & n/s	Bn \$ 207.80	✓
2	Front fender undershield o/s & n/s	CM \$ 545.20	✓
16	Front fender undershield clip o/s & n/s	ru \$ 206.40	✓
2	Front fender rear partition garnish o/s & n/s	\$ 190.40	?
6	Front fender rear partition garnish clip o/s & n/s	\$ 77.40	?
2	Front fender inner sponge insulation pad o/s & n/s	\$ 544.80	?
2	Front fender wheel arch garnish o/s & n/s	Dis / CM \$ 346.40	✓
16	Front fender wheel arch garnish clip o/s & n/s	ru \$ 206.40	✓
2	Front fender wheel arch garnish front retainer o/s & n/s	Dis \$ 25.00	✓
6	Front fender wheel arch garnish front retainer clip o/s & n/s	ru \$ 77.40	✓

Page 2

Page Total :

\$ 26,218.69

Page 2 balance c/f :

\$ 31,693.59

1	Front door rear view mirror assy o/s	Br	\$	1,441.90	✓
1	Front door rear view mirror cover o/s	n/s	\$	142.70	✓
1	Front door quarter glass o/s	sn	\$	111.30	X
1	Front door quarter glass rubber o/s	sn	\$	73.80	?
1	Front door quarter glass quarter pillar o/s	n/s	\$	457.80	✓
1	Front door window glass o/s	pin	\$	543.60	✓
1	Front door window scrap moulding o/s	sn	\$	125.60	✓
1	Front door assy n/s	n	\$	1,242.30	X
1	Front door window vertical black garnish n/s	n	\$	38.90	X
1	Front door window black sticker n/s	n	\$	28.40	X
7	Front door window top black moulding rivert n/s	n	\$	90.30	X
1	Front door lower protector n/s		\$	334.70	?
8	Front door lower protector clip n/s		\$	103.20	?
1	Rocker panel side skirt n/s	cm	\$	546.70	✓
8	Rocker panel side skirt clip n/s	n	\$	103.20	✓
1	Front suspension crossmember assy		\$	2,673.20	?
1	Front suspension crossmember o/s stay		\$	113.40	?
1	Front suspension crossmember n/s stay		\$	113.40	?
2	Front knuckle arm o/s & n/s	B	\$	1,170.40	✓
2	Front lower arm o/s & n/s		\$	1,275.00	?
2	Front lower arm ball joint o/s & n/s		\$	457.00	?
2	Front shock absorber o/s & n/s	\$ B	\$	907.20	✓
2	Front shock absorber mounting o/s & n/s		\$	380.20	?
1	Front driveshaft o/s		\$	2,272.90	?
1	Front driveshaft n/s	B	\$	2,055.80	✓
2	Front wheel bearing hub o/s & n/s	B/n	\$	1,098.40	✓
1	Front stabiliser bar		\$	239.50	?
2	Front stabiliser bar rod o/s & n/s		\$	393.40	?
1	Front steering rack and pinion		\$	1,658.20	?
2	Front steering rack end tie rod		\$	257.20	?
1	Front automatic transmission assy		\$	18,385.60	?
				TOTAL \$	70,528.79
				LESS \$	17,632.20
				\$	<u>52,896.59</u>

Special Nett

1	Front radiator coolant	\$ n	50.00	?
1	Auto transmission fluid	\$	120.00	?
2	Front tyre	Pn	\$400.00	508.00
2	Front alloy sport rim	n/s	\$	1,900.00

Total Materials Cost : \$ 55,666.59

Labour Cost

To remove all damaged parts with all necessary components/attachments. To apply hot-works where necessary, straighten chassis members, repair/reshape dented body panels, in accordance with factory specifications. Replace damaged parts, refit and align into position. Refit all necessary components/attachments.

\$ 2,800.00 1600

To remove/refit air-con condenser with all necessary pipes and hoses. Vacuum and replenish cooling agent. Check for proper function.

\$ 250.00 100

To remove/refit radiator assembly with all connecting hoses. Replenish cooling agent and check for proper function.

\$ 220.00 50

To remove/refit power steering rack assembly with all attachments. Refill power steering fluid, check for proper function.

\$ 350.00

To dismantle all necessary attachments/components, pipes, hoses, wirings in order to lift engine/gearbox assembly. Refit engine/gearbox with all necessary attachments and components. Reset and test engine for proper function.

\$ 850.00 ?

To conduct engine tests and reset to factory specifications.

\$ 250.00 150

To perform diagnostic checks on control units. Reset to factory specifications

\$ 380.00 ?

To set vehicle on chassis alignment bench, inclusive of all necessary preparatory works.

\$ 380.00 250

To remove/refit front undercarriage/suspension assembly with all attachments/components.

\$ 750.00 320

To conduct wheel alignment

\$ 120.00 60

To renew n/s front wheel rim/tyre and conduct wheel balancing.	\$	150.00	} 401
To renew o/s front wheel rim/tyre and conduct wheel balancing.	\$	150.00	
To transfer door window mechanisms with motor assembly, door glass and all attachments.	nn \$	220.00	X
To remove/renew front wire harness, all related connectors. Check proper function. Focus headlights.	\$	1,200.00	?
To remove andrefix front dashboard to facilitate the repairs.	\$	650.00	?
To provide towing service using "King Dolly	(B:11) \$	150.00	?
To spray paint replaced/repared body parts inclusive of preparatory works and painting materials.	\$	2,500.00	18001
To apply underseal and rust-proofing on the affected areas.	\$	280.00	1202

DURATION OF REPAIR: TWENTY EIGHT (28) WORKING DAY

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4543E
Vehicle Details	
Vehicle No.:	SLR9705D
Vehicle to be Exported:	No
Intended Deregistration Date:	03 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR8043694
Chassis No.:	ZYX102015961
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,828.00
Original Registration Date:	31 Aug 2017
First Registration Date:	31 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$42,445.00
Total Rebate Amount:	\$46,195.00

The information contained herein is correct as at 03 May 2019

OK

Prime Motor & Leasing

Posted: 27-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A G****\$105,500****\$11,880 /yr****22-Dec-2017****1,797 cc****-****SUV****Available****Fuel Type:** Petrol-Electric

Elegant Blue SUV, "G" Edition Model With High Specifications, Low Fuel Consumption With Hybrid, Almost Brand New Condition, With Warranty, Easy Financing, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 27-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A G****\$91,800****\$10,810 /yr****22-Jun-2017****1,797 cc****26,790 km****SUV****Available****Fuel Type:** Petrol-Electric

G Model, Highest Spec, Hottest SUV, Cruise Control, Almost Like New, Someday All Car Will Be Made This Way, Call Us.

Henly Enterprises Co

Posted: 24-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S****\$89,800****\$10,590 /yr****31-Jul-2017****1,797 cc****47,000 km****SUV****Available****Fuel Type:** Petrol-Electric

23.5 Km/L Fuel Consumption! Up To 100% Loan To Drive Away! This Actual Unit Has Proven Fuel Efficiency Of 21+ Km/L! Bumble Bee Inspired, Transformer Looking Toyota C-HR 1.8A Hybrid S! TRD Leather Seat...

Don Motoring

Posted: 20-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**BlackVue DR750S Car Camera**

Equipped with Sony Starvis CMOS Sensor, this blackvue full HD cloud camera gives you best image quality under any light condition. Find the list of the best cameras available, each with product information and user reviews.

Find out more!

**Toyota C-HR Hybrid 1.8A G****\$121,000****\$13,670 /yr****28-Dec-2017****1,797 cc****26,000 km****SUV****Available****Fuel Type:** Petrol-Electric

This Almost Brand New Condition Sporty Red Suv G Led Model Comes With Toyota Safety Sense Package, Led Lights, Cruise Control And Upgraded Ent. System. Under Utilised 3rd Car. Promotion: Now Till 7 Ap...

DIRECT OWNER

Posted: 19-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S****\$93,800****\$10,550 /yr****26-Dec-2017****1,797 cc****-****SUV****Available****Fuel Type:** Petrol-Electric

Sporty Silver SUV, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, With Warranty, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 18-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S****\$86,998****\$10,490 /yr****23-May-2017****1,797 cc****52,500 km****SUV****Available****Fuel Type:** Petrol-Electric

Loan Interest At 2.28%. Extremely Well Maintained By Previous Owner, This Beast Does Not Just Look Beautiful, It's 100% Accident Free. View To Believe! Up To 70% Financing Possible! Trade In Welcome! ...

PREMIUM ED

Posted: 16-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S****\$90,800****\$10,630 /yr****22-Aug-2017****1,797 cc****-****SUV****Available****Fuel Type:** Petrol-Electric

Elegant Silver SUV, Almost Brand New Condition, One Owner Only, Low Fuel Consumption With Hybrid, Low Maintenance Cost, With Warranty, Easy Financing, Flexible In- House Loan Packages Available.

Posted: 15-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S****\$86,700****\$9,760 /yr****02-Oct-2017****1,797 cc****25,000 km****SUV****Available****Fuel Type:** Petrol-Electric

Only 1 Owner, Low Mileage, Keyless Entry With Push Start / Stop Button, Auto Folding Mirror, Very Well Maintain, Mint Condition, Bank / In-House Finance Available. Price Nego. Call Us For A Discussion...

Posted: 13-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S****\$86,998****\$9,760 /yr****27-Dec-2017****1,797 cc****21,000 km****SUV****Available****Fuel Type:** Petrol-Electric

Good Buy! Best Deal! Call Now! \$0 Drive Away! Almost New Car Conditions! Family 2nd Car! Come With 3 Years Warranty And Free Servicing With Reputable Workshop! Flexible Bank/In House Loan! Why Wait? 1...

Posted: 13-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

**Toyota C-HR Hybrid 1.8A S****\$91,800****\$10,460 /yr****14-Nov-2017****1,797 cc****800 km****SUV****Available****Fuel Type:** Petrol-Electric

In House Loan Packages Available, Low Fuel Consumption.

Motor & Leasing

Compare

Posted: 05-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota



Toyota C-HR Hybrid 1.8A G **\$95,800** **\$10,760 /yr** **26-Dec-2017** **1,797 cc** **36,000 km** **SUV** **Available**

Fuel Type: Petrol-Electric

1 Owner, Accident Free! Road Tax Just Renewed For 6 Months! Fuel Efficiency, Hybrid Electric Motor Power, High Specs G Model That's Made In Japan! What More Could You Ask For In A Car! Excellent Sport...

PREMIUM AD

Car Buyers Automotive Pte Ltd

Posted: 05-Apr-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota



Toyota C-HR Hybrid 1.8A G **\$105,800** **\$12,270 /yr** **29-Aug-2017** **1,797 cc** **32,000 km** **SUV** **Available**

Fuel Type: Petrol-Electric

Full Bodykit! Very Good Fuel Consumption, Tire Pressure Indicator, D1 Spec Rs BBK, Simota Air Intake, Cusco Strut Bar And Undercarriage Bar, 4 x Magnetic Shades, Pioneer 5850 Head Unit, Automatic Boot...

PREMIUM AD

Posted: 29-Mar-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota



Toyota C-HR Hybrid 1.8A G **\$88,300** **\$10,000 /yr** **30-Sep-2017** **1,797 cc** **24,600 km** **SUV** **Available**

Fuel Type: Petrol-Electric

Guaranteed Lowest Price! 1 Owner, Highest Spec 'G' Model With 5 Year Warranty And Servicing Till 2022. Lowest Priced, Lowest Depreciation And Low Mileage. Assured Accident Free. Welcome STA/AA Evaluat...

PREMIUM AD

Bavarian Marques Pte Ltd

Posted: 28-Mar-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota chr, toyota chr Singapore, used toyota chr Singapore, used toyota chr, used vehicles Singapore or even buy used toyota chr Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Your password will expire in 11 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION REQUEST – SLR9705D vs SLX7271U (OI) on D.O.A.: 26/04/2019

From: Hor, Yinnul
To: 'assignments@kkauto.com', Admin A (admin-a@kkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Sent: 2/5/2019 9:36:43 AM
Attachments:  20190430173813.pdf

Hi,

Please refer to the enclosed request from Vision Law LLC.

Claim no : 9635537644SG003
Case Owner : NORSIAH BTE MD NOOR

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks & Regards,

Yin Rul, Hor (Viviana)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

From: elainetoh@visionlawllc.com [mailto:elainetoh@visionlawllc.com]
Sent: Tuesday, April 30, 2019 5:46 PM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; elainetoh@visionlawllc.com
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLX7271U AND SLR9705D ON 26/04/2019

Our Ref: SLR 9705 D (et)

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email on even date.

Please find attached herein a copy of our letter dated even date for your necessary action.

Thank you.

Regards,
Elaine Toh
Vision Law LLC

Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SLR 9705 D - By fax: 64816131 only

From: Hor, Yinnul
Sent: Tue, 30 Apr 2019 07:52:15 +0000
To: Elaine Toh
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLX7271U AND SLR9705D ON 26/04/2019

Without Prejudice

Your Reference : SLR 9705 D (et)
Our Reference : 9635537644SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations - Auto
Yinnul.Hor@aig.com | www.aig.sg

From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]
Sent: Tuesday, April 30, 2019 3:24 PM
To: Hor, Yinnul
Cc: 'Lily.Tan@aig.com'; 'Andy-SY.Fong@aig.com'; 'Baljit.Kaur@aig.com'; 'Lee-Ying.Chin@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'Imran.Ishak@aig.com'; 'ShengYang.Lim@aig.com'; 'Darshene.Supramaniam@aig.com'; 'Syazairdina.Azlan@aig.com'; 'Yokeshi.chan@aig.com'; Mithoosingh, Aashweenjeetkaur
Subject: [EXTERNAL] PRE REPAIR SURVEY --- YOUR REF: SLX 7271 U--- ACCIDENT INVOLVING SLR 9705 D AND SLX 7271 U ON 26 APRIL 2019 ALONG PUNGOL DRIVE TOWARDS PUNGOL PLACE AT ABOUT 1835 HOURS
Importance: High

This message is from an external sender; be cautious with links and attachments.

Our Ref: SLR 9705 D (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by H. L. CAR RENTAL PTE LTD to notify you of a road traffic accident on 26 April 2019 at about 1835 hours along Punggol Drive towards Punggol Place involving our client's vehicle registration number SLR 9705 D and vehicle registration number SLX 7271 U driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SLR 9705 D – By fax: 64816131 only

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors
(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI DIO MUNIANDY
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
SELWYN TAN YINGXIAN
CLARISSA CHEONG YUNHUI
EDISON TAM CHYI EU
SONIA LIM WEI LEI

Unique Entity Number: 200721148H

✓HEAD OFFICE

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓: (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref : SLR 9705 D (et)
Your Ref : SLX 7271 U

30 April 2019

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attention: Motor Claims Department

BY EMAIL ONLY

Dear Sirs,

ACCIDENT INVOLVING MOTOR VEHICLE SLR 9705 D AND SLX 7271 U ON 26 APRIL 2019 ALONG PUNGGOL DRIVE TOWARDS PUNGGOL PLACE AT ABOUT 1835 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Kenneth Kong – LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : LIAN HER MOTORS
Block 5038 Ang Mo Kio Avenue 3
#01-405 Ang Mo Kio Industrial Park 2
Singapore 569541
Contact Person : Mr. James @ 8299 0599 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully



DIANE ANG
(HEAD OFFICE)

cc: SLR 9705 D – By fax: 64816131 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Claim Audit

Nk2Sinh

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	02 May 2019 16:13	Clim Dtl Modified	Claimant's Name: -> -.	[A] Nivitha Govindasamy
2	02 May 2019 16:13	Clim Veh Model Changed	(205158) KIA CERATO 1.6 (A).	[A] Nivitha Govindasamy
3	02 May 2019 16:13	Clim Created	Reg No: SLR9705D. Acct Date: 2019/04/26. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Lian Her Motors ()	[A] Nivitha Govindasamy
4	02 May 2019 16:13	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
5	02 May 2019 16:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/13	[A] Nivitha Govindasamy
6	02 May 2019 16:13	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
7	02 May 2019 16:13	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	02 May 2019 16:13	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Nivitha Govindasamy
9	07 May 2019 16:51	Label Added	(19):Fastlane.	[A] Lau Shu Pei
10	07 May 2019 16:53	Clim Dtl Modified	Claimant's Name: - -> HL CAR RENTAL PTE LTD. Claimant's ID: -> 201004543E.	[A] Lau Shu Pei
11	07 May 2019 16:53	Clim Veh Model Changed	(205158) -> (205819) TOYOTA C-HR HYBRID 1.8 S (A).	[A] Lau Shu Pei
12	10 May 2019 10:41	Video Downloaded	Downloaded SLR 9705D TP VIDEO	[I] MdNoor, Norsiah
13	23 May 2019 20:12	Video Downloaded	Downloaded SLR 9705D TP VIDEO	[I] Khoo, Kay-Eng
14	25 May 2019 12:52	Video Downloaded	Downloaded SLR 9705D TP VIDEO	[I] Khoo, Kay-Eng
15	03 Jul 2019 12:08	Video Downloaded	Downloaded SLR 9705D TP VIDEO	[I] Tan, Wilson-KL
16	03 Jul 2019 13:53	Video Downloaded	Downloaded SLR 9705D TP VIDEO	[I] Tan, Wilson-KL
17	03 Jul 2019 14:08	Video Downloaded	Downloaded SLR 9705D TP VIDEO	[I] Tan, Wilson-KL
18	02 Aug 2019 09:54	Video Downloaded	Downloaded SLR 9705D TP VIDEO	[I] Tan, Wilson-KL
19	20 Aug 2019 16:04	Video Downloaded	Downloaded SLR 9705D TP VIDEO	[I] MdNoor, Norsiah
20	04 Sep 2019 16:51	Video Downloaded	Downloaded SLR 9705D TP VIDEO	[I] Boyogan, Joane
21	04 Sep 2019 17:29	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
22	04 Sep 2019 17:29	Clim Dtl Modified	JPJ Reg. Date: -> 2017/08/31.	[A] NUR SHAQILAH BTE ABDOL WAHAB
23	04 Sep 2019 17:29	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
24	09 Sep 2019 09:54	Adj Mandate Request	Cur.Req:38660.00:LIABILITY: 100% B:15 OID CHANGED LANE HIT TP	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2140462	09 May 2019 09:38:11	Video Upload	Motor	AIG Asia Pacific Insurance Pte. Ltd.	AIG Asia Pacific Insurance Pte. Ltd. (SG)	SLR9705D	Asher Sng Rong Yi	xx.xx
2269771	04 Sep 2019 17:29:23	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLR9705D	SLX7271U	11.77

2/11/2020

Merimen e-Claims

Print Received Message

This mail is associated with :

***SLR9705D (9635537644SG)**
[SLX7271U]

TP

HL CAR RENTAL PTE LTD

Apr 26 2019 12:00AM

[GOLDBELL CAR RENTAL PTE LTD]

Lian Her Motors

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 11/02/2020 14:16 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$38660.00) - SLR9705D - Claim Handler: MdNoor, Norsiah

Approved: 38660.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Apr 2019 Edit Reg		02 May 2019 00:00 Edit Adj Rpt	\$36,500.00 Edit Estimates	\$36,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D		
Main Claimant:	HL CAR RENTAL PTE LTD, Co. Reg. No.: 201004543E		
Vehicle Reg. No.:	SLR9705D	Date of Loss:	26/04/2019 00:00 - :59 [19 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9635537644SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLX7271U	Policy No. (Claimant):	5083403664-02
		Excess:	
Repairer:	Lian Her Motors () BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405, 569541 Ang Mo Kio - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/05/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (11/02/2020): Alert - Adj Mandate Approved (\$38660.00) - SLR9705D - Claim Handler: MdNoor, No...
- AIG_SG_EXPRESS (31/10/2019): Alert - Adj Mandate Maintained - SLR9705D - Claim Handler: MdNoor, Norsiah
- AIG_SG (03/05/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR9705D (9635537644SG)**
[SLX7271U]
TP
HL CAR RENTAL PTE LTD
Apr 26 2019 12:00AM
[GOLDBELL CAR RENTAL PTE LTD]
Lian Her Motors

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)														Thumbnail		Print	
1	09/05/19 09:38		SLR 9705D TP VIDEO														Load MP4			
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)														Thumbnail		Print	
1	(Draft)		Third Party Express Settlement – Payment Breakdown														Edit			
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)														Thumbnail		Print	
1	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
2	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
3	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
4	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
5	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
6	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
7	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
8	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
9	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
10	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
11	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
12	15/08/19 12:54		Odometer Reading														Load JPG		<input checked="" type="checkbox"/>	
13	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
14	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
15	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
16	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
17	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
18	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
19	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
20	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
21	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
22	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
23	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
24	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
25	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
26	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
27	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	
28	15/08/19 12:54		General View														Load JPG		<input checked="" type="checkbox"/>	

Video			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	15/08/19 12:54	General View	1 Load JPG	✓
30	15/08/19 12:54	General View	1 Load JPG	✓
31	15/08/19 12:54	Chassis Number	1 Load JPG	✓
32	15/08/19 12:54	General View	1 Load JPG	✓
33	15/08/19 12:54	General View	1 Load JPG	✓
34	15/08/19 12:54	General View	1 Load JPG	✓
35	15/08/19 12:54	General View	1 Load JPG	✓
36	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
37	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
38	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
39	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
40	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
41	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
42	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
43	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
44	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
45	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
46	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
47	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
48	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
49	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
50	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
51	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
52	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
53	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
54	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
55	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
56	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
57	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
58	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
59	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
60	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
61	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
62	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
63	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
64	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
65	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
66	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
67	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
68	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
69	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
70	15/08/19 12:58	Reinspection Photo	1 Load JPG	✓
71	15/08/19 12:58	Photo After Spray	1 Load JPG	✓
72	15/08/19 12:58	Photo After Spray	1 Load JPG	✓
73	15/08/19 12:58	Photo After Spray	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/19 16:52	EMAIL FROM AIG DD 02052019	1 Load PDF	

Video			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
2	07/05/19 16:52	NOTICE	Load PDF	
3	08/05/19 10:13	TP ESTIMATE- MARKED	Load PDF	
4	08/05/19 10:13	TP GIA REPORT	Load PDF	
5	05/09/19 17:54	LETTER TO OI	Load PDF	
6	05/09/19 17:54	LOD	Load PDF	
7	04/10/19 10:07	LTA PARF COE Rebate Details	Load PDF	
8	14/02/20 16:00	Authorisation to Act	Load PDF	
9	14/02/20 16:00	Release Voucher	Load PDF	
10	14/02/20 16:00	WORKSHOP INVOICE	Load PDF	
11	14/02/20 16:00	RENTAL RECEIPT	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/05/19 11:46	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLX7271U (Insd veh)	Model:	TOYOTA C-HR HYBRID 1.8 S
	SLR9705D (TP veh)		CVT (A)
Date of Accident:	26/04/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	67,316.59
Final Repair Cost	:	\$	36,500.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	2,160.00 18 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	38,660.00

Is Third Party Workshop GIA Registered?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:	Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks	_____		

Payment Instruction: Payee's Breakdown			
1)	Lian Her Motors	:	\$ 38,660.00
2)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

14 Feb
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19007727/KES3S2

Date: 14/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLR9705D

Insured Vehicle No : SLX7271U

Date of Loss: 26/04/2019

Nature of Claim: TP

Claim No: 9635537644SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR9705D

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A)

Engine No: 2ZR8043694

Reg. Date: 31/08/2017 (Man. Year: 2017)

Chassis No: ZYX102015961

Colour: Metallic Grey

Odometer: 139917 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size:

215/60 R17

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,666.59	39,008.67	16,657.92	29.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,650.00	5,530.00	6,120.00	52.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	67,316.59	44,538.67	22,777.92	33.84
Approved Total (Overridden) (S\$)		36,500.00		
Nett Amount (S\$)	67,316.59	36,500.00	30,816.59	45.78
+ Car Rental (18.0 x S\$120.00/day) (S\$)		2,160.00		
Nett Liability (S\$)		38,660.00		

INSPECTION

Date of Assignment: 02/05/2019

Date Inspected: 02/05/2019 Inspected At:

Lian Her Motors
BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405
Singapore 569541

Estimated Period of Repair: 18.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Bent / Cracked	1,236.70 FL	*1,236.70 FL
2	2		*FRONT BUMPER SIDE RETAINER	Cracked	232.60 FL	*232.60 FL
3	1		*FRONT BUMPER SIDE TRIANGLE GARNISH O/S & N/S	N/s Missing	157.20 FL	*78.60 FL
4	10		*FRONT BUMPER CLIP	Necessary	129.00 FL	*129.00 FL
5	1		*FRONT BUMPER CENTRE AIR GRILLE	Serviceable	154.70 FL	*- FL
6	1		*FRONT BUMPER NUMBER PLATE PLINTH	Serviceable	122.80 FL	*- FL
7	1		*FRONT BUMPER TOW HOOK COVER	Serviceable	38.00 FL	*- FL
8	1		*FRONT BUMPER LOWER SKIRT	Distorted / Cut	499.30 FL	*499.30 FL
9	2		*FRONT BUMPER LOWER SKIRT SENSOR COVER O/S & N/S	Serviceable	55.20 FL	*- FL
10	1		*FRONT BUMPER SPORT LAMP COVER N/S	Dented	177.60 FL	*177.60 FL
11	1		*FRONT BUMPER LOWER SKIRT CLIP	Necessary	129.00 FL	*129.00 FL
12	1		*FRONT BUMPER UPPER REINFORCEMENT	Repair	461.60 FL	*- FL
13	1		*FRONT BUMPER UPPER REINFORCEMENT SPONGE	Missing	90.20 FL	*90.20 FL
14	1		*FRONT BUMPER UPPER REINFORCEMENT BRACKET	N/s Distorted / O/s Repair	354.20 FL	*177.10 FL
15	1		*FRONT BUMPER LOWER REINFORCEMENT	Repair	237.60 FL	*- FL
16	1		*FRONT BUMPER LOWER REINFORCEMENT SPONGE	Missing	75.30 FL	*75.30 FL
17	1		*FRONT BUMPER LOWER REINFORCEMENT BRACKET	N/s Distorted / O/s Repair	144.20 FL	*72.10 FL
18	2		*FRONT ENGINE LOWER COVER N/S & O/S	Cracked	191.80 FL	*191.80 FL
19	8		*FRONT ENGINE LOWER COVER CLIP	Necessary	103.20 FL	*103.20 FL
20	1		*FRONT ENGINE MOUNTING N/S	Cracked	335.10 FL	*335.10 FL
21	1		*FRONT ENGINE MOUNTING BRACKET N/S	Distorted	128.70 FL	*128.70 FL
22	1		*FRONT ENGINE MOUNTING REAR	Cracked	295.10 FL	*295.10 FL
23	1		*FRONT ENGINE MOUNTING BRACKET REAR	Distorted	125.80 FL	*125.80 FL
24	1		*FRONT BONNET	Repair	1,260.40 FL	*- FL
25	1		*FRONT BONNET LOCK	Repair	92.40 FL	*- FL
26	8		*FRONT BONNET INSULATION CLIP	Not Necessary	103.20 FL	*- FL
27	3		*FRONT BONNET REAR SIDE HOLDER CLIP O/S	Not Necessary	38.70 FL	*- FL
28	2		*FRONT BONNET REAR SIDE HOLDER CLIP N/S	Not Necessary	38.70 FL	*- FL
29	1		*FRONT GRILLE ASSY	Cracked	434.80 FL	*434.80 FL
30	1		*FRONT GRILLE EMBLEM	Serviceable	1,654.60 FL	*- FL
31	1		*FRONT GRILLE REAR SLEEVE HOLDER	Serviceable	38.60 FL	*- FL
32	5		*FRONT GRILLE CLIP	Necessary	64.50 FL	*64.50 FL
33	1		*HEADLAMP ASSY O/S	Mtg Cracked	1,804.30 FL	*1,804.30 FL
34	1		*HEADLAMP ASSY N/S	Broken	1,804.30 FL	*1,804.30 FL
35	1		*HEADLAMP PANEL N/S	Bent	305.70 FL	*305.70 FL
36	3		*HEADLAMP CLIP N/S	Necessary	38.70 FL	*38.70 FL
37	1		*HEADLAMP PANEL O/S	Repair	305.70 FL	*- FL
38	3		*HEADLAMP CLIP O/S	Not Necessary	38.70 FL	*- FL
39	1		*HEADLAMP WIRE HARNESS N/S (COMPLETE FRONT WIRE HARNESS)	Torn	4,778.68 FL	*4,321.70 FL
40	1		*FRONT SUPPORT TOP ARCH PANEL	Bent	204.20 FL	*204.20 FL
41	1		*FRONT SUPPORT TOP ARCH PANEL COVER GARNISH	Cracked	245.60 FL	*245.60 FL
42	6		*FRONT SUPPORT TOP ARCH PANEL COVER GARNISH CLIP	Necessary	77.40 FL	*77.40 FL
43	1		*FRONT TOP SUPPORT PANEL	Repair	272.60 FL	*- FL
44	1		*FRONT TOP SUPPORT PANEL COVER GARNISH	Serviceable	214.60 FL	*- FL
45	6		*FRONT TOP SUPPORT PANEL COVER GARNISH CLIP	Not Necessary	77.40 FL	*- FL
46	1		*FRONT BRACE PANEL	Repair	145.70 FL	*- FL
47	1		*FRONT SUPPORT LOWER MEMBER	Punctured	404.70 FL	*404.70 FL
48	1		*FRONT AIRCOND CONDENSER	Bent	1,486.20 FL	*1,486.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	2		*FRONT AIRCOND CONDENSER SIDE GARNISH N/S & O/S	Serviceable	190.40 FL	*-FL
50	6		*FRONT AIRCOND CONDENSER SIDE GARNISH CLIP N/S & O/S	Not Necessary	77.40 FL	*-FL
51	1		*FRONT RADIATOR ASSY	Punctured	2,054.60 FL	*1,841.80 FL
52	1		*FRONT RADIATOR COOLING FAN ASSY	Cracked	958.90 FL	*958.90 FL
53	1		*FRONT MAIN RELAY BOX ASSY N/S	Serviceable	1,375.60 FL	*-FL
54	1		*FRONT WIPER TANK ASSY O/S	Dented	220.90 FL	*220.90 FL
55	1		*FRONT WIPER TANK MOTOR O/S	Serviceable	245.71 FL	*-FL
56	1		*FRONT WIPER TANK MOTOR O RING SEAL O/S	Serviceable	25.20 FL	*-FL
57	1		*FRONT WHEELHOUSE PANEL N/S	Bent	958.00 FL	*958.00 FL
58	2		*FRONT FENDER O/S & N/S	Bent	1,638.80 FL	*1,638.80 FL
59	2		*FRONT FENDER EMBLEM O/S & N/S	Necessary	115.60 FL	*115.60 FL
60	2		*FRONT FENDER BRACKET O/S & N/S	Bent	207.80 FL	*207.80 FL
61	2		*FRONT FENDER UNDERSHIELD O/S & N/S	Cracked	545.20 FL	*545.20 FL
62	16		*FRONT FENDER UNDERSHIELD CLIP O/S & N/S	Necessary	206.40 FL	*206.40 FL
63	2		*FRONT FENDER REAR PARTITION GARNISH O/S & N/S	Serviceable	190.40 FL	*-FL
64	6		*FRONT FENDER REAR PARTITION GARNISH CLIP O/S & N/S	Not Necessary	77.40 FL	*-FL
65	2		*FRONT FENDER INNER SPONGE INSULATION PAD O/S & N/S	Serviceable	544.80 FL	*-FL
66	2		*FRONT FENDER WHEEL ARCH GARNISH O/S & N/S	Distorted / Cracked	346.40 FL	*346.40 FL
67	16		*FRONT FENDER WHEEL ARCH GARNISH CLIP O/S & N/S	Necessary	206.40 FL	*206.40 FL
68	2		*FRONT FENDER WHEEL ARCH GARNISH FRONT RETAINER O/S & N/S	Distorted	25.00 FL	*25.00 FL
69	6		*FRONT FENDER WHEEL ARCH GARNISH FRONT RETAINER CLIP O/S & N/S	Necessary	77.40 FL	*77.40 FL
70	1		*FRONT DOOR REAR VIEW MIRROR ASSY O/S	Broken	1,441.90 FL	*1,441.90 FL
71	1		*FRONT DOOR REAR VIEW MIRROR COVER O/S	Missing	142.70 FL	*142.70 FL
72	1		*FRONT DOOR QUARTER GLASS O/S	Serviceable	111.30 FL	*-FL
73	1		*FRONT DOOR QUARTER GLASS RUBBER O/S	Serviceable	73.80 FL	*-FL
74	1		*FRONT DOOR QUARTER GLASS QUARTER PILLAR O/S	Dented	457.80 FL	*457.80 FL
75	1		*FRONT DOOR WINDOW GLASS O/S	Cut	543.60 FL	*543.60 FL
76	1		*FRONT DOOR WINDOW SCRAP MOULDING O/S	Scratched	125.60 FL	*125.60 FL
77	1		*FRONT DOOR ASSY N/S	Repair	1,242.30 FL	*-FL
78	1		*FRONT DOOR WINDOW VERTICAL BLACK GARNISH N/S	Not Necessary	38.90 FL	*-FL
79	1		*FRONT DOOR WINDOW BLACK STICKER N/S	Not Necessary	28.40 FL	*-FL
80	1		*FRONT DOOR WINDOW TOP BLACK MOULDING RIVET N/S	Not Necessary	90.30 FL	*-FL
81	1		*FRONT DOOR LOWER PROTECTOR N/S	Dented	334.70 FL	*334.70 FL
82	8		*FRONT DOOR LOWER PROTECTOR CLIP N/S	Necessary	103.20 FL	*103.20 FL
83	1		*ROCKER PANEL SIDE SKIRT N/S	Cracked	546.70 FL	*546.70 FL
84	8		*ROCKER PANEL SIDE SKIRT CLIP N/S	Necessary	103.20 FL	*103.20 FL
85	1		*FRONT SUSPENSION CROSSMEMBER ASSY	Bent	2,673.20 FL	*2,673.20 FL
86	1		*FRONT SUSPENSION CROSSMEMBER O/S STAY	Distorted	113.40 FL	*113.40 FL
87	1		*FRONT SUSPENSION CROSSMEMBER N/S STAY	Distorted	113.40 FL	*113.40 FL
88	2		*FRONT KNUCKLE ARM O/S & N/S	Bent	1,170.40 FL	*1,170.40 FL
89	2		*FRONT LOWER ARM O/S & N/S	Bent / Distorted	1,275.00 FL	*1,275.00 FL
90	2		*FRONT LOWER ARM BALL JOINT O/S & N/S	Bent	457.00 FL	*457.00 FL
91	2		*FRONT SHOCK ABSORBER O/S & N/S	Bent	907.20 FL	*907.20 FL
92	2		*FRONT SHOCK ABSORBER MOUNTING O/S & N/S	Bent	380.20 FL	*380.20 FL
93	1		*FRONT DRIVESHAFT O/S	Bent	2,272.90 FL	*1,535.90 FL
94	1		*FRONT DRIVESHAFT N/S	Bent	2,055.80 FL	*1,345.80 FL
95	2		*FRONT WHEEL BEARING HUB O/S & N/S	Bent / Necessary	1,098.40 FL	*1,098.40 FL
96	1		*FRONT STABILIZER BAR	Distorted	239.50 FL	*239.50 FL
97	2		*FRONT STABILIZER BAR ROD O/S & N/S	Serviceable	393.40 FL	*-FL
98	1		*FRONT STEERING RACK AND PINION	Bent / Jammed	1,658.20 FL	*1,658.20 FL
99	2		*FRONT STEERING RACK END TIE ROD	Serviceable	257.20 FL	*-FL
100	1		*FRONT AUTOMATIC TRANSMISSION ASSY (LOCAL REPAIR)	Housing Cracked	13,789.20 FS	*7,000.00 FS
101	1		*FRONT RADIATOR COOLANT	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
102	1		*AUTO TRANSMISSION FLUID	Necessary	120.00 FS	*120.00 FS
103	1		*FRONT TYRE	Punctured	700.00 FS	*400.00 FS
104	1		*FRONT ALLOY SPORT RIM	Dented	1,900.00 FS	*1,900.00 FS
F=Franchise part, S=SpcNett, L=ListItemDisc.						
Sub Total (\$\$)					68,702.39	48,854.90
- List Item Discount on L Items 25.00/25.00% (\$\$)					13,035.80	9,846.23
Total Parts (\$\$)					55,666.59	39,008.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENTS / ATTACHMENTS. TO APPLY HOT-WORKS WHERE NECESSARY, STRAIGHTEN CHASSIS MEMBERS, REPAIR / RESHAPE DENTED BODY PANELS. IN ACCORDANCE WITH FACTORY SPECIFICATION. REPLACE DAMAGED PARTS, REFIT AND ALIGN INTO POSITION. REFIT ALL NECESSARY COMPONENTS / ATTACHMENTS.	New	2,800.00	1,600.00
2	TO REMOVE / REFIT AIR-CON CONDENSER WITH ALL NECESSARY PIPS AND HOSES. VACUUM AND REPLENISH COOLING AGENT. CHECK FOR PROPER FUNCTION.	New	250.00	100.00
3	TO REMOVE / REFIT RADIATOR ASSEMBLY WITH ALL CONNECTING HOSES. REPLENISH COOLING AGENT AND CHECK FOR PROPER FUNCTION.	New	220.00	50.00
4	TO REMOVE / REFIT POWER STEERING RACK ASSEMBLY WITH ALL ATTACHMENTS. REFILL POWER STEERING FLUID, CHECK FOR PROPER FUNCTION.	New	350.00	0.00
5	TO REMOVE / REFIT FRONT UNDERCARRIAGE / SUSPENSION ASSEMBLY WITH ALL ATTACHMENTS / COMPONENTS.	New	750.00	320.00
6	TO DISMANTLE ALL NECESSARY ATTACHMENTS / COMPONENTS, PIPES, HOSES, WIRING IN ORDER TO LIFT ENGINE / GEARBOX ASSEMBLY. REFIT ENGINE / GEARBOX WITH ALL NECESSARY ATTACHMENTS AND COMPONENTS . RESET AND TEST ENGINE FOR PROPER FUNCTION.	New	850.00	450.00
7	TO CONDUCT ENGINE TESTS AND RESET TO FACTORY SPECIFICATIONS.	New	250.00	150.00
8	TO PERFORM DIAGNOSTIC CHECKS ON CONTROL UNITS. RESET TO FACTORY SPECIFICATIONS.	New	380.00	180.00
9	TO SET VEHICLE ON CHASSIS ALIGNMENT BENCH, INCLUSIVE OF ALL NECESSARY PREPARATORY WORKS.	New	380.00	250.00
10	TO CONDUCT WHEEL ALIGNMENT.	New	120.00	60.00
11	TO RENEW N/S FRONT WHEEL RIM / TYRE AND CONDUCT WHEEL BALANCING.	New	150.00	40.00
12	TO RENEW O/S FRONT WHEEL RIM / TYRE AND CONDUCT WHEEL BALANCING.	New	150.00	0.00
13	TO TRANSFER DOOR WINDOW MECHANISMS WITH MOTOR ASSEMBLY, DOOR GLASS AND ALL ATTACHMENTS.	New	220.00	0.00
14	TO REMOVE / RENEW FRONT WIRE HARNESS, ALL RELATED CONNECTORS. CHECK FOR PROPER FUNCTION. FOCUS HEADLIGHTS.	New	1,200.00	350.00
15	TO REMOVE AND REFIX FRONT DASHBOARD TO FACILITATE THE REPAIRS.	New	650.00	0.00
16	TO PROVIDE TOWING SERVICES USING KING DOLLY.	New	150.00	60.00
17	TO SPRAY PAINT REPLACED / REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.	New	2,500.00	1,800.00
18	TO APPLY UNDERSEAL AND RUST-PROOFING ON THE AFFECTED AREAS.	New	280.00	120.00
Gross Labour Cost (\$\$)			11,650.00	5,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >