

龙胜汽车服务 LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate
Singapore 678007

Tel: 67639733 Fax: 67639866
Email: lsmstyc@singnet.com.sg

hweejie@lkkauto.com

91803151

Poh Kin

Hwee Jie - LKK
3/5/19

L/S 6days. \$5600

Date: 29.04.2019
Owner: FRANCIS EMMANUEL NG HNG YONG
Attention: EQ Insurance Company Ltd - Motor Claims Department

RE: ACCIDENT FOR VEHICLE NO. SJK1955L HONDA STREAM 1.8X A (2007) DOA: 28.04.2019
estimated cost of repair of the above mentioned vehicle:-

Replacement Parts:-

Page 1

1 pc	Rear Bumper	DEF ✓	\$	793.10 ✓
2 pcs	Rear Bumper Side Retainer LH/RH @ S\$31.40	rec ✓	\$	62.80 ✓
10 pcs	Rear Bumper Clip @ S\$4.50	rec ✓	\$	30 45.00 ✓
1 pc	Rear Tailgate	BUC ✓	\$	916.40 ✓
1 pc	Rear Tailgate Outer Garnish	CRA ✓	\$	229.10 ✓
1 pc	Rear Tailgate Outer Garnish Logo Emblem	rec ✓	\$	39.10 ✓
1 pc	Rear Tailgate "STREAM" Emblem	rec ✓	\$	42.10 ✓
1 pc	Rear Tailgate Inner Lock	Jam ✓	\$	181.90 ✓
1 pc	Rear Tailgate Inner Weatherstrip	DEF ✓	\$	183.70 ✓
1 pc	Rear Tailgate Inner Trim	SCR ✓	\$	231.80 ✓
10 pcs	Rear Tailgate Inner Trim Clip @ S\$4.50	rec ✓	\$	20 45.00 ✓
1 pc	Rear Tailgate Wiper Arm	CRA ✓	\$	69.10 ✓
1 pc	Rear Tailgate Wiper Motor	Jam ✓	\$	361.90 ✓
1 pc	Rear Tailgate Windscreen Glass	CRA ✓	\$	923.10 ✓
1 pc	Rear Tailgate Windscreen Glass Moulding	rec ✓	\$	75.10 ✓
2 pcs	Rear Tail Lamp LH/RH @ S\$391.30	SCR ✓	\$	782.60 ✓
1 pc	Rear End Panel	BUC ✓	\$	381.10 ✓
1 pc	Rear End Panel Inner Garnish	DEF ✓	\$	171.60 ✓
10 pcs	Rear End Panel Inner Garnish Clip @ S\$4.50	rec ✓	\$	20 45.00 ✓
2 pcs	Rear Fender Inner Trim LH/RH @ S\$292.10	CRA ✓	\$	584.20 ✓
Less 20%			\$	6,163.70 6078.70
			\$	(1,232.74) (1215.74)
			\$	4,930.96 4862.96

To Repair

1pc Rear Floor Panel - To Repair

Special Nett:

Rear Number Plate	nn x	\$	60.00
Reverse Sensor	shorted ✓	\$	200 280.00
Rear Windscreen Sealant	rec ✓	\$	60 80.00
Towing Charges		\$	60.00 ✓

Add :

Labour Charges		\$	880.00 800 ✓
Spray Painting		\$	900.00 800 ✓
To Remove & Replace Rear Tailgate and Compartment		\$	180.00 50 ✓
To Remove & Replace Rear Tailgate Windscreen		\$	120.00 ✓
To Remove & Replace Rear Reverse Sensor		\$	60.00 30 ✓
Toff Kote		\$	80.00 40 ✓
Check Wiring		\$	60.00 20 ✓
Total Amount :		\$	7,690.96 7180