



Case Details

Case Reference Number : BUS/04/19/5056
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB1573S

Company Type : SMRT Buses Ltd
 Estimation ID : EST-6679-ID
 Assigned By : Audrey Woo Yee Shin

Insurance Company Name : India International Insurance Pte Ltd
 Accident Date and Time : 29/04/2019 12:00 AM
 Vehicle Age(In Months) : 52

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main	Body	6010153	COVER,HEADLAMP:FRT,LH,FOR MAN A22 BUS	1	974.70	974.70	10.00	877.23	Replace	1	877.2	Replace	
Standard	Main	Body	6010151	BUMPER,FRONT:CENTRE,FOR MAN A22 BUS	1	1,868.80	1,868.80	10.00	1,681.92	Replace	1	1,681	Replace	
Standard	Main	VE	6010304	HEADLAMP,LH (MAN BUS)	1	1,603.60	1,603.60	10.00	1,443.24	Replace	1	1,443	Replace	
Standard	Main	VE	6010306	FLASHER,AUX HEADLAMP,LH (MAN BUS)	1	904.40	904.40	10.00	813.96	Replace	1	813.9	Replace	
Total Spare Part Cost									4,816.35		Surveyor Total		4,816.35	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)		20.00	
Final Spare Part Cost									3,853.08		Final Sur Total		3,853.08	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,590.00	1,060.00	
Total:			1,590.00	1,060.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	878.00	708.00	
Total:			878.00	708.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,853.08	3,853.08
Total Labour Cost	1,590.00	1,060.00
Total Spray Painting	878.00	708.00
Other	0.00	0.00
Overall Total	6,321.08	5,621.08
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	0.00	5,600.00
Surveyor Approved Amount		5,600.00
No of Repair Days*	4	3
Remarks	-	L/S REPAIR. AFTER PAINT PHOTO.
Surveyor Name		Hwee jie
Signature		
Survey Date	02/05/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: