

REF: OSI/IPC19007738/bq d3 s2

Special Instruction:

From Person: Lilian Sim of IPC Date/Time: 29/4/2019  
 Estimated Cost: Nil Bill to:

Part by Part: \$13,383.82

Third Parties:

Claimant:

Surveyor: Tbc AutomobileWorkshop: Ming Hwa AutoOD/TP Re-inspection EvaluationTo Inspect Vehicle No: SGV1546L Insured: JKA 8736at Workshop m/s Ming Hwa Auto Tel: of 160 Sin Ming Drive # 02-16Policy No:  Claim No: 17/17/17/VC10/244777Sum Insured:  Excess: Make of Veh:  D.O.A.: 3/7/2017  
(Client's Record)

Market value of the vehicle at the material time of accident.

H.O.D. Enforcement/Date: Date/Time:  Person Contacted:  Vehicle IN / OUTDate/Time:  Confirmed with  Final Fig  days (Red \$  /  %; Original 9 days)Date/Time:  Submit Final Fig  days (Red \$  /  %; Original 9 days)

| Date/Time | Action/Instruction                 |
|-----------|------------------------------------|
| 2/5/19    | pending TP GIA Report<br>SGV1546-L |

08/15/19 To Submit 2/5 4100/- with 5 days of inv. (Red \$ 9,283.32, 69%)

Most items indicated HW as photos show no damage. Part price checked.

MV abt 33K at time of loss.

Vehicle renewed COE, one with later amount - So MV is COE paid + PARF

Para(1): Parts found not replaced (To highlight R or UB, LR, Etc)

RECEIVED 09 MAY 2019

Para(2): Comments on consistency of damages (Parts Not Consistent: NC)

Para(3): Nett Value

\* Market Value: \$ 33000 (est)  
 LTA  
 Salvage Value: \$ 24891 (est)  
 Nett Value: \$ 8109

Inspected/  
 Evaluated by:

Fee Charged:

Date:

Basic & Add  
 Transport  
 Photos  
 Others  
 Total

120

1) Date/Time: 29/5/19 File Pass to: turner3) Date/Time:  File Pass to: 5) Date/Time:  File Pass to: 2) Date/Time:  File Return to: 4) Date/Time:  File Return to: 6) Date/Time:  File Return to:

**Nivitha (LKK Auto)**

---

**From:** LILLIAN SIM BEE LIAN <lilliansim@lonpac.com>  
**Sent:** Monday, 29 April 2019 5:25 PM  
**To:** 'Admin-D (LKKAuto)'  
**Cc:** GERALD POH WEE BIN  
**Subject:** Second opinion - SGV 1546 L; DOL : 03/07/2017; OUR REF : 17/17/17/VC10/244777  
[External Confidential]  
**Attachments:** 244777 DOCS.pdf

**Lonpac External - Confidential**  
**WITHOUT PREJUDICE**

Dear Sirs,,

Refer to the above.

Would appreciate if you could help to get a second opinion from your panel adjusters on the reasonability of cost of repairs to the claimant's vehicle vis a vis the circumstances of accident as well as the **market value of the vehicle at the material time of accident**.

Attached please find the following:-

- 1) Claimant's survey report.
- 2) Vehicle registration details.

Thanks and regards,

LILLIAN SIM

**CLAIMS DEPARTMENT | LONPAC INSURANCE BHD**

T : 03-27237716 F : 03-20342654 EMAIL : lilliansim@lonpac.com

*Lonpac External - Confidential data is for use by authorised external parties only.*

## Shiau Chan (LKKAUTO)

---

**From:** LILLIAN SIM BEE LIAN <lilliansim@lonpac.com>  
**Sent:** Monday, 6 May 2019 2:55 PM  
**To:** Shiau Chan (LKKAUTO); Admin-D (LKKAUTO)  
**Cc:** GERALD POH WEE BIN  
**Subject:** RE: Second opinion - SGV 1546 L; DOL : 03/07/2017; OUR REF : 17/17/17/VC10/244777 [External Confidential]

### **Lonpac External - Confidential** **WITHOUT PREJUDICE**

Dear Shiau Chan,

Please note that our insured vehicle is JKA 8736.

Thanks and regards,

LILLIAN SIM

**CLAIMS DEPARTMENT | LONPAC INSURANCE BHD**

T : 03-27237716 F : 03-20342654 EMAIL : lilliansim@lonpac.com

*Lonpac External - Confidential data is for use by authorised external parties only.*

---

**From:** Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]  
**Sent:** Monday, 6 May, 2019 9:19 AM  
**To:** LILLIAN SIM BEE LIAN; Admin-D (LKKAUTO)  
**Cc:** GERALD POH WEE BIN  
**Subject:** RE: Second opinion - SGV 1546 L; DOL : 03/07/2017; OUR REF : 17/17/17/VC10/244777 [External Confidential]

Dear Lillian,

Kindly advise your insured vehicle is PLQ 5421 or JKA 8736.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** LILLIAN SIM BEE LIAN <lilliansim@lonpac.com>  
**Sent:** Friday, 3 May 2019 4:37 PM  
**To:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Cc:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Subject:** RE: Second opinion - SGV 1546 L; DOL : 03/07/2017; OUR REF : 17/17/17/VC10/244777 [External Confidential]

### **Lonpac External - Confidential** **WITHOUT PREJUDICE**

Dear Sirs,



KETUA POLIS DAERAH  
IBU PEJABAT POLIS DAERAH JOHOR BAHRU SELATAN  
80250 JOHOR BAHRU  
JOHOR

Tel : 072237977 Samb :

Ruj : J/BAHRU SELATAN/JKDNKA/KST/06006/17  
Tkh : 06-07-2017

LOO CHEE MENG No KP : 600823065059  
NO 46 JALAN SETIA 11/4 TAMAN SETIA INDAH JOHOR BAHRU  
81100 - Motokar SGV1546L

KEPUTUSAN PENYIASATAN KES

No. Pengaduan Polis : TRAFIK JOHOR BAHRU(S)/014658/17  
Tkh/Masa Rpt : 03-07-2017 22:10 HRS  
Kesalahan : R10 LN166/59  
Tkh/Masa Kemalangan : 03-07-2017 18:50 HRS  
Tempat Kemalangan : E LEBUHRAYA UTARA SELATAN

Dengan hormatnya saya merujuk kepada pengaduan yang dibuat sepertimana dinyatakan di atas.

2. Untuk makluman, pihak yang bertanggungjawab melakukan kesalahan di atas telah disaman polis (RM 300.00) pada 06-Jul-17 (AU470752).

3. Butir-butir pihak yang disalahkan adalah seperti berikut :-

NEO TIONG HUAT KP : 580927015245  
NO 18 JALAN GEMILANG 2/2 B TAMAN BANANG JAYA BATU PAHAT  
83000  
JKA8736 PEMANDU Lori Kecil

**"BERHATI-HATI DI JALAN RAYA"**

SYED AMRAN SYED ABAS (SJN 123364)  
PEN. PEG. PENYIASAT TRAFIK  
BALAI POLIS TRAFIK (JBS)  
JOHOR BAHRU

(R123364 - SYED AMRAN B. SYED ABAS)  
AIO TRAFIK  
80250 JOHOR BAHRU

s . k KST No : J/BAHRU SELATAN/JKDNKA/KST/06006/17  
[Notis ini hanya sebagai makluman anda sahaja]

SALINAN YANG DISAHKAN BENAR  
(HANYA UNTUK TUNTUTAN SIVIL)

KETUA TRAFIK DAERAH, JOHOR BAHRU, JOHOR.  
TIDAK BOLEH DIGUNAKAN UNTUK TUJUAN PERBICARAAN



# POLIS DIRAJA MALAYSIA

REPOt POLIS

Balai : TRAFIK JOHOR BAHRU(S) Pegawai Penyiasat : R123364  
Daerah : J/BAHRU SELATAN  
Kontinjen : JOHOR  
No Repot : TRAFIK JOHOR BAHRU(S)/014658/17  
Tarikh : 03/07/2017  
Waktu : 2210 PM  
Bahasa Diterima : B. Malaysia

## Butir-butir Penerima Repot

Nama : MUHAMMAD HELMI CHIN B ABDULLAH No Personel : R113900 Pangkat : L/KPL  
Butir-butir Jurubahasa (Jika Ada)  
Nama : --- No K/P (Baru) : --- No Polis/Tentera : ---  
No Pasport : --- Bahasa Asal : ---  
Alamat : ---

## Butir-butir Pengadu

Nama : LOO CHEE MENG  
No K/P (Baru) : 600823065059 No Polis/Tentera : 5964140 No Pasport : ---  
No Sijil Beranak : ---  
Jantina : Lelaki Tarikh Lahir : 23/08/1960 Umur : 56 tahun 10 bulan  
Keturunan : Cina Warganegara : Malaysia  
Pekerjaan : AIRCORN  
Alamat Tempat Tinggal : NO 46 JALAN SETIA 11/4 TAMAN SETIA INDAH 81100 JOHOR BAHRU JOHOR  
MALAYSIA  
Alamat Ibu/Bapa : ---  
Alamat Pejabat : ---  
No Tel (Rumah) : --- No Tel (Pejabat) : --- No Tel (HP) : 016-7823813  
Emel : ---

## Pengadu Menyatakan:-

PADA 3/7/2017 JAM LEBIH KURANG 1850HRS SAYA MEMANDU M/KAR SGV1546L DARI SINGAPURA MAHU  
BALIK TAMAN SETIA INDAH TIBA DI KM 2,5 LEBUHRAYA UTARA SELATAN TIBA-TIBA SEBUAH M/KAR  
PLQ5421 TELAH TERLANGGAR M/KAR SAYA DARI BELAKANG,KEROSAKAN M/KAR BUMPER  
BELAKANG,BONET BELAKANG,MARGART KANAN BELAKANG,LAMPU BESAR BELAKANG KANAN,SEKIAN  
LAPORAN SAYA.

Tandatangan Pengadu: Tandatangan Jurubahasa(Jika ada): Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak : R123364 | 06/07/2017 07:30:11 PM

SALINAN YANG DISAHKAN BEHAR  
(HANYA UNTUK TUNTUTAN SIVIL)

KETUA TRAFIK DAERAH, JOHOR BAHRU, JOHOR.  
TIDAK BOLEH DIGUNAKAN UNTUK TUJUAN PERBICARAAN

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars                                                                                                                                                                                               |                          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|
| Owner ID Type:                                                                                                                                                                                                          | Company                  |
| Owner ID:                                                                                                                                                                                                               | 0452E                    |
| Vehicle Details                                                                                                                                                                                                         |                          |
| Vehicle No.:                                                                                                                                                                                                            | SGV1546L                 |
| Vehicle to be Exported:                                                                                                                                                                                                 | No                       |
| Intended Deregistration Date:                                                                                                                                                                                           | 06 May 2019              |
| Vehicle Make:                                                                                                                                                                                                           | HONDA                    |
| Vehicle Model:                                                                                                                                                                                                          | AIRWAVE 1.5 A            |
| Primary Colour:                                                                                                                                                                                                         | Silver                   |
| Manufacturing Year:                                                                                                                                                                                                     | 2007                     |
| Engine No.:                                                                                                                                                                                                             | L15A5130056              |
| Chassis No.:                                                                                                                                                                                                            | GJ11125123               |
| Maximum Power Output:                                                                                                                                                                                                   | 81.0 kW (108 bhp)        |
| Open Market Value:                                                                                                                                                                                                      | \$15,168.00              |
| Original Registration Date:                                                                                                                                                                                             | 06 Jun 2007              |
| First Registration Date:                                                                                                                                                                                                | 06 Jun 2007              |
| Transfer Count:                                                                                                                                                                                                         | 1                        |
| Actual ARF Paid:                                                                                                                                                                                                        | \$16,685.00              |
| Intended PARF Rebate Details                                                                                                                                                                                            |                          |
| PARF Eligibility:                                                                                                                                                                                                       | Forfeited                |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | -                        |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$0.00                   |
| Intended COE Rebate Details                                                                                                                                                                                             |                          |
| COE Expiry Date:                                                                                                                                                                                                        | 05 Jun 2022              |
| COE Category:                                                                                                                                                                                                           | A - Car (1600cc & below) |
| COE Period(Years):                                                                                                                                                                                                      | 5                        |
| PQP Paid:                                                                                                                                                                                                               | \$25,313.00              |
| COE Rebate Amount:                                                                                                                                                                                                      | \$15,598.00              |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$15,598.00</b>       |
| Message                                                                                                                                                                                                                 |                          |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                          |

The information contained herein is correct as at 06 May 2019

OK

DOA: 03/7/17  
PARF = NIL  
COE = PQP  $\times \frac{\text{bal mth}}{60}$   
=  $25313 \times \frac{59}{60}$   
= 24891.  
LTA = PARF + COE = 24891.



**POLIS DIRAJA MALAYSIA**  
REPOT POLIS

Balai : TRAFIK JOHOR BAHRU(S)  
Daerah : J/BAHRU SELATAN  
Kontinjen : JOHOR  
No Repot : TRAFIK JOHOR BAHRU(S)/014729/17  
Tarikh : 04/07/2017  
Waktu : 1459 PM  
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R123364  
No Repot Bersangkut : TRAFIK JOHOR BAHRU  
(S)/014658/17

**Butir-butir Penerima Repot**

Nama : ADDANNY OMOL  
Butir-butir Jurubahasa (Jika Ada)  
Nama : ---  
No Paspot : ---  
Alamat : ---

No Personel : R197262  
Pangkat : KONST/P  
No K/P (Baru) : ---  
Bahasa Asal : ---  
No Polis/Tentera : ---

**Butir-butir Pengadu**

Nama : TAN TIAN YE  
No K/P (Baru) : 850213075649  
No Sijil Beranak : ---  
Jantina : Lelaki  
Keturunan : Cina  
Pekerjaan : -

No Polis/Tentera : ---  
No Paspot : ---  
Tarikh Lahir : 13/02/1985  
Warganegara : Malaysia  
Umur : 32 tahun 4 bulan

Alamat Tempat Tinggal : NO 159 BALIK PULAU VILLAGE AREA 11000 BALIK PULAU PULAU PINANG  
MALAYSIA

Alamat Ibu/Bapa : ---  
Alamat Pejabat : ---  
No Tel (Rumah) : ---  
Emel : ---

No Tel (Pejabat) : ---  
No Tel (HP) : 010-8845044

**Pengadu Menyatakan:-**

PADA 3/7/2017 JAM LEBIH KURANG 1850 HRS. SEMASA SAYA MEMANDU M/KAR NO:PLQ5421 DARI TAMAN MOLEK HENDAK KE SKUDAI. APABILA SAMPAI DI KM 2.5 LEBUHRAYA EDL SEMASA SAYA SEDANG JALAN TERUS KEADAAN LALULINTAS BERGERAK PERLAHAN TIBA-TIBA SEBUAH M/LORI NO:JKA8736 DATANG DARI ARAH BELAKANG MELANGGAR M/KAR SAYA LALU M/KAR SAYA BERGERAK KE HADAPAN DAN TERLANGGAR SEBUAH M/KAR NO:SGV1546L YANG BERADA DI HADAPAN SAYA. SAYA CEDERA DI BAHAGIAN DADA,BAHAGIAN MULUT. KEROSAKAN M/KAR SAYA DI BAHAGIAN BELAKANG; BUMPER,BONET,CERMIN,PINTU SEBELAH KIRI,LAMPU SEBELAH KIRI MANAKALA BAHAGIAN HADAPAN; BUMPER,MUDGUARD SEBELAH KIRI,LAMPU SEBELAH KIRI,NO.PLAT DAN LAIN-LAIN KEROSAKAN TIDAK PASTI LAGI. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa(Jika ada) :

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak :

SALINAN YANG DISAHKAN BENAR  
(HANYA UNTUK TUNTUTAN SIVIL)

KETUA TRAFIK DAERAH, JOHOR BAHRU, JOHOR.  
TIDAK BOLEH DIGUNAKAN UNTUK TUJUAN PERBICARAAN



**POLIS DIRAJA MALAYSIA**  
REPOT POLIS

Balai : TRAFIK JOHOR BAHRU(S)  
Daerah : J/BAHRU SELATAN  
Kontinjen : JOHOR  
No Repot : TRAFIK JOHOR BAHRU(S)/014664/17  
Tarikh : 03/07/2017  
Waktu : 2332 PM  
Bahasa Diterima : B. Malaysia

Pegawai Penylasat : R123364  
No Repot Bersangkut : TRAFIK JOHOR BAHRU  
(S)/014658/17

**Butir-butir Penerima Repot**

Nama : MOHD YUSOF BIN SHATO

No Personel : R120509

Pangkat : KPL

**Butir-butir Jurubahasa (Jika Ada)**

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Pasport : ---

Bahasa Asal : ---

Alamat : ---

**Butir-butir Pengadu**

Nama : NEO TIONG HUAT

No K/P (Baru) : 580927015245

No Polis/Tentera : 5591673

No Pasport : ---

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 27/09/1958

Umur : 58 tahun 9 bulan

Keturunan : Cina

Warganegara : Malaysia

Pekerjaan : PEMANDU

Alamat Tempat Tinggal : NO 18 JALAN GEMILANG 2/2 B TAMAN BANANG JAYA 83000 BATU PAHAT JOHOR MALAYSIA

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 017-7965354

Emel : ---

**Pengadu Menyatakan:-**

PADA 03/07/2017 JAM LEBIH KURANG 1850HRS SEMASA SAYA MEMANDU M/TANKER NO JKA8736 DARI PASIR GUDANG HENDAK KE BATU PAHAT. APABILA SAMPAI DI KM 2.5 LEBUHRAYA UTARA SELATAN TIBA-TIBA SEBUAH M/KAR NO PLQ5421 MEMBREK SECARA MENGEJUT OLEH KERANA JARAK TERLALU DEKAT SAYA BREK TETAPI TERLANGGAR JUGA M/KAR TERSEBUT. SAYA TIDAK CEDERA KEROSAKAN PADA M/TANKER SARUNG DEPAN SEBELAH KANAN, LAIN-LAIN KEROSAKAN TIDAK PASTI. SEKIAN REPOT SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

: R123364 | 06/07/2017 07:30:36 PM

**SALINAN YANG DISAHKAN BENAR  
(HANYA UNTUK TUNTUTAN SIVIL)**

.....  
KETUA TRAFIK DAERAH, JOHOR BAHRU, JOHOR.  
TIDAK BOLEH DISALAHKAN UNTUK TUJUAN PERBICARAAN



## Enquire Vehicle Registration Details

### Owner Particulars

NRIC/Passport/Company Cert No.: 201130452E  
 Owner ID Type: Company  
 Owner Name: INCORPORATE ENGINEERING PTE LTD  
 Registered Address: 5060 ANG MO KIO INDUSTRIAL PARK 2 #01-1239 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569563  
 Mailing Address: -  
 Birth Date: -

### Vehicle Particulars

Vehicle No.: SGV1546L  
 Previous Vehicle No.: -  
 Effective Date of Ownership: 10 Mar 2016  
 Original Regn Date: 06 Jun 2007  
 Registration Date: 06 Jun 2007  
 Year of Manufacture: 2007  
 Vehicle Type: Passenger (Co) Company Station Wagon (Single Rate)  
 Vehicle Scheme: -  
 Vehicle Attachment 1: With Sun Roof  
 Vehicle Attachment 2: -  
 Vehicle Attachment 3: -  
 Vehicle Make: HONDA  
 Vehicle Model: AIRWAVE 1.5 A  
 Primary Colour: Silver  
 Secondary Colour: -  
 Passenger Capacity: 4  
 Chassis No.: GJ11125123  
 Engine No.: L15A5130056  
 Engine Capacity/Power Rating: 1496 cc / -  
 Maximum Power Output: 81.0 kW (108 bhp)  
 Propellant: Petrol  
 Max Unladen Weight: 1180 kg  
 Maximum Laden Weight: 1455 kg  
 Open Market Value: \$15,168.00  
 PARF Eligibility: Forfeited  
 PARF Eligibility Expiry Date: -  
 Minimum PARF Benefit: -  
 No. of Transfers: 1  
 IU Label No.: 1020807351  
 COE No.: 2007060101001438G  
 COE Expiry Date: 05 Jun 2022  
 COE Category: A - Car (1600cc & below)  
 COE Registration Category: A - Car (1600cc & below)  
 Quota Premium (QP)/Prevailing Quota: \$16,159.00 / -

Text size + -

0% 25% 50% 75% 100%

**Transfer Of Vehicle Ownership (Acknowledgement)****Vehicle Details**

|                          |                                                          |                             |                   |
|--------------------------|----------------------------------------------------------|-----------------------------|-------------------|
| Vehicle No.:             | SGV1546L                                                 |                             |                   |
| Vehicle Type:            | N19 - Passenger (Co) Company Station Wagon (Single Rate) | Vehicle Scheme:             | Normal            |
| Vehicle Make:            | HONDA                                                    | Vehicle Model:              | AIRWAVE 1.5 A     |
| Chassis No.:             | GJ11125123                                               | Engine No.:                 | L15A5130056       |
| Motor No.:               | -                                                        | Trailer Chassis No.:        | -                 |
| Propellant:              | Petrol                                                   | Passenger Capacity:         | 4                 |
| Engine Capacity:         | 1496 cc                                                  | Power Rating:               | -                 |
| Unladen Weight:          | 1180 kg                                                  | Maximum Laden Weight:       | 1455 kg           |
| Primary Colour:          | Silver                                                   | Secondary Colour:           | -                 |
| IU Label No.:            | 1020807351                                               | Maximum Power Output:       | 81.0 kW (108 bhp) |
| First Registration Date: | 06 Jun 2007                                              | Original Registration Date: | 06 Jun 2007       |
| Manufacturing Year:      | 2007                                                     | Open Market Value:          | \$15,168.00       |
| PARF Eligibility:        | Yes                                                      | Minimum PARF Benefit:       | \$8,342.00        |
| No. of Transfer:         | 1                                                        | Actual ARF Paid:            | \$16,685.00       |

**Owner Particulars**

Owner Name: INCORPORATE ENGINEERING PTE LTD

Owner ID Type: Company

Owner ID: 201130452E

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 5060

Registered Street Name: ANG MO KIO INDUSTRIAL PARK 2

Registered Unit No.: # 01 - 1239

Registered Building Name:

Registered Postal Code: 569563

COE No./Expiry Date: 2007060101001438G / 05 Jun 2017

COE Bid Category: A - Car (1600cc & below)

QP Paid: \$16,159.00

**Transaction Details**

Business Transaction Ref. No.: 20160310120143198472

Business Transaction Date: 10 Mar 2016

Business Transaction Time: 12:01:43

**Message**

Vehicle has been successfully transferred to INCORPORATE ENGINEERING PTE LTD (201130452E).

Please note that \$11.00 will be deducted from your GIRO account.



# T & C AUTOMOBILE ASSESSORS

INCORPORATE ENGINEERING PTE LTD  
C/O MING HUA AUTO SERVICES  
160 Sin Ming Drive  
#02-16 Singapore 575722

REF : TC/2018/398

DATE : 14/7/2017

## VEHICLE SURVEY REPORT

### REFERENCE

Requested By : Workshop, on behalf of owner  
Date of Request : 6/7/2017  
Date of Accident : 3/7/2017  
Date of Inspection : 6/7/2017  
Inspected At : Ming Hua Auto Services  
160 Sin Ming Drive  
#02-16 Singapore 575722

### PARTICULARS OF VEHICLE

|                         |               |              |                       |
|-------------------------|---------------|--------------|-----------------------|
| Vehicle Registration No | : SGV1546L    | Make & Model | : HONDA AIRWAVE 1.5 A |
| Year Make               | : 2007        | Colour       | : SILVER              |
| Engine No               | : L15A5130056 | Chassis No.  | : GJ11125123          |
| Engine Capacity         | : 1496cc      |              |                       |

### CONDITION OF VEHICLE AND TYRES

|                   |               |              |               |
|-------------------|---------------|--------------|---------------|
| General Condition | : Good        | Mileage      | : 170073      |
| Brakes            | : Serviceable | Modification | : None        |
| Steering          | : Serviceable | Handbrake    | : Serviceable |

| <u>Tyres</u> | <u>Make</u> | <u>Size</u> | <u>Balance (MM)</u> |
|--------------|-------------|-------------|---------------------|
| Front RHS    | Yokohama    | 195/60R15   | 5                   |
| Front LHS    | Yokohama    | 195/60R15   | 5                   |
| Rear RHS     | Yokohama    | 195/60R15   | 6                   |
| Rear LHS     | Yokohama    | 195/60R15   | 6                   |

### DESCRIPTION OF DAMAGES

The Vehicle sustained damages at the rear portion.  
(For information of damages, please refer to Parts/Labour/Photographs attached)

### INSTRUCTION

This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.

**T & C AUTOMOBILE ASSESSORS****ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS**

Véhicule No : SGV1546L

Report No : TC/2018/398

| <u>S/NO</u> | <u>QTY</u> | <u>DESCRIPTION</u>                   | <u>CONDITION/<br/>REMARKS</u> | <u>REPAIRER'S<br/>ESTIMATES</u><br>S\$ | <u>OUR<br/>ASSESSMENT</u><br>S\$ |
|-------------|------------|--------------------------------------|-------------------------------|----------------------------------------|----------------------------------|
| 1           | 1          | Rear bumper                          | Deformed                      | 2,156.70                               | 2,156.70 ✓ 980.20                |
| 2           | 1          | Rear bumper beam                     | Bent                          | 271.30                                 | 271.30 NH                        |
| 3           | 1          | Rear RH bumper side retainer         | Necessary                     | 58.50                                  | 58.50 NH                         |
| 4           | 1 set      | Rear bumper clips                    | Necessary                     | 60.00                                  | 60.00 30/- SH                    |
| 5           | 1          | Rear tailgate                        | Dented                        | 2,282.40                               | 2,282.40 ✓ 1382.50               |
| 6           | 1          | Rear RH tailgate reflector           | Cracked                       | 245.30                                 | 245.30 ✓                         |
| 7           | 1          | Rear tailgate "AIRWAVE" emblem       | Necessary                     | 79.20                                  | 79.20 ✓                          |
| 8           | 1          | Rear tailgate top lock               | Bent                          | 376.60                                 | 376.60 NH                        |
| 9           | 1          | Rear tailgate inner trim board       | Deformed                      | 557.20                                 | 557.20 NH                        |
| 10          | 1 set      | Rear tailgate inner trim board clips | Necessary                     | 42.00                                  | 42.00 NH                         |
| 11          | 1          | Rear tailgate weatherstrip           | Cut                           | 386.40                                 | 386.40 ✓ 155.40                  |
| 12          | 1          | Rear tailgate glass moulding         | Necessary                     | 255.10                                 | 255.10 ✓                         |
| 13          | 1          | Rear RH fender                       | Dented                        | 1,057.80                               | 1,057.80 R                       |
| 14          | 1          | Rear RH fender inner shield          | Deformed                      | 257.20                                 | 257.20 NH                        |
| 15          | 1 set      | Rear RH fender inner shield clips    | Necessary                     | 42.00                                  | 42.00 NH                         |
| 16          | 1          | Rear RH taillamp                     | Broken/cracked                | 592.60                                 | 592.60 ✓                         |
| 17          | 1          | Rear end panel                       | Buckled                       | 1,016.90                               | 1,016.90 R                       |
| 18          | 1          | Rear end panel top garnish           | Deformed                      | 277.60                                 | 277.60 NH                        |
|             |            |                                      |                               | 10,014.80                              | 10,014.80                        |
|             |            |                                      |                               | Less : Discount 10% 20%                | -1,001.48                        |
|             |            |                                      |                               | <b>Total :</b>                         | <b>9,013.32</b>                  |

**SPECIAL NETT ITEMS**

|    |       |                              |             |                            |                  |
|----|-------|------------------------------|-------------|----------------------------|------------------|
| 19 | 1     | Reverse camera               | Malfunction | 550.00                     | 550.00 NH        |
| 20 | 1 set | Reverse sensor               | Malfunction | 380.00                     | 380.00 220/-     |
| 21 | 1     | Rear tailgate glass sealant  | Necessary   | 120.00                     | 120.00 40/-      |
| 22 | 1     | Rear number plate and casing | Dented      | 80.00                      | 80.00 NH         |
|    |       |                              |             | 1,130.00                   | 1,130.00         |
|    |       |                              |             | <b>Total Spare Parts :</b> | <b>10,143.32</b> |



# T & C AUTOMOBILE ASSESSORS

## LABOUR CHARGES

Vechile No : SGV1546L

Report No : TC/2018/398

| <u>S/NO</u> | <u>DESCRIPTION</u>                                                                                               | <u>REPAIRER'S<br/>ESTIMATES S\$</u> | <u>OUR<br/>ASSESSMENT<br/>S\$</u> |
|-------------|------------------------------------------------------------------------------------------------------------------|-------------------------------------|-----------------------------------|
| 1           | To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts. | 1,700.00                            | <del>1,400.00</del> 800/-         |
| 2           | To putty and respray painting on affected areas.                                                                 | 1,500.00                            | <del>1,200.00</del> 800/-         |
| 3           | To remove, refix rear windscreen glass.                                                                          | 180.00                              | <del>150.00</del> 120/-           |
| 4           | To check wirings and lighting.                                                                                   | 120.00                              | <del>80.00</del> 30/-             |
| 5           | To remove, refix reverse sensor and reverse camera.                                                              | 200.00                              | <del>150.00</del> 40/-            |
| 6           | To remove, refix tailgate fittings to facilitate repair.                                                         | 120.00                              | <del>80.00</del> 60/-             |
| 7           | To apply undersealing.                                                                                           | 220.00                              | <del>180.00</del> 40/-            |

|                        |           |           |
|------------------------|-----------|-----------|
| Total Labour Charges : | 4,040.00  | 3,240.00  |
| Total Spare Parts :    | 10,143.32 | 10,143.32 |
| Total Repair Costs :   | 14,183.32 | 13,383.32 |

### Assessor's Recommendation

|                     |           |
|---------------------|-----------|
| Repairer Estimate : | 14,183.32 |
| Our Adjustment :    | 13,383.32 |

### Remarks

The repairer has agreed to undertake the repair of S\$13,383.32, with a repair period of 9 working days.

Surveyed By:

THAM KOK SANG

5132.24

L/S 4100/-

5 days



## LONPAC INSURANCE BHD (307414-T)

Head Office : LG, 6th, 7th, 21st to 26th Floor, Bangunan Public Bank, No. 6, Jalan Sultan Sulaiman, 50000 Kuala Lumpur, Malaysia, P.O. Box 10708, 50722 Kuala Lumpur, Malaysia  
Tel: 03-2262 8688, 2723 7888 Fax: 03-2723 7892, 2715 1332, 2078 7455, 2034 2654, 2715 0722, 2072 3385, 2715 0695  
Website: www.lonpac.com (GST Reg. No : 002013003776)

Your Ref : To be advised  
Our Ref : 17/17/17/VC10/244777

23 JAN 2019

INCORPORATE ENGINEERING PTE LT  
NO. 205, JALAN SJ 5/12A  
TAMAN SEREMBAN JAYA  
70450 SEREMBAN  
NEGERI SEMBILAN

Dear Sir(s),

INSURED : ARAH TUJU TRANSPORT SDN BHD  
COMMERCIAL VEHICLE (A PERMITS - VEHICLE ONLY)  
Policy No. W/17/VC10/035884/KUL  
Accident on 03 JUL 2017 involving vehicles JKA 8736 and SGV 1546  
L

-----  
The above claim made refers.

We are looking into the matter and you will be informed on the progress of your claim.

Thank you.

Yours faithfully,  
LONPAC INSURANCE BHD.

SIM BEE LIAN  
SENIOR EXECUTIVE  
CLAIMS DEPARTMENT  
BLSIM / LINA

\*\*\* THIS IS A COMPUTER GENERATED DOCUMENT AND IT DOES NOT REQUIRE A SIGNATURE. \*\*\*



Your Ref: 17/17/17/VC10/244777

Date: 14<sup>th</sup> May 2019

Our Ref: CS1/LPC19007738/Dqd3s2

**M/s Lonpac Insurance Bhd**

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGV 1546L  
INSURED VEHICLE: JKA 8736 ACCIDENT DATE: 03/07/2017**

We thank you for your instruction on 29/04/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGV 1546L from M/s T & C Automobile Assessors.
- b) Polis Diraja Malaysia Statement of Vehicles SGV 1546L, PLQ 5421 and JKA 8736.
- c) Colour damaged vehicle photographs of SGV 1546L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

|                      |                       |
|----------------------|-----------------------|
| Registration Number  | : SGV 1546L           |
| Make & Model         | : Honda Airwave 1.5 A |
| Year of Registration | : 2007                |
| Chassis Number       | : GJ11125123          |
| Engine Capacity      | : 1496 cc             |

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 1546L

| Qty                                | Description of Parts                     | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|------------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                          |                      |                           |                   |
| 1                                  | REAR BUMPER                              | DEFORMED             | 2,156.70                  | 980.20            |
| 1                                  | REAR BUMPER BEAM                         | NOT NECESSARY        | 271.30                    | -                 |
| 1                                  | REAR RH BUMPER SIDE RETAINER             | NOT NECESSARY        | 58.50                     | -                 |
| 1                                  | REAR TAILGATE                            | DENTED               | 2,282.40                  | 1,382.50          |
| 1                                  | REAR RH TAILGATE REFLECTOR               | CRACKED              | 245.30                    | 245.30            |
| 1                                  | REAR TAILGATE "AIRWAVE" EMBLEM           | NECESSARY            | 79.20                     | 79.20             |
| 1                                  | REAR TAILGATE TOP LOCK                   | NOT NECESSARY        | 376.60                    | -                 |
| 1                                  | REAR TAILGATE INNER TRIM BOARD           | NOT NECESSARY        | 557.20                    | -                 |
| 1                                  | SET REAR TAILGATE INNER TRIM BOARD CLIPS | NOT NECESSARY        | 42.00                     | -                 |
| 1                                  | REAR TAILGATE WEATHERSTRIP               | CUT                  | 386.40                    | 155.40            |
| 1                                  | REAR TAILGATE GLASS MOULDING             | NECESSARY            | 255.10                    | 255.10            |
| 1                                  | REAR RH FENDER                           | TO REPAIR SEE LABOUR | 1,057.80                  | -                 |
| 1                                  | REAR RH FENDER INNER SHIELD              | NOT NECESSARY        | 257.20                    | -                 |
| 1                                  | SET REAR RH FENDER INNER SHIELD CLIPS    | NOT NECESSARY        | 42.00                     | -                 |
| 1                                  | REAR RH TAILLAMP                         | BROKEN / CRACKED     | 592.60                    | 592.60            |
| 1                                  | REAR END PANEL                           | TO REPAIR SEE LABOUR | 1,016.90                  | -                 |
| 1                                  | REAR END PANEL TOP GARNISH               | NOT NECESSARY        | 277.60                    | -                 |
|                                    | LESS 10% DISCOUNT                        |                      | -995.48                   | -                 |
|                                    | LESS 20% DISCOUNT                        |                      | -                         | -738.06           |
|                                    |                                          |                      | 8,959.32                  | 2,952.24          |
| 1                                  | SET REAR BUMPER CLIPS (SN)               | NECESSARY            | 60.00                     | 30.00             |
|                                    | LESS 10% DISCOUNT                        |                      | -6.00                     | -                 |
|                                    |                                          |                      | 54.00                     | 30.00             |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                          |                      |                           |                   |
| 1                                  | REVERSE CAMERA (SN)                      | NOT NECESSARY        | 550.00                    | -                 |
| 1                                  | SET REVERSE SENSOR (SN)                  | MALFUNCTION          | 380.00                    | 220.00            |
| 1                                  | REAR TAILGATE GLASS SEALANT (SN)         | NECESSARY            | 120.00                    | 40.00             |
| 1                                  | REAR NUMBER PLATE AND CASING (SN)        | NOT NECESSARY        | 80.00                     | -                 |
|                                    |                                          |                      | 1,130.00                  | 260.00            |

Report Ref No. CS1/LPC19007738/Dqd3s2



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                                                                                                                                                           | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|                                                                             | <b>LABOUR</b>                                                                                                                                                                  |           |                           |                   |
|                                                                             | TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING. ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR RH FENDER AND REAR END PANEL. |           | 1,700.00                  | 800.00            |
|                                                                             | TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.                                                                                                                               |           | 1,500.00                  | 800.00            |
|                                                                             | TO REMOVE, REFIX REAR WINDSCREEN GLASS.                                                                                                                                        |           | 180.00                    | 120.00            |
|                                                                             | TO CHECK WIRINGS AND LIGHTING.                                                                                                                                                 |           | 120.00                    | 30.00             |
|                                                                             | TO REMOVE, REFIX REVERSE SENSOR AND REVERSE CAMERA.                                                                                                                            |           | 200.00                    | 40.00             |
|                                                                             | TO REMOVE, REFIX TAILGATE FITTINGS TO FACILITATE REPAIR.                                                                                                                       |           | 120.00                    | 60.00             |
|                                                                             | TO APPLY UNDERCOATING.                                                                                                                                                         |           | 220.00                    | 40.00             |
|                                                                             |                                                                                                                                                                                |           | 4,040.00                  | 1,890.00          |
|                                                                             | <b>GRAND TOTAL</b>                                                                                                                                                             |           | <b>14,183.32</b>          | <b>5,132.24</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                                                |           |                           | <b>4,100.00</b>   |

Report Ref No. CS1/LPC19007738/Dqd3s2

MARKET VALUE: \$33,000.00 (EST)

LTA VALUE: \$24,891.00 (EST)

NETT VALUE: \$8,109.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.