

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900111
Date: 29 Apr 2019
Veh Reg No: SGD5071H
Make/Model: TOYOTA VIOS 1.5E A
Chasis No: MR053HY4204172006
Reg. Date: 20/02/2006
Your Ref No: SJC5088E

Claim Type: Third Party
Accident Date: 27/04/2019
TP Veh Reg No: SJC5088E

Vic

Estimate Repair Cost to Vehicle No :SGD5071H

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR BUMPER <i>Disch'd</i>	245.90 ✓	
2	1 PC REAR BUMPER SIDE RETAINER <i>new</i>	28.80 ✓	
3	1 PC REAR FENDER <i>Disch'd</i>	864.80 ✓	
4	1 PC REAR FENDER INNER TRIM <i>captured new</i>	155.60 ✓	
5	1 PC TAIL LAMP <i>Smashed</i>	251.60 ✓	
6	1 PC TAIL LAMP PANEL <i>Disch'd</i>	105.10 ✓	
7	1 PC REAR WINDSCREEN MOULDING <i>new</i>	96.70 ✓	
8	1 PC BOOT LID <i>Disch'd</i>	584.90 ✓	
9	1 PC BOOT LID RUBBER <i>lit</i>	175.30 ✓	
10	2 PCS BOOT LID HINGE <i>new</i>	135.80 ✓	
11	1 PC BOOTLID "1.5" EMBLEM <i>new</i>	36.80 ✓	
12	1 PC BOOT LID "E" EMBLEM <i>new</i>	36.80 ✓	
13	1 PC BOOT LID "VVTI" EMBLEM <i>new</i>	47.70 ✓	
14	1 PC BOOT LID LOGO	50.80 ✓	
15	1 PC BOOT LID "VIOS" EMBLEM	44.20 ✓	
16	1 PC BOOT LID LOCK <i>new</i>	165.90 ✓	
17	1 PC REAR PANEL <i>Disch'd</i>	720.10 ✓	
18	1 PC REAR PANEL TRIM <i>Disch'd</i>	137.20 ✓	
19	1 PC FLOORBOARD SIDE PANEL LH <i>Disch'd</i>	114.60 ✓	
20	1 PC REAR VENTILATION GARNISH LH <i>Disch'd</i>	58.80 ✓	
21	1 PC REAR FENDER MUDFLAP <i>Disch'd</i>	45.60 ✓	
		4,103.00	
		Less 25%	1,025.75
			3,077.29
Special Net			
22	1 SET REVERSE SENSORS <i>Disch'd</i>	250.00 ✓	
23	1 SET REAR BUMPER CLIPS <i>new</i>	48.00 ✓	
24	1 SET REAR FENDER INNER TRIM CLIPS <i>new</i>	60.00 ✓	
25	1 SET REAR PANEL TRIM CLIPS <i>new</i>	48.00 ✓	
		406.00	406.00
Labour			

3645.70

2734.27

270

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 27/04/2019
TP Veh Reg No: SJC5088E

Estimate No: EST1900111
Date: 29 Apr 2019
Veh Reg No: SGD5071H
Make/Model: TOYOTA VIOS 1.5E A
Chasis No: MR053HY4204172006
Reg. Date: 20/02/2006
Your Ref No: SJC5088E

Estimate Repair Cost to Vehicle No :SGD5071H

Quantity	Description	List Price	Amount
		SS	SS
26	1 TO CHECK WIRING	50.00	30
27	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	50
28	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
29	1 TO REMOVE AND REFIT REAR CUSHION	180.00	80
30	1 TO REMOVE AND REFIT PETROL TANK	150.00	80
31	1 REAR WINDSCREEN SEALANT	60.00	✓
32	1 REAR WINDSCREEN RUBBER	60.00	✓
33	1 TO SPRAY UNDERSEAL	150.00	80
34	1 (REAR) TO SPRAY PAINTING	1,400.00	1000
35	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,800.00	1300
		4,050.00	4,050.00
	Total		S\$ 7,533.29
	Add GST @ 7%		527.33
	Total Amount Payable		S\$ 8,060.62

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND SIXTY AND CENTS SIXTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Total: 5864.27

H/S: A.6K

Nett Value 3.3K