

INS. CASE OWNER: **BUMENAD** | CC6 /AIG1900 **7745, April** | LKK: **1316**
 Surveyor: **Adrian** | DOI: **WU/LA** | Date / Time: **nowela**
 Registered in Merimen: **WU/LA**

Pre-assign / CCU / FTE:



Insured Vehicle No.: **SGL 8851M**
 Name of Insured: **HUA HONG PRINTING WORKSHOP**
 Insured Tel No.: **SHIN HAN LIMO SERVICES**
 Excess Sec II :\$5
 Is driver the owner? (YES / NO)
 Nature of Accident:

Claim No.: **3117191144569**
 Policy No.:
 Make / Model :
 Place of Accident :

If NO. Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SGL 8851M

SEP 9412

SGL 8851M



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SEP 01/12/19

SGL 8851M

STAGE	DATE / PIC
Non-Reporting Itr (1st):	24/05/2019
Non-Reporting Itr (2nd):	14/06/2019
Non-Reporting Itr (Final):	
Notification Itr (if non-pickup):	
Call OI:	
After call Itr to OI:	11/11/19-JIC
Documentation Check List:	Handler Typist
Notification Itr (if non-pickup)	
After call Itr to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

24/06/19 @ 1:30PM

- NO OI GIA REPORT IN YET.
 - RA -> \$2.54 (CASH)
 - 2nd RA -> \$2.54
 - TP VIDEO IN. UPLOADED IN WORKSHOP
 - CALL OI TO FOR TP GIA. NO RESPONSE.
 - MINUSSED
 - TP LOD IN BY EMAIL
 - OI SEND LETTER. REQUEST TO SETtle CLAIM.

29/08/19

11/11/19

22/11/19

02/12/19

- NO OI GIA REPORT IN YET.
 - OI GIA REPORT IN
 - PIR REVIEWED OI RATE-ENDED TP.
 - TP REPORT HIGH. REPORT FORG
 - OFFER MANUATE APPROVAL TO AIG
 - AIG APPROVED MANUATE

PRELIMINARY ADVICE
08/12/19

- TP ACCEPTED OFFER.

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: L9	\$5 12,000.00	(14 days) Reduction: 59 %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with:	Confirm by:
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 28	Email ☐ Call ☐
Repair Cost:	\$5 12,000.00		
Loss of Rental (LOR):	\$5 -	(days)	
Loss of Use (LOU):	\$5 1,400.00	(100 x 14 days)	
Loss of Income (LOI):	\$5 -	(5 x days)	
LOR only ☐ LOU only ☐	☒ LOR + LOU ☐ LOR + LO ☐	(Tick only one)	
GIA/LTA Search:	\$5 7.45		
Medical:	\$5 -		
Unbursement:	\$5 -	(e.g. Time/ Independent)	
Legal Cost:	\$5 -		
Total:	\$5 13,407.45	Global Sum \$5: -	
FINAL PAYMENT	Date/Time:	Confirm with:	Confirm by:
Payee 1:	\$5 13,407.45	Name 1: HUA HONG PRINTING WORKSHOP	Email ☐ Call ☐
Payee 2: (Strike if N.A.)	\$5 -	Name 2: -	
Payee 3: (Strike if N.A.)	\$5 -	Name 3: -	

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: _____Veh No: SKP99712 Yr Regn: 2014 / Oct.Type: M.Cay / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 5 c.c. 1998Colour: Black A/C: Insured / Std / Nil / NASp. Reading: 119077 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: Jm6w1071F0119986Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil (S/Rim) / STD A/Rim orTyre Size: F: 225/45R17R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO (YOKO) or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 30/04/19Survey held at Hua mengDes. of Damages Fr / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPA16L16 \$12,000.00CRD: \$17,716.00 (59%)MV: 62KPV: 49.5KNett: 12.5K

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

RA\$2.34 x 2

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JmbCW1071F019986

AZME BIN YUNOS

BLK 212 PASIR RIS ST 21

#04-222

S 510212

Date

:16.05.2019

Vehicle No

SKP 9971 Z

Make/Model

:MAZDA 5

Accident date

:29.04.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 69.90 ✓
2	Rear tailgate <i>Distorted</i>	1	\$ 1886.50 ✓
3	Rear tailgate hinges@44.40 <i>new</i>	2	\$ 88.80 ✓
4	Rear tailgate upper lock <i>new</i>	1	\$ 273.90 ✓
5	Rear tailgate lower lock <i>new</i>	1	\$ 61.80 ✓
6	Rear tailgate weatherstrip <i>new</i>	1	\$ 204.50 ✓
7	Rear tailgate inner board <i>new</i>	1	\$ 420.00 ✓
8	Rear tailgate shock absorber@203.50 <i>new</i>	2	\$ 407.00 ✓
9	Rear tailgate centre emblem <i>new</i>	1	\$ 50.80 ✓
10	Rear tailgate handle <i>new</i>	1	\$ 142.80 ✓
11	Rear tailgate mazda emblem <i>new</i>	1	\$ 52.10 ✓
12	Rear tailgate 5 emblem <i>new</i>	1	\$ 41.80 ✓
13	Rear tailgate sky activ emblem	1	\$ 92.20 ✓
14	Rear tailgate reflector@471.80 <i>crushed</i>	2	\$ 943.60 ✓ 770.40
15	Rear tailgate inner handle <i>new</i>	1	\$ 60.50 ✓
16	Rear number plate lamp@66.60	2	\$ 133.20 ✓
17	Rear wiper motor <i>new</i>	1	\$ 313.50 ✓
18	Rear lamp@693.30 <i>crushed</i>	2	\$ 1386.60 ✓ 971.20
19	Rear lamp housing@214.50 <i>Repair</i>	2	\$ 429.00 ✓
20	Rear bumper <i>Distorted</i>	1	\$ 1107.70 ✓
21	Rear bumper side holder@54.90 <i>new</i>	2	\$ 109.80 ✓
22	Rear bumper reflector@60.90 <i>crushed</i>	2	\$ 121.80 ✓
23	Rear bumper reverse sensor <i>new</i>	2	\$ 418.00 ✓ 200/ea
24	Rear bumper reinforcement <i>new</i>	1	\$ 294.80 ✓
25	Rear bumper bracket@54.80 <i>new</i>	2	\$ 109.60 ✓
26	Rear bumper clips <i>new</i>	1	\$ 44.00 ✓
27	Rear end panel <i>Distorted</i>	1	\$ 594.00 ✓
28	Rear end panel inner top garnish <i>new</i>	1	\$ 462.00 ✓ 165.00
29	Rear fender inner garnish@556.40 <i>new</i>	2	\$ 1112.80 ✓
30	Rear spare tyre well <i>Repair</i>	1	\$ 1314.50 ✓
31	Rear spare tyre well insulation@385.00 <i>new</i>	2	\$ 770.00 ✓
32	Rear spare tyre top board <i>new</i>	1	\$ 407.00 ✓
33	Rear fender inner shield@49.50 <i>new</i>	2	\$ 99.00 ✓
34	Rear exhaust pipe <i>new</i>	1	\$ 1278.50 ✓ 99.3
35	Rear exhaust pipe chrome <i>new</i>	1	\$ 82.50 ✓

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

AZME BIN YUNOS

BLK 212 PASIR RIS ST 21

#04-222

S 510212

Date

:16.05.2019

Vehicle No

SKP 9971 Z

Make/Model

:MAZDA 5

Accident date

:29.04.2019

No	Description	Qty	Amount (\$\$)
36	Rear exhaust pipe mounting <i>Not new</i>	1	\$ 45.30
37	Bonnet <i>Dented</i>	1	\$ 1196.70
38	Bonnet hinges@62.60 <i>Not new</i>	2	\$ 125.20
39	Bonnet lock <i>Not new</i>	1	\$ 238.60
40	Bonnet lock bracket <i>Not new</i>	1	\$ 46.20
41	Bonnet inner rubber <i>Not new</i>	1	\$ 18.70
42	Susport panel <i>Cracked</i>	1	\$ 520.00
43	Bonnet inner outer rubber <i>Not new</i>	1	\$ 85.00
44	Bonnet insulation <i>Not new</i>	1	\$ 145.20
45	Front headlamp@1708.10 <i>Cracked</i>	2	\$ 3416.20
46	Front headlamp lower bracket@49.20 <i>Not new</i>	2	\$ 98.40
47	Front bumper <i>Cracked</i>	1	\$ 1277.00
48	Front bumper centre emblem <i>Not new</i>	1	\$ 52.60
49	Front bumper centre grille <i>Cracked</i>	1	\$ 809.30
50	Front bumper fod lamp@363.80 <i>Not new</i>	2	\$ 727.60
51	Front bumper fod lamp garnish <i>Not new</i>	2	\$ 91.20
52	Front bumper side holder@24.90 <i>Not new</i>	2	\$ 49.80
53	Front bumper reinforcement <i>Bent</i>	1	\$ 612.50
54	Front bumper bracket@29.70 <i>Not new</i>	2	\$ 59.40
55	Front bumper clips <i>Not new</i>	1	\$ 49.50
56	Rear spare tyre top tool board <i>Defound</i>	1	\$ 404.80
57	Rear spare <i>Not new</i>	1	\$ 24.20
58	Air con condenser <i>Dented</i>	1	\$ 936.30
59	Front fender@371.50 <i>Not new</i>	2	\$ 743.00
60	Front grille <i>Not new</i>	1	\$ 186.30
61	Front grille emblem <i>Not new</i>	1	\$ 52.10
			\$ 27395.60
Less 20% Disc			\$ 5479.10
Total			\$ 21916.50

Special Nett Items

1	Rear number plate <i>Bent</i>	1	\$ 55.00
2	Rear number plate holder <i>Defound</i>	1	\$ 55.00
3	Front number plate <i>Missing</i>	1	\$ 55.00
4	Front number plate holder	1	\$ 55.00
5	Rear camera <i>Damaged</i>	1	\$ 880.00
Total			\$ 1100.00

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

AZME BIN YUNOS
B1K 212 PASIR RIS ST 21
#04-222
S 510212

Date :16.05.2019
Vehicle No SKP 9971 Z
Make/Model :MAZDA 5
Accident date :29.04.2019

No	Description	Qty	Amount (\$S)
Labour Cost			
1	Towing fee		\$ 150.00 60
2	To supply rear windscreen sealant		\$ 50.00 ✓
3	To supply rear end panel inner sealant		\$ 200.00 60
4	Remove & reinstall rear windscreen		\$ 150.00 120
5	Remove & reinstall exhaust pipe		\$ 150.00 80
6	Remove & reinstall bootled inner garnish		\$ 200.00 80
7	Remove & reinstall petrol tank	3910	\$ 150.00 x
8	Remove & reinstall air con		\$ 150.00 120
9	Remove & reinstall reverse sensor		\$ 150.00 60
10	Remove ,replace & repair consistent to the accident		\$ 3000.00 1800
11	Respray painting		\$ 2200.00 1400
12	Tuff kote		\$ 150.00 80
Total			\$ 6700.00
Grand Total			\$ 29716.50

total: 19693.92

L/S: 121K (Nett Value)

14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 3472B

Vehicle Details

Vehicle No.: SKP9971Z
Vehicle to be Exported: Yes
Intended Deregistration Date: 30 Apr 2019
Vehicle Make: MAZDA
Vehicle Model: MAZDA5 5-DOOR WAGON 2.0L SP6EAT SUNROOF
Primary Colour: Black
Manufacturing Year: 2014
Engine No.: PE30689632
Chassis No.: JM6CW1071F0119986
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$18,333.00
Original Registration Date: 28 Oct 2014
First Registration Date: 28 Oct 2014
Transfer Count: 1
Actual ARF Paid: \$13,333.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Oct 2024
PARF Rebate Amount: \$9,999.00

Intended COE Rebate Details

COE Expiry Date: 27 Oct 2024
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$72,002.00
COE Rebate Amount: \$39,523.00
Total Rebate Amount: \$49,522.00

The information contained herein is correct as at 30 Apr 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Singapore NRIC
Owner ID:	3472B
Vehicle Details	
Vehicle No.:	SKP9971Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Apr 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	PE30689632
Chassis No.:	JM6CW1071F0119986
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$18,333.00
Original Registration Date:	28 Oct 2014
First Registration Date:	28 Oct 2014
Transfer Count:	1
Actual ARF Paid:	\$13,333.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Oct 2024
PARF Rebate Amount:	\$9,999.00
Intended COE Rebate Details	
COE Expiry Date:	27 Oct 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$72,002.00
COE Rebate Amount:	\$39,523.00
Total Rebate Amount:	\$49,522.00

The information contained herein is correct as at 30 Apr 2019

OK



Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

► **SEARCH** [Advanced Search](#)

► Used Car Comparison

--- Comparing 3 Vehicles ---

Mazda 5 2.0A Sunroof



Clear All

[Back to search result](#)

Mazda 5 2.0A Sunroof



Mazda 5 2.0A Sunroof



Use search bar above to set to compare

CAR DETAILS

Price	\$61,800	\$63,800	\$66,800	-
Instalment	\$783	\$758	\$766	-
Registration Date	24-Sep-2014	30-Jan-2015	13-May-2015	-
Manufactured	2014	2014	2015	-
Mileage	56,818 km	88,000 km	80,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,998 cc	1,998 cc	1,998 cc	-
Road Tax	\$1,210 /yr	\$1,210 /yr	\$1,210 /yr	-
Power	111.0 kW (148 bhp)	111.0 kW (148 bhp)	111.0 kW (148 bhp)	-
Curb Weight	1,535 kg	1,535 kg	1,535 kg	-
Features	2.0L DOHC SKYACTIV-G Engine, 148 BHP, 6 Speed Auto With Steptronic, Dual Powered Sliding Doors, ABS, EBD, Airbags, Auto Headlights And Rain Sensors.	2.0L 4 Cylinder Inline DOHC SKYACTIV-G With 6 Speed Transmission Producing 148 Bhp And 190 Nm. Achievable Fuel Consumption 14 To 15 Km/Litre.	2.0L 4 Cylinder Inline DOHC SKYACTIV-G With 6 Speed Transmission Producing 149 Bhp And 190 Nm. Achievable Fuel Consumption 14-15 Km/Litre. View Specs	-
Accessories	Sunroof, Sports Rims, Leather Seats, Pioneer DVD Player With Steering Controls, Reverse Camera/Sensors, Retractable Side Mirrors, Fog Lights.	Multi-Function Steering Wheel, Auto Headlights, Rain-Sensing Wipers, Electrical Retractable Side Mirrors, Navigation System, Reverse Camera.	Multi Function Steering Wheel, Auto Headlights, Rain Sensing Wipers, Retractable Side Mirrors, Navigation System, Reverse Camera, Auto Sliding Doors.	-
Description	Selling At Paper Value Plus Body Good Buy, Servicing Done, 1 Year Warranty Cover Engine And Gear Box, New Road Tax, Well Maintain By Previous Owner, Drive With Peace Of Mind! High Trade In And Loan Available, Please Call/SMS Our Sales Consultant For Viewing Appointment.	1 Owner, Well Taken Care By The Previous Owner. Loan Available With High Trade In. Price Negotiable. Call Now Or Visit Our Showroom Today!	Well Taken Care By The Previous Owner. High Loan And Trade In Available. Skyactive Engine Supreme Fuel Consumption For A Big MPV! Viewing By Appointment Only. Consignment Unit.	-
COE	\$71,990	\$75,200	\$78,001	-
OMV	\$18,762	\$17,542	\$17,889	-
ARF	\$13,762	\$12,542	\$12,889	-
Depreciation	\$10,160 /yr	\$9,990 /yr	\$10,000 /yr	-
No. of Owners	1	1	2	-
Type of Vehicle	MPV	MPV	MPV	-
Category	PARF Car	PARF Car	PARF Car, Premium Ad Car	-
Availability	Available	Available	Available	-

SELLER INFORMATION

View Received Message

This mail is associated with :

*SKP9971Z (3113191149SG)
[SGL8351M]

TP
AZME BIN YUNOS
Apr 29 2019 3:00PM

Hua Meng Spray Painting Workshop

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 03/05/2019 11:14 AM.
To LKK_HQ
Subject No OI GIA Report

Hi

Pls be advica that no OI GIA report received.
Pls find OI details below for your further actions.

OI name: Chan Fett Cheung (Not Driving)

Address: No. 58
Binjai Park
Singapore 589858

Mobile No: NA

Thank you.

Regards,
Divya

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19007745/Ajb3

07 May, 2019

Chan Fatt Cheung

No. 58 Binjai Park

Singapore 589858

Dear Sirs,

**ACCIDENT INVOLVING SKP 9971Z AND SGL 8351M ON 29/04/2019 ALONG/
AT PIE TOWARDS TUAS**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any mendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Joy Irene

Claims

Tel : 6841 2409

Fax: 6741 4108

Email : joyirene@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19007745/Ajb3

24 MAY 2019

By Registered Mail
First Reminder

Chan Fatt Cheung
No. 58 Binjai Park
Singapore 589858

Dear Sir,

**ACCIDENT INVOLVING SKP 9971Z AND SGL 8351M ON 29/04/2019
ALONG/AT PIE TOWARDS TUAS**

We refer to the above subject matter. Your insurer AIG Asia Pacific Insurance Pte Ltd (AIG) has received a third party claim(s) against your motor insurance policy, and has appointed LKK Auto Consultants Pte Ltd to act on their behalf to handle this matter.

We highlight that this accident has not been reported to AIG.

Please note that you had been notified by our via mail by post from our office on 07/05/2019

Kindly proceed to lodge your accident report immediately, giving the version of the accident amongst other things related to the accident. The accident report can be lodged at any of AIG reporting centres. For the listing of AIG reporting centres, you may refer to your Certificate of Insurance or visit AIG Singapore's website.

To enable us to look into the matter immediately, please let us hear from you within fourteen (14) days from date of this letter (**by 10/06/2019**).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s AIG Asia Pacific Insurance Pte Ltd reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Joy Irene
Claims
Tel : 6841 2409
Fax: 6741 4108
Email : joyirene@lkkauto.com

c.c *Claims Manager*
 AIG Asia Pacific Insurance Pte. Ltd
 (Motor Claims Dept)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19007745/Ajb3

14 JUNE 2019

By Registered Mail
(FINAL REMINDER)

Chan Fatt Cheung
No. 58 Binjai Park
Singapore 589858

Dear Sir,

**ACCIDENT INVOLVING SKP 9971Z AND SGL 8351M ON 29/04/2019
ALONG/AT PIE TOWARDS TUAS**

We refer to the above subject matter. Your insurer AIG Asia Pacific Insurance Pte Ltd (AIG) has received a third party claim(s) against your motor insurance policy, and has appointed LKK Auto Consultants Pte Ltd to act on their behalf to handle this matter.

We highlight that this accident has not been reported to AIG.

Please note that you had been notified by our via mail by post from our office on 07/05/2019 & 24/05/2019.

Kindly proceed to lodge your accident report immediately, giving the version of the accident amongst other things related to the accident. The accident report can be lodged at any of AIG reporting centers. For the listing of AIG reporting centers, you may refer to your Certificate of Insurance or visit AIG Singapore's website.

To enable us to look into the matter immediately, please let us hear from you within fourteen (14) days from date of this letter (by **01 JULY 2019**).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s AIG Asia Pacific Insurance Pte Ltd reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Joy Irene
Claims
Tel : 6841 2409
Fax: 6741 4108
Email : joyirene@lkkauto.com

c.c Claims Manager
 AIG Asia Pacific Insurance Pte. Ltd
 (Motor Claims Dept)

To : Traffic Police – Deputy Head, Investigations Department
Fax : 65474885

ONLY FOR ACCIDENTS IN SINGAPORE

NON-INJURY MOTOR ACCIDENT REPORT SCHEME
FORM ON NON-REPORTING BY INSUREDS

Please be informed that we have yet to receive a motor accident report from our insured with regard to a non-injury motor accident as follows: -

Date of accident : 29/04/2019
Time of accident : 15:30
Place of accident : PIE TOWARDS TUAS
Third Party's name : AZME BIN YUNOS
Third Party's vehicle number : SKP 9971Z
Our insured's name : CHAN FATT CHEUNG
Our insured's vehicle number : SGL 8351M
Our insured's NRIC number : NIL
Our insured's address : NO.58 BINJAI PARK SINGAPORE 589858
Our Insured's telephone number : NIL

A letter dated **(24/05/2019)** was sent to remind our insured to report the non-injury motor accident to us. No report has yet been made.

Please do not hesitate to contact the following for any clarification on the matter.
(Please cite our reference number: **(CC6/AIG19007745/Ajb3)**)

Name and address of insurance company : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#08-16
Singapore 079120

Name of contact person : Joy Irene
Contact Number : 6841 2409 Fax: 6741 4108
Date : 13/06/2019

LKK

I refuse to have another person SGL 83.51 M
to come and claim my insurance co. That car
had been sold to him.

Whatever he has done to that car is none of
my business now. I refuse to pay for the damages
(not from my insurance)

F66han

View Received Message

This mail is associated with :

***SKP9971Z (3113191149SG)
[SGL8351M]**

TP
AZME BIN YUNOS
Apr 29 2019 3:00PM
[Chan Fatt Cheung]
Hua Meng Spray Painting Workshop

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 02/12/2019 17:21 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13407.45) - SKP9971Z - Claim Handler: Ler, Bernard-JQ

Approved:13407.45:Cost of Repair \$12,000.00 As per surveyor finalization Loss of Use \$1,400.00 14 days @ S\$ 100/day LTA/ GIA Search Fee \$7.45
Total \$13,407.45

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2019 Edit Reg		30 Apr 2019 00:00 Edit Adj Rpt	S\$12,000.00 Edit Estimates	S\$12,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: SHIN-HAN LIMO SERVICE , Co. Reg. No.: NA									
Main Claimant: AZME BIN YUNOS , ID: S7243472B									
Vehicle Reg. No.:	SKP9971Z	Date of Loss:	29/04/2019 15:00 - :59 [54 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3113191149SG	Policy/Cover Note No.:	0999994405						
Vehicle Reg. No. (Insured):	SGL8351M	Policy No. (Claimant):	5098058340-01						
Excess:									
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (02/12/2019): Alert - Adj Mandate Approved (S\$13407.45) - SKP9971Z - Claim Handler: Ler, Berna... - AIG_SG (12/06/2019): Re: No OI GIA Report - AIG_SG (22/05/2019): Re: No OI GIA Report - AIG_SG (03/05/2019): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKP9971Z (3113191149SG)
[SGL8351M]

TP

AZME BIN YUNOS

Apr 29 2019 3:00PM

[SHIN-HAN LIMO SERVICE]

Hua Meng Spray Painting Workshop

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser v	
Video						1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	27/11/19 16:39	Video - Accident TP VIDEO FOOTAGE			 Load MP4		
Letters/Correspondences						1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown			 Edit		
Photos/Images						3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	21/05/19 17:57	General View			 Load JPG ☒		
2	21/05/19 17:57	General View			 Load JPG ☒		
3	21/05/19 17:57	Chassis Number			 Load JPG ☒		
4	21/05/19 17:57	General View			 Load JPG ☒		
5	21/05/19 17:57	General View			 Load JPG ☒		
6	21/05/19 17:57	General View			 Load JPG ☒		
7	21/05/19 17:57	General View			 Load JPG ☒		
8	21/05/19 17:57	General View			 Load JPG ☒		
9	21/05/19 17:57	General View			 Load JPG ☒		
10	21/05/19 17:57	General View			 Load JPG ☒		
11	21/05/19 17:57	General View			 Load JPG ☒		
12	21/05/19 17:57	General View			 Load JPG ☒		
13	21/05/19 17:57	General View			 Load JPG ☒		
14	21/05/19 17:57	General View			 Load JPG ☒		
15	21/05/19 17:57	General View			 Load JPG ☒		
16	21/05/19 17:57	General View			 Load JPG ☒		
17	21/05/19 17:57	General View			 Load JPG ☒		
18	21/05/19 17:57	General View			 Load JPG ☒		
19	21/05/19 17:57	General View			 Load JPG ☒		
20	21/05/19 17:57	General View			 Load JPG ☒		
21	21/05/19 17:57	General View			 Load JPG ☒		
22	21/05/19 17:57	General View			 Load JPG ☒		
23	21/05/19 17:57	General View			 Load JPG ☒		
24	21/05/19 17:57	General View			 Load JPG ☒		
25	21/05/19 17:57	General View			 Load JPG ☒		
26	21/05/19 17:57	General View			 Load JPG ☒		
27	21/05/19 17:57	General View			 Load JPG ☒		
28	21/05/19 17:57	General View			 Load JPG ☒		
29	21/05/19 17:57	General View			 Load JPG ☒		
30	21/05/19 17:57	General View			 Load JPG ☒		
31	21/05/19 17:57	General View			 Load JPG ☒		
32	21/05/19 17:57	General View			 Load JPG ☒		
33	21/05/19 17:57	General View			 Load JPG ☒		
34	21/05/19 17:57	General View			 Load JPG ☒		
35	21/05/19 17:57	General View			 Load JPG ☒		
36	21/05/19 17:57	General View			 Load JPG ☒		

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
37	21/05/19 17:57	General View	 Load JPG	☒
38	21/05/19 17:57	General View	 Load JPG	☒
39	21/05/19 17:57	General View	 Load JPG	☒
40	21/05/19 17:57	General View	 Load JPG	☒
41	21/05/19 17:57	General View	 Load JPG	☒
42	21/05/19 17:57	General View	 Load JPG	☒
43	21/05/19 17:57	General View	 Load JPG	☒
44	21/05/19 17:57	General View	 Load JPG	☒
45	21/05/19 17:57	General View	 Load JPG	☒
46	21/05/19 17:57	General View	 Load JPG	☒
47	21/05/19 17:57	General View	 Load JPG	☒
48	21/05/19 17:57	General View	 Load JPG	☒
49	21/05/19 17:57	General View	 Load JPG	☒
50	21/05/19 17:57	General View	 Load JPG	☒
51	21/05/19 17:57	General View	 Load JPG	☒
52	21/05/19 17:57	General View	 Load JPG	☒
53	21/05/19 17:57	General View	 Load JPG	☒
54	21/05/19 17:57	General View	 Load JPG	☒
55	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
56	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
57	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
58	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
59	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
60	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
61	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
62	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
63	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
64	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
65	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
66	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
67	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
68	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
69	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
70	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
71	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
72	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
73	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
74	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
75	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
76	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
77	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
78	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
79	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
80	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
81	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
82	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
83	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
84	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
85	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
86	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
87	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
88	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
89	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
90	28/08/19 11:54	Reinspection Photo	 Load JPG	☒
91	28/08/19 11:54	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
92	28/08/19 11:54	Reinspection Photo		☒
93	28/08/19 11:54	Reinspection Photo		☒
94	28/08/19 11:54	Reinspection Photo		☒
95	28/08/19 11:54	Reinspection Photo		☒
96	28/08/19 11:54	Reinspection Photo		☒
97	28/08/19 11:54	Reinspection Photo		☒
98	28/08/19 11:54	Reinspection Photo		☒
99	28/08/19 11:54	Reinspection Photo		☒
100	28/08/19 11:54	Reinspection Photo		☒
101	28/08/19 11:54	Reinspection Photo		☒
102	28/08/19 11:54	Reinspection Photo		☒
103	28/08/19 11:54	Reinspection Photo		☒
104	28/08/19 11:54	Reinspection Photo		☒
105	28/08/19 11:54	Reinspection Photo		☒
106	28/08/19 11:54	Reinspection Photo		☒
107	28/08/19 11:54	Reinspection Photo		☒
108	28/08/19 11:54	Reinspection Photo		☒
109	28/08/19 11:54	Reinspection Photo		☒
110	28/08/19 11:54	Reinspection Photo		☒
111	28/08/19 11:54	Reinspection Photo		☒
112	28/08/19 11:54	Reinspection Photo		☒
113	28/08/19 11:54	Reinspection Photo		☒
114	28/08/19 11:54	Reinspection Photo		☒
115	28/08/19 11:55	Reinspection Photo		☒
116	28/08/19 11:55	Reinspection Photo		☒
117	28/08/19 11:55	Reinspection Photo		☒
118	28/08/19 11:55	Reinspection Photo		☒
119	28/08/19 11:55	Reinspection Photo		☒
120	28/08/19 11:55	Reinspection Photo		☒
121	28/08/19 11:55	Reinspection Photo		☒
122	28/08/19 11:55	Reinspection Photo		☒
123	28/08/19 11:55	Reinspection Photo		☒
124	28/08/19 11:55	Reinspection Photo		☒
125	28/08/19 11:55	Reinspection Photo		☒
126	28/08/19 11:55	Reinspection Photo		☒
127	28/08/19 11:55	Reinspection Photo		☒
128	28/08/19 11:55	Reinspection Photo		☒
129	28/08/19 11:55	Reinspection Photo		☒
130	28/08/19 11:55	Reinspection Photo		☒
131	28/08/19 11:55	Reinspection Photo		☒
132	28/08/19 11:55	Reinspection Photo		☒
133	28/08/19 11:55	Reinspection Photo		☒
134	28/08/19 11:55	Reinspection Photo		☒
135	28/08/19 11:55	Reinspection Photo		☒
136	28/08/19 11:55	Reinspection Photo		☒
137	28/08/19 11:55	Reinspection Photo		☒
138	28/08/19 11:55	Reinspection Photo		☒
139	28/08/19 11:55	Reinspection Photo		☒
140	28/08/19 11:55	Reinspection Photo		☒
141	28/08/19 11:55	Reinspection Photo		☒
142	28/08/19 11:55	Reinspection Photo		☒
143	28/08/19 11:55	Reinspection Photo		☒
144	28/08/19 11:55	Reinspection Photo		☒
145	28/08/19 11:55	Reinspection Photo		☒
146	28/08/19 11:55	Reinspection Photo		☒
147	28/08/19 11:55	Reinspection Photo		☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
148	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
149	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
150	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
151	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
152	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
153	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
154	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
155	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
156	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
157	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
158	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
159	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
160	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
161	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
162	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
163	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
164	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
165	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
166	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
167	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
168	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
169	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
170	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
171	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
172	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
173	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
174	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
175	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
176	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
177	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
178	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
179	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
180	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
181	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
182	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
183	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
184	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
185	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
186	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
187	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
188	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
189	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
190	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
191	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
192	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
193	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
194	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
195	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
196	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
197	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
198	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
199	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
200	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
201	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
202	28/08/19 11:55	Reinspection Photo	Load JPG	☒
203	28/08/19 11:55	Reinspection Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
204	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
205	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
206	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
207	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
208	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
209	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
210	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
211	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
212	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
213	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
214	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
215	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
216	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
217	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
218	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
219	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
220	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
221	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
222	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
223	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
224	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
225	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
226	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
227	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
228	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
229	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
230	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
231	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
232	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
233	28/08/19 11:55	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/19 19:41	TP GIA REPORT	 Load PDF	
2	07/05/19 10:20	Non reporting letter	 Load PDF	
3	22/05/19 12:40	First Reminder Letter	 Load PDF	
4	24/06/19 13:25	FINAL REMINDER TO INSURED	 Load PDF	
5	29/08/19 14:08	LETTER FROM OI	 Load PDF	
6	11/11/19 08:58	OID DRIVING LICENCE STATUS	 Load PDF	
7	22/11/19 08:58	LOD	 Load PDF	
8	22/11/19 08:58	LTA SEARCH	 Load PDF	
9	23/11/19 12:53	LETTER TO OI	 Load PDF	
10	27/11/19 16:39	TP SCENE PHOTOS	 Load PDF	
11	27/12/19 08:26	WORKSHOP INVOICE	 Load PDF	
12	27/12/19 08:26	AUTHORISATION TO ACT FORM	 Load PDF	
13	27/12/19 08:26	Release Voucher	 Load PDF	
14	27/12/19 08:26	Registered Mail Fee	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SGL8351M (Insd veh)	Model:	MAZDA 5 2.0 (A)
	SKP9971Z (TP veh)		
Date of Accident:	29/04/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	29,716.48
Final Repair Cost	:	\$	12,000.00
Loss of Use	:	\$	1,400.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	13,407.45

14.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 100 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hua Meng Spray Painting Workshop	:	\$ 13,407.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

27 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19007745/AHB3Q2

Date: 27/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994405

Claimant

Vehicle No : SKP9971Z

Insured Vehicle No : SGL8351M

Date of Loss: 29/04/2019

Nature of Claim: TP

Claim No: 3113191149SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKP9971Z

Make & Model: MAZDA 5, 2.0 (A)

Engine No: PE30689632

Reg. Date: 28/10/2014 (Man. Year: 2014)

Chassis No: JM6CW1071F0119986

Colour: Black

Odometer: 119077 km

Engine Capacity: 1998 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,016.48	15,983.92	7,032.56	30.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,700.00	3,910.00	2,790.00	41.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,716.48	19,893.92	9,822.56	33.05
Approved Total (Overridden) (S\$)		12,000.00		
Nett Amount (S\$)	29,716.48	12,000.00	17,716.48	59.62
+ Loss of Use (14.0 x S\$100.00/day) (S\$)		1,400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,407.45		

INSPECTION

Date of Assignment: 30/04/2019

Date Inspected: 30/04/2019 Inspected At:

Hua Meng Spray Painting Workshop (HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Necessary	69.90 FL	*69.90 FL
2	1		*REAR TAILGATE	Distorted	1,886.50 FL	*1,886.50 FL
3	2		*REAR TAILGATE HINGES	Necessary	88.80 FL	*88.80 FL
4	1		*REAR TAILGATE UPPER LOCK	Damaged	273.90 FL	*273.90 FL
5	1		*REAR TAILGATE LOWER LOCK	Bent	61.80 FL	*61.80 FL
6	1		*REAR TAILGATE WEATHERSTRIP	Cut	204.50 FL	*204.50 FL
7	1		*REAR TAILGATE INNER BOARD	Deformed	420.00 FL	*420.00 FL
8	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	407.00 FL	*- FL
9	1		*REAR TAILGATE CENTRE EMBLEM	Necessary	50.80 FL	*50.80 FL
10	1		*REAR TAILGATE HANDLE	Not Necessary	142.80 FL	*- FL
11	1		*REAR TAILGATE MAZDA EMBLEM	Necessary	52.10 FL	*52.10 FL
12	1		*REAR TAILGATE 5 EMBLEM	Necessary	41.80 FL	*41.80 FL
13	1		*REAR TAILGATE SKY ACTIV EMBLEM	Necessary	92.20 FL	*92.20 FL
14	2		*REAR TAILGATE REFLECTOR	Cracked	943.60 FL	*770.40 FL
15	1		*REAR TAILGATE INNER HANDLE	Not Necessary	60.50 FL	*- FL
16	2		*REAR NUMBER PLATE LAMP	Not Necessary	133.20 FL	*- FL
17	1		*REAR WIPER MOTOR	Damaged	313.50 FL	*313.50 FL
18	2		*REAR LAMP	Cracked	1,386.60 FL	*971.20 FL
19	2		*REAR LAMP HOUSING	Repair	429.00 FL	*- FL
20	1		*REAR BUMPER	Distorted	1,107.70 FL	*1,107.70 FL
21	2		*REAR BUMPER SIDE HOLDER	Necessary	109.80 FL	*109.80 FL
22	2		*REAR BUMPER REFLECTOR	Cracked	121.80 FL	*121.80 FL
23	2		*REAR BUMPER REVERSE SENSOR	Damaged	334.40 FS	*200.00 FS
24	1		*REAR BUMPER REINFORCEMENT	Bent	294.80 FL	*294.80 FL
25	2		*REAR BUMPER BRACKET	Not Necessary	109.60 FL	*- FL
26	1		*REAR BUMPER CLIPS	Necessary	44.00 FL	*44.00 FL
27	1		*REAR END PANEL	Distorted	594.00 FL	*594.00 FL
28	1		*REAR END PANEL INNER TOP GARNISH	Deformed	462.00 FL	*165.20 FL
29	2		*REAR FENDER INNER GARNISH	Deformed	1,112.80 FL	*1,112.80 FL
30	1		*REAR SPARE TYRE WELL	Repair	1,314.50 FL	*- FL
31	2		*REAR SPARE TYRE WELL INSULATION	Not Necessary	770.00 FL	*- FL
32	1		*REAR SPARE TYRE TOP BOARD	Deformed	407.00 FL	*407.00 FL
33	2		*REAR FENDER INNER SHIELD	Deformed	99.00 FL	*99.00 FL
34	1		*REAR EXHAUST PIPE	Bent	1,278.50 FL	*993.00 FL
35	1		*REAR EXHAUST PIPE CHROME	Bent	82.50 FL	*82.50 FL
36	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	45.30 FL	*- FL
37	1		*BONNET	Dented	1,196.70 FL	*1,034.00 FL
38	2		*BONNET HINGES	Not Necessary	125.20 FL	*- FL
39	1		*BONNET LOCK	Not Necessary	238.60 FL	*- FL
40	1		*BONNET LOCK BRACKET	Not Necessary	46.20 FL	*- FL
41	1		*BONNET INNER RUBBER	Not Necessary	18.70 FL	*- FL
42	1		*SUPPORT PANEL	Cracked	520.00 FL	*520.00 FL
43	1		*BONNET INNER OUTER RUBBER	Not Necessary	85.00 FL	*- FL
44	1		*BONNET INSULATION	Not Necessary	145.20 FL	*- FL
45	2		*FRONT HEADLAMP	Cracked	3,416.20 FL	*3,416.20 FL
46	2		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	98.40 FL	*- FL
47	1		*FRONT BUMPER	Deformed	1,277.00 FL	*1,045.00 FL
48	1		*FRONT BUMPER CENTRE EMBLEM	Necessary	52.60 FL	*52.60 FL
49	1		*FRONT BUMPER CENTRE GRILLE	Cracked	809.30 FL	*657.00 FL
50	2		*FRONT BUMPER FOG LAMP	Not Necessary	727.60 FL	*- FL
51	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	91.20 FL	*- FL
52	2		*FRONT BUMPER SIDE HOLDER	Necessary	49.80 FL	*49.80 FL
53	1		*FRONT BUMPER REINFORCEMENT	Bent	612.50 FL	*506.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	2		*FRONT BUMPER BRACKET	Not Necessary	59.40 FL	*- FL
55	1		*FRONT BUMPER CLIPS	Necessary	49.50 FL	*30.00 FL
56	1		*REAR SPARE TYRE TOP TOOL BOARD	Deformed	404.80 FL	*404.80 FL
57	1		*REAR SPARE SCREW	Bent	24.20 FL	*24.20 FL
58	1		*AIR CON CONDENSER	Dented	936.30 FL	*936.30 FL
59	2		*FRONT FENDER	Not Necessary	743.00 FL	*- FL
60	1		*FRONT GRILLE	Not Necessary	186.30 FL	*- FL
61	1		*FRONT GRILLE EMBLEM	Not Necessary	52.10 FL	*- FL
62	1		*REAR NUMBER PLATE	Bent	55.00 FS	*30.00 FS
63	1		*REAR NUMBER PLATE HOLDER	Deformed	55.00 FS	*30.00 FS
64	1		*FRONT NUMBER PLATE	Missing	55.00 FS	*30.00 FS
65	1		*FRONT NUMBER PLATE HOLDER	Missing	55.00 FS	*30.00 FS
66	1		*REAR CAMERA	Damaged	880.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,412.00	19,804.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,395.52	3,820.98
Total Parts (\$\$)	23,016.48	15,983.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	150.00	60.00
2	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
3	TO SUPPLY REAR END PANEL INNER SEALANT	New	200.00	60.00
4	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	120.00
5	REMOVE & REINSTALL EXHAUST PIPE	New	150.00	80.00
6	REMOVE & REINSTALL BOOTLED INNER GARNISH	New	200.00	80.00
7	REMOVE & REINSTALL PETROL TANK	New	150.00	0.00
8	REMOVE & REINSTALL AIR CON	New	150.00	120.00
9	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	60.00
10	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	3,000.00	1,800.00
11	RESPRAY PAINTING	New	2,200.00	1,400.00
12	TUFF KOTE	New	150.00	80.00
Gross Labour Cost (S\$)			6,700.00	3,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >