



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving TPVD MITSUBISHI OUTLANDER 2.4 CVT ABS  
D/AIRBAG AWD S/R (SKT1452L)

Date of Loss 22 June 2018

Time of Loss 13.45

Loss Description GBG4893C (INSD) C/W SKT1452L (TP)

Comment

### Workshop Details

Total Rebate Amount

0

Nett Loss Amount \$0.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work  
completion \*

20



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Vehicle &amp; Driver Details

Vehicle Registration# SKT1452L

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

26/05/2015



Mileage

Age of Vehicle

3

CATEGORY

POLICY INFORMATION

ASSESSMENT  
INFORMATIONManufacturing  
Year

2015

Make

TPVD MITSUBISHI

MITSUBISHI

Model

OUTLANDER 2.4 CVT  
ABS D/AIRBAG AWD S/R

OUTLANDER 2

## Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY  
INFORMATION

Driver Name

MAK TZE LIN

Date of Birth

3 July 1982



dd/mm/yyyy



Age

36

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value="▼"/>
Type of Paint		<input type="text"/>
Chassis No		<input type="text" value="JMYXTGF3WFz"/>
Engine No		<input type="text" value="4B12PL4690"/>
Engine Capacity		<input type="text" value="2360"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text" value="▼"/>
Driving Experience	0	
Driver License #		<input type="text"/>
License Type		<input type="text" value="▼"/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 
Address	61E CHOA CHU, KANG ROAD, 689393, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Female	<input type="text"/>
Marital status	Unknown	<input type="text"/>
Identification #	S8271667Z	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

17/05/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver Excess

0

Other Excess

## Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

## Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/55R18

Rear Tyre Size

225/55R18

Front left side

ROADSTONE6mm

Rear left side

ROADSTONE6mm

Front right side

ROADSTONE6mm

Rear right side

ROADSTONE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

### Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



## &lt;&lt; Assessment Details

General &amp; Workshop Details Vehicle &amp; Driver Details Vehicle Condition Taxes &amp; Ratio Parts &amp; Labour Miscellaneous Summary

## Parts

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMO
<input type="checkbox"/>		0	1		TAILGATE ASSEMBLY	Replaced	0	1166	No		10			1049.4	Reviewing	
<input type="checkbox"/>		0	1		TAILGATE WINDSCREEN GLASS	Serviceable	0	0	No		10			0	Deny	
<input type="checkbox"/>		0	1		TAILGATE WINDSCREEN GLASS MOULDING	Replaced	0	121	No		10			108.9	Reviewing	
<input type="checkbox"/>		0	1		TAILGATE WINDSCREEN DAM KIT	Replaced	0	110	No		10			99	Reviewing	
<input type="checkbox"/>		0	1		TAILGATE WINDSCREEN WIPER BLADE	Replaced	0	35	No		10			31.5	Reviewing	
<input type="checkbox"/>		0	1		TAILGATE WINDSCREEN WIPER ARM	Replaced	0	70	No		10			63	Reviewing	
<input type="checkbox"/>		0	1		TAILGATE WINDSCREEN WIPER MOTOR	Serviceable	0	0	No		10			0	Deny	
<input type="checkbox"/>		0	1		TAILGATE OUTER REFLECTOR	Replaced	0	752	No		10			676.8	Reviewing	


















	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMO
		0	11		TAILGATE OUTER REFLECTOR CLIP	Replaced	0	4	No		10			39.6	Reviewing	
		0	1		TAILGATE OUTER REFLECTOR MITSUBISHI LOGO	Replaced	0	37	No		10			33.3	Reviewing	
		0	2		TAILGATE LICENSE PLATE LAMP	Serviceable	0	0	No		10			0	Deny	
		0	1		TAILGATE OUTLANDER EMBLEM	Replaced	0	103	No		10			92.7	Reviewing	
		0	1		TAILGATE MIVEC TECHNOLOGY PLATE	Replaced	0	83	No		10			74.7	Reviewing	
		0	1		TAILGATE MOTORISED LOCK ASSEMBLY	Replaced	0	628	No		10			565.2	Reviewing	
		0	1		REAR END OUTER PANEL	Replaced	0	296	No		10			266.4	Reviewing	
		0	1		REAR END PANEL TOP GARNISH	Replaced	0	123	No		10			110.7	Reviewing	
		0	4		REAR END PANEL TOP GARNISH CLIP	Replaced	0	4	No		10			14.4	Reviewing	
		0	1		TAILGATE LOCK STRIKER	Replaced	0	24	No		10			21.6	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMO
		0	1		TAILGATE OPENING WEATHER-STRIP	Replaced	0	232	No		10			208.8	Reviewing	
		0	1		REAR COMBINATION LAMP - O/S	Replaced	0	748	No		10			673.2	Reviewing	
		0	1		REAR COMBINATION LAMP - N/S	Serviceable	0	0	No		10			0	Deny	
		0	1		REAR BUMPER FACE	Replaced	0	1158	No		10			1042.2	Reviewing	
		0	6		REAR BUMPER CLIP	Replaced	0	3	No		10			16.2	Reviewing	
		0	1		REAR BUMPER REVERSE LAMP - O/S	Serviceable	0	0	No		10			0	Deny	
		0	1		REAR BUMPER REVERSE LAMP - N/S	Serviceable	0	0	No		10			0	Deny	
		0	1		REAR BUMPER REVERSE LAMP BEZEL - O/S	Replaced	0	73	No		10			65.7	Reviewing	
		0	1		REAR BUMPER REVERSE LAMP BEZEL - N/S	Replaced	0	73	No		10			65.7	Reviewing	
		0	1		REAR BUMPER LOWER GUARD	Repair	0	0	No		10			0	Deny	
		0	1		REAR BUMPER IMPACT BRACKET - O/S	Replaced	0	78	No		10			70.2	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMO
		0	1		REAR BUMPER IMPACT BRACKET - N/S	Replaced	0	78	No		10			70.2	Reviewing	
		0	1		REAR BUMPER SIDE RETAINER - O/S	Replaced	0	20	No		10			18	Reviewing	
		0	1		REAR BUMPER SIDE RETAINER - N/S	Serviceable	0	0	No		10			0	Deny	

#### Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMO
		0		TO CUT / WELD REAR END OUTER PANEL TO RENEW AND REPAIR REAR BUMPER LOWER GUARD INCLUDING REPLACEMENT OF THE REAR ACCIDENT DAMAGED PARTS	0	900	0	0	Reviewing		
		0		TO REMOVE / INSTALL TAILGATE WINDSCREEN GLASS TO FACILITATE THE REPLACEMENT OF THE TAILGATE PANEL INCLUDE PERFORMING WATER LEAKAGE TEST	0	120	0	0	Reviewing		
		0		TO TRANSFER TAILGATE LOCKING MECHANISM AND OTHER COMPONENTS TO NEW TAILGATE PANEL INCLUDE CHECKING COMPONENTS FOR FUNCTION	0	60	0	0	Reviewing		
		0		TO TRANSFER TAILGATE PARKING AID CAMERA TO NEW TAILGATE PANEL INCLUDE TESTING FOR FUNCTIONS	0	40	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMO'
 	0		TO REMOVE / INSTALL TRUNK COMPARTMENT TRIM FINISHERS, GARNISHES AND INTERIOR UPHOLSTERY TO FACILITATE THE REPLACEMENT OF THE REAR END OUTER PANEL	0	60	0	0	Reviewing		
 	0		TO CHECK REAR LIGHTINGS AND RIGHT SIDE DOOR ELECTRICAL WIRING SYSTEMS INCLUDE PERFORMING WATER LEAKAGE TEST	0	30	0	0	Reviewing		
 	0		TO INSTALL REAR BUMPER PARKING SENSORS TO NEW BUMPER FACE INCLUDE TESTING FOR FUNCTIONS	0	30	0	0	Reviewing		
 	0		TO PUTTY AND RE-SPRAY PAINTING ON TAILGATE, REAR END OUTER PANEL, REAR BUMPER FACE AND REAR BUMPER LOWER GUARD	0	800	0	0	Reviewing		
 	0		RUST-PROOFING ON THE REAR ACCIDENT AFFECTED PORTIONS	0	40	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary



Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 7 DAYS	Reviewing				
	0	REAR BUMPER PARKING SENSOR - 2 PCS	Reviewing		200	REPLACED	
	0	TAILGATE INNER SEALER	Reviewing		60	REPLACED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	TAILGATE WINDSCREEN GLASS SEALANT	Reviewing	60	REPLACED	
		0	REAR LICENSE PLATE WITH CASING	Reviewing	45	REPLACED	
		0	TAILGATE C&C PLATE	Reviewing	30	REPLACED	
		0	REAR END OUTER PANEL JOINT SEALANT	Reviewing	40	REPLACED	

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

## Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Estimated Claim  
Amount

\$0.00

Adjusted Claim Amount

\$7,992.40

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$5,477.40

Labour

\$0.00

\$2,080.00

Miscellaneous

\$0.00

\$435.00

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	FINAL LUMP SUM	Reviewing	6400		





SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$6,400.00

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$6,400.00

Submit for Review