

Trans-cab Auto Services Pte Ltd

AAD1904-257

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9884B

Not Authored
61 Snp @ 7650/

Vehicle No.:

SHB 9884P

Chassis No.:

VF1ABL15AUC273396

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

29.4.2019

Third Party Insurer :

FCIL

Date of Registration :

30/8/2013

PART		LIST	
1	BUMPER COVER FRT	\$	CM 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	MR 181.75 ✓
1	BUMPER ABSORBER FRT	\$	MR 394.68 ✓
1	BUMPER RETAINER FRT RH	\$	CM 150.77 ✓
1	BUMPER SUPPORT FRT	\$	CM 123.88 ✓
1	BUMPER UNDERTRAY FRT	\$	CM 472.83 ✓
1	BUMPER GRILLE LOWER FRT	\$	SL 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	MR 207.21 ✓
1	BUMPER BEAM FRT	\$	MR 914.08 ✓
1	HEADLAMP RH	\$	CM 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	MR 152.15 ✓
1	HEADLAMP LH	\$	SL 1,184.43 X
1	HEADLAMP PANEL FRT LH	\$	MR 152.15 X
1	FENDER PANEL FRT RH	\$	MR 783.83 ✓
1	WHEELARCH FRT RH	\$	CM 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	MR 15.79 ✓
1	FENDER INSULATOR RH	\$	SL 130.84 X
1	DOOR PANEL FRT RH	\$	MR 2,844.66 X
1	RADIATOR GRILLE	\$	SL 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	SL 225.36
1	RADIATOR GRILLE FRAME	\$	SL 1,353.75
1	RADIATOR FAN COWLING	\$	SL 820.54
1	RADIATOR FAN MOTOR LH	\$	SL 967.36
1	RADIATOR FAN MOTOR RH	\$	SL 1,479.46
1	FRAME FULL SUPPORT PANEL	\$	MR 615.90
1	FRAME FULL SUPPORT BRACKET	\$	MR 89.79
1	DOOR MIRROR ASSY RH	\$	SL 1,483.40
1	DOOR PANEL FRT RH	\$	MR 2,844.66
1	BONNET	\$	MR 1,941.63 ✓
1	BONNET INSULATOR	\$	SL 405.73 X

Trans-cab Auto Services Pte Ltd

AAD1904-257

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9884B

1	BONNET STRUT LH	\$	88.61	
1	BONNET STRUT RH	\$	88.61	
1	BONNET HINGE LH	\$	348.31	
1	BONNET HINGE RH	\$	348.31	
1	BONNET LOCK	\$	305.48	
1	BONNET CABLE	\$	119.19	
1	BONNET CABLE COVER	\$	161.03	
1	BONNET SEAL OUTER	\$	92.36	
1	BONNET SEAL INNER	\$	157.28	
1	SUBFRAME OUTER FRT	\$	2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	92.36	
1	SUBFRAME BRACKET OUTER RH	\$	92.36	
1	ENGINE UNDERTRAY	\$	564.98	
1	A/C CONDENSER	\$	2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	39.67	
1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	
1	A/C CONDENSER GARNISH LH	\$	58.81	
1	A/C CONDENSER GARNISH RH	\$	59.60	
1	LOWER ARM RH	\$	685.76	
1	KUNCKLE ARM RH	\$	846.98	
1	ABSORBER FRT RH	\$	360.54	
1	STABILIZER BAR FRT	\$	604.65	
1	DRIVESHAFT RH	\$	1,747.45	
1	WIPER RESERVOIR	\$	348.25	✓
1	WIPER RESERVOIR NECK	\$	136.11	X
1	WIPER RESERVOIR MOTOR	\$	270.06	X

TOTAL	\$	36,963.11
10%	\$	3,696.31
	\$	33,266.80

Specical Nett

1SET	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X

Trans-cab Auto Services Pte Ltd**AAD1904-257**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9884B

2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1SET	WHEELARCH CLIP FRT RH	\$	nn	30.50	
6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	} X
2	BONNET STRUT L70Y	\$	nn	88.61	
2	BONNET CABLE CLIP L70Y	\$	nn	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	
1	WINDSCREEN SEALANT	\$	nn	253.80	
1	FRONT WINDSCREEN MOULDING	\$	nn	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	nn	80.00	60sn
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	nn	50.00	15sn
1	FRONT RIGHT TYRE	\$	nn	330.00	80sn
1	FRONT RIGHT TYRE RIM	\$	nn	380.00	X

TOTAL	\$	1,734.88
--------------	-----------	-----------------

TOTAL PARTS	\$	35,001.68
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,500.00	500l
----	----------	------

Putty and spray painting of the affected portion.

\$	4,000.00	880l
----	----------	------

To rust-proofing of the affected areas.

\$	170.00	90l
----	--------	-----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	nn	380.00 X
----	----	----------

To check steering geometry and computer wheel alignment

\$	220.00	60l
----	--------	-----

To transfer of tire, rim and on wheel balancing.

\$	nn	170.00 X
----	----	----------

Trans-cab Auto Services Pte Ltd**AAD1904-257**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9884B

To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00	X
To replace, refix and top up coolant for radiator	\$	nn 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00	X
To transfer of front windscreen fittings and conduct water seepage test	\$	nn 170.00	X

TOTAL	\$	11,090.00
--------------	-----------	------------------

Over All Total	\$	46,091.68
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**15 DAYS****3 days**

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--