

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0566/2019/DY/TF
Date : 2-May-19

Vehicle IN workshop kindly arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Yong Sen Stephen
Address : 46 Lorong Marican
Singapore 417225
Telephone : HP +65 83210808
Type of Claim : Own Damage Claims
Policy No. : 1800143243
Vehicle No : **SME 9593 K** ✓
Model Code : Audi A3 SEDAN 1.4 TFSI CO
Model / Year : Nov-18
Engine No : CZE 846444
Chassis No : WAUZZZ8V6K1003903
Mileage : -
Date In : 2-May-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-May-19
Place of Accident : Junction of Aljunied Rd and Sims Drive

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 9593 K

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rhs front door's multi-lock systems and power window devices. Inspect for damages and renew if necessary.	S/N \$ 280.00 X
2	To dismantle and renew rhs front door and rhs wing mirror assy. Re-organize crash management components. Reinstall all parts removed.	\$ 1,400.00 500
3	To respray rhs front door and rhs wing mirror cover,	\$ 1,500.00 150.
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 3,372.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 9593 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	WIND MIRROR MOUNTING - RH <i>2nd</i>	\$ 938.00	✓
2	WIND MIRROR CAP - RH <i>Missing</i>	\$ 136.00	✓
3	WIND MIRROR GLASS- RH <i>Shattered</i>	\$ 1,553.00	✓
4	FRONT DOOR CORNER TRIM - RH <i>new</i>	\$ 41.00	✓
5	FRONT DOOR WINDOR GUIDE STRIP - RH <i>new</i>	\$ 235.00	✓
6	FRONT DOOR WINDOW SLOT SEAL CHROME - RH <i>new</i>	\$ 282.00	✓
7	FRONT DOOR - RH <i>new</i>	\$ 2,279.00	✓
8	FRONT DOOR OUTER SEAL - RH <i>new</i>	\$ 146.00	✓
9	BONDING AGENT <i>2</i>	\$ 45.00	✓
10	CLEANING SOLUTION <i>new</i>	\$ 65.00	✓
11	APPLICATOR	\$ 7.00	✓
12	FRONT DOOR ATTACHMENT PARTS <i>2</i>	\$ 218.00	✓
13	FRONT DOOR CATCH - RH <i>new</i>	\$ 96.00	✓
14	FRONT DOOR TYRE PRESSURE DATA	\$ 26.00	✓
15	SUNDRIES <i>?</i>	\$ 500.00	?
TOTAL SPARE PARTS		\$ 6,567.00	
TOTAL LABOUR CHARGES		\$ 3,372.00	
GRAND TOTAL		\$ 9,939.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian Wang
: 23/05/19
:
:
:
:
: Authorised Reps, 02 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant