

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0520/2019/DY/TF
Date : 23-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SKM 872 B

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Kim Huat
Address : Blk 289 Bishan Street 24
#12-21
Singapore 570289
Telephone : 92278620
Type of Claim : Own Damage Claims
Policy No. : 1700047720-01
Vehicle No : **SGC 8218 M**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Sep-17
Engine No : CHZ 515241
Chassis No : WAUZZZ8VXJ1008407
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 17-Apr-19
Place of Accident : Along Road 1 Sunbird Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGC 8218 M

S/N	Nature of Jobs		Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	s/n	\$ 360.00	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 2,100.00	1000
3	To respray front bumper and rhs front fender.		\$ 1,600.00	1100
4	To renew rhs front rim and carry out wheel alignment.	s/n	\$ 280.00	x
5	To carry out diagnostic check.	s/n	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 4,532.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Parts for Accident Vehicle SGC 8218 M

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	\$ 1,830.00	<i>x</i>
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	<i>x</i>
3	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 35.00	<i>x</i>
4	FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	\$ 270.00	<i>x</i>
5	FRONT BUMPER COVER TRIM - RH <i>new</i>	\$ 148.00	<i>x</i>
6	FRONT BUMPER ADAPTER - RH <i>new</i>	\$ 34.00	<i>x</i>
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	\$ 171.00	<i>x</i>
8	FRONT FENDER- RH <i>Dented</i>	\$ 778.00	<i>✓</i>
9	POP RIVET <i>new</i>	\$ 15.00	<i>-</i>
10	FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$ 65.00	<i>x</i>
11	FRONT FENDER BRACKET - RH <i>?</i>	\$ 60.00	<i>?</i>
12	FRONT BUMPER BRACE - RH <i>?</i>	\$ 88.00	<i>?</i>
13	FRONT WHEEL HOUSING LINER SEAL - RH <i>new</i>	\$ 31.00	<i>x</i>
14	FRONT WHEEL HOUSING LINER - RH <i>new</i>	\$ 158.00	<i>✓</i>
15	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 81.00	<i>x</i>
16	LED HEADLIGHT - RH <i>?</i>	\$ 5,029.00	<i>?</i>
17	HEADLIGHT LIFT CYLINDER - RH <i>new</i>	\$ 128.00	<i>x</i>
18	FRONT TYRE RIM - RH <i>new</i>	\$ 666.00	<i>x</i>
19	RUBBER VALVE <i>new</i>	\$ 13.00	<i>x</i>
20	SUNDRIES <i>?</i>	\$ 500.00	<i>?</i>
TOTAL SPARE PARTS		\$ 10,270.00	
TOTAL LABOUR CHARGES		\$ 4,532.00	
GRAND TOTAL		\$ 14,802.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lj*
Surveyed Date : *02/05/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Authorised Repairs, 04 Days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant