

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 8786C (Supplementary)

DATE : 9.05.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

1/1 Ah me

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Engine Crossmember <i>distorted</i>			\$ 2,094.40 ✓
	SUB TOTAL			\$ 2,094.40
	LESS 20%			\$ 418.88
	DISCOUNTED TOTAL			\$ 1,675.52
	<i>1</i> <i>ng</i> <i>2kk And</i> <i>8</i>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				