

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 23/05/2019

Survey Details:

Date of loss	26-Apr-19
Date of appointment	3-May-19
Date of survey	6-May-19
Location of survey	188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKS 3523H
Make and Model	MERCEDES BENZ B200 STYLE (R16 LED)
Date of registration	9/4/2015
Excess	NIL
Market Value	\$82,000
Parf Rebate	\$59,038
Nett Loss	\$22,962

Repair details:

Initial Estimate	22,430.33 (INCLUSIVE SUPPLEMENTARY)
------------------	-------------------------------------

Proposed/Revised repair cost:

Parts	\$6,063.29 (INCLUSIVE SUPPLEMENTARY)
Check items (estimate)	\$226.05
Labour	\$10,040.00
Total	\$16,329.34
Lump Sum(if applicable)	\$

Number of days for repair	8 DAYS
---------------------------	---------------



Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL.
KINDLY LET US HAVE YOUR APPROVAL OF THE
SUPPLEMENTARY AMOUNT \$ 321.72. WE HAVE NOT
AUTHORIZE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	