

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Soh Li Ping

Date: 10 Jun 2019

Preliminary Advice

Vehicle No	: SFH823D	Accident Date	: 27/04/2019
Make	: TOYOTA FORTUNER	Policy No.	: 29080339QMX
Assignment Date	: 06/05/2019	Excess	: S\$1,000.00
Date of Inspection	: 06/05/2019	Est. Duration of Repair	: 12 days
Inspection At	: Shu Fatt Auto Works (HQ) Block 1009 Bukit Merah Lane 3, #01-90 Singapore 159723		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,379.89 (Inclusive supp)
Revised Amount	:S\$	5,478.89 (Inclusive supp)
Check Items (Estimated)	:S\$	2,612.50
Total	:S\$	8,091.39

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	38,000.00
COE / PARF Rebate	:S\$	24,481.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,519.00

Remarks

(X) The vehicle is economical for repair. Supplementary amount is \$ 425.50.

() The above survey was conducted on a 'without prejudice' basis.