

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4473L

DATE 2/5/2019 14:50

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>Cont</i>			\$ 544.50
	Front Bumper Bracket Top (RH) <i>Xm</i>			\$ 22.40
	Front Bumper Bracket (LRH) <i>Xm</i>			\$ 24.60
	Front Fender (LRH) <i>Cont</i>			\$ 566.30
	Front Fender Shield (RH) <i>X sm</i>			\$ 175.90
	Front Fender Retainer <i>X sm</i>			\$ 24.60
	Frt Wheel Hub Cap, RH <i>Cont</i>			\$ 107.10
	SUB TOTAL			\$ 1,465.40
	LESS 20%			\$ 293.08
	DISCOUNTED TOTAL			\$ 1,172.32
	Front Fender Advertisement Logo (RH) <i>acc</i>			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 400.00 <i>300</i>
	Spray Painting Charge		<i>400</i>	\$ 600.00
	Wiring			\$ 50.00
	Tuff Kote			\$ 50.00 <i>20</i>
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,180.00
	ESTIMATE TOTAL			\$ 2,452.32

Kalin 1/1/19

2/5/19 1605 hrs.

2 Days

PIP

Before Paint photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.