

228280

ASS. REC. BY: Naz

REF: CS/PC1 19007829 / N435

Special Instruction:

CWS

Assigner: Naz

ASSIGNMENT (Office)

From (Person): Henry Kao

at FCI

Date/Time: 3.5.19 3.59p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJY 64U

Insured: SHC 0697D

at Workshop n/s San Te Auto

Tel: 67 55 6710

of Blk 1019 # 01-388 Yishu Industrial Park A

Policy No:

Claim No: D19002846 m FSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 27.4.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3.5.19 4.15p.m

Person Contacted: Deni

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SJY 64U - C-1/TA 300 5537/AY 102	ROA - 15/11/2012
	SHC 0697D - X	
09/5/19 @	10.15am revised to Henry Kao by email.	
07/6/19	Submit Prel. report. - The vehicle has not send in for repair.	

SL

waiting for ST to accept car.

- Naz

* MV: \$19K (est); LTA: \$14285; NV: \$4715

2/9/19

* Reopen ref. for submit final report.

- after reopen, kindly assist pass to tourist Calise 19/9/19.

19/11/19 1st DOZ 12/6/19, reopen ref only ↓

Surveyor

NAL

REF: FCI

ASSIGNMENT

From:

Date: 1.5.2019

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SVV 614U

at Workshop n/s: San Tee Auto

of BIC 1019 # 01-388 Yichun Industrial Park A

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: 2009m owner washing

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

19K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res:

Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

"w/p"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SVV 614U

Yr Began 9 JAN 2010

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

NISSAN TEANA

CC 1997

Colour:

BLACK

A/C

☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading

217,817

V/Radio

☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng No:

C/No:

JN/BDUT3220001401

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / ☐ S/Rim / ☒ STD / ☐ R/Rim or

Tyre Size:

F:

215/60 R16

R:

11

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

27/4/19

D.O.I.

7/5/19.

Survey held at

SAN TEE AUTO

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

WE EXP. 8/1/20

COE Rebate: \$14,285

Repair Margin: \$4K

FINALIZED Lump Sum REPAIR \$650.00 / 2 REPAIR DAYS

(Red @ 2362, 78%)

FCI L/S

RECEIVED 07 JUN 2019

Date/Time, File Pass to:

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to:

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Days Of Repair: 2

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + R5. 21

Tools:

Others:

TOTAL

130
50

15

195

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	3042A
Vehicle No.:	SJV614U
Vehicle to be Exported:	No
Intended Deregistration Date:	08 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	TEANA 2.0L CVT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	MR20880379A
Chassis No.:	JN1BDUJ32Z0001401
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$26,013.00
Original Registration Date:	09 Jan 2010
First Registration Date:	09 Jan 2010
Transfer Count:	2
Actual ARF Paid:	\$26,013.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jan 2020
PARF Rebate Amount:	\$13,006.00
COE Expiry Date:	08 Jan 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,190.00
COE Rebate Amount:	\$1,279.00
Total Rebate Amount:	\$14,285.00

The information contained herein is correct as at 08 May 2019

OK

Search Selection	nissan teana	Any	Any	2010	Any	Any	Any	Any
------------------	--------------	-----	-----	------	-----	-----	-----	-----



\$26,300

\$9,550 /yr

24-Sep-
2010

1,997 cc

124,092
km

Luxury

Available

New Tyre And Road Tax Till Sep 2019. Loan Available. Welcome Old Car 1-1 Exchange Without Cash Top Up.

Top Up.



\$28,800 \$10,860 /yr

14-Aug-
2010

2,496 cc

96,088 km

Luxury

Available

Low Interest Rate. 1 Year Warranty. Balloon Scheme, In-house Financing Options Available. Buy With A Peace Of Mind. Low Mileage. 100% Genuine Mileage. Well Maintained. No Chassis/Structural Damage. Im...

GOWHEELER PTE LTD

Posted: 28-Apr-2019

Tags: 2010 Nissan Teana, 2010 Nissan Teana, Nissan Teana, Nissan Teana, Nissan, Teana, teana, Uten Nissan



€19.288

\$9.030 /yr

18-Jan-201

1.997 cc

133,990

Luxury

Available

The Car Is In Excellent Condition, Low Mileage. Very Well Kept, Luxury, Comfortable, Quiet And Responsive Engine. Good For COE Renewal. Just Did A Engine Top Overhaul. Excellent Gear Box, New Battery....

☆ <http://www.elsevier.com/locate/ymbs>

Save this search criteria, to get email alerts whenever a match is found.

 Save Search

For old advertisements, view **Expired ads**

results/page

SAN TEE AUTO PTE LTD

BLK 1019 #01-388 YISHUN INDUSTRIAL PARK A SINGAPORE 768761

TEL: (65)67538276 FAX: (65)67592034 H/P: (65)97232449

EMAIL: santeeauto@singnet.com.sg

Survivor

TO: C/O LKK

DATE:

6TH MAY 2019

ATTN: 3RD PARTY CLAIM / DIRECT SETTLEMENT

RE: 3RD PARTY CLAIM VEHICLE NO. SJV614U AND SHC697D
ALONG PIE TOWARDS CHANGI NEAR
NEAR KIM KEAT LINK

S/NO	DESCRIPTION	AMOUNT
		\$
1	REAR BUMPER	520.60 ? / CRK
2	REAR BUMPER RETAINER - 2PCS	95.90 ? X SVC
3	BUMPER ENFORCEMENT	301.40 ? X SVC
4	END PANEL	315.10 ? X SVC
		less 30% or 10% ??
	LABOUR TO REPLACE REAR BUMPER AND RETAINER, CLIPS ETC ALIGNMENT, ALIGN, END PANEL ALIGNMENT AND KNOCKING	364.42
	LABOUR TO SPRAY PAINT INNER AND OUTER BUMPER	750.00 200
	TO REMOVE ALL WIRE HARNESS IN ORDER TO FACILITATE REPAIR WORKS AND INSTALLATION	850.00 200 200
		180.00 30
		\$3,013.00

ISSUED BY: DEVI

NAZ LKK
7/5/19 1410

LIS

2 DAYS

CHECK ITEMS PHOTO

AFTER REPAIR PHOTO

NAZ @ lkkauto.com

PARTS 3520.60

LESS 30% \$364.42

LABOUR \$430.00

TOTAL \$794.42

LESS LIS 20% \$635.53

LIS TOTAL \$650.00

98804220

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

/ 2 REPAIR DAYS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19007829/Nqd3s2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 697D	Veh. Inspected	SVJ 614U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002846MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	03/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN TEANA	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JN1BDUJ32Z0001401	Colour	BLACK	
Odometer	217817	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60R16	DUNLOP	5 mm	
L/H Front Tyre	215/60R16	DUNLOP	5 mm	
R/H Rear Tyre	215/60R16	DUNLOP	5 mm	
L/H Rear Tyre	215/60R16	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/04/2019	Inspection Date	07/05/2019	
Survey held at	SAN TEE AUTO PTE LTD BLK 1019 #01-388 YISHUN INDUSTRIAL PARK A SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 614U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CRACKED	520.60	520.60
2	REAR BUMPER RETAINER	SERVICEABLE	95.90	-
1	BUMPER ENFORCEMENT	SERVICEABLE	301.40	-
1	END PANEL	SERVICEABLE	315.10	-
	LESS 30% DISCOUNT		-	-156.18
			1,233.00	364.42
	<u>LABOUR</u>			
	LABOUR TO REPLACE REAR BUMPER AND RETAINER. CLIPS ETC ALIGNMENT, ALIGN, END PANEL ALIGNMENT AND KNOCKING.		750.00	200.00
	LABOUR TO SPRAY PAINT INNER AND OUTER BUMPER.		850.00	200.00
	TO REMOVE ALL WIRE HARNESS IN ORDER TO FACILITATE REPAIR WORKS AND INSTALLATION.		180.00	30.00
			1,780.00	430.00
	GRAND TOTAL		3,013.00	794.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				650.00

Report Ref No. CS/FCI19007829/Nqd3s2

MARKET VALUE: \$19,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,285.00=NETT VALUE: \$4,715.00

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.