



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKD204C

LONPAC INSURANCE BHD
MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information
WIP No 33070
Reg No/Reg Date SKD204C / 15/11/2018
Date In/Mileage / 0
Chassis No WDD2221662A4363593
Engine No 27682430936981
Make/Model MB/MB S 450 SEDAN LONG
Colour/Trim 027 775 Iridium sil/ 048 801 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	03/05/2019/ 09:13	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :1800134679 // 02-05-2019 DRIVE IN:02-05-2019 // TP CAR NO:SGC8598R (LONPAC INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT				480.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				960 1440.00
A BPIRES RESPRAY REAR BUMPER				600 720.00
M REAR BUMPER repair	1.00	2120.83	00.00	2120.83
M LH/R BUMPER GARNISH	1.00	113.42	00.00	113.42
M RH/R BUMPER GARNISH	1.00	113.42	00.00	113.42
M REAR BOTTOM PANEL	1.00	555.88	00.00	555.88
M CT/R BASIC MOUNTING FOR BUMPER	1.00	124.10	00.00	124.10
M CT/R BUMPER BOTTOM GARNISH	1.00	114.09	00.00	114.09
M CT/R PARKING SENSOR	4.00	177.22	00.00	708.88
M CT/R PARKING SENSOR SEAL	4.00	6.42	00.00	25.68
M REAR CROSS MEMBER	1.00	1131.84	00.00	1131.84

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
Tel: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 7,648.14
7% GST on 7648.14 535.37

Total Payable 8,183.51

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKD204C

Finalization

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Rasul

Vehicle & Document Information

WIP No	33070
Reg No/Reg Date	SKD204C / 15/11/2018
Date In/Mileage	09/07/2019 / 14309
Chassis No	WDD2221662A4663593
Engine No	27682430936981
Make/Model	MB/MB S 450 SEDAN LONG
Colour/Trim	027 775 Iridium sil/ 048 801 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	26/08/2019/ 22:56	AQ	305 / Alan Quek Ai Lun
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount

M BPNSUN

POLIC NO/ACC DATE : 1800184679 // 02-05-2019
DRIVE IN: 02-05-2019 // TP CAR NO: S008598R (LONPAC INSURANCE)
DATE IN/DATE SURVEY: 08-07-2019 // LKK RASUL
BY/AUTHORIZED ON : ASHER SNG // 15-06-2019

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT
ASSY COMPONENTS & REFINISH.

A BPIRES

RESPRAY REAR BUMPER

X LH/R BUMPER GARNISH

X RH/R BUMPER GARNISH

X REAR BOTTOM PANEL

X BLIND RIVET

X REAR BOTTOM LEFT TRIM STRIP

480.00✓

960.00✓

600.00✓

1.00	114.32	00.00	114.32
1.00	114.32	00.00	114.32
1.00	560.33	00.00	560.33
10.00	2.20	00.00	22.00
1.00	168.94	00.00	168.94

3 Days
ESTIMATE

Alan Quek

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	3,019.91
7% GST on	3019.91	211.39

Authorized signatory and company stamp

Total Payable 3,231.30

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKD204C

SUPPLEMENTARY

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No 33070
Reg No/Reg Date SKD204C / 15/11/2018
Date In/Mileage 09/07/2019 / 14308
Chassis No WED2211662A4068598
Engine No 27682430936981
Make/Model MB/MB S 450 SEDAN LONG
Colour/Trim 027 775 Iridium sil/ 048 801 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	
WL001605	Credit	26/08/2019/ 22:55	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN
POLICY NO/ACC DATE : 1800184679 // 02-05-2019
DRIVE IN: 02-06-2019 // TP CAR NO: SGC8598R (LONPAC INSURANCE)
DATE IN/DATE SURVEY: 08-07-2019 // LKK RASUL
BY/AUTHORIZED ON : ASHER SNG // 15-06-2019
X BLIND RIVET
X REAR BOTTOM LEFT TRIM STRIP

10.00	2.20	00.00	22.00
168.94	00.00		168.94

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	190.94
7% GST on	190.94	13.37
Total Payable		204.31

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg