



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2005508
INV Date 12/08/2020
Reference CC4/LPC19007868/Ada3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SLZ 7308M
Insured Veh. GBA 4837Y
Claim No. 18/19/19/VC05/021736
Policy No.
Accident Date 28/04/2019
Inspection Date 03/05/2019

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19007868/Ada3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 12-08-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 4837Y	Veh. Inspected	SLZ 7308M
Policy No.		Coverage (\$)	0.00
Claim No.	18/19/19/VC05/021736	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	02/05/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71209526	Colour	BLACK
Odometer	19713	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/04/2019	Inspection Date	03/05/2019
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 7308M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT RIGHT FENDER	DENTED	880.00	489.90
1	ABSORBER -FRONT RIGHT	BENT	310.00	310.00
1	ABSORBER MOUNTING -FRONT RIGHT	DAMAGED	450.00	55.00
1	ABSORBER BEARING -FRONT RIGHT	NECESSARY	380.00	65.00
1	KNUCKLE & BEARING -FRONT RIGHT	BENT	410.00	410.00
1	STEERING TIE ROD END -FRONT RIGHT	NOT NECESSARY	450.00	-
1	STEERING BALL JOINT -FRONT RIGHT	NOT NECESSARY	280.00	-
1	STEERING COLUMN -FRONT RIGHT	NOT NECESSARY	620.00	-
1	LOWER ARM	BENT	345.00	345.00
1	BUMPER BRACKET -RIGHT (ADDITIONAL)	NECESSARY	95.00	95.00
1	FRONT BUMPER (ADDITIONAL) (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-844.00	-353.98
			3,376.00	1,415.92
<u>SPECIAL NETT ITEMS</u>				
1	RIM -FRONT RIGHT (SN)	CUT	220.00	220.00
1	'HYBRID' EMBLEM (SN)	NECESSARY	95.00	65.00
			315.00	285.00
<u>LABOUR</u>				
	TO PUTTY & SPRAY PAINT OF AFFECTED AREA.		400.00	200.00
	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		600.00	200.00
	WHEEL BALANCING & ALIGNMENT.		100.00	80.00
	REMOVE UNDERCARRIAGE.		350.00	220.00
	TO PUTTY & SPRAY PAINT OF AFFECTED AREA. (ADDITIONAL)		350.00	200.00
			1,800.00	900.00
GRAND TOTAL			5,491.00	2,600.92
RECOMMENDED COST OF REPAIRS				2,600.92

Report Ref No. CC4/LPC19007868/Ada3n2



Report Ref No. CC4/LPC19007868/Ada3n2

A handwritten signature in black ink, appearing to read 'A.L.P.' or similar, enclosed in a light blue rectangular box.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 7308M

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 7308M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 7308M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

