



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883
ROB No: 53291793 | Tel: 6741-1730 / 731, Fax: 6744-5246, Email: liusbro@gmail.com

Invoice/Ref No: GBB7447P190425

6

Customer

Estimate

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 03-05-19

Address: Motor Claims Department

Vehicle No: GBB7447P

78 Shenton Way #07-16

Model/Make: Mitsubishi

AIG Building

Singapore 079120

FB70BB:SRDEA

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Tailgate <i>11</i>	\$ 1,200.00	X
2	Tailgate Lock Bar <i>11</i>	\$ 400.00	X
3	Rear Lh Tailgate <i>11</i>	\$ 1,200.00	X
4	Rear Support Rubber Panel 02 pcs (@ S\$180.00) <i>2</i>	\$ 360.00	X
5	Support Rubber 04 pcs (@ S\$180.00) <i>Turn</i>	\$ 720.00	X <i>s.w</i>
6	Tail Lamp 02 pcs (@ S\$239.60) <i>25%</i>	\$ 479.20	X
7	Number Plate Lamp <i>one</i>	\$ 97.00	X
8	Number Plate "Metal" <i>Self</i>	\$ 28.00	SN <i>145.2</i>
9	"Corporate" Advertisement & Artwork <i>11</i>	\$ 1,600.00	SN X
	To check all wiring & electrical component for proper function	\$ 62.00	- <i>20</i>
	Remove and refix rear tailgate components & mechanism	\$ 120.00	- <i>11 X</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,000.00	- <i>600</i>
	To putty & spray painting & including touch up paint on accident affected area	\$ 800.00	- <i>200</i>
	To apply Rust Proofing, rescal tuff-coating treatment on accident area	\$ 80.00	- <i>11 X</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 8,146.20

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not authorized
date

VIC

2/5/1300
40%

6/5/19
Wah Ph. Attorney

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any spray painting
- To replace damaged part(s) during resurvey
- Part(s) to be subject to confirmation
- This work subject to a "Without Prejudice" basis
- No replacement allowed
- Supplementary work must be resurveyed and subject to approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

9700
25%
1- 72.75
s.w - 734
roh - 820
1626.75
207
1301.