

Form 1

ASS. REC. BY:

REF: CS/CT119007883/9a13

Special Instruction:

Surveyor: GB

ASSIGNMENT (Office)

From (Person): Elaine Chong

of CTL

Date/Time: 6.9.19 11.15 a.m

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBA 9762X

Insured: GBB 2362H

at Workshop m/s Tan Hup Seng Auto

Tel: 98306069

of BK 19 sin ming Industrial Estate, A01-09

Policy No: DMCVSN3044671804

Claim No: SXM19D201892C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26.4.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 6.5.19 11.24 a.m

Person Contacted: Tony

Vehicle IN / OUT

Date/Time	Action/Instruction
	Estimate (✓) Inspection: 160 sin ming Auto city 01-03
	GBA 9762X - C04/AS11130232151 A1163 D.O.A. = 22/12/2018
	GBB 2362H - C06/CI118013762/A16312 D.O.A. = 07/07/2018
	Repair agreed and survey for survey.

Surveyor: Cal. REF: CTi C0866E (-2022)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐
 To Inspect Vehicle No: _____
 at Workshop m/s Tan Hup Geng Auto
 of _____
 Insured: 9183 3008 Han.
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$15K.
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBA9762X Yr Regn: 07 May 2008
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Opel combo C.C. 1686
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 302898 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: W060XCF258.4003730
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or _____
 Brake: ☒ In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD / Rim or _____
 Tyre Size: F: 185/60R15
 R: 11
☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. _____ D.O.I. 06-05-19
 Survey held at w/s 5:30pm
 Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
06/5 Finalized \$3800 with Boss
(Red to 3756.40, 46%)

RECEIVED 10 MAY 2019.

Date/Time, File Pass to? ☐ : Prel. Report

11/6/5 Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Report Format : MEM-TP

Lump Sum / I.B.F. (\$) 3800

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2019		06 May 2019 11:15 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: GIM TIAN CIVIL ENGINEERING PTE LTD, Co. Reg. No.: +									
Vehicle Reg. No.: GBA9762X		Date of Loss: 26/04/2019 14:00 - :59							
Claim Type: TP / SNM19D201892C02		Policy/Cover Note No.: DMCVSN3044671804							
Vehicle Reg. No. (Insured): GBB2362H		Policy No. (Claimant): VCA/P1603235							
		Excess: S\$500.00							
Repairer: Tan Hup Seng Auto Repair Workshop (HQ) BLK 19 SIN MING INDUSTRIAL ESTATE, #01-09, 575677 Sin Ming - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Articles](#)


HIGH GLOSS, LESS MAINTENANCE, LASTING

► Check out the list of Paint Protection Film services available

► **SEARCH** Opel Combo Price Range ▼ Depreciation ▼ > 10 yrs ▼ Vehicle Type ▼

Home » Used Cars » A M T Automobile » Opel Combo 1.7 (COE till 06/2023)

► Opel Combo 1.7 (COE till 06/2023)

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price	\$16,800	Lifespan	12-Jun-2028
Depreciation ⓘ	\$4,100 /yr	Reg Date	13-Jun-2008 (4yrs 1mth 5days COE left)
Mileage	N.A.	Manufactured ⓘ	2007
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$13,829 as of today (change)	OMV ⓘ	\$19,931
COE ⓘ	\$16,859	ARF ⓘ	\$997
Engine Cap	1,686 cc	No. of Owners ⓘ	3
Curb Weight ⓘ	1,240 kg		
Type of Vehicle	Van		

Category

COE Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

☆ Shortlist

📄 Report Error

Seller Information

Company

Address

Location

Office No

Upfront Payment

► more Financial Info

Tra

Compare

\$25

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2019		06 May 2019 11:15 Edit Adj Rpt	S\$3,800.00 Edit Estimates	S\$3,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: ~, ID: ~									
Main Claimant: GIM TIAN CIVIL ENGINEERING PTE LTD. Co. Reg. No.: ~									
Vehicle Reg. No.: GBA9762X		Date of Loss: 26/04/2019 14:00 - :59 [131 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D201892C02		Policy/Cover Note No.: DMCVSN3044671804							
Vehicle Reg. No. (Insured): GBB2362H		Policy No. (Claimant): VCA/P1603235							
		Excess: S\$500.00							
Repairer: Tan Hup Seng Auto Repair Workshop (HQ) BLK 19 SIN MING INDUSTRIAL ESTATE, #01-09, 575677 Sin Ming - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 15/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBA9762X (SNM19D201892C02)
[GBB2362H]
TP
GIM TIAN CIVIL ENGINEERING PTE LTD
Apr 26 2019 2:00PM
[-]
Tan Hup Seng Auto Repair Workshop

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page		☒			
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)							Thumbnail		Print			
1	29/04/19 13:44	Accident Statement									Load HTML			
Photos/Images									3 per page		☒			
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)							Thumbnail		Print			
1	29/04/19 13:34	Accident Photo [Linked Accident Report Documents]									Load JPG		☒	
2	29/04/19 13:34	Accident Photo [Linked Accident Report Documents]									Load JPG		☒	
3	29/04/19 13:34	Accident Photo [Linked Accident Report Documents]									Load JPG		☒	
4	29/04/19 13:34	Accident Photo [Linked Accident Report Documents]									Load JPG		☒	
5	29/04/19 13:34	Accident Photo [Linked Accident Report Documents]									Load JPG		☒	
6	29/04/19 13:34	Accident Photo [Linked Accident Report Documents]									Load JPG		☒	
7	29/04/19 13:34	Accident Photo [Linked Accident Report Documents]									Load JPG		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	08/05/19 10:30	General View									Load JPG		☒	
2	08/05/19 10:30	General View									Load JPG		☒	
3	08/05/19 10:30	General View									Load JPG		☒	
4	08/05/19 10:30	General View									Load JPG		☒	
5	08/05/19 10:30	General View									Load JPG		☒	
6	08/05/19 10:30	General View									Load JPG		☒	
7	08/05/19 10:30	General View									Load JPG		☒	
8	08/05/19 10:30	General View									Load JPG		☒	
9	08/05/19 10:30	General View									Load JPG		☒	
10	08/05/19 10:30	General View									Load JPG		☒	
11	08/05/19 10:30	General View									Load JPG		☒	
12	08/05/19 10:30	General View									Load JPG		☒	
13	08/05/19 10:30	General View									Load JPG		☒	
14	08/05/19 10:30	General View									Load JPG		☒	
15	08/05/19 10:30	General View									Load JPG		☒	
16	08/05/19 10:30	General View									Load JPG		☒	
17	08/05/19 10:30	General View									Load JPG		☒	
18	08/05/19 10:30	General View									Load JPG		☒	
19	08/05/19 10:30	General View									Load JPG		☒	
20	08/05/19 10:30	General View									Load JPG		☒	
21	08/05/19 10:30	General View									Load JPG		☒	
22	08/05/19 10:30	General View									Load JPG		☒	
23	08/05/19 10:30	General View									Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
24	08/05/19 10:30	General View		☒
25	08/05/19 10:30	General View		☒
26	08/05/19 10:30	General View		☒
27	08/05/19 10:30	General View		☒
28	08/05/19 10:30	General View		☒
29	08/05/19 10:30	General View		☒
30	08/05/19 10:30	General View		☒
31	08/05/19 10:30	General View		☒
32	08/05/19 10:30	General View		☒
33	08/05/19 10:30	General View		☒
34	08/05/19 10:30	General View		☒
35	08/05/19 10:30	General View		☒
36	08/05/19 10:30	General View		☒
37	08/05/19 10:30	General View		☒
38	08/05/19 10:30	General View		☒
39	08/05/19 10:30	General View		☒
40	08/05/19 10:30	General View		☒
41	08/05/19 10:30	General View		☒
42	08/05/19 10:30	General View		☒
43	08/05/19 10:30	General View		☒
44	08/05/19 10:30	General View		☒
45	08/05/19 10:30	General View		☒
46	08/05/19 10:30	General View		☒
47	08/05/19 10:30	General View		☒
48	08/05/19 10:30	Odometer Reading		☒
49	08/05/19 10:30	Chassis Number		☒
50	13/05/19 11:01	Photo After Spray		☒
51	13/05/19 11:01	Photo After Spray		☒
52	13/05/19 11:01	Photo After Spray		☒
53	13/05/19 11:01	Photo After Spray		☒
54	13/05/19 11:01	Photo After Spray		☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/05/19 11:25	PRS		☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/04/19 13:37	Sketch Plan [Linked Accident Report Documents]		☒
2	29/04/19 13:37	Sketch Plan #2 [Linked Accident Report Documents]		☒
3	29/04/19 13:37	Sketch Plan #3 [Linked Accident Report Documents]		☒
4	29/04/19 13:37	Sketch Plan #4 [Linked Accident Report Documents]		☒

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/04/19 13:44	Accident Statement		☒
Photos/Images			3 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print

Assessment Reports				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	29/04/19 13:34	Accident Photo		Load JPG	☒
2	29/04/19 13:34	Accident Photo		Load JPG	☒
3	29/04/19 13:34	Accident Photo		Load JPG	☒
4	29/04/19 13:34	Accident Photo		Load JPG	☒
5	29/04/19 13:34	Accident Photo		Load JPG	☒
6	29/04/19 13:34	Accident Photo		Load JPG	☒
7	29/04/19 13:34	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	29/04/19 13:37	Sketch Plan		Load TIF	
2	29/04/19 13:37	Sketch Plan #2		Load TIF	
3	29/04/19 13:37	Sketch Plan #3		Load TIF	
4	29/04/19 13:37	Sketch Plan #4		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119007883/GQD3Q2

Date: 17/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3044671804

Claimant Vehicle
No: GBA9762XInsured Vehicle
No: GBB2362H

Date of Loss: 26/04/2019

Nature of Claim: TP

Claim
No: SNM19D201892C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBA9762X

Make & Model: OPEL COMBO, 1.6 (M)

Engine No: Z17DTH01673657

Reg. Date: 07/05/2008 (Man. Year: 2007)

Chassis No: W0L0XCF2584003730

Colour: White

Odometer: 302898 km

Engine Capacity: 1686 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,176.40	3,944.40	1,232.00	23.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,190.00	690.00	36.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,056.40	5,134.40	1,922.00	27.24
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	7,056.40	3,800.00	3,256.40	46.15

INSPECTION

Date of Assignment: 06/05/2019

Date Inspected: 06/05/2019 Inspected At:

Tan Hup Seng Auto Repair Workshop
(HQ)
BLK 19 SIN MING INDUSTRIAL ESTATE,
#01-09
Singapore 575677

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2019)
Parts:	144	OPEL COMBO 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA9762X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	760.00 FL	*760.00 FL
2	1		*REAR BUMPER ENFORCEMENT	Bent	380.00 FL	*380.00 FL
3	4		*REAR BUMPER SIDE CLIP	Necessary	28.00 FL	*28.00 FL
4	1		*REAR BOOT DOOR (RH)	Bent	1,650.00 FL	*1,360.00 FL
5	1		*REAR BOOT DOOR (LH)	Bent	1,650.00 FL	*1,360.00 FL
6	1		*REAR BOOT DOOR PROTECTOR (RH)	Scratched	220.00 FL	*125.00 FL
7	1		*REAR BOOT DOOR PROTECTOR (LH)	Scratched	160.00 FL	*125.00 FL
8	1		*REAR OPEL ELBEM	Necessary	65.00 FL	*65.00 FL
9	1		*COMBO 17CDTI ELBEM	Necessary	85.00 FL	*85.00 FL
10	1		*REAR BOOT WEATHER SEAL (RH)	Twisted	120.00 FL	*120.00 FL
11	1		*REAR BOOT WEATHER SEAL (LH)	Twisted	120.00 FL	*120.00 FL
12	1		*REAR END PANEL	Repair	480.00 FL	*- FL
13	1		*REAR BOOT LOCKING DERVICE	Bent	280.00 FL	*140.00 FL
14	1		*REAR SUPPORT PANEL LOCK CATCH	Repair	110.00 FL	*- FL
15	1		*PAX STICKER	Necessary	5.00 FS	*5.00 FS
16	1		*70KM/H STICKER	Necessary	5.00 FS	*5.00 FS
17	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,398.00	4,878.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,221.60	933.60
Total Parts (\$\$)	5,176.40	3,944.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REPLACE OF REAR BOOT PANEL,REAR END PANEL,REAR BOOT DOOR & BUMPER	New	850.00	500.00
2	RESPRAY PAINTWORKS	New	650.00	500.00
3	WIRING OF LIGHTING & DOOR CONTROL	New	100.00	30.00
4	DISMANTLE OF REAR BOOT DOOR GLASS CHARGES	New	280.00	160.00
Gross Labour Cost (\$\$)			1,880.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >