

ASS. REC. BY:

REF:

CS/ASM19007892/Kqd312

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Jas Tan

of

ASM (AAA)

Date/Time:

6/5/19

Estimated Cost:

Bill to:

OD

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

8KE 8806H

Insured:

at Workshop m/s:

K Kim Hin

Tel:

64527018

of

160 Sin Ming Drive #02-20

Policy No.:

Claim No.:

S9M01MSV

Sum Insured:

Excess:

\$300.00

Make of Vehi:

(Client's Record)

D.O.A

1/5/19

CA

REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1145am 6/5/19

Person Contacted:

Sundren

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

07/5/19 @

8KE8806H - X

11.45am revert to Jas Tan via Smart Claim.

07/5/19

revert to Jas Tan via Smart Claim. Repairer asking P/P basis due to no 2nd hand parts available.)

08/5/19 @

7.36pm Jas Tan informed C/A via Smart Claim.

08/5/19 @

3.45pm informed Simon C/A on P/P basis, ex: \$300 by email.

ASS. REC. BY:

REF: 121 / C / ASM190078921 kgd 3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s 10111111

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 3000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: \$35K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKE 88064 Yr Regn: 04, 12Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Privia 1497 c.c.Colour: M-Blue A/C: Insured / Std / NI / NASp. Reading: 49091 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKD 3B 33 01503604Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / RIM orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 2 mmL/Bal. 2 mmD.O.A. 1/5/19

Rear

R/Bal. 2 mmL/Bal. 2 mmD.O.A. 6/5/19

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to

20/05/19 @ 4.54pm confirmed with Meng Huet final fig \$923.89, 5 days.
(Red \$1439.80, 20%)

RECEIVED 17 OCT 2019

Date/Time, File Pass to?

1) 12/10 11:10

Date/Time, File Return to?

☐ : Prell. Report☐ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:
\$ - RS - St

Fees

Others

TOTAL

900

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

Smart Claim\$923.89

◀ Service Request Details

Claim

S9M01M5V

Reference

None 

Loss Date

May 1, 2019

Report Date

May 2, 2019 1:57:01 PM

Request Date

May 6, 2019

Due Date

May 13, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKE8806H

PRODUCT

PRIUS 1.5

Service Address

160 Sin Ming Drive, #, , , 575722

Primary Contact/Insured

OW YEONG SUET YEE

05-01, 26 Duchess Road, 269029, Singapore

suetjee_owyeong@yahoo.com.sg

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

K KIM HIN OD XS \$300

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Shiau Chan (LKKAUTO)

From: survey@kkimhin.com.sg
Sent: Tuesday, 20 August 2019 4:54 PM
To: Shiau Chan (LKKAUTO)
Cc: survey2@kkimhin.com.sg; 'Sandra (Gmail)'; simon@kkimhin.com.sg; service@kkimhin.com.sg
Subject: RE: SKE8806H AXA OD CLAIM

Hi Shiau Chan,

Confirm you figure P/P=\$5,923.89
Thank you.

Regard
Meng Huat
K.Kim Hin Auto

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 20 August 2019 4:36 PM
To: survey@kkimhin.com.sg
Cc: survey2@kkimhin.com.sg; Sandra (Gmail) <sandrakhong@gmail.com>; simon@kkimhin.com.sg; service@kkimhin.com.sg
Subject: RE: SKE8806H AXA OD CLAIM

Dear Meng Huat,

WITHOUT PREJUDICE

Offer final fig \$5,923.89 before excess \$300.00 & GST and 5 repair days.

Kindly check and confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 17 June 2019 11:58 AM
To: survey@kkimhin.com.sg
Cc: survey2@kkimhin.com.sg; Sandra (Gmail) <sandrakhong@gmail.com>; simon@kkimhin.com.sg; service@kkimhin.com.sg
Subject: RE: SKE8806H AXA OD CLAIM

Dear Meng Huat,

Kindly assist to check the status of vehicle.

If done of repair, kindly send us the final bill for finalise.

Best Regards,

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 8 May 2019 3:45 PM
To: Simon
Cc: KKH; Survey KKH
Subject: RE: SKE8806H AXA OD CLAIM

Dear Simon,

As instructed by our client, please proceed to repair the insured vehicle **SKE 8806H on part by part basis (Excess \$300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon <simon@kkimhin.com.sg>
Sent: Wednesday, 8 May 2019 12:16 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: KKH <service@kkimhin.com.sg>; Survey KKH <survey@kkimhin.com.sg>
Subject: Re: SKE8806H AXA OD CLAIM

Hi Siao Chan,

Noted.

Awaiting for your further instruction.

Regards

Simon

64527018

K. Kim Hin Auto Pte Ltd

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, May 08, 2019 11:27 AM
To: Simon
Cc: KKH ; Survey KKH
Subject: RE: SKE8806H AXA OD CLAIM

Dear Simon,

As spoken with you.



Re:RE: Re:LATEST IA OF VEHICLE SKE 8806H UPLOADED

Type

🔗 Question

Message

thanks, please proceed on part by part.

Reply

<< RE: Re:LATEST IA OF VEHICLE SKE 8806H UPLOADED

Type

🔗 Question

Message

Dear Jas, according to our surveyor, the model vehicle popular in local market and not many scrap early,
Hence no used or recon parts. - Shiau Chan

Reply

<< Re:LATEST IA OF VEHICLE SKE 8806H UPLOADED

Type

🔗 Question

Message

Hi, please get your surveyor to check used parts availability from stockist. thanks.

[Reply](#)

This model vehicle popular in local market and
not many ~~let~~ scrap early. Hence no used or recon parts.



Auto
Consultants
Pte Ltd

51 UBI AVE L, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

7/5/2019

Survey Details:

Date of loss	1-May-19
Date of appointment	6-May-19
Date of survey	6-May-19
Location of survey	K KIM HIN AUTO PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKE 8806H
Make and Model	TOYOTA PRIUS C CVT
Date of registration	12/4/2012
Excess	\$ 300.00
Market Value	\$ 35,000.00
Parf Rebate	\$ 25,461.00
Nett Loss	\$ 9,539.00

Repair details:

Initial Estimate	\$ 7,268.23
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,170.30
Check items (estimate)	\$ 2,699.40
Labour	\$ 1,110.53
Total	\$ 5,980.23
Lump Sum(if applicable)	-

Number of days for repair	<u>5</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563501 FAX : (065) 62564318

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.
REPAIRER ASKING REPAIR ON PART BY PART BASIS AS NO
SECOND HAND PARTS AVAILABLE. WE HAVE NOT
AUTHORISE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563361 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

7/5/2019

Survey Details:

Date of loss	1-May-19
Date of appointment	6-May-19
Date of survey	6-May-19
Location of survey	K KIM HIN AUTO PTE LTD

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKE 8806H
Make and Model	TOYOTA PRIUS C CVT
Date of registration	12/4/2012
Excess	\$ 300.00
Market Value	\$ 35,000.00
Parf Rebate	\$ 25,461.00
Nett Loss	\$ 9,539.00

Repair details:

Initial Estimate	\$ 7,268.23
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,170.30
Check items (estimate)	\$ 2,699.40
Labour	\$ 1,110.53
Total	\$ 5,980.23
Lump Sum(if applicable)	-

Number of days for repair	<u>5</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE
HAVE AUTHORISE REPAIR.

Mandate:

Liability(TP)		%
Proposed repair cost		\$
Loss of use		\$ no. of days
Loss of rental		\$ no. of days
Loss of income		\$ no. of days
LTA search fees		\$
Others		\$
Proposed Total		#VALUE!

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6516B
Vehicle Details	
Vehicle No.:	SKE8806H
Vehicle to be Exported:	No
Intended Deregistration Date:	02 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS C CVT
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	1NZ6159413
Chassis No.:	JTDKD3B3301503604
Maximum Power Output:	54.0 kW (72 bhp)
Open Market Value:	\$22,923.00
Original Registration Date:	12 Apr 2012
First Registration Date:	12 Apr 2012
Transfer Count:	0
Actual ARF Paid:	\$13,754.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Apr 2022
PARF Rebate Amount:	\$8,252.00
Intended COE Rebate Details	
COE Expiry Date:	11 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$58,501.00
COE Rebate Amount:	\$17,209.00
Total Rebate Amount:	\$25,461.00

The information contained herein is correct as at 02 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2019 15:33
Date Of Accident	01/05/2019 09:00
Exact Location Of Accident	ALONG BLK 30 BENDEMEER ROAD CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE8806H
Insured/Policyholder	
Name Of Registered Owner	OW YEONG SUET YEE
NRIC No	S7106516B
Email Address	SUETYEE_OWYEONG@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96726828
Alternative Phone No	OFFICE-96726828

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS C CVT-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA023976
Cover Note Number	

Driver

Name of Driver	OW YEONG CHEE HOY
NRIC No	S0616979A
Date Of Birth	19/08/1937
Occupation	INDOOR
Date Of Driving Pass	07/03/1958
Driving Experience	61 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96179266
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	12 WOODLEIGH CLOSE #02-09
Postcode	357907
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIOW LEE CHOO
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB1574
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/FIN No



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- ⊗ Around 9am in the morning of 1st May 2019, I entered the carpark along Bendemeer Road next to BIK 30. I tried to reverse park my car into lot 59A. I was not accurate the 1st attempt so I tried to move forward and do it again. But somehow my car surged forward and hit a stationary white car (SKB 1574) at its back. This car (SKB 1574) was parked next to lot 175. The owner of SKB 1574 (a couple) was then approaching and about to reach their car. The couple took down the details of my driving licence and phone number.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name

NRIC/FIN No

(IN) 0D AXA

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
Assessment number: 004154
Version: 1810
Date calculated: 03/05/2019 12:20 PM

Full Report
Registration: SKE8806H
Printed: 03/05/2019 12:20 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	SANDRA KHONG	Currency:	SGD
Claim Reference:		Date of Incident:	01/05/19
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS C
Sub Model:	BASE MODEL
Model Sheet Number:	70 4P 01
Registration:	SKE8806H
VIN number:	JTDKD3B3301503604
Odometer:	

Model Specs

AUTO AIR CON	FOG LAMPS	1.5 LTR 74KW	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA			

 Authorised
1-B.1
Repair by pain
Ex \$300/-
Tel: 62564315
Workshop unable to repair as 11 days,
no 2nd parts available.

K. Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
Assessment number: 004154
Version: 1810
Date calculated: 03/05/2019 12:20 PM

Full Report
Registration: SKE8806H
Printed: 03/05/2019 12:20 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		16.0	72.00
B020)	RENEW FRONT BUMPER REINFORCEMENT		3.0	13.50
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.50
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.50
B040)	ADJUST HEADLAMPS		2.0	9.00
B100	R + R L/F WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WHEELHOUSE COVER AND A-PILLAR TRIM		5.0	22.50
B100	R + R R/F WING		5.0	22.50

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 004154

Version: 1810

Date calculated: 03/05/2019 12:20 PM

Full Report

Registration: SKE8806H

Printed: 03/05/2019 12:20 PM

Code	Description	WU	Price SGD
	(BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WHEELHOUSE COVER AND A-PILLAR TRIM		
NO NUMBER	RENEW L/F WING BADGE	1.0	4.50
NO NUMBER	RENEW R/F WING BADGE	1.0	4.50
B140	RENEW FRONT PANEL CPL	14.0	63.00
NO NUMBER	RENEW L/F SIDEMEMBER REINFORCEMENT	10.0	45.00
NO NUMBER	RENEW R/F SIDEMEMBER REINFORCEMENT	10.0	45.00
B060	RENEW BONNET INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AND IF NEC RENEW	3.0	13.50
B080	R + R BONNET HINGE/S	1.0	4.50
M010	R + R CONDENSER	9.0	40.50
M010)	RENEW CONDENSER	1.0	4.50
002889	REFILL AIR CONDITIONING	7.0	31.50
M020	R + R RADIATOR INCLUDES: BLEED COOLING SYSTEM	6.0	27.00
M020)	RENEW RADIATOR (REMOVED)	4.0	18.00
NO NUMBER	R + R LEFT FRONT WHEEL		
NO NUMBER	R + R RIGHT FRONT WHEEL		
4479	COMPR/CONDENSER TUBE CHECK	5.0*	7 22.50
4482	CONDENSER TUBE CHECK	5.0*	7 22.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		11.00	110.0
Total of Labour			495.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	BONNET NEW PART PAINTING	14.0
	L/F WING NEW PART PAINTING	10.0
	R/F WING NEW PART PAINTING	10.0
	L/F SUPPORT BRACKET SURFACE PAINT	4.0
	R/F SUPPORT BRACKET SURFACE PAINT	4.0
	FRONT PANEL CPL SURFACE PAINT	6.0
	FRONT BUMPER NEW PART PAINT K1R	13.0
	LID COVER NEW PART PAINT K1R	3.0

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 004154

Version: 1810

Date calculated: 03/05/2019 12:20 PM

Full Report

Registration: SKE8806H

Printed: 03/05/2019 12:20 PM

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	37.15
0741	L/F WING NEW PART PAINTING	18.06
0742	R/F WING NEW PART PAINTING	18.06
1005	L/F SUPPORT BRACKET SURFACE PAINT	2.99
1006	R/F SUPPORT BRACKET SURFACE PAINT	2.99
1009	FRONT PANEL CPL SURFACE PAINT	13.20
0281	FRONT BUMPER NEW PART PAINT K1R	61.50
0357	LID COVER NEW PART PAINT K1R	0.98

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		64.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
Total	10 WU/h	94.0	423.00

Material Cost - Paint

	Price SGD
New Part Painting	73.27
New Part Painting - Plastic K1R	62.48
Surface-/Blend Paint	19.18
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	192.53

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0253	FRONT LWR AIR GRILLE	53112 52370		CM	85.00 ✓
0255	L/F LOWER BUMPER LID	81482 52380		SL	60.00 X
0256	R/F LOWER BUMPER LID	81481 52450		SL	60.00 X
0258	FRT NO PLATE REINF	KNPL0		CM	55.00 ✓
0281	FRONT BUMPER	52119 52978		Bu	265.00 ✓
0317	L/F BUMPER BRACKET	52536 52110		Ry	38.00 7✓
0318	R/F BUMPER BRACKET	52535 52150		Ry	38.00 7✓
0333	FRT BUMPER ABSORBER	52611 52150		CM	50.00 7✓
0340	FRT BUMPER REINF	52131 52250		Ry	140.00 7✓
0353	LOWER COVER	52618 52050		SL	85.00 X
0357	LID COVER	52127 52941		mir	18.00 ✓

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 004154

Version: 1810

Date calculated: 03/05/2019 12:20 PM

Full Report

Registration: SKE8806H

Printed: 03/05/2019 12:20 PM

Code	Description	Part Number	Supplier	Price SGD	
0410	GRILLE	53111 52570		CM 120.00	✓
0431	MANUFACTURER BADGE	75310 52010		na 45.00	✓
0471	BONNET	53301 52370		B 240.00	✓
0475	L/BONNET HINGE	53420 52360		111 R 40.00	X
0476	R/BONNET HINGE	53410 52350		017 R 40.00	X
0493	BONNET LOCK	53510 52790		011 58.00	✓
0561	LEFT HEADLAMP ASSY	81150 52E61		my cm 400.00	✓
0562	RIGHT HEADLAMP ASSY	81110 52E61		my cm 400.00	X
0639	L/F FOG LAMP	81221 12230		pu 115.00	X
0640	R/F FOG LAMP	81211 12230		pu 115.00	X
0641	L/F INDICATOR	81521 52030		pu 70.00	X
0642	R/F INDICATOR	81511 52030		pu 70.00	X
0745	L/F WING BADGE	75374 52020		na 35.00	✓
0746	R/F WING BADGE	75374 52010		na 35.00	X
1005	L/F SUPPORT BRACKET	53203 52220		B 95.00	✓
1006	R/F SUPPORT BRACKET	53202 52230		B 95.00	✓
1009	FRONT PANEL CPL	53210 52917		Bu 330.00	✓
1012	R/UPP WIND DEFLECTOR	53285 52410		pu 0.00	X
1018	FRONT PANEL STRUT	53208 52901		B 85.00	✓
1021	UPPER RADIATOR COVER	53289 52080		011/1u 100.00	✓
1227	L/F REINFORCEMENT	57014 52030		R 70.00	7X
1228	R/F REINFORCEMENT	57013 52040		R 70.00	7X
1318	FRT BUMPER BRACKET	52521 52040		Bu 60.00	✓
1319	FRT BUMPER SEAL	53395 52050		na 35.00	✓
4465	CONDENSER	88460 52170		pu 520.00	✓
7761	RADIATOR	16400 21330		pu 580.00	✓
7767	RADIATOR SHROUD	16711 21150		pu 120.00	7X
7790	FAN MOTOR	16363 21060		pu 185.00	7X
7793	BLOWER	16361 21120		pu 95.00	7X
9646	HORN	86520 68010		pu 48.00	7X
1003	FRT CLIPS@1.50	FRT CLIPS		na 18.00	✓
1004	RAD TOP CLIP@1.50	RAD TOP CLIPS		na 9.00	✓
1005	HOOD INS CLIP@2.00	INS CLIP		na 10.00	X
1006	RAD TOP COVER	RAD TOP COVER		cm 55.00	✓
1007	RAD AIR GUIDE L TOP	RAD AIR GUIDE L		cm 35.00	✓
1008	RAD AIR GUIDE R TOP	RAD AIRGUIDE R		cm 35.00	✓
1009	RAD AIR GUIDE L LWR	RAD AIRGUIDE L		011 35.00	✓
1010	RAD AIR GUIDE R LWR	RAD AIRGUIDE R		011 35.00	✓
1011	RAD LWR COVER	RAD LWR CVR		pu 30.00	7X

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal

0.00
5,427.00

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
 Assessment number: 004154
 Version: 1810
 Date calculated: 03/05/2019 12:20 PM

Full Report
 Registration: SKE8806H
 Printed: 03/05/2019 12:20 PM

Addition(+10.00%)	542.70
Total	5,969.70

Extras

Code	Description	Price SGD
1000	RADIATOR COOLANT	48.00* <i>201A</i>
1001	AIR CON GAS	100.00* <i>50%</i>
1002	FRT NUMBER PLATE	40.00*
	Total Extras	188.00

Final Calculation

	SGD	SGD
Parts	5,427.00	
Addition(+10.00%)	542.70	
Total Parts		5,969.70
Labour Time Base 10 WU/h		
Total 110.0 WU X 45.00 SGD/h	495.00	
Total of Labour		495.00
Total Of Extras		188.00
Paint Work Time Base 10 WU/h		
Labour Cost 94.0 WU X 45.00 SGD/h	423.00	
Material Cost	192.53	
Total Paint Including Material		615.53
Repair Cost Excludes GST		7,268.23
GST (+7.0%)		508.78
Repair Cost Included GST		7,777.01

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 004154

Version: 1810

Date calculated: 03/05/2019 12:20 PM

Full Report

Registration: SKE8806H

Printed: 03/05/2019 12:20 PM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
Assessment number: 190220
Version: 1810
Date calculated: 16/08/2019 3:15 PM

Full Report
Registration: SKE8806H
Printed: 16/08/2019 5:05 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	SANDRA KHONG	Currency:	SGD
Claim Reference:		Date of Incident:	01/05/19
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS C
Sub Model:	BASE MODEL
Model Sheet Number:	70 4P 01
Registration:	SKE8806H
VIN number:	JTDKD3B3301503604
Odometer:	

Model Specs

AUTO AIR CON	FOG LAMPS	1.5 LTR 74KW	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA			

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
 Assessment number: 190220
 Version: 1810
 Date calculated: 16/08/2019 3:15 PM

Full Report
 Registration: SKE8806H
 Printed: 16/08/2019 5:05 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		16.0	72.00
B020)	RENEW FRONT BUMPER REINFORCEMENT		3.0	13.50
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.50
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.50
B040)	ADJUST HEADLAMPS		2.0	9.00
B100	R + R L/F WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WHEELHOUSE COVER AND A-PILLAR TRIM		5.0	22.50
B100	R + R R/F WING		5.0	22.50

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
 Assessment number: 190220
 Version: 1810
 Date calculated: 16/08/2019 3:15 PM

Full Report
 Registration: SKE8806H
 Printed: 16/08/2019 5:05 PM

Code	Description	WU	Price SGD
	(BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WHEELHOUSE COVER AND A-PILLAR TRIM		
NO NUMBER	RENEW L/F WING BADGE	1.0	4.50
B140	RENEW FRONT PANEL CPL	14.0	63.00
B060	RENEW BONNET	3.0	13.50
	INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AND IF NEC RENEW		
B080	R + R BONNET HINGE/S	1.0	4.50
M010	R + R CONDENSER	9.0	40.50
M010)	RENEW CONDENSER	1.0	4.50
002889	REFILL AIR CONDITIONING	7.0	31.50
M020	R + R RADIATOR	6.0	27.00
	INCLUDES: BLEED COOLING SYSTEM		
M020)	RENEW RADIATOR (REMOVED)	4.0	18.00
NO NUMBER	R + R LEFT FRONT WHEEL		
NO NUMBER	R + R RIGHT FRONT WHEEL		
1207	L/F SIDE MEMBER REPAIR	20 30.0*	135.00 un
1208	R/F SIDE MEMBER REPAIR	20 30.0*	135.00 un
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	13.90	139.0
	Total of Labour		625.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	BONNET NEW PART PAINTING	14.0
	L/F WING NEW PART PAINTING	10.0
	R/F WING NEW PART PAINTING	10.0
	L/F SUPPORT BRACKET SURFACE PAINT	4.0
	R/F SUPPORT BRACKET SURFACE PAINT	4.0
	FRONT PANEL CPL SURFACE PAINT	6.0
	FRONT BUMPER NEW PART PAINT K1R	13.0
	LID COVER NEW PART PAINT K1R	3.0
	L/F SIDE MEMBER SURFACE PAINT	5.0
	R/F SIDE MEMBER SURFACE PAINT	5.0

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
 Assessment number: 190220
 Version: 1810
 Date calculated: 16/08/2019 3:15 PM

Full Report
 Registration: SKE8806H
 Printed: 16/08/2019 5:05 PM

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	37.15
0741	L/F WING NEW PART PAINTING	18.06
0742	R/F WING NEW PART PAINTING	18.06
1005	L/F SUPPORT BRACKET SURFACE PAINT	2.99
1006	R/F SUPPORT BRACKET SURFACE PAINT	2.99
1009	FRONT PANEL CPL SURFACE PAINT	13.20
0281	FRONT BUMPER NEW PART PAINT K1R	61.50
0357	LID COVER NEW PART PAINT K1R	0.98
1207	L/F SIDE MEMBER SURFACE PAINT	4.98
1208	R/F SIDE MEMBER SURFACE PAINT	4.98

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		74.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
Total	10 WU/h	104.0	468.00

Material Cost - Paint

	Price SGD
New Part Painting	73.27
New Part Painting - Plastic K1R	62.48
Surface-/Blend Paint	29.14
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	202.49

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0253	FRONT LWR AIR GRILLE	53112 52370			85.00
0258	FRT NO PLATE REINF	KNPL0			55.00
0281	FRONT BUMPER	52119 52978			265.00
0317	L/F BUMPER BRACKET	52536 52110			38.00
0318	R/F BUMPER BRACKET	52535 52150			38.00
0333	FRT BUMPER ABSORBER	52611 52150			50.00
0340	FRT BUMPER REINF	52131 52250			140.00
0357	LID COVER	52127 52941			18.00
0410	GRILLE	53111 52570			120.00

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:

Assessment number: 190220

Version: 1810

Date calculated: 16/08/2019 3:15 PM

Full Report

Registration: SKE8806H

Printed: 16/08/2019 5:05 PM

Code	Description	Part Number	Supplier	Price SGD
0431	MANUFACTURER BADGE	75310 52010		45.00
0471	BONNET	53301 52370		240.00
0475	L/BONNET HINGE	53420 52360		40.00
0476	R/BONNET HINGE	53410 52350		40.00
0493	BONNET LOCK	53510 52790		58.00
0561	LEFT HEADLAMP ASSY	81150 52E61		400.00
0562	RIGHT HEADLAMP ASSY	81110 52E61		400.00
0745	L/F WING BADGE	75374 52020		35.00
1005	L/F SUPPORT BRACKET	53203 52220		95.00
1006	R/F SUPPORT BRACKET	53202 52230		95.00
1009	FRONT PANEL CPL	53210 52917		330.00
1012	R/UPP WIND DEFLECTOR	53285 52410		0.00
1018	FRONT PANEL STRUT	53208 52901		85.00
1021	UPPER RADIATOR COVER	53289 52080		100.00
1318	FRT BUMPER BRACKET	52521 52040		60.00
1319	FRT BUMPER SEAL	53395 52050		35.00
4465	CONDENSER	88460 52170		520.00
7761	RADIATOR	16400 21330		580.00
1003	FRT CLIPS@1.50	FRT CLIPS		18.00
1004	RAD TOP CLIP@1.50	RAD TOP CLIPS		9.00
1006	RAD TOP COVER	RAD TOP COVER		55.00
1007	RAD AIR GUIDE L TOP	RAD AIR GUIDE L		35.00
1008	RAD AIR GUIDE R TOP	RAD AIRGUIDE R		35.00
1009	RAD AIR GUIDE L LWR	RAD AIRGUIDE L		35.00
1010	RAD AIR GUIDE R LWR	RAD AIRGUIDE R		35.00

f: OEM Parts

n: Non-OEM Parts

u: Used parts

Savings

Subtotal

Addition(+10.00%)

Total

0.00

4,189.00

418.90

4,607.90

Extras

Code	Description	Price SGD
1000	RADIATOR COOLANT	20.00*
1001	AIR CON GAS	50.00*
1002	FRT NUMBER PLATE	40.00*
Total Extras		110.00

K.Kim Hin Auto Pte Ltd
160 Sin Ming Drive, #02-20, Sin
Ming AutoCity
575722

Claim Reference:
Assessment number: 190220
Version: 1810
Date calculated: 16/08/2019 3:15 PM

Full Report
Registration: SKE8806H
Printed: 16/08/2019 5:05 PM

Final Calculation

	SGD	SGD
Parts	4,189.00	
Addition(+10.00%)	418.90	
Total Parts		4,607.90
Labour Time Base 10 WU/h		
Total 139.0 WU X 45.00 SGD/h	625.50	
Total of Labour		625.50
Total Of Extras		110.00
Paint Work Time Base 10 WU/h		
Labour Cost 104.0 WU X 45.00 SGD/h	468.00	
Material Cost	202.49	
Total Paint Including Material		670.49
Repair Cost Excludes GST		6,013.89
GST (+7.0%)		420.97
Repair Cost Included GST		6,434.86

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

NOS: K.KIM HIN AUTO PTE LTD

160 SIN MING DRIVE

#02-18/19/20/21 SIN MING AUTOCITY

SINGAPORE 575722

SKE8806H

SIMON

NO: DL19217401

PAGE: 1

DATE: 09/05/2019

A/C CODE: LDKK241

TERMS: CR

VEH NO: SKE8806H

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1	T52114-52040 ✓	FR BUMPER EXT MTGIN	1	55.00	55.00
2	T52119-52978	BUMPER FR	1	265.00	265.00
3	T52127-52941 ✓	FR BUMPER TOW HOOK CVR	1	18.00	18.00
4	T53112-52370 ✓	FR BUMPER LWR GRILLE	1	85.00	85.00
5	T75310-52010	FR GRILLE LOGO	1	45.00	45.00
6	T53395-52050 ✓	FR BONNET SEAL	1	35.00	35.00
7	T53111-52570	GRILLE	1	120.00	120.00
8	T52131-52250	BUMPER REINF FR	1	140.00	140.00
9	T52611-52150	FR BUMPER SPONGE	1	50.00	50.00
10	T52161-16010-1	CLIP,FR BUMPER	12	1.50	18.00
11	T52535-52150 ✓	FR BUMPER RETAINER RH	1	38.00	38.00
12	T52536-52110 ✓	RETAINER FR LH	1	38.00	38.00
13	T52521-52040	FR BUMPER RETAINER TOP	1	60.00	60.00
14	T53210-52913	SUPPORT PANEL	1	330.00	330.00
15	T53208-52901 ✓	BRACE PANEL	1	85.00	85.00
16	T53289-52080	RAD SUPPORT CVR	1	100.00	100.00
17	T90467-07214	CLIP,SUPPORT TOP GARNISH	6	1.50	9.00
18	T53202-52230 ✓	H/LAMP PANEL RH	1	95.00	95.00
19	T53203-52220	H/LAMP PANEL LH	1	95.00	95.00
20	T81110-52E60	H/LAMP ASSY RH	1	400.00	400.00
21	T81150-52E60	H/LAMP ASSY LH	1	400.00	400.00
22	T53301-52330	BONNET	1	240.00	240.00

Print / MJT / 09/05/2019 9:47:31 AM

...Cont'd





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4290

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923R

M/S: K. KIM HEN AUTO PTE LTD

TAX INVOICE

PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount
23	T53510-52630 ✓	BONNET LOCK -52790	DUIB84	1	58.00
24	T53410-52150 ✓	BONNET HINGE RH	DUIAD19-2	1	40.00
25	T53420-52360 ✓	BONNET HINGE	DUIAD20-3	1	40.00
26	T88460-52170 ✓	CONDENSER	DB2H	1	520.00
27	T16400-21330 ✓	RADIATOR	DB1A13	1	580.00
28	T16712-21020 ✓	SHROUD FAN NO1	DDS	1	55.00
29	T53285-52410 ✓	RADIATOR SEAL NO1	DUIAB27-4	1	35.00
30	T53286-52330 ✓	RADIATOR SEAL NO2	DUIAB27-7	1	35.00
31	T53287-52170 ✓	RAD SUPPORT EXT RH	DUIAB27-7	1	35.00
32	T53288-52170 ✓	RAD SUPPORT EXT LH	DUIAB27-7	1	35.00
33	T75374-52020	FENDER LOGO HYBRID	DSHOP	1	35.00

TOTAL QUANTITY:

49 TOTAL

SIN 4,189.00

ADD GST @ 7% 293.23

GRAND TOTAL SIN 4,482.23

#02-21

Print / MT / 09/05/2019 9:47:32 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: 190220
Version: 1810
Date calculated: 20/08/2019 4:34 PM

Full Report
Registration: SKE8806H
Printed: 20/08/2019 4:34 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	01/05/19
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS C
Sub Model:	BASE MODEL
Model Sheet Number:	70 4P 01
Registration:	SKE8806H
VIN number:	JTDKD3B3301503604
Odometer:	

Model Specs

AUTO AIR CON	FOG LAMPS	1.5 LTR 74KW	PREPARE OFF VEHICLE
TWO COAT PEARL/MICA			

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 190220
 Version: 1810
 Date calculated: 20/08/2019 4:34 PM

Full Report
 Registration: SKE8806H
 Printed: 20/08/2019 4:34 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		16.0	72.00
B020)	RENEW FRONT BUMPER REINFORCEMENT		3.0	13.50
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.50
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	4.50
B040)	ADJUST HEADLAMPS		2.0	9.00
B100	R + R L/F WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WHEELHOUSE COVER AND A-PILLAR TRIM		5.0	22.50
B100	R + R R/F WING		5.0	22.50

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: 190220

Version: 1810

Date calculated: 20/08/2019 4:34 PM

Full Report

Registration: SKE8806H

Printed: 20/08/2019 4:34 PM

Code	Description	WU	Price SGD
	(BUMPER AND HEADLAMP REMOVED)		
	INCLUDES: R + R WHEELHOUSE COVER AND A-PILLAR TRIM		
NO NUMBER	RENEW L/F WING BADGE	1.0	4.50
B140	RENEW FRONT PANEL CPL	14.0	63.00
B060	RENEW BONNET	3.0	13.50
	INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AND IF NEC RENEW		
B080	R + R BONNET HINGE/S	1.0	4.50
M010	R + R CONDENSER	9.0	40.50
M010)	RENEW CONDENSER	1.0	4.50
002889	REFILL AIR CONDITIONING	7.0	31.50
M020	R + R RADIATOR	6.0	27.00
	INCLUDES: BLEED COOLING SYSTEM		
M020)	RENEW RADIATOR (REMOVED)	4.0	18.00
NO NUMBER	R + R LEFT FRONT WHEEL		
NO NUMBER	R + R RIGHT FRONT WHEEL		
1207	L/F SIDE MEMBER REPAIR	20.0*	90.00
1208	R/F SIDE MEMBER REPAIR	20.0*	90.00
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	11.90	119.0
	Total of Labour		535.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	BONNET NEW PART PAINTING	14.0
	L/F WING NEW PART PAINTING	10.0
	R/F WING NEW PART PAINTING	10.0
	L/F SUPPORT BRACKET SURFACE PAINT	4.0
	R/F SUPPORT BRACKET SURFACE PAINT	4.0
	FRONT PANEL CPL SURFACE PAINT	6.0
	FRONT BUMPER NEW PART PAINT K1R	13.0
	LID COVER NEW PART PAINT K1R	3.0
	L/F SIDE MEMBER SURFACE PAINT	5.0
	R/F SIDE MEMBER SURFACE PAINT	5.0

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 190220
 Version: 1810
 Date calculated: 20/08/2019 4:34 PM

Full Report
 Registration: SKE8806H
 Printed: 20/08/2019 4:34 PM

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	37.15
0741	L/F WING NEW PART PAINTING	18.06
0742	R/F WING NEW PART PAINTING	18.06
1005	L/F SUPPORT BRACKET SURFACE PAINT	2.99
1006	R/F SUPPORT BRACKET SURFACE PAINT	2.99
1009	FRONT PANEL CPL SURFACE PAINT	13.20
0281	FRONT BUMPER NEW PART PAINT K1R	61.50
0357	LID COVER NEW PART PAINT K1R	0.98
1207	L/F SIDE MEMBER SURFACE PAINT	4.98
1208	R/F SIDE MEMBER SURFACE PAINT	4.98

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		74.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
Total	10 WU/h	104.0	468.00

Material Cost - Paint

	Price SGD
New Part Painting	73.27
New Part Painting - Plastic K1R	62.48
Surface-/Blend Paint	29.14
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	202.49

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0253	FRONT LWR AIR GRILLE	53112 52370			85.00
0258	FRT NO PLATE REINF	KNPL0			55.00
0281	FRONT BUMPER	52119 52978			265.00
0317	L/F BUMPER BRACKET	52536 52110			38.00
0318	R/F BUMPER BRACKET	52535 52150			38.00
0333	FRT BUMPER ABSORBER	52611 52150			50.00
0340	FRT BUMPER REINF	52131 52250			140.00
0357	LID COVER	52127 52941			18.00
0410	GRILLE	53111 52570			120.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: 190220

Version: 1810

Date calculated: 20/08/2019 4:34 PM

Full Report

Registration: SKE8806H

Printed: 20/08/2019 4:34 PM

Code	Description	Part Number	Supplier	Price SGD
0431	MANUFACTURER BADGE	75310 52010		45.00
0471	BONNET	53301 52370		240.00
0475	L/BONNET HINGE	53420 52360		40.00
0476	R/BONNET HINGE	53410 52350		40.00
0493	BONNET LOCK	53510 52790		58.00
0561	LEFT HEADLAMP ASSY	81150 52E61		400.00
0562	RIGHT HEADLAMP ASSY	81110 52E61		400.00
0745	L/F WING BADGE	75374 52020		35.00
1005	L/F SUPPORT BRACKET	53203 52220		95.00
1006	R/F SUPPORT BRACKET	53202 52230		95.00
1009	FRONT PANEL CPL	53210 52917		330.00
1012	R/UPP WIND DEFLECTOR	53285 52410		0.00
1018	FRONT PANEL STRUT	53208 52901		85.00
1021	UPPER RADIATOR COVER	53289 52080		100.00
1318	FRT BUMPER BRACKET	52521 52040		60.00
1319	FRT BUMPER SEAL	53395 52050		35.00
4465	CONDENSER	88460 52170		520.00
7761	RADIATOR	16400 21330		580.00
1003	FRT CLIPS@1.50	FRT CLIPS		18.00
1004	RAD TOP CLIP@1.50	RAD TOP CLIPS		9.00
1006	RAD TOP COVER	RAD TOP COVER		55.00
1007	RAD AIR GUIDE L TOP	RAD AIR GUIDE L		35.00
1008	RAD AIR GUIDE R TOP	RAD AIRGUIDE R		35.00
1009	RAD AIR GUIDE L LWR	RAD AIRGUIDE L		35.00
1010	RAD AIR GUIDE R LWR	RAD AIRGUIDE R		35.00
				0.00
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				
Subtotal				4,189.00
Addition(+10.00%)				418.90
Total				4,607.90

Extras

Code	Description	Price SGD
1000	RADIATOR COOLANT	20.00*
1001	AIR CON GAS	50.00*
1002	FRT NUMBER PLATE	40.00*
Total Extras		110.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 190220
 Version: 1810
 Date calculated: 20/08/2019 4:34 PM

Full Report
 Registration: SKE8806H
 Printed: 20/08/2019 4:34 PM

Final Calculation

	SGD	SGD
Parts	4,189.00	
Addition(+10.00%)	418.90	
Total Parts		4,607.90
Labour Time Base 10 WU/h		
Total 119.0 WU X 45.00 SGD/h	535.50	
Total of Labour		535.50
Total Of Extras		110.00
Paint Work Time Base 10 WU/h		
Labour Cost 104.0 WU X 45.00 SGD/h	468.00	
Material Cost	202.49	
Total Paint Including Material		670.49
Repair Cost Excludes GST		5,923.89
GST (+7.0%)		414.67
Repair Cost Included GST		6,338.56
Deductions (Excludes GST)		
Deduction For Excess	-300.00	
Total Of Deductions (Excludes GST)		-300.00
Grand Total Excludes GST		5,623.89
GST (+7.0%)		393.67
Grand Total Included GST		6,017.56

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS