



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2012 TOYOTA PRIUS 1.5 (SKE8806H)

Date of Loss

1 May 2019

Time of Loss

9.20

Loss Description

SKE8806H (INSD) C/W SKB1574M (TP)

Comment

Workshop Details

Total Rebate Amount

25461

Nett Loss Amount

\$9,539.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion *

20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SKE8806H

Purchase Date

Registration State

Registration Date *

Mileage



Age of Vehicle 7

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2012	<input type="text" value="2012"/>
Make	TOYOTA	<input type="text" value="TOYOTA"/>
		<input type="text"/>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	OW YEONG SUET YEE	<input type="text"/>
Date of Birth	22 February 1971	<input type="text" value="dd/mm/yyyy"/>

Model CATEGORY	PRIUS 1.5 POLICY INFORMATION	PRIUS C CVT INFORMATION
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	JTDKD3B3301503604	JTDKD3B3301
Engine No	1NZ6159413	1NZ6159413
Engine Capacity		1497
Sum Insured	0	0
Market Value	0	35000

CATEGORY Age	FNOL INFORMATION 48	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	18	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	05-01, 26 Duchess Road, 269029, Singapore	<input type="text"/>
Address type	Residential	<input type="text" value="▼"/>
Gender	Female	<input type="text" value="▼"/>
Marital status	Married	<input type="text" value="▼"/>
Identification #	S7106516B	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

06/05/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

300

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary















Parts























Add

























Approve

























Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRONT LWR AIR GRILLE (WCP) (10%)	Cracked	0	93.5	No					93.5	Reviewing
		0	1		L/F LOWER BUMPER LID	Serviceable	0	0	No					0	Deny
		0	1		R/F LOWER BUMPER LID	Serviceable	0	0	No					0	Deny
		0	1		FRT NO PLATE REINF (WCP) (10%)	Cracked	0	60.5	No					60.5	Reviewing
		0	1		FRONT BUMPER (WCP) (10%)	Buckled	0	291.5	No					291.5	Reviewing
		0	1		L/F BUMPER BRACKET (WCP) (10%)	Bent	0	41.8	No					41.8	Reviewing
		0	1		R/F BUMPER BRACKET (WCP) (10%)	Bent	0	41.8	No					41.8	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRT BUMPER ABSORBER (WCP) (10%)	Cracked	0	55	No					55	Reviewing
		0	1		FRT BUMPER REINF (WCP) (10%)	Bent	0	154	No					154	Reviewing
		0	1		LOWER COVER	Serviceable	0	0	No					0	Deny
		0	1		LID COVER (WCP) (10%)	Missing	0	19.8	No					19.8	Reviewing
		0	1		GRILLE (WCP) (10%)	Cracked	0	132	No					132	Reviewing
		0	1		MANUFACTURER BADGE (WCP) (10%)	Necessary	0	49.5	No					49.5	Reviewing
		0	1		BONNET (WCP) (10%)	Bent	0	264	No					264	Reviewing
		0	1		L/BONNET HINGE (WCP) (10%)	Damaged	0	44	No					44	Reviewing
		0	1		R/BONNET HINGE (WCP) (10%)	Damaged	0	44	No					44	Reviewing
		0	1		BONNET LOCK (WCP) (10%)	Damaged	0	63.8	No					63.8	Reviewing
		0	1		LEFT HEADLAMP ASSY (WCP) (10%)	Cracked	0	440	No					440	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		RIGHT HEADLAMP ASSY (WCP) (10%)	Cracked	0	440	No					440	Reviewing
		0	1		L/F FOG LAMP	Serviceable	0	0	No					0	Deny
		0	1		R/F FOG LAMP	Serviceable	0	0	No					0	Deny
		0	1		L/F INDICATOR	Serviceable	0	0	No					0	Deny
		0	1		R/F INDICATOR	Serviceable	0	0	No					0	Deny
		0	1		L/F WING BADGE (WCP) (10%)	Necessary	0	38.5	No					38.5	Reviewing
		0	1		R/F WING BADGE	Serviceable	0	0	No					0	Deny
		0	1		L/F SUPPORT BRACKET (WCP) (10%)	Bent	0	104.5	No					104.5	Reviewing
		0	1		R/F SUPPORT BRACKET (WCP) (10%)	Bent	0	104.5	No					104.5	Reviewing
		0	1		FRONT PANEL CPL (WCP) (10%)	Buckled	0	363	No					363	Reviewing
		0	1		R/UPP WIND DEFLECTOR	Serviceable	0	0	No					0	Deny
		0	1		FRONT PANEL STRUT (WCP) (10%)	Bent	0	93.5	No					93.5	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		UPPER RADIATOR COVER (WCP) (10%)	Cut	0	110	No					110	Reviewing
		0	1		L/F REINFORCEMENT	Repair	0	0	No					0	Deny
		0	1		R/F REINFORCEMENT	Repair	0	0	No					0	Deny
		0	1		FRT BUMPER BRACKET (WCP) (10%)	Buckled	0	66	No					66	Reviewing
		0	1		FRT BUMPER SEAL (WCP) (10%)	Necessary	0	38.5	No					38.5	Reviewing
		0	1		CONDENSER (WCP) (10%)	Damaged	0	572	No					572	Reviewing
		0	1		RADIATOR (WCP) (10%)	Damaged	0	638	No					638	Reviewing
		0	1		RADIATOR SHROUD	Serviceable	0	0	No					0	Deny
		0	1		FAN MOTOR	Serviceable	0	0	No					0	Deny
		0	1		BLOWER	Serviceable	0	0	No					0	Deny
		0	1		HORN	Serviceable	0	0	No					0	Deny
		0	12		FRT CLIPS (WCP) (10%)	Necessary	0	1.65	No					19.8	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	6		RAD TOP CLIP (WCP) (10%)	Missing	0	1.65	No					9.9	Reviewing
<input type="checkbox"/>		0	5		HOOD INS CLIP	Serviceable	0	0	No					0	Deny
<input type="checkbox"/>		0	1		RAD TOP COVER (WCP) (10%)	Cracked	0	60.5	No					60.5	Reviewing
<input type="checkbox"/>		0	1		RAD AIR GUIDE TOP (WCP) (10%)	Cracked	0	38.5	No					38.5	Reviewing
<input type="checkbox"/>		0	1		RAD AIR GUIDE R TOP (WCP) (10%)	Cracked	0	38.5	No					38.5	Reviewing
<input type="checkbox"/>		0	1		RAD AIR GUIDE L LWR (WCP) (10%)	Damaged	0	38.5	No					38.5	Reviewing
<input type="checkbox"/>		0	1		RAD AIR GUIDE R LWR (WCP) (10%)	Damaged	0	38.5	No					38.5	Reviewing
<input type="checkbox"/>		0	1		RAD LWR COVER	Serviceable	0	0	No					0	Deny

Labour

Add	Approve	Deny	Submit All							
	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		110.0 WU X 45.00 SGD/H	0	535.5	0	0	Reviewing	
		0		LABOUR COST 94.0 WU X 45.00 SGD/H	0	468	0	0	Reviewing	
		0		MATERIAL COST	0	202.49	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 5 DAYS	Reviewing		0		
<input type="checkbox"/>		0	RADIATOR COOLANT	Reviewing		20	NECESSARY	
<input type="checkbox"/>		0	AIR CON GAS	Reviewing		50	NECESSARY	
<input type="checkbox"/>		0	FRT NUMBER PLATE	Reviewing		40	BENT	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
------	----------	------	--------	---------------------	--------------------	---------	--------



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00				Adjusted Claim Amount	\$5,623.89	
CATEGORY		ESTIMATE		ADJUSTED				
Spare Parts		\$0.00		\$4,607.90				
Labour		\$0.00		\$1,205.99				
Miscellaneous		\$0.00		\$110.00				
Excess				-\$300.00				

Submit for Review