

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5952J**AAD1905-008***Not Notified
L1 Sing & Good*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5952J

VF1ABL15AUC281662

RENAULT

LATITUDE

1.5.19

LONPAC

26/6/2015

PART**LIST**

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	BOOT REAR
14	1	BOOT FINISHER
15	1	BOOT WHEATERSTRIP
16	1	BOOT REFLECTOR LAMP LH
17	1	BOOT REFLECTOR LAMP RH
18	1	BOOT BADGE 'RENAULT'
19	1	BOOT BADGE
20	1	BOOT STRUT LH
21	1	BOOT STRUT RH
22	1	BOOT HINGE LH
23	1	BOOT HINGE RH
24	1	BOOT INNER TRIM
25	1	BOOT SWITCH
26	1	BOOT LOCK
27	1	BOOT LOCK CATCH
28	2	LICENCE PLATE LAMP
29	2	BOOT RUBBER PLUG
30	1	FENDER PANEL INNER TRIM REAR RH

\$	<i>R</i>	1,108.46	—
\$	<i>R</i>	768.84	—
\$	<i>SL</i>	113.47	X
\$	<i>DIS</i>	135.97	✓
\$	<i>SL</i>	44.99	X
\$	<i>BR</i>	43.61	✓
\$	<i>SL</i>	135.97	X
\$	<i>SL</i>	44.99	X
\$	<i>SL</i>	43.61	X
\$	<i>R</i>	777.52	✓
\$	<i>R</i>	225.95	X
\$	<i>R</i>	225.95	✓
\$	<i>R</i>	2,872.68	X
\$	<i>SL</i>	470.06	X
\$	<i>SL</i>	323.05	X
\$	<i>SL</i>	493.35	X
\$	<i>SL</i>	493.35	X
\$	<i>MR</i>	225.36	—
\$	<i>MR</i>	225.36	—
\$	<i>SL</i>	276.08	} X
\$	<i>SL</i>	276.08	
\$	<i>R</i>	367.84	
\$	<i>R</i>	367.84	
\$	<i>SL</i>	586.45	
\$	<i>R</i>	168.13	
\$	<i>R</i>	202.67	
\$	<i>R</i>	74.40	
\$	<i>SL</i>	50.52	}
\$	<i>SL</i>	221.81	
\$	<i>SL</i>	671.45	}

Trans-cab Auto Services Pte Ltd

AAD1905-008

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5952J

31	1	FENDER PANEL REAR RH
32	1	WHEELARCH REAR RH
33	1	TAILLAMP RH
34	1	TAILLAMP PANEL RH
35	1	TAILLAMP LH
36	1	TAILLAMP PANEL LH
37	1	OUTER PANEL REAR (End Panel)
38	1	OUTER PANEL REAR (End Panel)TRIM
39	1	SPARE WHEEL PANEL (Luggage Floor Panel)
40	1	SPARE WHEEL PANEL TRIM
41	1	EXHAUST REAR
42	1	EXHAUST CAP REAR

\$	<i>Bur</i>	3,299.13	✓
\$	<i>Sn</i>	543.47	X
\$	<i>ngem</i>	552.55	✓
\$	<i>n</i>	986.70	} X
\$	<i>Sn</i>	552.55	
\$	<i>n</i>	986.70	
\$	<i>n</i>	1,471.77	
\$	<i>Sn</i>	404.56	
\$	<i>n</i>	2,189.88	
\$	<i>Sn</i>	612.21	
\$	<i>n</i>	7,489.05	
\$	<i>n</i>	230.49	
TOTAL	\$	31,354.89	
10%	\$	3,135.49	
	\$	28,219.40	

Special Nett

1	1SET	PARKING AID
2	1SET	REAR BUMPER CLIP
3	1SET	BUMPER BRACKET CTR CLIP
4	1SET	BUMPER BRACKET SIDE CLIP RH RR
5	1SET	BUMPER RETAINER RH CLIP RR
6	1SET	BUMPER BRACKET SIDE CLIP LH RR
7	1SET	BUMPER RETAINER CLIP LH RR
8	1SET	BUMPER LOWER REAR RIVET
9	1SET	BUMPER LOWER REAR CLIP
10	1	EXHAUST MOUNTING REAR
11	1SET	BOOT FINISHER CLIP
12	1	BOOT STICKER "Trans-cab"
13	1	BOOT STICKER "6555-3333"
14	1	BOOT INNER TRIM CLIP
15	1SET	FENDER WHEELARCH REAR RH CLIP
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)
17	1	SPARE TYRE
18	1	FENDER INNER TRIM CLIP RH
19	1	TAILLAMP CLIP RH
20	2	REAR WINDSCREEN SEALANT
21	1	WINDSCREEN MOULDING

\$	<i>Shon</i>	700.00	<i>500.00</i>
\$	<i>na</i>	66.00	✓
\$	<i>na</i>	33.00	✓
\$	<i>na</i>	10.00	X
\$	<i>na</i>	20.00	X
\$	<i>na</i>	10.00	X
\$	<i>na</i>	20.00	X
\$	<i>na</i>	22.00	X
\$	<i>na</i>	66.00	✓
\$	<i>Sn</i>	17.82	X
\$	<i>na</i>	24.20	X
\$	<i>na</i>	30.00	✓
\$	<i>na</i>	30.00	✓
\$	<i>na</i>	45.00	X
\$	<i>na</i>	35.00	X
\$	<i>Sn</i>	385.00	X
\$	<i>Sn</i>	330.00	X
\$	<i>na</i>	28.00	X
\$	<i>na</i>	5.00	✓
\$	<i>na</i>	80.00	<i>40.00</i>
\$	<i>na</i>	100.00	✓

Trans-cab Auto Services Pte Ltd

AAD1905-008

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5952J

22	1	REAR WINDSCREEN INNER SPONGE SEAL
23	1	TAILLAMP CLIP LH

\$ na 100.00 30sm
\$ na 5.00 X

TOTAL	\$	2,162.02
--------------	-----------	-----------------

TOTAL PARTS	\$	30,381.42
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.

\$ 6,000.00 8801

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 4,200.00 12001

To reinstall rear bumper parking sensor.

\$ 170.00 601

To transfer of bootlid fittings, attachments and
perform water seepage test.

\$ na 170.00 X

To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe.

\$ 170.00 601

To transfer of rear end panel fittings, attachment and
perform water seepage test.

\$ 170.00 }
1001

To transfer of rear luggage floor panel fittings,
attachment and perform water seepage test.

\$ 170.00

To check steering geometry and computer wheel
alignment

\$ na 220.00 X

To Rust-Proofing Of The Affected Areas.

\$ 170.00 601

To repair and realign rear exhaust pipe.

\$ na 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ na 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1905-008**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5952J

To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i>	380.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$		170.00	<i>120/</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	<i>X</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i>	380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>20/</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>na</i>	380.00	<i>X</i>

TOTAL \$ **14,780.00****Over All Total** \$ **45,161.42****(LUMP SUM) Repair Days****20 DAYS***8 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: