



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

China Taiping Insurance (S) Pte Ltd		NAME : Ms Ren Xiaorong		WIP : 45298	
3 Anson Rd, #16-00 Springleaf Tower, Singapore 079909		ADDRESS : 238 Orchard Boulevard #21-07 Singapore 237973		EXCESS :	
ATTN. : MOTOR CLAIMS		TEL :		DATE: 30.04.2019	
FAX :					
VEH NO :	SKL9661P	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZZ95ZJLB05019	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Macan	DATE REG.:	12.02.2018	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description		QTY	REVISED	PRICES
1	FRONT BUMPER (SPORT DESIGN)		1	\$ 4,853.00	\$ 3,970.50
2	FRONT BUMPER GRILLE SUPPORT LH		1	\$ 768.00	\$ 768.00
3	BUMPER GRILLE SUPPORT COVER LH		1	\$ 144.20	\$ 144.20
4	FRONT BUMPER SIDE TRIM COVER LH		1	\$ 731.22	\$ 731.20
5	FRONT BUMPER SIDE TRIM GARNISH		1	\$ -	\$ 365.60
6	EXPANSION RIVET		6	\$ 9.00	\$ 9.00
7	BRACKET, CHARGE AIR COOLER		1	\$ 225.00	\$ 225.00
8	BUMPER GUIDE		1	\$ 77.40	\$ 77.40
9	BONNET		1	\$ 3,057.90	\$ 3,057.90
10	P000-043-305-51-/CAVITY PRESERVATION (AK		1	\$ -	\$ 75.30
11	HOOD BADGE NUT		2	\$ 3.00	\$ 3.00
12	BONNET SOUND ABSORBER		1	\$ -	\$ 229.90
13	BONNET SEAL		2	\$ 14.80	\$ 14.80
14	HEADLAMP TRIM COVER		1	\$ 53.80	\$ 53.80
15	EXPANSION RIVET		1	\$ 2.20	\$ 2.20
16	LED HEADLAMP		1	\$ 5,098.70	\$ 5,098.70
17	ADDITIONAL HEADLAMP		1	\$ 348.30	\$ 348.30
18	P000-043-301-47-/ANTIFREEZE PROTECTION		6	\$ 190.20	\$ 190.20
SUPPLEMENTARY PARTS					
1	HEADLAMP RETAINER PLATE (A) / BR		1	\$ 111.00	\$ 111.00
TOTAL PARTS				\$ 15,687.72	\$ 15,476.00
LESS 10%				\$ 1,568.77	\$ 1,547.60
TOTAL PARTS COST				\$ 14,118.95	\$ 13,928.40
Labour Description					
1	TO REPLACE BONNET, FRONT BUMPER, CHARGE AIR COOLER BRACKET & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 3,120.00	\$ 6,240.00
2	TO RESPRAY BONNET, FRONT BUMPER			\$ 2,400.00	\$ 3,500.00
3	TO SUPPLY 1 PC CHASSIS STICKER			\$ 150.00	\$ 150.00
4	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.			\$ 500.00	\$ 500.00