

ASS. REC. BY:

REF: CS/CT19007907/Asd3N2

Special Instruction:

Surveyor: Adnan

## ASSIGNMENT (Office)

From (Person):

Ong chin kiat

of

CT1

Date/Time:

6.5.19 14.53p.m

Estimated Cost:

Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 4065A

Insured:

GBE 6332

at Workshop m/s

VISION AUTOWORK

Tel:

63416789

of 8 Kaki Bukit Ave 4 #08-09 Premier

Policy No:

DMCVSN30565418000

Claim No:

SNM19D201996102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6.5.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time:

6.5.19

Person Contacted:

Michelle

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

SJM 4065A - X

GBE 6332 - X

27/05/19

Confirmed L/S \$ 14,000/- @ 18 days with Admin  
( \$ 22,146.20 Red - 61% )

ASS. REC. BY:

REF:

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SJM406SA Yr Regn: 2008, DecType: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axio c.c. 1496Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 149676 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NZE1416074213Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapsen

Front

Rear

F/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 06/05/19Survey held at VisionDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Claim

COE Expiry: 30/12/23

MV: 27k

PV: 12.8k

Nett: 14.2k

RECEIVED 27 MAY 2019

Resurvey no. of Trip - 1

Date/Time, File Pass to?

Date/Time, File Return to?

1) 27/05/19

2)

3) Typical

4)

5)

6)

Prel. Report:

Final Report: HC \$14/k

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 May 2019		06 May 2019 14:53 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>																						
Insured:	YI CHUANG, Co. Reg. No.: 53029610A																							
Main Claimant:	MOHAMMAD HAFIZ BIN ABDUL JABBAR, ID: S8944255I																							
Vehicle Reg. No.:	SJM4065A	Date of Loss:	06/05/2019 09:00 - :59 [124 Months and 6 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / SNM19D201996C02	Policy/Cover Note No.:	DMCVSN30565418000 (Comprehensive) Coverage: 23/08/2018 - 23/08/2019																					
Vehicle Reg. No. (Insured):	GBE633Z	Policy No. (Claimant):	PNPV2019-00002607																					
		Excess:	\$50.00																					
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]																							
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2019]																							
Adj Asg. Remarks:	please assign Mr Adrian Ling for SJE survey. thank you.																							
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>																						
There are no mail for this case.																								
<div> <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								



Almost New Condition, View To Believe, Nice Number, Call Now!



Posted: 02-May-2019 Tags: 2007 Toyota Corolla, 2007 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Axio 1.5A X  
(COE till 11/2022)

\$22,800

\$6,430 /yr

23-Nov-2007

1,496 cc

128,000 km

Sedan

Available

"One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, Bank & In-House Loan Available, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, Fu...

Carway



Posted: 04-May-2019 Tags: 2007 Toyota Corolla, 2007 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Axio 1.5M X  
(COE till 05/2023)

\$19,800

\$4,900 /yr

21-May-2008

1,496 cc

153,000 km

Sedan

Available

We Are Full Loan Specialist, Very Well Maintained, With All Wear And Tear Parts Recently Replaced. Fuel Economy Car Suitable For Daily Usage, Act Now Before It's Gone.

Iaxis



Posted: 02-May-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Axio 1.5A X  
(COE till 05/2023)

\$27,500

\$6,760 /yr

03-Jun-2008

1,496 cc

-

Sedan

Available

One Owner. Clean And Neat Interior. New Engine Mounting, New Shock Absorber, New Lower Arm, New Drive Shaft Cover, New Rear Shock Absorber, New Air Con Compressor, New Tie Rod End, New Air Con Cooling...



Posted: 06-May-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Free Valuation by sgCarMart Quotz

Trading-in your Car? Make a better informed decision by getting your Car accurately valued with Quotz, based on SG's largest car database, sgCarMart. Get notified via Phone, SMS, Email. Sell your Car for more - Get your Free Valuation Today.

Find out more!



☐ Toyota Corolla Axio 1.5A X  
(COE till 07/2023)

\$23,800

\$5,630 /yr

29-Jul-2008

1,496 cc

-

Sedan

Available

Lucky Win Preowned Cars! Well Maintained By 1 Fussy Owner. In House Loan Of \$20K With A Monthly Of \$556 Only. No Gimmicks! Call Us For A Non Obligation Test Drive Today! Quality Cars At Affordable Pri...



Posted: 06-May-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Axio 1.5A X  
(COE till 07/2028)

\$49,600

\$5,370 /yr

01-Aug-2008

1,496 cc

-

Sedan

Available

Gearbox Filter, Gearbox Cooler, Pan Gasket, Lower Arm, Steering Rack, Tie Rod, Japan Engine Mounting Changed Total \$4K. No Leaking At All.

**DIRECT ORDER**



Posted: 01-Apr-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Axio 1.5A X  
(COE till 08/2023)

\$27,800

\$6,450 /yr

29-Aug-2008

1,496 cc

150,000 km

Sedan

Available

"One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, New Paintwork, Bank & In-House Loan Available, Purchase Comes With Official Warranty Certificate For A Pe...

Carway



Posted: 05-May-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Axio 1.5A X  
(COE till 10/2023)

\$26,900

\$6,080 /yr

10-Oct-2008

1,496 cc

115,000 km

Sedan

Available

New Spraywork. Dash Console Done. Front & Rear Suspension Replaced. Aircon Compressor & Condenser Replaced. Consignment Unit. Call Now For A Viewing Appointment. Loan/Insurance Available. Trade-In Wel...

**CONSIGNMENT**

Prem Roy Motoring



Posted: 30-Apr-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Axio 1.5A X  
(New 5-yr COE)

\$29,800

\$5,950 /yr

28-Oct-2008

1,496 cc

120,000 km

Sedan

Available

Just Arrived! Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.



Posted: 04-Mar-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Axio 1.5A X  
(COE till 11/2023)

\$25,766

\$5,730 /yr

03-Nov-2008

1,496 cc

109,586 km

Sedan

Available

Loan Available. Engine And Gearbox Inspected By Our Mechanic, Even Undercarriage All In Very Good Condition, Definitely Worth Renewing COE, Don't Miss Out, Call Or Sms Our Staffs To Arrange For Viewin...

Creative Auto



Posted: 06-May-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota





☐ **Toyota Corolla Axio 1.5A X** **\$40,766** **\$4,240 /yr** **19-Dec-2008** **1,496 cc** **115,500 km** **Sedan** **Available**  
(COE till 12/2028)

Full Loan Amount Stated, Flexible Loan Package. Beautifully Maintained, Low Mileage Usage With Excellent Engine And Gear Condition, Definitely Worth Renew For 10 Years COE, Very Good Fuel Efficiency, ...

Creative Auto

★ Posted: 27-Apr-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ **Toyota Corolla Axio 1.5A X** **\$27,800** **\$5,550 /yr** **22-Dec-2008** **1,496 cc** **101,896 km** **Sedan** **Available**  
(New 5-yr COE)

Loan Available. Engine And Gearbox Inspected By Our Mechanic, Even Undercarriage All In Very Good Condition, Definitely Worth Renewing COE, Don't Miss Out, Call Or Sms Our Staffs To Arrange For Viewin...

Creative Auto

★ Posted: 29-Apr-2019 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ **Toyota Corolla Axio 1.5A X** **\$25,800** **\$5,500 /yr** **13-Jan-2009** **1,496 cc** **137,000 km** **Sedan** **Available**  
(COE till 01/2024)

100% Loan Approval Monthly At \$628. Bank And In-House Loan Available! High Approval Rate! Super Well Maintained By Previous Owner Who Believes In Weekly Polishing! Owner's Spare Car And Superb Well M...

Viking Motor Pte Ltd

★ Posted: 05-May-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ **Toyota Corolla Axio 1.5A X** **\$29,800** **\$6,360 /yr** **13-Jan-2009** **1,496 cc** **103,339 km** **Sedan** **Available**  
(COE till 01/2024)

1 Year Comprehensive Warranty Inclusive! Accident Free Quality Pre Owned With Low Mileage Done For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Options. View Today!

Cosmo Automobiles

★ Posted: 04-May-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make  Model  Price  Depreciation  Reg Date  Eng Cap  Mileage  Veh Type  Status

For old advertisements, view Expired ads

« Back ( 1 2 ) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Axio, Axio Singapore, used Axio Singapore, used Axio, used vehicles Singapore or even buy used Axio Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4255I
Vehicle Information	
Vehicle No.:	SJM4065A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	1NZC977999
Chassis No.:	NZE1416074213
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$13,110.00
Original Registration Date:	31 Dec 2008
First Registration Date:	31 Dec 2008
Transfer Count:	4
Actual ARF Paid:	\$9,367.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,786.00
COE Rebate Amount:	\$12,807.00
Total Rebate Amount:	\$12,807.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 May 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/05/2019 13:44
Date Of Accident	06/05/2019 09:35
Exact Location Of Accident	BKE TWDS PIE B4 EXIT 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM4065A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHAMMAD HAFIZ BIN ABDUL JABBAR
NRIC No	S8944255I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98459234
Alternative Phone No	OFFICE-98459234

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA AXIO-1.5 X (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00002607
Cover Note Number	

### Driver

Name of Driver	MOHAMMAD HAFIZ BIN ABDUL JABBAR
NRIC No	S8944255I
Date Of Birth	15/12/1989
Occupation	INDOOR
Date Of Driving Pass	27/06/2008
Driving Experience	10 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98459234
Fax Number	
Contact Number	OFFICE-98459234
Email Address	NOEMAIL

Address 465 CHOA CHU KANG AVE 4 #08-03 S680465

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 4

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE633Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GY8793C



Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GZ8022P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name

MOHAMMAD HAFIZ BIN ABDUL JABBAR

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJM4065A

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan #3


### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:

# Sketch Plan

## SKETCH PLAN



A-SSM 4065A

B-GBE 633 Z

C-9Y 8793 C

D-9Z 8022 P


## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to attach

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Person's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2

On 06.05.19 at about 09:35 hours at along BKE towards PIE (Before Exit 1). While I was travelling on the lane two and traffic was moderate, my front vehicle slow down and stop hence I follow suit.

Suddenly, I heard a loud bang from behind and the impact forced my vehicle (A) to move forward to hit onto the rear portion of Vehicle (D). When I alighted I realized it was vehicle (B) who hit my rear portion of my vehicle (A) causing damages to my front & rear portion of my vehicle. It was a chain collision of total 4 vehicles involved.

Vehicle (A) : SJM4065A

Vehicle (B) : GBE633Z

Vehicle (C) : GY8793C

Vehicle (D) : GZ8022P



# Vision Autowork Pte.Ltd.

( ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 06.05.19

TO : CHINA MOTOR CLAIMS DEPTS  
VEHICLE NO : SJM4065A  
MODEL : TOYOTA COROLLA AXIO  
DATE OF ACCIDENT : 06.05.19  
TIME OF ACCIDENT : 09:35HRS

Shirley  
NZE1416074213

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Replaced</i>	1	\$ 79.10	\$ 79.10
2	FRONT BUMPER FOGLAMP <i>New</i>	2	\$ 299.00	\$ 598.00
3	FRONT BUMPER FOGLAMP COVER <i>New</i>	2	\$ 78.00	\$ 156.00
4	FRONT BUMPER INNER BOTTOM GARNISH <i>new</i>	1	\$ 217.00	\$ 217.00
5	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 58.00	\$ 116.00
6	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 385.00	\$ 385.00
7	FRONT FENDER <i>Brucked</i>	2	\$ 745.00	\$ 1,490.00
8	FRONT FENDER INNER COWLING <i>new</i>	2	\$ 176.00	\$ 352.00
9	FRONT RADIATOR GRILLE WITH LOGO <i>new</i>	1	\$ 327.00	\$ 327.00
10	HEADLAMP <i>new</i>	2	\$ 890.00	\$ 1,780.00
11	BONNET <i>Distorted</i>	1	\$ 905.00	\$ 905.00
12	BONNET INNER RUBBER <i>new</i>	1	\$ 58.00	\$ 58.00
13	BONNET HINGE <i>new</i>	2	\$ 65.00	\$ 130.00
14	BONNET STOPPER <i>new</i>	2	\$ 14.50	\$ 29.00
15	BONNET LOCK <i>new</i>	1	\$ 95.00	\$ 95.00
16	FRONT SUPPORT PANEL <i>Distorted</i>	1	\$ 895.00	\$ 895.00
17	FRONT BRACE PANEL <i>Best</i>	1	\$ 105.00	\$ 105.00
18	AIR CONDENSOR <i>Best</i>	1	\$ 1,500.80	\$ 1,500.80
19	RADIATOR <i>New</i>	1	\$ 1,795.00	\$ 1,795.00
20	RADIATOR MOUNTING <i>new</i>	4	\$ 19.00	\$ 76.00
21	RADIATOR TOP BRACKET <i>new</i>	2	\$ 48.60	\$ 97.20
22	RADIATOR TOP HOSE <i>new</i>	1	\$ 85.00	\$ 85.00
23	RADIATOR TOP SUPPORT GARNISH <i>new</i>	1	\$ 217.00	\$ 217.00
24	RADIATOR FAN COWLING <i>new</i>	1	\$ 369.00	\$ 369.00
25	BATTERY BRACKET <i>new</i>	1	\$ 95.00	\$ 95.00
26	AIR CON PIPE PRESSURE <i>new</i>	1	\$ 394.00	\$ 394.00
27	BOOT LID <i>Distorted</i>	1	\$ 645.80	\$ 645.80
28	BOOT LID INSULATOR <i>New</i>	1	\$ 495.80	\$ 495.80
29	BOOT LID HINGE <i>Best</i>	2	\$ 75.00	\$ 150.00

1290.

1386

TO : CHINA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SJM4065A  
 MODEL : TOYOTA COROLLA AXIO  
 DATE OF ACCIDENT : 06.05.19  
 TIME OF ACCIDENT : 09:35HRS

30	BOOT LID LOCK <i>Damaged</i>	1	\$ 95.00	\$ 95.00	✓
31	BOOT LID LOWER CATCH <i>new</i>	1	\$ 42.00	\$ 42.00	✓
32	BOOT LID LOGO <i>2</i>	1	\$ 58.00	\$ 58.00	✓
33	BOOT LID EMBLEM "AXIO" <i>1</i>	1	\$ 58.00	\$ 58.00	✓
34	BOOT LD EMBLEM "X" <i>1</i>	1	\$ 45.00	\$ 45.00	✓
35	BOOT LID WEATHER STRIP <i>1</i>	1	\$ 169.00	\$ 169.00	✓
36	BOOTLID OUTER MOULDING <i>Cracked</i>	1	\$ 285.00	\$ 285.00	+
37	BOOT LID KEY LOCK <i>new</i>	1	\$ 138.10	\$ 138.10	+
38	REAR NUMBER PLATE LAMP <i>new</i>	1	\$ 68.00	\$ 68.00	+
39	REAR BUMPER <i>Distorted</i>	1	\$ 698.00	\$ 698.00	459.
40	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 98.00	\$ 196.00	76.
41	REAR BUMPER BRACKET <i>Dented</i>	2	\$ 85.00	\$ 170.00	✓
42	TAIL LAMP <i>Cracked</i>	2	\$ 345.60	\$ 691.20	✓
43	TAIL LAMP LOWER BRACKET <i>Cracked</i>	2	\$ 98.00	\$ 196.00	128.
44	TAIL LAMP PANEL <i>Dented</i>	2	\$ 245.80	\$ 491.60	321.60.
45	REAR DOOR INNER LOCK <i>new</i>	2	\$ 476.00	\$ 952.00	+
46	REAR FENDER <i>LH Buckled</i>	2	\$ 955.00	\$ 1,910.00	955
47	REAR FENDER INNER COWLING <i>new</i>	2	\$ 85.00	\$ 170.00	+
48	REAR FENDER INNER TRIM <i>torn</i>	2	\$ 395.00	\$ 790.00	566.40
49	REAR FENDER AIR VENT LH <i>new</i>	1	\$ 195.00	\$ 195.00	+
50	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 165.00	\$ 165.00	✓
51	REAR SPARE TYRE BOLT <i>new</i>	1	\$ 38.00	\$ 38.00	✓
52	REAR END PANEL <i>Distorted</i>	1	\$ 465.00	\$ 465.00	✓
53	REAR END PANEL TOP GARNISH <i>Behind</i>	1	\$ 195.00	\$ 195.00	✓
54	REAR FLOOR PANEL <i>Buckled</i>	1	\$ 795.00	\$ 795.00	✓
55	REAR FLOOR PANEL TOP BOARD <i>Behind</i>	1	\$ 535.00	\$ 535.00	✓
56	REAR TOOLS SPONGE <i>new</i>	1	\$ 198.00	\$ 198.00	+
57	REAR CHASSIS MEMBER <i>Repis</i>	1	\$ 255.00	\$ 255.00	+
58	CENTER EXHAUST <i>2 Best</i>	1	\$ 2,720.00	\$ 2,720.00	1570.
59	CENTER EXHAUST INSULATOR <i>new</i>	1	\$ 180.00	\$ 180.00	+
60	CENTER EXHAUST GASKET (SET) <i>new</i>	1	\$ 120.00	\$ 120.00	35
61	REAR EXHAUST PIPE <i>Best</i>	1	\$ 975.00	\$ 975.00	449.60
62	REAR EXHAUST INSULATOR <i>new</i>	1	\$ 185.00	\$ 185.00	+
63	REAR EXHAUST GASKET (SET) <i>new</i>	1	\$ 120.00	\$ 120.00	55
64	REAR EXHAUST MOUNTING <i>new</i>	4	\$ 45.00	\$ 180.00	70.

16953.50 torn  
 12715.12

TOTAL PRICE \$ 28,181.60  
 LESS 25% \$ 7,045.40  
 SUB TOTAL PRICE \$ 21,136.20



TO : CHINA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SJM4065A  
 MODEL : TOYOTA COROLLA AXIO  
 DATE OF ACCIDENT : 06.05.19  
 TIME OF ACCIDENT : 09:35HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>culd</i>	1	\$ 50.00	\$ 50.00 ✓
2	FRONT BUMPER CLIP (SET) <i>on</i>	1	\$ 80.00	\$ 80.00 30
3	FRONT FENDER INNER COWLING LH (SET) <i>on</i>	1	\$ 50.00	\$ 50.00 +
4	FRONT GRILLE CARBON FIBRE (SPECIAL TYPE) <i>separated</i>	1	\$ 1,200.00	\$ 1,200.00 +.
5	BONNET SEALANT <i>neu</i>	1	\$ 80.00	\$ 80.00 +
6	FRONT SUPPORT PANEL SEALANT <i>neu</i>	1	\$ 80.00	\$ 80.00 +
7	HORN (SPECIAL TYPE) <i>neu</i>	2	\$ 110.00	\$ 220.00 +
8	RADIATOR COOLANT <i>neu</i>	1	\$ 40.00	\$ 40.00 ✓
9	REAR NUMBER PLATE <i>neu</i>	1	\$ 50.00	\$ 50.00 +
10	REAR BUMPER CLIPS <i>neu</i>	1	\$ 80.00	\$ 80.00 30
11	BOOT LID SEALANT <i>neu</i>	1	\$ 80.00	\$ 80.00 +
12	BOOT LID INSULATOR CLIP (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00 +
13	TAILLAMP CLIP (SET) <i>neu</i>	1	\$ 30.00	\$ 30.00 20
14	TAIL LAMP PANEL SEALANT <i>neu</i>	2	\$ 80.00	\$ 160.00 +
15	REAR FENDER SEALANT <i>neu</i>	2	\$ 150.00	\$ 300.00 +.
16	REAR FENDER COWLING CLIPS (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00 +
17	REAR FENDER INNER TRIM CLIPS (SET) <i>neu</i>	1	\$ 50.00	\$ 50.00 ✓
18	REAR WINDSCREEN SEALANT <i>neu</i>	1	\$ 80.00	\$ 80.00 40
19	REAR WINDSCREEN INNER SEAL <i>neu</i>	1	\$ 60.00	\$ 60.00 40.
20	REAR WINDSCREEN SOLAR FILM <i>neu</i>	1	\$ 550.00	\$ 550.00 +
21	REAR END PANEL TOP GARNISH CLIPS (SET) <i>neu</i>	1	\$ 30.00	\$ 30.00 +
22	REAR END PANEL INSULATION SEAL <i>neu</i>	1	\$ 150.00	\$ 150.00 60
23	REAR FLOOR PANEL INSULATION SEAL <i>neu</i>	1	\$ 350.00	\$ 350.00 200
24	BREAKDOWN TRIANGLE SIGN <i>culd</i>	1	\$ 180.00	\$ 180.00 120.
25	REVERSE CAMERA <i>dayd</i>	1	\$ 450.00	\$ 450.00 380
26	REVERSE SENSOR <i>dayd</i>	1	\$ 220.00	\$ 220.00 200

TOTAL \$ 4,720.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	1000
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	1000.
3	REFOCUS HEADLAMP BEAM	\$ 80.00	30

1260

TO : CHINA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SJM4065A  
 MODEL : TOYOTA COROLLA AXIO  
 DATE OF ACCIDENT : 06.05.19  
 TIME OF ACCIDENT : 09:35HRS

4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60

2150.

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,800.00	1800
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	1400.
3	TUFF COAT	\$ 250.00	120.
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	100.
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	30
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
9	REAR CHASSIS ALIGNMENT	\$ 250.00	X
10	TRANSFER BOOTLID MECHANISM	\$ 80.00	X
11	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
13	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	✓
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

3750

**TOTAL \$10,290.00**

TO : CHINA MOTOR CLAIMS DEPTS  
VEHICLE NO : SJM4065A  
MODEL : TOYOTA COROLLA AXIO  
DATE OF ACCIDENT : 06.05.19  
TIME OF ACCIDENT : 09:35HRS

---

TOTAL PARTS COST : \$ 25,856.20  
TOTAL LABOUR COST : \$ 10,290.00  
TOTAL REPAIR COST : \$ 36,146.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

*ABBY*

SERVICE ADVISOR  
ABBY  
HP : 9856 4815

*Adrian Limy  
L/S 06/05/19*

*18 Days.*

*total: 15875.12  
L/S: 141k  
(Nett Value)*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19007907/ASD3N2

Date: 03/06/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30565418000
Claimant Vehicle No :	SJM4065A	Insured Vehicle No :	GBE633Z
Date of Loss:	06/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D201996C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJM4065A	Engine No:	1NZC977999
Make & Model:	TOYOTA COROLLA AXIO, 1.5 X (A)	Chassis No:	NZE1418074213
Reg. Date:	31/12/2008 (Man. Year: 2008)	Odometer:	149676 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	25,856.20	13,975.12	11,881.08	45.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,290.00	5,900.00	4,390.00	42.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>36,146.20</b>	<b>19,875.12</b>	<b>16,271.08</b>	<b>45.01</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>14,000.00</b>		
<b>(S\$)</b>	<b>36,146.20</b>	<b>14,000.00</b>	<b>22,146.20</b>	<b>61.27</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,530.23</b>	<b>980.00</b>	<b>1,550.23</b>	<b>61.27</b>
<b>Nett Amount (S\$)</b>	<b>38,676.43</b>	<b>14,980.00</b>	<b>23,696.43</b>	<b>61.27</b>

## INSPECTION

Date of Assignment: 06/05/2019  
 Date Inspected: 06/05/2019 Inspected At:

Vision Autowork Pte Ltd (HQ)  
 8 KAKI BUKIT AVE 4, #08-09  
 PREMIER @ KAKI BUKIT  
 Singapore 415875

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2019)
Parts:	143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM4065A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	79.10 FL	*79.10 FL
2	2	*FRONT BUMPER FOGLAMP	Not Necessary	598.00 FL	*- FL
3	2	*FRONT BUMPER FOGLAMP COVER	Not Necessary	156.00 FL	*- FL
4	1	*FRONT BUMPER INNER BOTTOM GARNISH	Cracked	217.00 FL	*217.00 FL
5	2	*FRONT BUMPER SIDE RETAINER	Necessary	116.00 FL	*116.00 FL
6	1	*FRONT BUMPER REINFORCEMENT	Bent	385.00 FL	*385.00 FL
7	2	*FRONT FENDER	Buckled	1,490.00 FL	*1,290.00 FL
8	2	*FRONT FENDER INNER COWLING	Not Necessary	352.00 FL	*- FL
9	1	*FRONT RADIATOR GRILLE WITH LOGO	Cracked	327.00 FL	*327.00 FL
10	2	*HEADLAMP	Cracked	1,780.00 FL	*1,396.00 FL
11	1	*BONNET	Distorted	905.00 FL	*905.00 FL
12	1	*BONNET INNER RUBBER	Not Necessary	58.00 FL	*- FL
13	2	*BONNET HINGE	Not Necessary	130.00 FL	*- FL
14	2	*BONNET STOPPER	Not Necessary	29.00 FL	*- FL
15	1	*BONNET LOCK	Damaged	95.00 FL	*95.00 FL
16	1	*FRONT SUPPORT PANEL	Distorted	895.00 FL	*895.00 FL
17	1	*FRONT BRACE PANEL	Bent	105.00 FL	*105.00 FL
18	1	*AIR CONDENSOR	Bent	1,500.80 FL	*1,500.80 FL
19	1	*RADIATOR	Not Necessary	1,795.00 FL	*- FL
20	4	*RADIATOR MOUNTING	Necessary	76.00 FL	*76.00 FL
21	2	*RADIATOR TOP BRACKET	Not Necessary	97.20 FL	*- FL
22	1	*RADIATOR TOP HOSE	Not Necessary	85.00 FL	*- FL
23	1	*RADIATOR TOP SUPPORT GARNISH	Cracked	217.00 FL	*217.00 FL
24	1	*RADIATOR FAN COWLING	Cracked	369.00 FL	*369.00 FL
25	1	*BATTERY BRACKET	Not Necessary	95.00 FL	*- FL
26	1	*AIR CON PIPE PRESSURE	Not Necessary	394.00 FL	*- FL
27	1	*BOOT LID	Distorted	645.80 FL	*645.80 FL
28	1	*BOOT LID INSULATOR	Not Necessary	495.80 FL	*- FL
29	2	*BOOT LID HINGE	Bent	150.00 FL	*150.00 FL
30	1	*BOOT LID LOCK	Damaged	95.00 FL	*95.00 FL
31	1	*BOOT LID LOWER CATCH	Not Necessary	42.00 FL	*- FL
32	1	*BOOT LID LOGO	Necessary	58.00 FL	*58.00 FL
33	1	*BOOT LID EMBLEM AXIO	Necessary	58.00 FL	*58.00 FL
34	1	*BOOT LID EMBLEM X	Necessary	45.00 FL	*45.00 FL
35	1	*BOOT LID WEATHER STRIP	Cut	169.00 FL	*169.00 FL
36	1	*BOOTLID OUTER MOULDING	Not Necessary	285.00 FL	*- FL
37	1	*BOOT LID KEY LOCK	Not Necessary	138.10 FL	*- FL
38	1	*REAR NUMBER PLATE LAMP	Not Necessary	68.00 FL	*- FL
39	1	*REAR BUMPER	Distorted	698.00 FL	*459.00 FL
40	2	*REAR BUMPER SIDE RETAINER	Necessary	196.00 FL	*76.00 FL
41	2	*REAR BUMPER BRACKET	Dented	170.00 FL	*170.00 FL
42	2	*TAIL LAMP	Cracked	691.20 FL	*691.20 FL
43	2	*TAIL LAMP LOWER BRACKET	Cracked	196.00 FL	*128.00 FL
44	2	*TAIL LAMP PANEL	Dented	491.60 FL	*321.60 FL

Report was unsubmitted during this print-out.



No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	2	*REAR DOOR INNER LOCK	Not Necessary	952.00 FL	*- FL
46	1	*REAR FENDER	N/s Buckled	1,910.00 FL	*955.00 FL
47	2	*REAR FENDER INNER COWLING	Not Necessary	170.00 FL	*- FL
48	2	*REAR FENDER INNER TRIM	Torn	790.00 FL	*566.40 FL
49	1	*REAR FENDER AIR VENT LH	Not Necessary	195.00 FL	*- FL
50	1	*REAR WINDSCREEN MOULDING	Necessary	165.00 FL	*165.00 FL
51	1	*REAR SPARE TYRE BOLT	Cracked	38.00 FL	*38.00 FL
52	1	*REAR END PANEL	Distorted	465.00 FL	*465.00 FL
53	1	*REAR END PANEL TOP GARNISH	Deformed	195.00 FL	*195.00 FL
54	1	*REAR FLOOR PANEL	Buckled	795.00 FL	*795.00 FL
55	1	*REAR FLOOR PANEL TOP BOARD	Deformed	535.00 FL	*535.00 FL
56	1	*REAR TOOLS SPONGE	Not Necessary	198.00 FL	*- FL
57	1	*REAR CHASSIS MEMBER	Repair	255.00 FL	*- FL
58	1	*CENTER EXHAUST	Bent	2,720.00 FL	*1,570.00 FL
59	1	*CENTER EXHAUST INSULATOR	Not Necessary	180.00 FL	*- FL
60	1	*SET CENTER EXHAUST GASKET	Necessary	120.00 FL	*55.00 FL
61	1	*REAR EXHAUST PIPE	Bent	975.00 FL	*449.60 FL
62	1	*REAR EXHAUST INSULATOR	Not Necessary	185.00 FL	*- FL
63	1	*SET REAR EXHAUST GASKET	Necessary	120.00 FL	*55.00 FL
64	4	*REAR EXHAUST MOUNTING	Torn	180.00 FL	*70.00 FL
65	1	*FRONT NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
66	1	*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
67	1	*SET FRONT FENDER INNER COWLING LH	Not Necessary	50.00 FS	*- FS
68	1	*FRONT GRILLE CARBON FIBRE (SPECIAL TYPE)	Repeated	1,200.00 FS	*- FS
69	1	*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
70	1	*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
71	2	*HORN (SPECIAL TYPE)	Not Necessary	220.00 FS	*- FS
72	1	*RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS
73	1	*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
74	1	*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
75	1	*BOOT LID SEALANT	Not Necessary	80.00 FS	*- FS
76	1	*SET BOOT LID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
77	1	*SET TAIL LAMP CLIP	Necessary	30.00 FS	*20.00 FS
78	2	*TAIL LAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
79	2	*REAR FENDER SEALANT	Not Necessary	300.00 FS	*- FS
80	1	*SET REAR FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
81	1	*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
82	1	*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
83	1	*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
84	1	*REAR WINDSCREEN SOLAR FILM	Not Necessary	550.00 FS	*- FS
85	1	*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
86	1	*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
87	1	*REAR FLOOR PANEL INSULATION SEAL	Necessary	350.00 FS	*200.00 FS
88	1	*BREAKDOWN TRIANGLE SIGN	Cracked	180.00 FS	*120.00 FS
89	1	*REVERSE CAMERA	Damaged	450.00 FS	*380.00 FS
90	1	*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>32,901.60</b>	<b>18,213.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>7,045.40</b>	<b>4,238.38</b>
<b>Total Parts (\$\$)</b>	<b>25,856.20</b>	<b>13,975.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,600.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,000.00
3	REFOCUS HEADLAMP BEAM	New	80.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	PANEL BEATING, REMOVING AND REPLACING PARTS	New	2,800.00	1,800.00
7	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,400.00
8	TUFF COAT	New	250.00	120.00
9	WIRING CHECK	New	180.00	30.00
10	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	100.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
12	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
13	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
14	REAR CHASSIS ALIGNMENT	New	250.00	0.00
15	TRANSFER BOOTLID MECHANISM	New	80.00	0.00
16	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
17	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
18	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	New	80.00	80.00
19	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			10,290.00	5,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >