

22/05/2019

ASS/REC BY:

REF: CS/CT1190079121 Tlqd3k2

Special Instruction:

Survey: Taukikh
Min/min

ASSIGNMENT (Office)

From (Person): Chong Boon Senof CT1Date/Time: 6.5.19 13.08 pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: XD 702K

Insured:

at Workshop m/s VFX AUTOTel: 64552957of 60 Kaki Bukit Ave 6 ARK@KBPolicy No: DMCVSN1804891901Claim No: SRM19D2019 4101

Sum Insured:

Excess: \$1500.00

Make of Veh:

(Client's Record)

D.O.A. 24.4.2019

CA / REV / REP. / REV 24 HRS

7.5.2019Date/Time: 6.5.19 2.19 pm

H.O.D. Endorsement:

Person Contacted: Yee BingVehicle IN/OUT

Date/Time	Action/Instruction
	Eshwari (✓) Inspection: 26 Chia Ping Road 619977
	XD 702K - NA/CT1190079121/24 D.O.A - 24/04/2019
08/5/19 @ 3.47pm	visit to Chong Boon Sen via Messenger.
14/5/19 @ 4.15pm	So Chon informed CA via messenger.
15/5/19 @ 7.08pm	Informed Yee Bing C/A on US \$ 6000 & ex: \$ 1500 by email.
15/11/19 @ 1.20pm	Taukikh finalised with Weng Sheng US \$ 31050, 12 days. (Ref \$ 28733.13, 48%)

Signature

Tan J M

REF: CTI

ASSIGNMENT

From: Date: 7.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XD 7022K

at Workshop n/s Vix Auto

of 26 Chin Ping Road

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: 64552957 (ye Bing)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

110K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: XD 7022K Yr Regn: 2013 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Tipper Truck

Make: Volvo FMX420 cc 12777

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 531783 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: yv2j910670A740282

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 315 / S1672-5 R: (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front

R/Bal: 8 mm R/Bal: 5/8 mm

L/Bal: 8 mm L/Bal: 2/5 mm

D.O.A: D.O.I: 7/5/19

Survey held at: Vix Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
15/11	1st 31,500, 12 days e-mail to Wang

RECEIVED 15 NOV 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) 18/11 11:15 AM ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

IS + RS: \$

Photos:

Others:

TOTAL

770

770

Report Format: MER-TP

Lump Sum / L.B. (\$): 31050

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 May 2019		06 May 2019 13:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD, Co. Reg. No.: 199904117E								
Vehicle Reg. No.:	XD7022K	Date of Loss:	24/04/2019 18:00 - :59						
Claim Type:	OD / SNM19D201941C01	Policy/Cover Note No.:	DMCVSN1804891901 (Comprehensive)						
		Excess:	S\$1,500.00						
Repairer:	Vfix Auto Pte Ltd (HQ) 60 KAKI BUKIT AVE 6 ARK@KB, 417892 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2019]								
Driver/Custodian:	ZHAO JUNLIANG (50 / Male), NRIC: G8230879U, Tel: +6590365563 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 15 May 2019 2:08 PM
To: ybsim@vfixauto.com.sg
Subject: OD VEHICLE XD 7022K (DOA: 24/04/2019)

Dear Yee Bing,

As instructed by our client, please proceed to repair the insured vehicle **XD 7022K** at repair cost on Lump Sum basis. (Excess \$1,500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	06 May 2019 13:07	Cim Veh Model Changed	(204101) VOLVO FMX410 10.8 D 84RT RAS DC WB5200 (M).		[I] Chong Boon Sen
2	06 May 2019 13:07	Cim Created	Reg No: XD7022K. Policy No: DMCVSN1804891901. Acct Date: 2019/04/24. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Vfix Auto Pt e Ltd (HQ). Ins.Status => Incoming Claim. Created from SAS:MNA119053535		[I] Chong Boon Sen
3	06 May 2019 13:08	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[I] Chong Boon Sen
4	06 May 2019 13:08	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/15		[I] Chong Boon Sen
5	06 May 2019 13:08	Adj Mandate Set	Approved:0.00.		[I] Chong Boon Sen
6	06 May 2019 13:39	Assignment 1st Accessed			[A] LEE SU THING
7	06 May 2019 15:43	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID		[A] LEE SU THING
8	08 May 2019 13:46	Adj Rpt Initiated			[A] SHIAU CHAN
9	08 May 2019 13:46	Cim Dtl Modified	JPJ Reg. Date: -> 2013/04/10.		[A] SHIAU CHAN
10	08 May 2019 13:46	Cim Details Notified			[A] SHIAU CHAN
11	08 May 2019 15:41	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/05/15		[A] SHIAU CHAN
12	08 May 2019 15:42	Adj Mandate Request	Cur.Req:43767.39:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
13	15 May 2019 09:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/15		[I] Chee So Chow
14	15 May 2019 09:15	Adj Mandate Set	Approved:43767.39.		[I] Chee So Chow

Date From



Date To



Audit Type

None



Go

ACTIVITY

[06/05/2019 15:37] LEE SU THING:

Please be informed that repairer agreed to survey on 7/5/2019.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2139638	08/05/2019 13:46	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	XD7022K		10.70

Shiau Chan (LKKAUTO)

From: wskoh@vfixauto.com.sg
Sent: Friday, 15 November 2019 1:24 PM
To: Taufikh (LKKAUTO); Shiau Chan (LKKAUTO)
Cc: ybsim@vfixauto.com.sg; jeffbz@vfixauto.com.sg; jessicassy@vfixauto.com.sg; kentsh@vfixauto.com.sg; alancik@vfixauto.com.sg
Subject: RE: Own damage claim -XD7022K Finalize
Attachments: FSDV.pdf

Dear Taufikh & Shiau Chan,

Good day.

We accept your offer COR Lump Sump \$31,050 (before GST).

Kindly refer the attached DV & Tax Invoice for your kind perusal.

Original copies we will post up to China Taiping directly .

Please proceed to next step.



Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Sent: Thursday, 14 November 2019 12:58 PM
To: wskoh@vfixauto.com.sg
Subject: RE: Own damage claim -XD7022K Finalize

Hi Weng,

COR l/s \$31,050 , 12 days.

Regards
Taufikh
Lkk Auto

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Sent: Wednesday, 13 November 2019 12:40 PM
To: wskoh@vfixauto.com.sg
Subject: RE: Own damage claim -XD7022K Finalize

Hi Weng,

Refer attached. COR revise to l/s \$29,150 , 12 days. Only turbo intercooler given photo shows dented, but radiator no damage seen in photo.

Regards
Taufikh
Lkk Auto

From: wskoh@vfixauto.com.sg [mailto:wskoh@vfixauto.com.sg]
Sent: Friday, 8 November 2019 10:59 AM
To: 'SUR'; taufikh@lkkauto.com; khanchna@lkkauto.com; 'Admin A'; 'Jia Le (LKK Auto)'
Cc: ybsim@vfixauto.com.sg; jeffbz@vfixauto.com.sg; jessicassy@vfixauto.com.sg; alancik@vfixauto.com.sg; kentsh@vfixauto.com.sg
Subject: RE: Own damage claim -XD7022K Finalize
Importance: High

REMINDER(2)!!!

Dear Taufik and LKK Team,

We refer to our email dated 24.08.19.

Can we know what is the status for above mention case?

Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng
Motor Claim Operation Admin
Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd
26 Chia Ping Road Singapore 619977
Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: wskoh@vfixauto.com.sg <wskoh@vfixauto.com.sg>
Sent: Wednesday, 30 October 2019 3:18 PM
To: 'SUR' <sur@lkkauto.com>; 'taufikh@lkkauto.com' <taufikh@lkkauto.com>
Cc: 'ybsim@vfixauto.com.sg' <ybsim@vfixauto.com.sg>; 'jeffbz@vfixauto.com.sg' <jeffbz@vfixauto.com.sg>; 'jessicassy@vfixauto.com.sg' <jessicassy@vfixauto.com.sg>; 'alancelk@vfixauto.com.sg' <alancelk@vfixauto.com.sg>
Subject: RE: Own damage claim -XD7022K Finalize

REMINDER(1)!!!

Dear Taufik,

We refer to the email dated 24/08/2019.

Kindly let us have the status.

Much appreciated if you could processing of this claim .

Thank You.

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: wskoh@vfixauto.com.sg <wskoh@vfixauto.com.sg>
Sent: Monday, 16 September 2019 10:54 AM
To: 'SUR' <sur@lkkauto.com>; 'taufikh@lkkauto.com' <taufikh@lkkauto.com>
Cc: 'ybsim@vfixauto.com.sg' <ybsim@vfixauto.com.sg>; 'jeffbz@vfixauto.com.sg' <jeffbz@vfixauto.com.sg>; 'jessicassy@vfixauto.com.sg' <jessicassy@vfixauto.com.sg>; 'alancelk@vfixauto.com.sg' <alancelk@vfixauto.com.sg>
Subject: RE: XD7022K question mark item photo

Dear Taufik,

Any good new from your side?

Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: wskoh@vfixauto.com.sg <wskoh@vfixauto.com.sg>

Sent: Saturday, 24 August 2019 10:37 AM

To: 'SUR' <sur@lkkauto.com>; 'taufikh@lkkauto.com' <taufikh@lkkauto.com>


Cc: 'LKK Paya Ubi' <rspu@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; 'jeffbz@vfixauto.com.sg' <jeffbz@vfixauto.com.sg>; 'jessicassy@vfixauto.com.sg' <jessicassy@vfixauto.com.sg>; 'alancelk@vfixauto.com.sg' <alancelk@vfixauto.com.sg>

Subject: RE: XD7022K question mark item photo

Dear Taufik ,

Kindly find attached estimate for proceed COR.

Thank You.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 08 May 2019

Preliminary Advice

Vehicle No	: XD7022K	Accident Date	: 24/04/2019
Make	: VOLVO FMX410	Policy No.	: DMCVSN1804891901
Assignment Date	: 06/05/2019	Excess	: S\$1,500.00
Date of Inspection	: 07/05/2019	Est. Duration of Repair	: 12.00
Inspection At	: VFIX AUTO PTE LTD (HQ) 60 KAKI BUKIT AVE 6 ARK@KB SINGAPORE 417892		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	51,794.23
Revised Amount	:S\$	20,394.09
Check Items (Estimated)	:S\$	23,373.30
Total	:S\$	43,767.39

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	20,964.00
Salvage Value	:S\$	
Margin for Repair	:S\$	89,036.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4117E
Vehicle Details	
Vehicle No.:	XD7022K
Vehicle to be Exported:	No
Intended Deregistration Date:	08 May 2019
Vehicle Make:	VOLVO
Vehicle Model:	FMX420 84RT SC
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	D13379246
Chassis No.:	YV2JG10G7DA740282
Maximum Power Output:	-
Open Market Value:	\$149,767.00
Original Registration Date:	10 Apr 2013
First Registration Date:	10 Apr 2013
Transfer Count:	0
Actual ARF Paid:	\$7,489.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Apr 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$53,489.00
COE Rebate Amount:	\$20,964.00
Total Rebate Amount:	\$20,964.00

The information contained herein is correct as at 08 May 2019

OK

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: 199904117E
 Owner ID Type: Company
 Owner Name: KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD
 Registered Address: 27 PANDAN CRESCENT SINGAPORE 128476
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: XD7022K
 Previous Vehicle No.: -
 Effective Date of Ownership: 10 Apr 2013
 Original Regn Date: 10 Apr 2013
 Registration Date: 10 Apr 2013
 Year of Manufacture: 2012
 Vehicle Type: Goods (Open) Tipper/Dumper Truck
 Vehicle Scheme: -
 Vehicle Attachment 1: No Attachment
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: VOLVO
 Vehicle Model: FMX420 84RT SC
 Primary Colour: White
 Secondary Colour: -
 Passenger Capacity: 1
 Chassis No.: YV2JG10G7DA740282
 Engine No.: D13379246
 Engine Capacity / Power Rating: 12777 cc / -
 Maximum Power Output: -
 Propellant: Diesel
 Max Unladen Weight: 14840 kg
 Maximum Laden Weight: 34000 kg
 Open Market Value: \$149,767.00
 PARF Eligibility: No
 PARF Eligibility Expiry Date: -
 Minimum PARF Benefit: -
 No. of Transfers: 0
 IU Label No.: 2010441315
 COE No.: 2013030105000335N
 COE Expiry Date: 09 Apr 2023
 COE Category: C - Goods Vehicle & Bus
 COE Registration Category: C - Goods Vehicle & Bus
 Quota Premium (QP) / Prevailing Quota Premium: \$53,489.00 / -
 Actual QP Paid: \$53,489.00
 QP (Regn Cat): \$53,489.00
 OPC Cash Rebate Eligibility: No
 QP during COE Bidding Exercise: \$53,489.00
 Additional Registration Fee Rate: 5.00 %
 Actual ARF Paid: \$7,489.00
 Vehicle Lifespan Expiry Date: 09 Apr 2033
 CO2 Emission: -
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -
 Message: To renew the COE, the Prevailing Quota Premium payable is that of Category C.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/04/2019 13:42
Date Of Accident	24/04/2019 18:00
Exact Location Of Accident	JUNC MARINA EAST DR TWDS FORD RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD7022K
Insured/Policyholder	
Name Of Registered Owner	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD
Co Reg No	199904117E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-899999999

Vehicle Particulars

Manufacturer	VOLVO
Model	FMX420 84RT SC
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1804891901
Cover Note Number	

Driver

Name of Driver	ZHAO JUNLIANG
Passport No/FIN	G8230879U
Date Of Birth	21/02/1969
Occupation	OUTDOOR
Date Of Driving Pass	14/10/2008
Driving Experience	10 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90365563
Fax Number	
Contact Number	OFFICE-90365563
Email Address	NOEMAIL

Address 27 PANDAN CRESCENT
 Postcode 128476
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD6751X
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

WILLIAM PEARCE

7. This label must be completed by the Polls/Ballot and/or the Authorized Driver.

趙君亮

Responsible Person's Name: _____
 Name: _____
 Title: _____

Accident Sketch Plan

W. 11111111



A 10000000
B 10000000

REMARKS ON CIRCUMSTANCES OF THE ACCIDENT

Refer to statement

Handwritten notes and a large diagonal line drawn across the form.

DECLARATION

I hereby declare that the above information is true and correct to the best of my knowledge.

Signature of the Driver
Date: 11/11/11

Signature of the Driver
Date: 11/11/11

Signature of the Driver
Date: 11/11/11

Accident Sketch Plan

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG THE STATED VENUE. I DID NOT NOTICED THAT VEHICLE B WAS IN STATIONARY POSITION. AS A RESULT, MY VEHICLE HIT ONTO VEHICLE B REAR PORTION.



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email : contact@vfixauto.com.sg
Tel : 6448 9268 Fax: 6445 2368
UEN / GST Reg No. : 201830761R

ESTIMATE

DATE :
ACC DATE :
REF NO :
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :XD7022K VOLVO FMX420 YV2JG10G7DA740282

DESCRIPTION	AMOUNT S\$
1 1 FRONT WINDSCREEN <i>car</i>	1,470.00
2 1 FRONT WINDSCREEN RUBBER <i>car</i>	367.00
3 1 FRONT PANEL . ?	1,650.60
4 1 FRONT WIPER GARNISH <i>car</i>	796.00
5 2 FRONT WIPER SIDE GARNISH <i>car</i>	74.00 148.00
6 2 FRONT WIPER ARM <i>LH & RH-bl</i>	310.00 620.00
7 2 FRONT WIPER ARM COVER <i>car</i>	45.00 90.00
8 2 FRONT WIPER BLADE ?	76.00 152.00
9 1 BONNET <i>car</i>	3,200.00
10 1 BONNET GRILLE <i>car</i>	1,254.80
11 1 BONNET GRILLE BADGE <i>car</i>	124.00
12 1 BONNET GRILLE INNER GARNISH <i>car</i>	458.00
13 1 BONNET TOP CHROME PLATE <i>car</i>	790.00
14 1 BONNET TOP CHROME PLATE EMBLEM(FMX) <i>car</i>	120.00
15 2 BONNET HINGE <i>bl</i>	120.00 240.00
16 2 BONNET HINGE PULL HANDLE ?	120.00 240.00
17 2 BONNET LOCK(FEMALE) <i>LH-mis- RH &</i>	81.00 162.00
18 2 BONNET LOCK(MALE) <i>LH-bl- RH &</i>	<i>bl</i> 34.00 168.00
19 2 BONNET ABSORBER <i>LH-mis- RH-?</i>	178.00 356.00
20 1 FRONT CORNER PANEL LH <i>bl</i>	300.00
21 1 FRONT BUMPER <i>car</i>	4,043.40
22 1 FRONT BUMPER REINFORCEMENT ?	890.00
23 1 FRONT BUMPER TOP PAD ?	458.00
24 1 FRONT BUMPER TOP PAD CENTER GARNISH ?	245.00
25 1 FRONT BUMPER CENTER GRILLE <i>car</i>	487.90
26 1 FRONT BUMPER SIDE PAD ?	457.60
27 1 FRONT BUMPER LOWER PAD ?	475.00
28 1 FRONT BUMPER LOWER PAD OUTER COVER ?	326.50
29 1 FRONT BUMPER LOWER GRILLE <i>x</i>	475.00
30 1 FRONT BUMPER LOWER STEP PLATE <i>x</i>	370.00
31 1 FRONT BUMPER LOWER STEP PLATE TOP CHROME <i>x</i>	245.60
32 1 FRONT BUMPER TOWING COVER <i>mis-</i>	42.00
33 1 FRONT BUMPER FOG LAMP LH <i>x</i>	420.00
34 1 FRONT BUMPER FOG LAMP COVER LH <i>car</i>	120.00
35 1 FRONT SIDE BUMPER LH <i>x</i>	476.00
36 1 FRONT HEAD LAMP LH	375.00
37 1 FRONT HEAD LAMP RIM LH ?	195.70

38	1	FRONT PARKING LAMP LH		274.00
39	1	FRONT SIGNAL LAMP LH		252.00
40	1	CABIN FRONT SUPPORT PANEL	bt	670.00
41	1	CABIN ROLLER BAR		3,831.40
42	2	CABIN ROLLER HINGE	750.00	1,500.00
43	2	CABIN ROLLER HINGE BUSING	680.00	1,360.00
44	2	CABIN FRONT ABSORBER	LH-bt-RH-?	420.00
45	1	FRONT WIRING COVER	Ans	310.00
46	1	AIR CON CONDENSER	bt	1,540.00
47	2	AIR CON CONDENSER BRACKET	bt	120.00
48	1	CONDENSER AIR PIPE		378.90
49	1	CONDENSER SUCTION PIPE		285.00
50	1	CONDENSER DISCHARGE PIPE		294.30
51	1	CONDENSER DRYER		271.80
52	1	RADIATOR		2,622.50
53	1	TURBO INTERCOOLER		3,910.20
54	1	FRONT DOOR BOTTOM STEP GARNISH LH	old damage	450.00
55	1	FRONT DOOR BOTTOM STEP GARNISH SIDE COVER LH	old damage	680.00
56	1	HORN		74.50
57	1	FRONT AIR DUCT	Ans	476.00
58	1	FRONT DOOR PILLAR LH	RH	890.00
59	1	AIR CON BLOWER		2,500.00
60	1	AIR CON EVAPORATOR		1,545.00

\$ 48,004.70

LESS 10%

\$ 43,204.23

DESCRIPTIONS	UNIT PRICE	AMOUNT S\$
<u>SPECAIL NETT</u>		3061-
1 <u>FRONT NUMBER PLATE</u>		\$ 50.00

LABOUR & MISCELLANEOUS :	AMOUNT S\$
1 To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	1,800.00 1400
2 To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	1,600.00 1200
3 To remove, refit front windscreen	140.00 ✓
4 To remove, refit dash board and interior	650.00 300? photo
5 To remove, refit condenser and intercooler	550.00 450? photo
6 To remove, refit cabin	2,000.00 600
7 To check and refit wiring	600.00 300
8 To reset and diagnos failt code	1,200.00 200
	\$ 8,540.00

GRAND TOTAL : \$ 51,794.23

Vfix Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged partial during resurvey
- Parts price with 10% extra for confirmation
- Third party liability
- New/old accident
- Date of accident

Insurance Policy No. 123456789
Insurance Company: ABC Insurance Co. Ltd.

Accepted: _____
Signature: _____
Date: _____

[Signature]
8/5/19

Tangkh 97495349
91 7/5/19 1645
Revert, Not Authorise.

12 days
Ex\$1500
Lumpsum
Resurvey after repair
SURE/lkkauto.com

ESTIMATE

DATE :
ACC DATE :
REF NO :
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :XD7022K VOLVO FMX420 YV2JG10G7DA740282

DESCRIPTION	AMOUNT S\$
1 1 FRONT WINDSCREEN <i>car</i>	1,470.00 ✓
2 1 FRONT WINDSCREEN RUBBER <i>wh</i>	367.00 ✓
3 1 FRONT PANEL <i>X un</i>	1,650.60 X
4 1 FRONT WIPER GARNISH <i>car</i>	796.00 ✓
5 2 FRONT WIPER SIDE GARNISH <i>car</i>	74.00 148.00 ✓
6 2 FRONT WIPER ARM <i>LH-7, RH-bt</i>	310.00 ✓ 620.00
7 2 FRONT WIPER ARM COVER <i>car</i>	45.00 90.00 ✓
8 2 FRONT WIPER BLADE <i>X un</i>	76.00 152.00 X
9 1 BONNET <i>car</i>	3,200.00 ✓
10 1 BONNET GRILLE <i>car</i>	1,254.80 ✓
11 1 BONNET GRILLE BADGE <i>car</i>	124.00 ✓
12 1 BONNET GRILLE INNER GARNISH <i>car</i>	458.00 ✓
13 1 BONNET TOP CHROME PLATE <i>car</i>	790.00 ✓
14 1 BONNET TOP CHROME PLATE EMBLEM(FMX) <i>car</i>	120.00 ✓
15 2 BONNET HINGE <i>bt</i>	120.00 240.00 ✓
16 2 BONNET HINGE PULL HANDLE <i>? X un</i>	120.00 240.00 X
17 1/2 BONNET LOCK(FEMALE) <i>LH-mis, RH X un</i>	81.00 ✓ 162.00
18 1/2 BONNET LOCK(MALE) <i>LH-bt, RH X un</i>	34.00 ✓ 168.00
19 2 BONNET ABSORBER <i>LH-mis, RH-bt</i>	178.00 356.00 ✓
20 1 FRONT CORNER PANEL LH <i>bt</i>	300.00 ✓
21 1 FRONT BUMPER <i>car</i>	4,043.40 ✓
22 1 FRONT BUMPER REINFORCEMENT <i>bt</i>	890.00 ✓
23 1 FRONT BUMPER TOP PAD <i>? de</i>	458.00 ✓
24 1 FRONT BUMPER TOP PAD CENTER GARNISH <i>? de</i>	245.00 ✓
25 1 FRONT BUMPER CENTER GRILLE <i>car</i>	487.90 ✓
26 1 FRONT BUMPER SIDE PAD <i>? car</i>	457.60 ✓
27 1 FRONT BUMPER LOWER PAD <i>car</i>	475.00 ✓
28 1 FRONT BUMPER LOWER PAD OUTER COVER <i>bt</i>	326.50 ✓
29 1 FRONT BUMPER LOWER GRILLE <i>X un</i>	475.00 X
30 1 FRONT BUMPER LOWER STEP PLATE <i>X un</i>	370.00 X
31 1 FRONT BUMPER LOWER STEP PLATE TOP CHROME <i>X un</i>	245.60 X
32 1 FRONT BUMPER TOWING COVER <i>mis</i>	42.00 ✓
33 1 FRONT BUMPER FOG LAMP LH <i>X un</i>	420.00 X
34 1 FRONT BUMPER FOG LAMP COVER LH <i>car</i>	120.00 ✓
35 1 FRONT SIDE BUMPER LH <i>X un</i>	476.00 X
36 1 FRONT HEAD LAMP LH <i>X un</i>	375.00 X
37 1 FRONT HEAD LAMP RIM LH <i>X un</i>	195.70 X

38	1	FRONT PARKING LAMP LH	X		274.00	X un
39	1	FRONT SIGNAL LAMP LH	X		252.00	X un
40	1	CABIN FRONT SUPPORT PANEL	bt		670.00	✓
41	1	CABIN ROLLER BAR	bt		3,831.40	✓
42	2	CABIN ROLLER HINGE	X	750.00	1,500.00	X un
43	2	CABIN ROLLER HINGE BUSHING	X	680.00	1,360.00	X un
44	2	CABIN FRONT ABSORBER	LH - bt - RH - X un	420.00	840.00	✓
45	1	FRONT WIRING COVER	bt		310.00	✓
46	1	AIR CON CONDENSER	bt		1,540.00	✓
47	2	AIR CON CONDENSER BRACKET	bt	120.00	240.00	✓
48	1	CONDENSER AIR PIPE	?		378.90	X } X un
49	1	CONDENSER SUCTION PIPE	?		285.00	X }
50	1	CONDENSER DISCHARGE PIPE	?		294.30	X }
51	1	CONDENSER DRYER	?		271.80	X un
52	1	RADIATOR	?		2,622.50	bt
53	1	TURBO INTERCOOLER	?		3,910.20	bt
54	1	FRONT DOOR BOTTOM STEP GARNISH LH	✓ old damage		450.00	X un
55	1	FRONT DOOR BOTTOM STEP GARNISH SIDE COVER LH	X old damage		680.00	X un
56	1	HORN	?		74.50	X un
57	1	FRONT AIR DUCT	ans		476.00	✓
58	1	FRONT DOOR PILLAR LH	RH		890.00	X R
59	1	AIR CON BLOWER	? ans		2,500.00	✓
60	1	AIR CON EVAPORATOR	X		1,545.00	X un

	\$	48,004.70
LESS 10%	\$	43,204.23

34204.30
30783.87

DESCRIPTIONS	UNIT PRICE	AMOUNT S\$
<u>SPECIAL NETT</u>		307.87 ✓
1 <u>FRONT NUMBER PLATE</u>		\$ 50.00

LABOUR & MISCELLANEOUS :	AMOUNT S\$
1 To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	1,800.00 1400
2 To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	1200 1,600.00
3 To remove, refit front windscreen	✓ 140.00
4 To remove, refit dash board and interior	300? photo 650.00
5 To remove, refit condenser and intercooler	450? photo 550.00
6 To remove, refit cabin	600 ✓ 2,000.00
7 To check and refit wiring	300 ✓ 600.00
8 To reset and diagnos fault code	200 / 1,200.00
	4450 \$ 8,540.00

GRAND TOTAL : \$ 51,794.23

Vfix Auto Pte Ltd

307.83.87
30
4450
3556.80
38820.67
1/5 \$ 31,050 #
12 days

Tan Jiah 974915749
G1 7/5/19 1645
Revert, Not Authorise.
12 days
Ex \$1500
Lump sum
Repay after repair
SURE / hkauto.com

5928313



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email : contact@vfixauto.com.sg
Tel : 6448 9268 Fax: 6445 2368
UEN / GST Reg No. : 201830761R

ESTIMATE

DATE :
ACC DATE :
REF NO :
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :XD7022K VOLVO FMX420 SUPPLEMENTARY

DESCRIPTION	AMOUNT S\$
1 DASH BOARD LH	2,742.00
1 DASH BOARD RH	3,579.00
1 FRONT WIPER MOTOR	790.00
1 FRONT WIPER MOTOR LINK	1,210.00

3952
10% - 3556.80
\$ 8,321.00
LESS 10% \$ 7,488.90

DESCRIPTIONS	UNIT PRICE	AMOUNT S\$
<u>SPECAIL NETT</u>		

LABOUR & MISCELLANEOUS :	AMOUNT S\$
	\$ -

GRAND TOTAL : #REF!

Vfix Auto Pte Ltd

Handwritten signature
22/5/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 May 2019		06 May 2019 13:08 Edit Adj Rpt	S\$31,050.00 Edit Estimates	S\$31,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD , Co. Reg. No.: 199904117E								
Vehicle Reg. No.:	XD7022K	Date of Loss:	24/04/2019 18:00 - :59 [72 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D201836C01	Policy/Cover Note No.:	DMCVSN1804891901 (Comprehensive)						
		Excess:	S\$1,500.00						
Repairer:	Vfix Auto Pte Ltd (HQ) 26 Chia Ping Road, 619977 Boon Lay - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/05/2019]								
Driver/Custodian:	ZHAO JUNLIANG (50 / Male) , NRIC: G8230879U, Tel: +6590365563 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (21/11/2019): OWN DAMAGE CLAIM - CHINA_TAIPING (15/05/2019): Alert - Adj Mandate Approved (S\$43767.39) - XD7022K - Claim Handler: Chong Boon ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD7022K (SNM19D201836C01)

OD

Apr 24 2019 6:00PM

[KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD]

Vfix Auto Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)
View [View in Browser](#)

Assessment Reports				1 per page		
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print	
1	25/04/19 13:49	Accident Statement		Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	08/05/19 15:41	Adjuster Immediate Advice		Load HTM		
Photos/Images				3 per page		
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print	
1	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
2	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
3	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
4	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
5	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
6	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
7	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
8	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
9	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
10	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
11	25/04/19 13:47	Accident Photo [Linked Accident Report Documents]		Load JPG		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	08/05/19 15:05	Chassis Number		Load JPG		
2	08/05/19 15:05	Odometer Reading		Load JPG		
3	08/05/19 15:05	General View		Load JPG		
4	08/05/19 15:05	General View		Load JPG		
5	08/05/19 15:05	General View		Load JPG		
6	08/05/19 15:05	General View		Load JPG		
7	08/05/19 15:05	General View		Load JPG		
8	08/05/19 15:05	General View		Load JPG		
9	08/05/19 15:05	General View		Load JPG		
10	08/05/19 15:05	General View		Load JPG		
11	08/05/19 15:05	General View		Load JPG		
12	08/05/19 15:05	General View		Load JPG		
13	08/05/19 15:05	General View		Load JPG		
14	08/05/19 15:05	General View		Load JPG		
15	08/05/19 15:05	General View		Load JPG		
16	08/05/19 15:05	General View		Load JPG		
17	08/05/19 15:05	General View		Load JPG		
18	08/05/19 15:05	General View		Load JPG		
19	08/05/19 15:05	General View		Load JPG		
20	08/05/19 15:05	General View		Load JPG		
21	08/05/19 15:05	General View		Load JPG		
22	08/05/19 15:05	General View		Load JPG		
23	08/05/19 15:05	General View		Load JPG		
24	08/05/19 15:05	General View		Load JPG		

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Uhl)	Thumbnail	Print
25	08/05/19 15:05	General View		☒
26	08/05/19 15:05	General View		☒
27	08/05/19 15:05	General View		☒
28	08/05/19 15:05	General View		☒
29	08/05/19 15:05	General View		☒
30	08/05/19 15:05	General View		☒
31	08/05/19 15:05	General View		☒
32	08/05/19 15:05	General View		☒
33	08/05/19 15:05	General View		☒
34	08/05/19 15:05	General View		☒
35	08/05/19 15:05	General View		☒
36	08/05/19 15:05	General View		☒
37	08/05/19 15:05	General View		☒
38	08/05/19 15:05	General View		☒
39	08/05/19 15:05	General View		☒
40	08/05/19 15:05	General View		☒
41	08/05/19 15:05	General View		☒
42	08/05/19 15:05	General View		☒
43	08/05/19 15:05	General View		☒
44	08/05/19 15:05	General View		☒
45	08/05/19 15:05	General View		☒
46	08/05/19 15:05	General View		☒
47	08/05/19 15:05	General View		☒
48	08/05/19 15:05	General View		☒
49	08/05/19 15:05	General View		☒
50	08/05/19 15:05	General View		☒
51	08/05/19 15:05	General View		☒
52	08/05/19 15:05	General View		☒
53	08/05/19 15:05	General View		☒
54	08/05/19 15:05	General View		☒
55	08/05/19 15:05	General View		☒
56	08/05/19 15:05	General View		☒
57	08/05/19 15:05	General View		☒
58	08/05/19 15:05	General View		☒
59	08/05/19 15:05	General View		☒
60	08/05/19 15:05	General View		☒
61	08/05/19 15:05	General View		☒
62	08/05/19 15:05	General View		☒
63	08/05/19 15:05	General View		☒
64	08/05/19 15:05	General View		☒
65	08/05/19 15:05	General View		☒
66	08/05/19 15:05	General View		☒
67	08/05/19 15:05	General View		☒
68	08/05/19 15:05	General View		☒
69	08/05/19 15:05	General View		☒
70	08/05/19 15:05	General View		☒
71	08/05/19 15:05	General View		☒
72	08/05/19 15:05	General View		☒
73	08/05/19 15:05	General View		☒
74	08/05/19 15:05	General View		☒
75	08/05/19 15:05	General View		☒
76	08/05/19 15:05	General View		☒
77	08/05/19 15:05	General View		☒
78	08/05/19 15:05	General View		☒
79	08/05/19 15:05	General View		☒
80	08/05/19 15:05	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
81	08/05/19 15:05	General View		☒
82	08/05/19 15:05	General View		☒
83	08/05/19 15:05	General View		☒
84	08/05/19 15:05	General View		☒
85	08/05/19 15:05	General View		☒
86	08/05/19 15:05	General View		☒
87	08/05/19 15:05	General View		☒
88	08/05/19 15:05	General View		☒
89	08/05/19 15:05	General View		☒
90	08/05/19 15:05	General View		☒
91	08/05/19 15:05	General View		☒
92	08/05/19 15:05	General View		☒
93	08/05/19 15:05	General View		☒
94	08/05/19 15:05	General View		☒
95	08/05/19 15:05	General View		☒
96	08/05/19 15:05	General View		☒
97	08/05/19 15:05	General View		☒
98	08/05/19 15:05	General View		☒
99	08/05/19 15:05	General View		☒
100	08/05/19 15:05	General View		☒
101	08/05/19 15:05	General View		☒
102	08/05/19 15:05	General View		☒
103	08/05/19 15:05	General View		☒
104	08/05/19 15:05	General View		☒
105	08/05/19 15:05	General View		☒
106	08/05/19 15:05	General View		☒
107	08/05/19 15:05	General View		☒
108	08/05/19 15:05	General View		☒
109	08/05/19 15:05	General View		☒
110	08/05/19 15:05	General View		☒
111	18/11/19 14:07	Reinspection Photo		☒
112	18/11/19 14:07	Reinspection Photo		☒
113	18/11/19 14:07	Reinspection Photo		☒
114	18/11/19 14:07	Reinspection Photo		☒
115	18/11/19 14:07	Reinspection Photo		☒
116	18/11/19 14:07	Reinspection Photo		☒
117	18/11/19 14:07	Reinspection Photo		☒
118	18/11/19 14:07	Reinspection Photo		☒
119	18/11/19 14:07	Reinspection Photo		☒
120	18/11/19 14:07	Reinspection Photo		☒
121	18/11/19 14:07	Reinspection Photo		☒
122	18/11/19 14:07	Reinspection Photo		☒
123	18/11/19 14:07	Reinspection Photo		☒
124	18/11/19 14:07	Reinspection Photo		☒
125	18/11/19 14:07	Reinspection Photo		☒
126	18/11/19 14:07	Reinspection Photo		☒
127	18/11/19 14:07	Reinspection Photo		☒
128	18/11/19 14:07	Reinspection Photo		☒
129	18/11/19 14:07	Reinspection Photo		☒
130	18/11/19 14:07	Reinspection Photo		☒
131	18/11/19 14:07	Reinspection Photo		☒
132	18/11/19 14:07	Reinspection Photo		☒
133	18/11/19 14:07	Reinspection Photo		☒
134	18/11/19 14:07	Reinspection Photo		☒
135	18/11/19 14:07	Reinspection Photo		☒
136	18/11/19 14:07	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
137	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
138	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
139	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
140	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
141	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
142	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
143	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
144	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
145	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
146	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
147	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
148	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
149	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
150	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
151	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
152	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
153	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
154	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
155	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
156	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
157	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
158	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
159	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
160	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
161	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
162	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
163	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
164	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
165	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
166	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
167	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
168	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
169	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
170	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
171	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
172	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
173	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
174	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
175	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
176	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
177	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
178	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
179	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
180	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
181	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
182	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
183	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
184	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
185	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
186	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
187	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
188	18/11/19 14:07	Reinspection Photo	Load JPG	☒
189	18/11/19 14:07	Reinspection Photo	Load JPG	☒
190	18/11/19 14:07	Reinspection Photo	Load JPG	☒
191	18/11/19 14:07	Reinspection Photo	Load JPG	☒
192	18/11/19 14:07	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
193	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
194	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
195	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
196	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
197	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
198	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
199	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
200	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
201	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
202	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
203	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
204	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
205	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
206	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
207	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
208	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
209	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
210	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
211	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
212	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
213	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
214	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
215	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
216	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
217	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
218	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
219	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
220	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
221	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
222	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
223	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
224	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
225	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
226	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
227	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
228	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
229	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
230	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
231	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
232	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
233	18/11/19 14:07	Reinspection Photo	 Load JPG	☒
234	18/11/19 14:08	Reinspection Photo	 Load JPG	☒
235	18/11/19 14:08	Reinspection Photo	 Load JPG	☒
236	18/11/19 14:08	Reinspection Photo	 Load JPG	☒
237	18/11/19 14:08	Reinspection Photo	 Load JPG	☒
238	18/11/19 14:08	Reinspection Photo	 Load JPG	☒
239	18/11/19 14:08	Reinspection Photo	Load JPG	☒
240	18/11/19 14:08	Reinspection Photo	Load JPG	☒
241	18/11/19 14:08	Reinspection Photo	Load JPG	☒
242	18/11/19 14:08	Reinspection Photo	Load JPG	☒
243	18/11/19 14:08	Reinspection Photo	Load JPG	☒
244	18/11/19 14:08	Reinspection Photo	Load JPG	☒
245	18/11/19 14:08	Reinspection Photo	Load JPG	☒
246	18/11/19 14:08	Reinspection Photo	Load JPG	☒
247	18/11/19 14:08	Reinspection Photo	Load JPG	☒
248	18/11/19 14:08	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
249	18/11/19 14:08	Reinspection Photo		☒
250	18/11/19 14:08	Reinspection Photo		☒
251	18/11/19 14:08	Reinspection Photo		☒
252	18/11/19 14:08	Reinspection Photo		☒
253	18/11/19 14:08	Reinspection Photo		☒
254	18/11/19 14:08	Reinspection Photo		☒
255	18/11/19 14:08	Reinspection Photo		☒
256	18/11/19 14:08	Reinspection Photo		☒
257	18/11/19 14:08	Reinspection Photo		☒
258	18/11/19 14:08	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/05/19 13:08	OD ESTIMATE		☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/04/19 13:48	Accident Sketch Plan [Linked Accident Report Documents]		☒
2	25/04/19 13:48	Accident Sketch Plan [Linked Accident Report Documents]		☒
3	25/04/19 13:48	Accident Sketch Plan [Linked Accident Report Documents]		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/05/19 15:04	ESTIMATE		☒
2	02/12/19 10:13	Supplementary		☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/04/19 13:49	Accident Statement		☒
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/04/19 13:47	Accident Photo		☒
2	25/04/19 13:47	Accident Photo		☒
3	25/04/19 13:47	Accident Photo		☒
4	25/04/19 13:47	Accident Photo		☒
5	25/04/19 13:47	Accident Photo		☒
6	25/04/19 13:47	Accident Photo		☒
7	25/04/19 13:47	Accident Photo		☒
8	25/04/19 13:47	Accident Photo		☒
9	25/04/19 13:47	Accident Photo		☒
10	25/04/19 13:47	Accident Photo		☒
11	25/04/19 13:47	Accident Photo		☒
Documentation			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/04/19 13:48	Accident Sketch Plan		☒
2	25/04/19 13:48	Accident Sketch Plan		☒
3	25/04/19 13:48	Accident Sketch Plan		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19007912/T1QD3E2

Date: 02/12/2019

REFERENCE

Insured/Claimant: KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD

Policy No: DMCVSN1804891901

Date of Loss: 24/04/2019

Nature of Claim: OD

Claim No: SNM19D201836C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD7022K	Engine No:	D13379246
Make & Model:	VOLVO FMX420, 12.8 D (M)	Chassis No:	YV2JG10G7DA740282
Reg. Date:	10/04/2013 (Man. Year: 2012)	Odometer:	531783 km
Colour:	White		
Engine Capacity:	12777 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D)
Front Left Side:	Triangle 8 mm	Rear Left Side:	Triangle 8/8 mm
Front Right Side:	Triangle 8 mm	Rear Right Side:	Triangle 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,743.13	34,370.67	16,372.46	32.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,540.00	4,590.00	3,950.00	46.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	59,283.13	38,960.67	20,322.46	34.28
Approved Total (Overridden) (S\$)		31,050.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	57,783.13	29,550.00	28,233.13	48.86
+ GST 7.00/7.00% (S\$)	4,044.82	2,068.50	1,976.32	48.86
Nett Amount (S\$)	61,827.95	31,618.50	30,209.45	48.86

INSPECTION

Date of Assignment: 06/05/2019

Date Inspected: 07/05/2019 Inspected At:

26 Chia Ping Road
Repairer : Vfix Auto Pte Ltd (HQ)

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Dec 2019)	
Parts:	N/A	VOLVO FMX420 12.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD7022K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	1,470.00 FL	*1,470.00 FL
2	1		*FRONT WINDSCREEN RUBBER	Necessary	367.00 FL	*367.00 FL
3	1		*FRONT PANEL	Not Necessary	1,650.60 FL	*- FL
4	1		*FRONT WIPER GARNISH	Cracked	796.00 FL	*796.00 FL
5	2		*FRONT WIPER SIDE GARNISH	Cracked	148.00 FL	*148.00 FL
6	2		*FRONT WIPER ARM	O/S Bent / N/S Not Necessary	620.00 FL	*310.00 FL
7	2		*FRONT WIPER ARM COVER	Cracked	90.00 FL	*90.00 FL
8	2		*FRONT WIPER BLADE	Not Necessary	152.00 FL	*- FL
9	1		*BONNET	Cracked	3,200.00 FL	*3,200.00 FL
10	1		*BONNET GRILLE	Cracked	1,254.80 FL	*1,254.80 FL
11	1		*BONNET GRILLE BADGE	Cut	124.00 FL	*124.00 FL
12	1		*BONNET GRILLE INNER GARNISH	Cracked	458.00 FL	*458.00 FL
13	1		*BONNET TOP CHROME PLATE	Cracked	790.00 FL	*790.00 FL
14	1		*BONNET TOP CHROME PLATE EMBLEM (FMX)	Necessary	120.00 FL	*120.00 FL
15	2		*BONNET HINGE	Bent	240.00 FL	*240.00 FL
16	2		*BONNET HINGE PULL HANDLE	Not Necessary	240.00 FL	*- FL
17	1		*BONNET LOCK (FEMALE)	N/S Missing / N/S Not Necessary	162.00 FL	*81.00 FL
18	1		*BONNET LOCK (MALE)	N/S Bent / N/S Not Necessary	168.00 FL	*34.00 FL
19	2		*BONNET ABSORBER	N/S Missing / O/S Bent	356.00 FL	*356.00 FL
20	1		*FRONT CORNER PANEL LH	Bent	300.00 FL	*300.00 FL
21	1		*FRONT BUMPER	Cracked	4,043.40 FL	*4,043.40 FL
22	1		*FRONT BUMPER REINFORCEMENT	Bent	890.00 FL	*890.00 FL
23	1		*FRONT BUMPER TOP PAD	Deformed	458.00 FL	*458.00 FL
24	1		*FRONT BUMPER TOP PAD CENTER GARNISH	Deformed	245.00 FL	*245.00 FL
25	1		*FRONT BUMPER CENTER GRILLE	Cut	487.90 FL	*487.90 FL
26	1		*FRONT BUMPER SIDE PAD	Cut	457.60 FL	*457.60 FL
27	1		*FRONT BUMPER LOWER PAD	Cut	475.00 FL	*475.00 FL
28	1		*FRONT BUMPER LOWER PAD OUTER COVER	Bent	326.50 FL	*326.50 FL
29	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	475.00 FL	*- FL
30	1		*FRONT BUMPER LOWER STEP PLATE	Not Necessary	370.00 FL	*- FL
31	1		*FRONT BUMPER LOWER STEP PLATE TOP CHROME	Not Necessary	245.60 FL	*- FL
32	1		*FRONT BUMPER TOWING COVER	Missing	42.00 FL	*42.00 FL
33	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	420.00 FL	*- FL
34	1		*FRONT BUMPER FOG LAMP COVER LH	Cut	120.00 FL	*120.00 FL
35	1		*FRONT SIDE BUMPER LH	Not Necessary	476.00 FL	*- FL
36	1		*FRONT HEAD LAMP LH	Not Necessary	375.00 FL	*- FL
37	1		*FRONT HEAD LAMP RIM LH	Not Necessary	195.70 FL	*- FL
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*FRONT PARKING LAMP LH	Not Necessary	274.00 FL	*- FL
39	1		*FRONT SIGNAL LAMP LH	Not Necessary	252.00 FL	*- FL
40	1		*CABIN FRONT SUPPORT PANEL	Bent	670.00 FL	*670.00 FL
41	1		*CABIN ROLLER BAR	Bent	3,831.40 FL	*3,831.40 FL
42	2		*CABIN ROLLER HINGE	Not Necessary	1,500.00 FL	*- FL
43	2		*CABIN ROLLER HINGE BUSHING	Not Necessary	1,360.00 FL	*- FL
44	1		*CABIN FRONT ABSORBER	N/S Bent / O/S Not Necessary	840.00 FL	*420.00 FL
45	1		*FRONT WIRING COVER	Cracked	310.00 FL	*310.00 FL
46	1		*AIR CON CONDENSER	Bent	1,540.00 FL	*1,540.00 FL
47	2		*AIR CON CONDENSER BRACKET	Bent	240.00 FL	*240.00 FL
48	1		*CONDENSER AIR PIPE	Not Necessary	378.90 FL	*- FL
49	1		*CONDENSER SUCTION PIPE	Not Necessary	285.00 FL	*- FL
50	1		*CONDENSER DISCHARGE PIPE	Not Necessary	294.30 FL	*- FL
51	1		*CONDENSER DRYER	Not Necessary	271.80 FL	*- FL
52	1		*RADIATOR	Bent	2,622.50 FL	*2,622.50 FL
53	1		*TURBO INTERCOOLER	Dented	3,910.20 FL	*3,910.20 FL
54	1		*FRONT DOOR BOTTOM STEP GARNISH LH (NOT NECESSARY)	Old Damaged	450.00 FL	*- FL
55	1		*FRONT DOOR BOTTOM STEP GARNISH SIDE COVER LH (NOT NECESSARY)	Old Damaged	680.00 FL	*- FL
56	1		*HORN	Not Necessary	74.50 FL	*- FL
57	1		*FRONT AIR DUCT	Cracked	476.00 FL	*476.00 FL
58	1		*FRONT DOOR PILLAR LH	Repair	890.00 FL	*- FL
59	1		*AIR CON BLOWER	Cracked	2,500.00 FL	*2,500.00 FL
60	1		*AIR CON EVAPORATOR	Not Necessary	1,545.00 FL	*- FL
61	1		*DASH BOARD LH	Cracked	2,742.00 FL	*2,742.00 FL
62	1		*DASH BOARD RH	Not Necessary	3,579.00 FL	*- FL
63	1		*FRONT WIPER MOTOR	Not Necessary	790.00 FL	*- FL
64	1		*FRONT WIPER MOTOR LINK	Cracked	1,210.00 FL	*1,210.00 FL
65	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 56,375.70 38,186.30
 - List Item Discount on L Items 10.00/10.00% (\$\$) 5,632.57 3,815.63

Total Parts (\$\$) 50,743.13 34,370.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED BODY PANEL WITH ALL NECESSARY COMPONENTS/ ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT DOOR PILLAR, REPAIR/ RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS/ ATTACHMENTS.	New	1,800.00	1,400.00
2	TO SPRAY PAINT REPLACED/ REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.	New	1,600.00	1,200.00
3	TO REMOVE, REFIT FRONT WINDSCREEN.	New	140.00	140.00
4	TO REMOVE, REFIT DASH BOARD AND INTERIOR.	New	650.00	300.00
5	TO REMOVE, REFIT CONDENSER AND INTERCOOLER.	New	550.00	450.00
6	TO REMOVE, REFIT CABIN.	New	2,000.00	600.00
7	TO CHECK AND REFIT WIRING.	New	600.00	300.00
8	TO RESET AND DIAGNOS FAULT CODE.	New	1,200.00	200.00
Gross Labour Cost (S\$)			8,540.00	4,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >