

12/03/2013

ASS. REC. BY:

REF: CS/SMO190079171 Nvd3

Special Instruction:

Surveyor:

NAZ

ASSIGNMENT (Office)

From (Person): Hwang Shiang Yi

of SMO

Date/Time: 6.5.19 13.46 PM

Estimated Cost: Bill to:

OD/REP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 5794 D

Insured: FBG 8211U

at Workshop m/s SMRT Automotive

Tel: 68662671

of NO 61 woodlands Industrial Park Ea, #04-04

Policy No: D19MTMCO1000001

Claim No: CMTD190079

Sum Insured:

Excess:

Make of Veh:

D.O.A. 3.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 6.5.19 1.58p.m

Person Contacted: shanti

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	SHB 5794D - CC3/AIG/160156 01/KY9392		
	FBG 8211U - X		
7/5/19	Send preli revised via merimen		

D.O.A - 18/08/2016

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 May 2019		06 May 2019 13:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ABDOL RAHIM BIN ZAIN, ID: S0032337C		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHB5794D	Date of Loss:	03/05/2019 14:00 - :59
Claim Type:	TP / CMTD1902179	Policy/Cover Note No.:	D19MTMC01000001 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	FBG8211U	Policy No. (Claimant):	
		Excess:	
Repairer:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:		
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2019]		
Adj Asg. Remarks:	WS: SHANTI 6866 2671/2 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Hwang Shiang Yi	Date: 07 May 2019

Preliminary Advice

Insured Vehicle No	: FBG8211U	Accident Date	: 03/05/2019
TP Vehicle No	: SHB5794D	Assignment Date	: 06/05/2019
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 2
Date of Inspection	: 6/5/2019		
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,597.95
Revised Amount	:S\$	2,188.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,188.60
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ Other comments : The above survey was conducted on a 'Without Prejudice' basis.

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 6 May, 2019 1:43 PM
To: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis); 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis); Koo Yew Chung (Auto Svcs/ARC/AR & SC); Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis); Grace Ng Siu Ching (Auto Svcs/ARC/AR & SC/Taxis); 'limkhachiew@smrt.com.sg'; Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis); Hwang, Shiang Yi; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1902179/SYH - LKK/ FBG8211U(nr) & SHB5794D ACC ON 03.05.19

Without Prejudice

Our Reference: CMTD1902179/SYH
Your Reference: SHB5794D

Hi Shanti,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case.

Please be informed, we have appointed **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SHB5794D on a without Prejudice and any admission of liability basis.

Please submit your report via Merimen upon completion of survey

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) [mailto:BThaiyalN@smrt.com.sg]

Sent: Monday, May 06, 2019 12:48 PM

To: 'motorsurvey@sompo.com.sg'

Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis); Koo Yew Chung (Auto Svcs/ARC/AR & SC); Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis); Grace Ng Siu Ching (Auto Svcs/ARC/AR & SC/Taxis); Lim Kha Chiew (Auto Svcs/ARC/AR & SC/Taxis); Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis)

Subject: RE:SHB5794D - Sompo Insurance

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHB5794D** within 48 hours according to GIA guide line, involving your insured **FBG8211U**

Vehicle in Woodlands Depot

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/05/2019 10:24
Date Of Accident	03/05/2019 14:30
Exact Location Of Accident	BUKIT TIMAH ROAD TOWARDS WOODLANDS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5794D
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	TAN SIEW TECK
NRIC No	S1804110C
Date Of Birth	08/12/1967
Occupation	OUTDOOR
Date Of Driving Pass	12/05/1988
Driving Experience	30 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG BUKIT TIMHA ROAD TOWARDS WOODLANDS WITH ONE PASSENGER (FEMALE CAUCASIAN) ON BOARD. SUDDENLY I FELT AN IMPACT AT THE RIGHT WING MIRROR AND A MOTORCYCLE AND THE RIDER FELL INFRONT ON MY TAXI. AFTER ALIGHTED I REALISED THAT THE MOTORCYCLE HIT ONTO A COMFORT TAXI SHA3671T WHICH WAS TRAVELLING ON MY RIGHT BEFORE HITTING ONTO MY TAXI. TRAFFIC POLICE AND AMBULANCE WERE AT THE SCENE BUT NO ONE WAS CONVEYED TO THE HOSPITAL

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBG8211U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	ABDUL RAHIM BIN ZAIN
NRIC/Passport Number	S0032337C
Contact Number	
Address	

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHA3671T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHA3671T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

4-5-2019

Khem Hock Rd

A - SHB 5794 D

B-FBG 82114

C-SHA 3671 T

Duncarn RD \rightarrow City

Woodland

Bukit Timah Rd

Bukit Timah Rd

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB5794D
Vehicle to be Exported:	No
Intended Deregistration Date:	07 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS110809
Chassis No.:	JTDKB3FU203575939
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$28,155.00
Total Rebate Amount:	\$31,905.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 May 2019

OK



Case Details

Case Reference Number : TAX/05/19/2017

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5794D

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-6754-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : Sompo Insurance Singapore

Pte. Ltd

Accident Date and Time : 03/05/2019 06:30 AM

Vehicle Age(In Months) : 17

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOC Type	Costing Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	0	0	Not Given	SUL
One Time Key In	Main			UNIT, HEADLAMP, RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Not Given	SUL
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	R
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace	NFC
One Time Key In	Main			COVER SUB- ASSY, FRONT PILLAR, UPR RH	1	96.90	96.90	25.00	72.68	Replace	0	0	Not Given	SUL
One Time Key In	Main			PANEL SUB- ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	0	Repair	R
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	NFC
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW, RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	1	1,236.15	Replace	CCR
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	1	67.13	Replace	CRK
									Total Spare Part Cost	5,812.95				
									Lump Sum Discount (%)	0.00				
									Final Spare Part Cost	5,812.95				
												Surveyor Total	1,428.60	
												Lump Sum Dis (%)	0	
												Final Sur Total	1,428.60	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	200	
Total:			845.00	200.00	

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	0	NN
2	Main	TO REPSRAY FRONT FENDER RH	378.00	200	
Total:			1,314.00	450.00	

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
4	Main	TO RESPRAY VIEW MIRROR	180.00	50	
Total:			1,314.00	450.00	

Other Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
4	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	NN
5	Main	TO REMOVE AND REFIX WING MIRROR	120.00	40	
6	Main	TO WASH AND VACUUM	60.00	0	NN
Total:			616.00	110.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	5,812.95	1,425.60
Total Labour Cost	845.00	200.00
Total Spray Painting	1,314.00	450.00
Other	616.00	110.00
Overall Total	8,587.95	2,185.60
Lump Sum Repair Option		
Lump Sum Total	0.00	2,185.60
Surveyor Approved Amount		2,185.60
No of Repair Days*	5	2
Remarks		PART BY PART REPAIR 2 DAYS BEFORE PAINT PHOTOS
Surveyor Name		NAZ
Signature		

Survey Date

06/05/2019

NAZ LKK

PIP 1

20mm

B4 PAINT PHOTO

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:



Section A - Accident Details

Registration Number	SHB5794D
Case Reference Number	TAX/05/19/2017
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN SIEW TECK
Type of Accident	Side Swipe
Accident Date and Time	3/5/2019 2:30 PM
Accident Reported Date and Time	4/5/2019 10:42 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101363
Special Instruction to ARC, if any	TOWED \$40/TP SOMPO
Prepared Date and Time	6/5/2019 8:55 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



p/s

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$200.00
Total Spray Cost	\$1,314.00	\$450.00
Total Spare Part Cost	\$5,812.95	\$1,428.61
Total Other Cost	\$616.00	\$150.00
TOTAL COST	\$8,587.95	\$2,228.61 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Naz (LKK) / Sompo
ARC / Surveyor Sign Off Date	06/05/2019 10:57 AM	06/05/2019 3:46 PM
Signature		
Remarks	PART BY PART REPAIR 2 DAYS BEFORE PAINT PHOTOS	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1905-0177	Invoice Number	
Quotation Date	09.05.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$200.00
Total Labour	\$845.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$1,314.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$55.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$40.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$615.00	\$150.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	0.00	\$495.50	0.00	\$0.00	Replace	Not Given X
		81145476 91	UNIT, HEADLAMP, RH	0.00	\$2,558.90	0.00	\$0.00	Replace	Not Given X
		53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair x f
		75310470 60	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.33	Replace	Replace
		60117470 20	COVER SUB-ASSY, FRONT PILLAR, UPR RH	0.00	\$96.90	0.00	\$0.00	Replace	Not Given X
		67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair x f
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		87910474 50	MIRROR ASSY, OUTER REAR VIEW, RH	1.00	\$1,373.50	10.00	\$1,236.15	Replace	Replace
		87915470 70A1	COVER, OUTER MIRROR, RH	1.00	\$89.50	25.00	\$67.13	Replace	Replace
Total					\$6,944.10		\$1,428.61		

1428.61
+ 200.00
+ 600.00
2228.61 / 2 days

FINALIZED PART BY PART REPAIR \$ 2228.61 / 2 REPAIR DAYS

Veron Chen (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 24 July 2019 9:10 AM
To: Naz (LKKAUTO)
Cc: SUR; Veron Chen (LKKAUTO)
Subject: RE: SHB 5794D FINALIZATION

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

From: Naz (LKKAUTO) [mailto:Naz@lkkauto.com]
Sent: Tuesday, 23 July 2019 5:59 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Cc: SUR; Veron Chen (LKKAUTO)
Subject: Re: SHB 5794D FINALIZATION

Dear Ms Yeo,

Finalized Part by Part Repair \$2228.61 / 2 Repair Days subject to insurance approval.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 23 July 2019 8:47 AM
To: Naz (LKKAuto) <Naz@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; SUR <sur@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Subject: FW: SHB5794D

Hi Naz,

I still pending for your finalization since May 2019.

Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Sent: Thursday, 9 May 2019 10:51 AM
To: 'Naz (LKKAuto)'
Cc: SUR; CS A Team
Subject: SHB5794D

Hi Naz,

Attached herewith the repair estimate of SHB 5794D having Case No: TAX/05/19/2017.

There is no change to the approved amount of \$2,228.61 @ 2 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Sent: Thursday, 9 May 2019 10:47 AM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: Scan Data from FX-D421D6

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 May 2019		06 May 2019 13:46 Edit Adj Rpt	S\$2,228.61 Edit Estimates	S\$2,228.61 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ABDOL RAHIM BIN ZAIN, ID: S0032337C			
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K			
Vehicle Reg. No.:	SHB5794D	Date of Loss:	03/05/2019 14:00 - :59 [16 Months and 21 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / CMTD1902179	Policy/Cover Note No.:	D19MTMC01000001 (TP, Fire & Theft)	
Vehicle Reg. No. (Insured):	FBG8211U	Policy No. (Claimant):		
		Excess:		
Repairer:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 15/05/2019]			
Adj Asg. Remarks:	WS: SHANTI 6866 2671/2 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHB5794D (CMTD1902179)**
[FBG8211U]

TP

SMRT TAXIS PTE LTD

May 3 2019 2:00PM

[ABDOL RAHIM BIN ZAIN]

Smrt Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼



No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/19 13:31	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page ▼



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/19 12:00	General View	Load JPG	
2	07/05/19 12:00	General View	Load JPG	
3	07/05/19 12:00	General View	Load JPG	
4	07/05/19 12:00	General View	Load JPG	
5	07/05/19 12:00	General View	Load JPG	
6	07/05/19 12:00	General View	Load JPG	
7	07/05/19 12:00	General View	Load JPG	
8	07/05/19 12:00	General View	Load JPG	
9	07/05/19 12:00	General View	Load JPG	
10	07/05/19 12:00	General View	Load JPG	
11	07/05/19 12:00	General View	Load JPG	
12	07/05/19 12:00	General View	Load JPG	
13	07/05/19 12:00	General View	Load JPG	
14	23/07/19 18:01	Replacement Part Photo	Load JPG	
15	23/07/19 18:01	Replacement Part Photo	Load JPG	
16	23/07/19 18:01	Replacement Part Photo	Load JPG	
17	23/07/19 18:01	Replacement Part Photo	Load JPG	
18	23/07/19 18:01	Replacement Part Photo	Load JPG	
19	23/07/19 18:02	Replacement Part Photo	Load JPG	
20	23/07/19 18:02	Replacement Part Photo	Load JPG	
21	23/07/19 18:02	Replacement Part Photo	Load JPG	
22	24/07/19 12:55	Reinspection Photo	Load JPG	
23	24/07/19 12:55	Reinspection Photo	Load JPG	
24	24/07/19 12:55	Reinspection Photo	Load JPG	
25	24/07/19 12:55	Reinspection Photo	Load JPG	
26	24/07/19 12:55	Reinspection Photo	Load JPG	

Documentation

1 per page ▼



No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	06/05/19 13:44	TP - GIA	Load PDF	
2	06/05/19 13:44	TP - ACK+ASSIGN LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007917/NVD3S2

Date: 29/07/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTMC01000001
Claimant Vehicle No :	SHB5794D	Insured Vehicle No :	FBG8211U
Date of Loss:	03/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902179

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5794D	Engine No:	2ZRS110809
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU203575939
Reg. Date:	12/12/2017 (Man. Year: 2017)	Odometer:	195000 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R16	Rear Tyre Size:	195/65R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,944.10	1,428.61	5,515.49	79.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,775.00	800.00	1,975.00	71.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,719.10	2,228.61	7,490.49	77.07

INSPECTION

Date of Assignment:	06/05/2019	Smrt Automotive Services Pte Ltd (HQ)
Date Inspected:	06/05/2019 Inspected At:	No. 61 Woodlands Industrial Park E9, #04-04 Premium Building
Estimated Period of Repair:	2.0 days	Singapore 757047

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB5794D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM ASSY FRONT (DISC 25%)	Necessary	87.10 F	*65.33 F
2	1		*COVER, OUTER MIRROR, RH (DISC 25%)	Cracked	89.50 F	*67.13 F
3	1		*MIRROR ASSY, OUTER REAR VIEW, RH (DISC 10%)	Cracked	1,373.50 F	*1,236.15 F
4	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
5	1		*COVER, FR BUMPER	Serviceable	495.50 F	*- F
6	1		*UNIT, HEADLAMP, RH	Serviceable	2,558.90 F	*- F
7	1		*COVER SUB-ASSY, FRONT PILLAR, UPR RH	Serviceable	96.90 F	*- F
8	1		*FENDER SUB-ASSY, FR RH	Repair	933.10 F	*- F
9	1		*PANEL SUB-ASSY, FRONT DOOR RH	Repair	1,249.60 F	*- F
					Total Parts (S\$)	6,944.10 1,428.61

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	845.00	200.00
2	SPRAY PAINT.	New	1,314.00	450.00
3	TOWING CHARGE.	New	56.00	40.00
4	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	40.00
6	TO REMOVE AND REFIT WIRE HARDESS.	New	200.00	0.00
7	TO REMOVE AND REFIX WING MIRROR.	New	120.00	40.00
8	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (\$\$)			2,775.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >