

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 06/05/2019
TP Vehicle No. : SLV-4196-J
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : PACIFICA FOODS PTE. LTD.
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5097524363-01
Vehicle No. : GBC-8751-Z
Make & Model : NISSAN NV350 PANEL VAN A/T EURO 5 2.5 G (A)

Accident Date: 02/05/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

Nett Item

1	TAILGATE	body \$1,850.00	—
1	TAILGATE EMBLEM "NV350"	new \$150.30	—
1	TAILGATE LOGO	new \$65.70	—
1	TAILGATE CHROME GARNISH BASE	new \$585.60	X
1	TAILGATE LOCK	new \$350.60	2
1	TAILGATE LOCK CATCH	new \$150.60	X
1	TAILGATE STEP PANEL	new \$215.60	2
1	REAR STEP PANEL GARNISH	NS \$185.60	X
1	REAR BUMPER	new \$750.60	—
1	REAR BUMPER BRACKET LH	new \$95.60	X
1	REAR BUMPER BRACKET RH	new \$95.60	X
10	REAR BUMPER CLIPS	new \$50.00	—
1	RH REAR FENDER	new \$2,680.90	X
1	RH TAILLAMP	new \$250.80	X
1	LH TAILLAMP	new \$250.80	X
1	REAR WINDSCREEN MOULDING	NS \$215.60	X
Sub Total		\$7,943.90	
Discount 10% on Parts		(\$794.39)	
		\$7,149.51	

Special Nett

1	REAR WINDSCREEN SEALANT	new \$65.00	40
1	REAR BUMPER REVERSE SENSOR	new \$450.00	200
Sub Total		\$515.00	

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$2,000.00	1000
TO SPRAY PAINT ON AFFECTED AREAS	\$2,000.00	1000
TO CHECK LIGHTING AND FOCUS TAILLAMP	\$150.00	30
TO TRANSFER OLD TAILGATE PARTS TO NEW TAILGATE.	\$150.00	60

Date : 06/05/2019
TP Vehicle No. : SLV-4196-J
To : **AIG ASIA PACIFIC INSURANCE PTE LTD**
Attn : **Motor Claim Department**

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : PACIFICA FOODS PTE. LTD.
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5097524363-01
Vehicle No. : GBC-8751-Z
Make & Model : NISSAN NV350 PANEL VAN A/T EURO 5 2.5 G (A)

Accident Date: 02/05/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	TO REMOVE AND REFX REVERSE SENSOR AND WIRING	\$150.00	50
	TO TRANSFER REAR WINDSCREEN FITTING	\$150.00	120
	Sub Total	\$4,600.00	

Sub Total \$12,264.51
GST 7% \$858.52
Total \$13,123.03

LKK Auto Consultant hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: