

22/03/2011

ASS. REC. BY:

REF: CS/CT119007920/AT d3n2

Special Instruction:

Summary: 6389 630 ASSIGNMENT (Office)

From (Person): Elaine Cheong of CT1 Date/Time: 13/5/2019 1.20 p.m.

Estimated Cost: Bill to:

OD-TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SCQ 31K Insured: GY 268E

at Workshop m/s Sin Y. Sin Tel: 9199 3103

of 11calci Bulciff Ave 6 # 01-52

Policy No: Claim No: SNM190201894

Sum Insured: Excess:

Make of Veh: D.O.A. 28.4.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time 13/5/2019 1 Person Contacted: Wei Lung H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (✓)
	SCQ 31-X
	GY 268E - MA/INC 08015520 / TITIHI DCA-2310571008
	lump sum \$4,900 - (Red 7074.50, 59%)

08/11/19

Surveyor

Adnan

REF:

C71

ASSIGNMENT

From:

Date:

14/05/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SCQ 31K

at Workshop m/s

Sin Yu Sin Wksp

of

1 Kaki Bukit Ave 6 #01-52

Insured:

Autobay @ Kaki Bukit

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Wei Kang @ 9199 3103

@ after 10.30am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SCQ 31K

Yr Regn: 2016 / Jan.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Jaguar XE

c.c 1999

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

54530

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SA JAB4AN76A 926014

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/35R19

R:

245/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

14/05/19

Survey held at

Sin Yu Sin

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Chm.

RECEIVED 21 JUN 2019

Date/Time, File Pass to?



: Preli. Report

1) H16 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

Report Format :

TP

* Lump Sum / I.B.I. (\$

4900/-

220

Nivitha (LKK Auto)

From: Accident@kscgp.com
Sent: Monday, 13 May 2019 3:31 PM
To: elaine.cheong@sg.cntaiping.com; sur@lkkauto.com; assignments@lkkauto.com
Cc: paul.ong@wearnes.com
Subject: RE: OUR REF: SNM19D201894 -GY268E - Notice to conduct pre-repairsurvey (Your Ref: GY 268E; Our Ref: SCQ 31K/WL/ca/ws)
Attachments: 2nd PRS.pdf

Dear Elaine,

We refer to the above matter and to our earlier tele-conversation today.

Please find enclosed herein a copy of our 2nd Notice of Pre-Repair Inspection. As spoken, our client is agreeable to using Adrian Ling from LKK Auto Consultants Pte Ltd as the Single Joint Expert.

The workshop details are as follows:-

Sin Yu Sin Workshop
1 Kaki Bukit Avenue 6
#01-52 Autobay @ Kaki Bukit
Singapore 417883

Contact person: Wei Leang (Tel: 9199 3103)

Adrian
14/5/19

Thank you.

Regards,
Candice
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Elaine Cheong [mailto:elaine.cheong@sg.cntaiping.com]
To: Accident@kscgp.com,sur@lkkauto.com,assignments@lkkauto.com
Cc: paul.ong@wearnes.com

Sent: Mon, 13 May 2019 04:01:08 +0000

Subject:

WITHOUT PREJUDICE

Dear Wan Sim,

We refer to your email of 10.05.19.

Since we have previously assigned M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle at Wearnes Automotive, we will be assigning the same surveyor to survey your client's vehicle.

Please advise name of workshop & advise our surveyor accordingly.

Aside to LKK,

Please refer email below and liaise with TP solicitor on survey.

Thank you.

Regards,

Elaine Cheong

Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com

From: Claims Dept of CTI

Sent: Friday, 10 May, 2019 12:06 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Accident@kscgp.com; Chee So Chow
<sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; SUR <sur@lkkauto.com>;
paul.ong@wearnes.com

Subject: OUR REF: SNM19D201894 -GY268E - Notice to conduct pre-repair survey (Your Ref: GY 268E; Our Ref: SCQ
31K/WL/ca/ws)

Dear Elaine,

URGENT

We have received PRS from KSCG on even date.

Please look into this case urgently, you have already appointed LKK to conduct PRS when received f Third Party from Wearnes on 30.4.2019

Regards

Angie Foo

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896186 - F: (65) 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Accident@kscgp.com [<mailto:Accident@kscgp.com>]

Sent: Friday, 10 May, 2019 9:40 AM

To: Claims Dept of CTI

Subject: Notice to conduct pre-repair survey (Your Ref: GY 268E; Our Ref: SCQ 31K/WL/ca/ws)

Dear Sirs,

We enclose herewith our 1st Notice to conduct pre-repair survey for your necessary action.

Thank you.

Regards,

Wan Sim

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Catherine Chong (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Monday, 6 May, 2019 1:20 PM
To: Paul Ong Qing Yong; 'assignments'
Subject: RE: TP Claim - SCQ31K; TP Vehicle GY268E DOA 28/04/2019 (SNM19D201894C02/8)
Attachments: FW: TP Claim - SCQ31K; TP Vehicle GY268E DOA 28/04/2019 (1.32 MB)
Sensitivity: Confidential

WITHOUT PREJUDICE

Dear Paul,

We refer to your email of 06.05.19.

Our insured have yet to report the accident to us.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please refer email below and proceed to survey the third party vehicle.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Paul Ong Qing Yong [mailto:paul.ong@wearnes.com]
Sent: Monday, 6 May, 2019 11:45 AM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Subject: Re: TP Claim - SCQ31K; TP Vehicle GY268E DOA 28/04/2019 (SNM19D201894C02/8)
Sensitivity: Confidential

Please assign
XING QUO QIANG

Paul Ong
Service Consultant
Bodyshop & Paint

Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Elaine Cheong
Sent: Monday, 6 May, 11:41
Subject: RE: TP Claim - SCQ31K; TP Vehicle GY268E DOA 28/04/2019 (SNM19D201894C02/8)
To: Paul Ong Qing Yong

WITHOUT PREJUDICE

Dear Paul,

We refer to your email of 30.04.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING

| Kelvin Ang |

| SEE CHEW SENG |

MOHD FADHILAH BIN
OSMAN

| XING QUO QIANG |

KENNETH KONG

| SIMON HO |

| CHUA WEIJIE |

MARCUS CHUA

HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower

Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Claims Dept of CTI
Sent: Tuesday, 30 April, 2019 3:30 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Cc: Angie Foo <angie.foo@sg.cntaiping.com>
Subject: FW: TP Claim - SCQ31K; TP Vehicle GY268E DOA 28/04/2019
Importance: High
Sensitivity: Confidential

Dear Elaine,

Please conduct PRS – TP: SCQ31K (SNM19D201894) soonest possible.
The file is with you.

From: Paul Ong Qing Yong [<mailto:paul.ong@wearnes.com>]
Sent: Tuesday, 30 April 2019 3:04 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: TP Claim - SCQ31K; TP Vehicle GY268E DOA 28/04/2019
Importance: High
Sensitivity: Confidential

Attached for TP Claim,

Please advise if can do direct settlement .

Paul Ong

Service Consultant

Bodyshop & Paint



WEARNES

Wearnes Automotive Pte Ltd

249 Alexandra Road Singapore 159935

M

(65) 8126 1237

D

(65) 6378 9336

(65) 6473 1488

F

(65) 6430 4702

D

(65) 1234 5678

M

(65) 1234 5678

www.wearnesauto.com

paul.ong@wearnes.com

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2019 10:27
Date Of Accident	28/04/2019 17:15
Exact Location Of Accident	JALAN EUNOS BETWEEN LAMP POST 16 & 18
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCQ31K
Insured/Policyholder	
Name Of Registered Owner	LIEWW YUEN HUA
NRIC No	S1418890H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96161661
Alternative Phone No	OFFICE-96161661

Vehicle Particulars

Manufacturer	JAGUAR
Model	XE-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0021178-MVA
Cover Note Number	

Driver

Name of Driver	FOK CHEN MENG
NRIC No	S2510291F
Date Of Birth	04/05/1961
Occupation	INDOOR
Date Of Driving Pass	25/06/1982
Driving Experience	36 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97283133
Fax Number	
Contact Number	
Email Address	FOKCM@HOTMAIL.COM

Address	1A JALAN SENTOSA
Postcode	418212
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : WIFE GENDER: : FEMALE
Passenger 2	NAME: : DAUGHTER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

FRONT VEHICLE ALL STOP, I ALSO STOP. SUDDENLY, VEHICLE B HIT MY VEHICLE FROM BEHIND.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY268E
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 29/4/19

5.25 PM

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

front veh all stop, I also stop, suddenly veh B
hit my veh from behind

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

29/4/19 @ 5:24pm
Reporting Centro Personnel's Signature
Name:
NRIC/FIN No.:

SIN YU SIN WORKSHOP

LKK Auto Consultants hereby notifies the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be subject to final approval from insurance Company

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103/ 97825292 Fax: (65) 68163103

Email: Sinyusin@hotmail.com

TP China.
Denise.

Acknowledged by Repairer

Signature: 14 May 2019

Date: QUOTATION FOR ACCIDENT REPAIR OF SCQ31K JAGUAR XE

THIRD PARTY INSURER: China Taiping

S/No.	Parts List	Qty	Amount (\$)
1.	Rear bootlid <i>Denis</i>	1	\$ 1769.00 <i>x</i>
2.	Rear bootlid "LOGO" emblem	1	\$ 200.00 <i>✓</i>
3.	Rear bootlid "JAGUAR" emblem	1	\$ 126.00 <i>✓</i>
4.	Rear bootlid "XE" emblem	1	\$ 114.00 <i>✓</i>
5.	Rear bootlid "2.0d" emblem	1	\$ 131.00 <i>✓</i>
6.	Rear bootlid side garnish L/R <i>2 pieces RH & LH</i>	2	\$ 772.00 <i>+ 386.</i>
7.	Rear bootlid mechanism lock	1	\$ 256.00 <i>x</i>
8.	Rear bootlid lock striker <i>3 pieces</i>	1	\$ 85.00 <i>x</i>
9.	Rear bootlid weather strip	1	\$ 250.00 <i>x</i>
10.	Rear bootlid reflector lamp RH <i>cut</i>	1	\$ 355.00 <i>✓</i>
11.	Rear taillamp RH <i>could</i>	1	\$ 547.00 <i>✓</i>
12.	Rear taillamp side garnish RH <i>3 pieces</i>	1	\$ 170.00 <i>x</i>
13.	Rear taillamp side garnish clip L/R	4	\$ 22.00 <i>x</i>
14.	Rear bumper <i>Red</i>	1	\$ 1188.00 <i>✓</i>
15.	Rear bumper side retainer L/R <i>2 pieces</i>	2	\$ 110.00 <i>✓</i>
16.	Rear bumper reinforcement beam	1	\$ 662.00 <i>✓</i>
17.	Rear bumper centre support bracket <i>could</i>	1	\$ 158.00 <i>✓</i>
18.	Rear bumper reverse sensor <i>2 pieces</i>	4	\$ 4024.00 <i>512</i>
19.	Rear bumper reverse sensor holder <i>new</i>	4	\$ 340.00 <i>✓</i>
20.	Rear bumper lower spoiler <i>Red</i>	1	\$ 661.00 <i>✓</i>
21.	Rear end panel <i>Denis</i>	1	\$ 780.00 <i>x</i>
22.	Rear end panel garnish <i>new</i>	1	\$ 285.00 <i>x</i>
	<i>5490</i>	Subtotal before discount	\$ 10005
	<i>4941</i>	Discount 10%	\$ 1000.50
		Subtotal 1	\$ 9004.50

LABOUR

To diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning

\$ 150 *100*

To remove, replace and reinstall rear reverse sensor

\$ 120 *60*

To remove and reinstall rear interior trims, garnish, seats etc

1260

\$ 180 *x*

To spray anti-rust coating on new and affected panel

\$ 120 *x*

To straighten, repair, realign on rear affected area and replace damaged parts

\$ 1200 *500*

To spray painting on affected area

\$ 1200 *600*

Total Labour Cost

\$ 2970

Total Cost Of Repairs (Total cost of parts + Total labour cost) **\$11,974.50**

total: 6201
n/s: 4.9K

Adrian Lim
4/5 14/05/19
04 Days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19007920/ATD3N2

Date: 26/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1820521800	
Claimant Vehicle No :	SCQ31K	Insured Vehicle No :	GY268E	
Date of Loss:	28/04/2019	Nature of Claim:	TP	Claim No: SNM19D201894C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCQ31K	Engine No:	150925W0226204DTD
Make & Model:	JAGUAR XE, 2.0 (A)	Chassis No:	SAJAB4AN7GA926014
Reg. Date:	22/01/2016 (Man. Year: 2015)	Odometer:	54530 km
Colour:	Black		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,004.50	4,941.00	4,063.50	45.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	1,260.00	1,710.00	57.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,974.50	6,201.00	5,773.50	48.21
Approved Total (Overridden) (\$\$)		4,900.00		
Nett Amount (\$\$)	11,974.50	4,900.00	7,074.50	59.08

INSPECTION

Date of Assignment:	06/05/2019	
Date Inspected:	14/05/2019	Inspected At: Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit) Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2019)
Parts:	143	JAGUAR XE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCQ31K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOTLID	Repair	1,769.00 FL	*- FL
2	1	*REAR BOOTLID LOGO EMBLEM	Necessary	200.00 FL	*200.00 FL
3	1	*REAR BOOTLID JAGUAR EMBLEM	Necessary	126.00 FL	*126.00 FL
4	1	*REAR BOOTLID XE EMBLEM	Necessary	114.00 FL	*114.00 FL
5	1	*REAR BOOTLID 2.0D EMBLEM	Necessary	131.00 FL	*131.00 FL
6	1	*REAR BOOTLID SIDE GARNISH L/R	O/s Deformed	772.00 FL	*386.00 FL
7	1	*REAR BOOTLID MECHANISM LOCK	Not Necessary	256.00 FL	*- FL
8	1	*REAR BOOTLID LOCK STRICKER	Not Necessary	85.00 FL	*- FL
9	1	*REAR BOOTLID WEATHER STRIP	Not Necessary	250.00 FL	*- FL
10	1	*REAR BOOTLID REFLECTOR LAMP RH	Cut	355.00 FL	*355.00 FL
11	1	*REAR TAILLAMP RH	Cracked	547.00 FL	*547.00 FL
12	1	*REAR TAILLAMP SIDE GARNISH RH	Not Necessary	170.00 FL	*- FL
13	4	*REAR TAILLAMP SIDE GARNISH CLIP L/R	Not Necessary	22.00 FL	*- FL
14	1	*REAR BUMPER	Deformed	1,188.00 FL	*1,188.00 FL
15	2	*REAR BUMPER SIDE RETAINER L/R	Necessary	110.00 FL	*110.00 FL
16	1	*REAR BUMPER REINFORCEMENT BEAM	Bent	662.00 FL	*662.00 FL
17	1	*REAR BUMPER CENTRE SUPPORT BRACKET	Deformed	158.00 FL	*158.00 FL
18	1	*REAR BUMPER REVERSE SENSOR (4 Pcs)	Damaged (2pcs Only)	1,024.00 FL	*512.00 FL
19	4	*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	340.00 FL	*340.00 FL
20	1	*REAR BUMPER LOWER SPOILER	Deformed	661.00 FL	*661.00 FL
21	1	*REAR END PANEL	Repair	780.00 FL	*- FL
22	1	*REAR END PANEL GARNISH	Not Necessary	285.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	10,005.00	5,490.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,000.50	549.00
Total Parts (\$\$)	9,004.50	4,941.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DIAGNOSE, REPLACE AND / OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	150.00	100.00
2	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSOR.	New	120.00	60.00
3	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISH, SEATS ETC.	New	180.00	0.00
4	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANEL.	New	120.00	0.00
5	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS.	New	1,200.00	500.00
6	TO SPRAY PAINTING ON AFFECTED AREA.	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,970.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >