

WASH STATE

REF:

CS/CT#1900742/USD302

Special Instruction

Surveyor

Marcus

ASSIGNMENT (Office)

From (Person)

Chong Boon Sen

of

CT#

Date/Time

6/5/19 @ 10.50am

Estimated Cost

Bill to

OD ☒ WS/TP RES / OJ RES / EVA / INV / MY / CS

To Inspect Vehicle No.

SLN183P

Insured

SLC34U

at Workshop no/

Specialist Motor

Tel:

6747 2112

of

Blk 3018A Ubi Rd 1 #01-24 / 25

Policy No.

Claim No.

SNM1902201979

Sum Insured

Excess

Make of Veh.

D.O.A

3/5/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

11.40am @ 6/5/19

Person Contacted

Irene

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLN183P-X

SLC 344-X

(08/11/13) wef

REF:

ASS. REC. BY: *Marcus*

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD *(TP) WS / TP RES / OD RES / EVA / INV / MV*

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

*6*

days

Res.: Yes or No

Lum Sum:

*20*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

*L7A14928*

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

*net 4071**100 until 26-4-2022 2yrs incl.**6/5/19 confirmed 2/5 \$4000 with inc.**(\$4,679.12 red - 54%)*

Veh No:

*SLN183P*

Yr Regn:

*41 07*Type: *(M) Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

*(A)*

Make:

*Honda civic*

C.C

*1598*

Colour:

*white*

A/C:

Insured / Std / NI / NA

Sp. Reading

*148534*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: *(Good)* / Fair / Poor / BurntSteering: *(In order)* / Jammed / Leaked / Burnt orBrake: *(In order)* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

*205/55 R16*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU *(PIR)* SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

*6*

mm

R/Bal.

*6*

mm

L/Bal.

*6*

mm

L/Bal.

*6*

mm

D.O.A.

*3/5/19*

D.O.I.

*6/5/19*

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 09 MAY 2019

Date/Time, File Pass to?

*09/05/19*1) *Typist*

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

*6*

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) \$ + RS. \$



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$ *4,000/- L/S*)

TOTAL

*220*

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 6 May 2019 10:50 AM  
**To:** Specialists Motor Pte Ltd  
**Cc:** assignments  
**Subject:** RE: ACCIDENT INVOLVING SLN183P AND SLC34U ON 03/05/2019 AT ANCHORVALE CRESCENT SLIP ROAD TOWARDS ANCHORVALE ST / OUR REF: SNM19D201979

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Specialists Motor Pte Ltd [mailto:cardoc@singnet.com.sg]  
**Sent:** Monday, 6 May, 2019 11:00 AM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: ACCIDENT INVOLVING SLN183P AND SLC34U ON 03/05/2019 AT ANCHORVALE CRESCENT SLIP ROAD TOWARDS ANCHORVALE ST / OUR REF: SNM19D201979

Without Prejudice

Dear Boon Sen

Please assign Marcus Chua to survey the vehicle SLN183P.

And also please check for us the above claim liability as soon as possible.

Thanks & Regards  
Irene Ting  
6747 2112

---

**From:** Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]  
**Sent:** Monday, 6 May, 2019 10:39 AM  
**To:** [cardoc@singnet.com.sg](mailto:cardoc@singnet.com.sg)  
**Subject:** RE: ACCIDENT INVOLVING SLN183P AND SLC34U ON 03/05/2019 AT ANCHORVALE CRESCENT SLIP ROAD TOWARDS ANCHORVALE ST / OUR REF: SNM19D201979

### WITHOUT PREJUDICE

Dear Sir,

We refer to your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

#### WITHOUT PREJUDICE

Dear sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

#### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Claims Dept of CTI

**Sent:** Monday, 6 May, 2019 10:36 AM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; [cardoc@singnet.com.sg](mailto:cardoc@singnet.com.sg)

**Cc:** Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>

**Subject:** FW: ACCIDENT INVOLVING SLN183P AND SLC34U ON 03/05/2019 AT ANCHORVALE CRESCENT SLIP ROAD TOWARDS ANCHORVALE ST

Dear Boon Sen,

Please conduct PRS – TP: SLN183P (SNM19D201979) soonest possible.

**From:** Specialists Motor Pte Ltd [<mailto:cardoc@singnet.com.sg>]  
**Sent:** Monday, 6 May 2019 10:15 AM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Subject:** ACCIDENT INVOLVING SLN183P AND SLC34U ON 03/05/2019 AT ANCHORVALE CRESCENT SLIP ROAD TOWARDS ANCHORVALE ST

Without Prejudice

Dear Sir/ Madam

Please refer to the above matter.

Our client (SLN183P) is claiming against your insured SLC34U.

Attached estimate, claim form and photos for your perusal.

Kindly check for us the above claim liability and arrange surveyor to survey the above vehicle at  
Specialists Motor Pte Ltd  
Blk 3018A, Ubi Road 1  
#01-24/25/26  
Singapore 408711

Thanks & Regards  
Irene  
67472112

**From:** [cardoc@singnet.com.sg](mailto:cardoc@singnet.com.sg) [<mailto:cardoc@singnet.com.sg>]  
**Sent:** Monday, 6 May, 2019 8:50 AM  
**To:** CARDOC  
**Subject:** Attached Image



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

500+ dealers  
competed to  
buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

[SELL YOUR CAR](#)



 Price Range 

 Depreciation 

 > 10 year: 

 Vehicle Type 


 Advanced  
Search

[Home](#) » [Used Cars](#) » [SQ Car Credit](#) » [Honda Civic 1.6A VTI-S \(COE till 02/2022\)](#)

## Honda Civic 1.6A VTI-S (COE till 02/2022)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[PREMIUM AD](#)
**Price** \$24,800

**Depreciation** \$8,840 /yr

**Reg Date** 24-Feb-2007  
(2yrs 9mths 17days COE left)

**Mileage** 162,122 km (13.3k /yr)

**Manufactured** 2007

**Road Tax** \$888 /yr

**Transmission** Auto

**Dereg Value** \$14,138 as of today (change)

**OMV** \$17,992

**COE** \$25,197

**ARF** \$19,792

**Engine Cap** 1,595 cc

**Power** 92.0 kW (123 bhp)

**Curb Weight** 1,220 kg

**No. of Owners** 4

**Type of Vehicle** Mid-Sized Sedan

### Features

1.6L Powerful VTEC Engine, 5 Speed Auto Transmission. Dual Airbags, ABS, Retractable Side Mirrors. View specs of the Honda Civic (2006-2012)

### Accessories

Sport Rims, Leather Seat, Climatic Aircon, Knockdown Rear Seat, Reverse Sensors, Electric Retractable Side Mirrors, Factory Fitted Audio Player.

### Description

One Of The Best And Popular Sedan In Market. Sporty White Outlook With Its Well Maintained Leather Upholstery. Reliable And Powerful Engine Yet Low Fuel Consumption. No Gimmicks. Low Mileage. Trade In Welcome. Various Loan Package ( Bank / InHouse ) For Your Options. Call Us Now To Arrange Viewing.

### Category

COE Car, Premium Ad Car

### Status

Available

### Resources



#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



#### Car Valuation - Free

Find out the market value of your existing car for free. [Get started](#)



Location Map

[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

### Seller Information

<b>Company</b>	SQ Car Credit	
	* dealer's pricelist * 3 vehs sold   13 vehs available	
<b>Address</b>	18 Sin Ming Lane #04-02C	
	<a href="#">Search cars nearby this location</a>	
<b>Location</b>	Midview City	
<b>Office No</b>	63390586	
<b>Contact Person(s)</b>	Ken	93388994
	Justin	91827511
	Jack	91416611
	Rachel	91126538

Posted on: 03-May-2019 | Last Updated on: 03-May-2019

[Compare](#)

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9993I

### Vehicle Details

Vehicle No.: SLN183P

Vehicle to be Exported: No

Intended Deregistration Date: 06 May 2019

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.6L VTI AUTO

Primary Colour: Grey

Manufacturing Year: 2007

Engine No.: R16A12001012

Chassis No.: JHMFD46207S200499

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$18,233.00

Original Registration Date: 27 Apr 2007

First Registration Date: 27 Apr 2007

Transfer Count: 2

Actual ARF Paid: \$20,057.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 26 Apr 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$25,115.00

COE Rebate Amount: \$14,929.00

**Total Rebate Amount: \$14,929.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 May 2019

OK



# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLN183P/1905060

03<sup>rd</sup> May 2019

The Manager  
Motor Claim Department  
China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Summit to insurance

Not Afford  
note  
1/5 \$4000/  
6/5/19  
The H. Attorney  
6/5/19

Date of Accident : 03<sup>rd</sup> May 2019  
Location : Anchorvale Crescent Slip Road Towards Anchorvale Street  
Third Party Claim Vehicle No : SLC 34 U  
Repair Cost For Vehicle No : SLN 183 P Honda Civic

## Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover	1	610.20	\$ 610.20
2	Rear boot cover hinge L&RH	2	48.60	\$ 97.20
3	Rear boot cover logo (H)	1	25.70	\$ 25.70
4	Rear boot cover emblem (Civic)	1	29.10	\$ 29.10
5	Rear boot cover emblem (1.6)	1	27.20	\$ 27.20
6	Rear boot cover emblem (I-otec)	1	34.10	\$ 34.10
7	Rear boot cover w/strip	1	97.60	\$ 97.60
8	Rear boot cover lock	1	85.00	\$ 85.00
9	Rear boot cover catch	1	16.00	\$ 16.00
10	Rear number plate lamp	2	28.20	\$ 56.40
11	Rear number plate lamp garnish	1	121.60	\$ 121.60
12	Rear boot cover lamp L&RH	2	145.90	\$ 291.80
13	Rear lamp L&RH	2	226.40	\$ 452.80
14	Rear bumper fascia 638	1	230.20	\$ 230.20
15	Rear bumper clips	1 set	35.00	\$ 35.00
16	Rear bumper side retainer L&RH	2	15.60	\$ 31.20
17	Rear bumper bracket L&RH	2	23.90	\$ 47.80
18	Rear fender inner finisher RH	1	140.00	\$ 140.00
19	Rear end panel	1	300.50	\$ 300.50
20	Rear end panel inner garnish	1	56.10	\$ 56.10
21	Rear end panel inner garnish clips	1 set	35.00	\$ 35.00
				\$ 3,320.50





## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19007921/USD3N2

Date: 13/05/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30148819000	
Claimant Vehicle No :	SLN183P	Insured Vehicle No :	SLC34U	
Date of Loss:	03/05/2019	Nature of Claim:	TP	Claim No: SNM19D201979C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLN183P	Engine No:	R16A12001012
Make & Model:	HONDA CIVIC, 1.6 VTI (A)	Chassis No:	JHMF46207S200499
Reg. Date:	27/04/2007 (Man. Year: 2007)	Odometer:	148534 km
Colour:	White		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,539.12	2,824.48	1,714.64	37.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,140.00	2,320.00	1,820.00	43.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,679.12</b>	<b>5,144.48</b>	<b>3,534.64</b>	<b>40.73</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,000.00</b>		
<b>(\$\$)</b>	8,679.12	4,000.00	4,679.12	53.91
<b>+ GST 7.00/7.00% (\$\$)</b>	607.54	280.00	327.54	53.91
<b>Nett Amount (\$\$)</b>	<b>9,286.66</b>	<b>4,280.00</b>	<b>5,006.66</b>	<b>53.91</b>

## INSPECTION

Date of Assignment:	09/05/2019	
Date Inspected:	06/05/2019	Inspected At: Specialist Motor Pte Ltd (HQ) BLK 3018A UBI ROAD 1 #01-24-26 Singapore 408711

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2019)
<b>Parts:</b> 143	HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLN183P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Badly Dented	610.20 FL	*610.20 FL
2	2		*REAR BOOT COVER HINGE L&RH	Not Necessary	97.20 FL	*- FL
3	1		*REAR BOOT COVER LOGO H	Necessary	25.70 FL	*25.70 FL
4	1		*REAR BOOT COVER EMBLEM (CIVIC)	Necessary	29.10 FL	*29.10 FL
5	1		*REAR BOOT COVER EMBLEM (1.6)	Necessary	27.20 FL	*27.20 FL
6	1		*REAR BOOT COVER EMBLEM (I-VTEC)	Necessary	34.10 FL	*34.10 FL
7	1		*REAR BOOT COVER W/STRIP	Twisted	97.60 FL	*97.60 FL
8	1		*REAR BOOT COVER LOCK	Twisted	85.00 FL	*85.00 FL
9	1		*REAR BOOT COVER CATCH	Not Necessary	16.00 FL	*- FL
10	2		*REAR NUMBER PLATE LAMP	Not Necessary	56.40 FL	*- FL
11	1		*REAR NUMBER PLATE LAMP GARNISH	Not Necessary	121.60 FL	*- FL
12	2		*REAR BOOT COVER LAMP L&RH	Cracked	291.80 FL	*291.80 FL
13	2		*REAR LAMP L&RH	Cracked	452.80 FL	*452.80 FL
14	1		*REAR BUMPER FASCIA	Distorted	730.20 FL	*638.00 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
16	2		*REAR BUMPER SIDE RETAINER L&RH	Bent	31.20 FL	*31.20 FL
17	2		*REAR BUMPER BRACKET L&RH	Bent	47.80 FL	*47.80 FL
18	1		*REAR FENDER INNER FINISHER RH	Deformed/Torn	140.00 FL	*140.00 FL
19	1		*REAR END PANEL	Badly Dented	300.50 FL	*300.50 FL
20	1		*REAR END PANEL INNER GARNISH	Twisted	56.10 FL	*56.10 FL
21	1		*SET REAR END PANEL INNER GARNISH CLIPS	Not Necessary	35.00 FL	*- FL
22	1		*REAR EXHAUST SILENCER	Repair	514.20 FL	*- FL
23	1		*REAR SPARE TYRE PANEL	Repair	948.20 FL	*- FL
24	1		*REAR SPARE TYRE BOARD	Warped	316.00 FL	*316.00 FL
25	1		*REAR END PANEL SEALER	Necessary	80.00 FS	*50.00 FS
26	1		*REAR BUMPER SENSOR	Shorted	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,558.90</b>	<b>3,468.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,019.78</b>	<b>643.62</b>
<b>Total Parts (\$\$)</b>	<b>4,539.12</b>	<b>2,824.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CUT OUT,RENEW,KNOCKING & WELDING REAR BOOT FLOOR PANEL,REAR BOOT COVER,REAR END PANEL,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN & RE-ALIGN BODY	New	1,800.00	1,000.00
2	SPRAY PAINTING ON DAMAGE PARTS	New	2,100.00	1,180.00
3	REMOVE & REFIX REAR BUMPER SENSOR	New	80.00	50.00
4	CHECK ALL LIGHTING AFTER REPAIRS	New	60.00	30.00
5	REMOVE & INSTALL REAR EXHAUST SILENCER	New	100.00	60.00
Gross Labour Cost (\$\$)			4,140.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >