	Catholic Sections		mer CS3/ICS 19	007925/A	cd3 1,	
wran	Sanvojev From (Person)	Adnama C	ASSIGNME	Jes	- Desc/Time	615/1913 rotsom
	Estima <u>te</u> d Cost	02		Billio		
	To Juspect Veh at Workshop in	ř.	SGD 55 MSCar Au	to	Tet 68	JL 4854U .
	of	81	conki BK Ave 4	1 H 1-17	premier	
	Policy No.			Claim No:	DMPC 19001	22H/02/CT
	Sum brancal			Excess.		alalia .
	Make of Veh: (Client's Record				0.0.4	
		114pm@6/5/1		June	Vehicle 1N	
				. lecturalism -	8 kg to Blot Ave	4 # 06-21 premia
	Dale/Time	Action/Instruction	- NA I MSG 180	2055941 z4	DOA	- 26/03/2018
			1 - NA/INC090			- 07/03/2009
		DESmant	e = 2/5/2019		- C-	
		WHE REP	nor - 42/5/19			

Date/Time, File Pass to?	Oate/Time, File Return to?	Part Pric	es Check:	Survey Fee:	Date;
1) PRS 3) 5) Preli Report:	2) - (6)	IN	OUT	Basic & Add. S + RS, SI Photos	
Final Report:	1			Others TOTAL	

...CLAIM SUBFOLDER...(Pending for Survey Report) Midnight Accident

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad Sub	mitted	Ins Auth ed	Status		
Main	(Not Notified) Edit Reg		06 May 2019 00:00 Edit Adj Rpt					Pendir Report Cancel	Service and the service of the servi	rvey
	Main	Re	ference		Claim Details		Document	s) [Show All
CLAIM S	JBFOLDER DE	TAILS		NAME OF TAXABLE PARTY.		[Created	by adjuster]	-		The Sales and the Sales
Insured:							o, anjusteri			-
Main Claimant:	-									
Vehicle Re No.:	9. SGD550	7T			Date of Loss:	02/05/201	9 00:00 - :59			
Claim Type	TP / DMP	C1900122H/C	г		Policy/Cover Note No.:	(Compreh	ensive)			
Vehicle Reg No. (Insured):	SJL4854U				Policy No. (Claimant):					
D					Excess:					
Repairer:	Ms Car Au	to Pte Ltd (HQ)	8 KAKI BUKIT AV	E 4 #01-07	PREMIER @ KAR	CI BUKIT, 4	15875 Kaki Bukit	- Tel: 638	51838	
Handling Insurer:	ECICS Lim	ited (HQ) - Tel:	53374779 /6303	0178 [H	andled by Cryst a	belle Tan	- 6303 0190]			
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Handled by A	DRIAN LI	NG] [Final R	pt due	15/05/20	0191
ASSOCIA	TED MAIL REC						56.5(8)	lew All		Case Mail
There are r	no mail for this o	case.					_			
ALL ASSO	CIATED TASE	(S⊟				View All	Search Tasks	Create N	ew Tack	Complete
Due Dat	e Priority	Type Task	Group Subje	ect Hand	dler Assign		Completed On		ated On	Done?
No results.										

Nivitha (LKK Auto)

From:

ECICS Claims <claims@ecics.com.sg>

Sent:

Monday, 6 May 2019 10:15 AM

To:

Pei Qi; assignments

Cc:

joshua@roypartners.com.sg; 'Chia Jia Rong'; mscarautopl@gmail.com; Crystabelle

Tan Gek Peng (ECICS, Claims); ECICS Claims

Subject:

RE: Pre-Repair Inspection

WITHOUT PREJUDICE

Hi Pei Qi

Thank you for your email.

We are not agreeable with your proposal surveyors.

We will assign LKK Auto for the PRS.

Aside to LKK

Please assist to arrange for TP PRS.

This case is handled by Ms Crystabelle Tan and our claim no DMPC1900122H/02/CT.

Thank you.

Best regards

Janice Goh

Senior Associate | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email janice goh@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Pei Qi [mailto:peiqi@roypartners.com.sg]

Sent: Monday, 6 May 2019 9:55 AM

To: ECICS Claims

Cc: joshua@roypartners.com.sg; 'Chia Jia Rong'; mscarautopl@gmail.com; Crystabelle Tan Gek Peng (ECICS, Claims)

Subject: RE: Pre-Repair Inspection

Dear Sirs.

We refer to the above matter and your email on even date.

Our client rejects your list of proposed motor surveyors.

Our client does not have a list of 10 motor surveyors. Our client propose their motor surveyor namely Mr. Patrick Ng from CarLink Consultancy and Mr. Dave from Sincere Appraisal as the Single Joint Expert

Pursuant to the new NIMA protocol, kindly let us know within **2 working days** of receipt of our letter whether you agree or have any objection to any of the motor surveyors proposed by our client, failing which you are deemed to have agreed to the appointment of any of the motor surveyors listed by our client

Thanks & regards,

Pei Qi

M/s Roy & Partners 101 Cecil Street #11-09 Tong Eng Building Singapore 069533

Tel: 6536 8466 Fax: 6536 1963 Email: peiqi@roypartners.com.sg

IMPORTANT NOTE: The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

From: ECICS Claims [mailto:claims@ecics.com.sg]

Sent: Monday, 6 May, 2019 9:30 AM To: Pei Qi <peiqi@roypartners.com.sg>

Cc: joshua@roypartners.com.sg; 'Chia Jia Rong' <jiarong@roypartners.com.sg>; mscarautopl@gmail.com;

ECICS Claims <claims@ecics.com.sg>; Crystabelle Tan Gek Peng (ECICS, Claims)

<Crystabelle_Tan@ecics.com.sg>
Subject: RE: Pre-Repair Inspection

Without prejudice

Dear Pei Qi

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop.

We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

- LKK
- 2. JP knight
- 3. Formteam
- Appraisal Associates
- Autoprobe
- 6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Best regards

Janice Goh



DID (65) 6303 0182

Tel (65) 6337 4779

Email janice goh@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Pei Qi [mailto:peiqi@roypartners.com.sg]

Sent: Friday, 3 May 2019 2:48 PM

To: ECICS Claims

Cc: joshua@roypartners.com.sg; 'Chia Jia Rong'; mscarautopl@gmail.com

Subject: Pre-Repair Inspection

Your Insured: SJL 4854U

Our Ref: MKR/307/8898/2019/jk.pq

Dear Sirs,

CLAIMANT: ABDUL RAHMAN BIN MOHAMAD SALIM
ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SGD 5507T AND SJL 4854U ALONG
UPPER WELD ROAD JUNCTION OF SUNGEI ROAD ON 02.05.2019 AT ABOUT 2030 HOURS.

We refer to the above matter.

We act for ABDUL RAHMAN BIN MOHAMAD SALIM, the owner of the motor car No. SGD 5507T.

We are instructed by our client to notify you of a road traffic accident on 2nd May 2019 at about 2030 hours UPPER WELD ROAD JUNCTION OF SUNGEI ROAD between motor vehicle registration number SGD 5507T and motor vehicle registration number SJL 4854U driven by your insured at the material time. A copy of the Singapore General Insurance report is enclosed.

As a result of the accident, our client's motor vehicle SGD 5507T been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor vehicle SGD 5507T at our client's repairer workshop, M/s MS Car Auto Pte Ltd No 8 Kaki Bukit Avenue 4, #01-07 Premier @ Kakit Bukit, Singapore 415875, Your said surveyor may contact June Yap at 6385 1838 to arrange the said inspection. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motorcycle without further reference to you.

Thanks & regards,

Pei Oi

M/s Roy & Partners 101 Cecil Street #11-09 Tong Eng Building Singapore 069533

Tel: 6536 8466 Fax: 6536 1963 Email: peiqi@roypartners.com.sg

IMPORTANT NOTE: The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. But he ladgement of this report to the incurers you bereful concept to the prohiting of this report at the center of

	ACCIDENT STATEMENT
Date Of Report	03/05/2019 18:18
Date Of Accident	02/05/2019 20:30
Exact Location Of Accident	JUNCTION OF WELD ROAD & SUNGEI ROAD
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SGD5507T
Insured/Policyholder	
Name Of Registered Owner	ABDUL RAHMAN BIN MOHAMAD SALIM
NRIC No	S1181517J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94552571
Alternative Phone No	OFFICE-94552571
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	B29069724QMX
Cover Note Number	
Driver	
Name of Driver	ABDUL RAHMAN BIN MOHAMAD SALIM

NRIC No S1181517J Date Of Birth 25/11/1955 Occupation INDOOR 14/10/1977 Date Of Driving Pass

Driving Experience 41 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-94552571

Fax Number

OFFICE-94552571 Contact Number

EMail Address NOEMAIL Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1

	1 1	QUEEN ST
SKETCH PLAN	-7 1	000 Rus DEP67.
-> 1		COL 10 2 1 10 2 10 10 10 10 10 10 10 10 10 10 10 10 10
(BYG DEMIN) CANAL	1 1 2	A: 540 55077 B: S56 48544
(BIG DEMIN)	T A A A	12 B. SDT 482AA
CAPACITA		witness: SLB 5114U.
	图图	(a) <
		SUNGE, RD
uppe wea		
DESCRIBE CIRCUMSTANCES OF		
on mentioned a	dute and time,	2 was diving along
UPP WELD RD	TOWARD JUN A	BESAR.
M The traffic	light turn 30	reen" of the junction
CONTRACT OFFICIAL	1 , L proceed	straight utilst
Bons Strage R	and Duc to his	Sale act and sales
his car collio	led against m	rashaet and negliegene y relicle. My relicle ess relicle which was
drag to RH	side The with	est vehicle which was
traivelling or	The RH able	to stop in time.
non vehicle	and witness ve	enicle never contact/
collide aguir	not each ofur	1. Ather the Collision
Veticle we e	Exchange Partic	wars and left the
Scent - On	my way back	I fel uncomfortable
and might	ne seeting in	edical treatment.
385677		
DECLARATION o		
I/We declare the foregoing particular	s are true in every respect.	
Policyholder's Signature Date & Time:	Driver's Signature (if driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Mehidle Ownor Panticulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	1517J	
Vehicle Details		
Vehicle No.:	SGD5507T	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	07 May 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	WISH 1.8 A	
Primary Colour:	Grey	
Manufacturing Year:	2005	
Engine No.:	1ZZ2479523	
Chassis No.:	ZNE100290476	
Maximum Power Output:	97.0 kW (130 bhp)	
Open Market Value:	\$19,710.00	
Original Registration Date:	17 Feb 2006	
First Registration Date:	17 Feb 2006	
Transfer Count:	0	
Actual ARF Paid:	\$21,681.00	
Intended PARF Rebate Details		10
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	(2)	
PARF Rebate Amount:	\$0.00	
Intended COERebate Details		
COE Expiry Date:	16 Feb 2021	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	5	
PQP Paid:	\$28,218.00	
COE Rebate Amount:	\$10,027.00	
Total Rebate Amount:	\$10,027.00	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 May 2019

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.


Find out mo











GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Wish 1.8A (COE till 03/2021)

\$16,800

\$9,080 /yr

13-Mar-2006

1.794 cc

MPV

Available

Engine, Gearbox And Undercarriage Are All In Good Running Condition, No Repair Is Needed. Owner Registering Existing Car Plate Numbers To New Car. A New Car Plate Numbers Will Be Allocated.





Toyota Wish 1,8A Sunroof (COE till 05/2021)

\$17,800

\$8,850 /yr

11-May-2006

1,794 cc 151,000 km MPV


Available

"One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, Bank & In-House Loan Available, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, Fu...

Carway



Posted: 05-May-2019: Tags: 2006-Toyota Wish, 2006-toyota Wish, Toyota Wish, Toyota Wish, Toyota, Wish, Wish, Wish, Used Toyota



...CLAIM SUBFOLDER...(Pending for Survey Report) Midnight Accident

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Sub	mitted	Ins Auth'ed	Status		
	28 May 2019 14:56 Edit Reg		06 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estima	tes	S\$0.00 View Rp	Control of the Contro		Pendi Repo	Pending for Survey Report Cancel Case	
М	lain	Re	ference	T d	laim I	Details		Docume	ents	7	Show All
CLAIM SUE	FOLDER DE	TAILS	d sub-turning column	Marie Constitution		Carl District	Create	ed by adjuster	T CONTRACTOR OF THE PARTY OF TH		AND DESCRIPTION
Insured:	-, Co. Re	g. No.: -, Email:	EMAIL@YAHOO.	СОМ			-				
Main Claimant:	2		787								
Vehicle Reg. No.;	SGD550	7 T			Date	of Loss:		019 00:00 - :59 onths and 15 Day	ys From LTA	Reg Date	(Man Yr)1
Claim Type:	P. U. 10										
Vehicle Reg. No. (Insured):	SJL4854U					y No. mant):					
					Exce						
Repairer:	Ms Car Au	to Pte Ltd (HQ)	8 KAKI BUKIT AV	/E 4 #01-07	PREMI	ER @ KAK	KI BUKIT,	415875 Kaki Bul	kit - Tel: 63	851838	
Handling Insurer:		nited (HQ) - Tel:						and the second second			
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	. [Han	dled by A	DRIAN I	LING] [Final	Rpt due	15/05/2	019]
ASSOCIATE	D MAIL RE	CEIVED							View All	Compose	e Case Mail
There are no	mail for this	case.									
ALL ASSOC	IATED TAS	KS⊟					View A	II Search Tasks	I Create	New Task	Complete
Due Date	Priority	Type Task	Group Subj	ect Hand	ter	Assign		Completed C		eated On	Done
No results.											

Claim Documents

*SGD5507T (DMPC1900122H/CT) [SJL4854U]

> May 2 2019 12:00AM [-] Ms Car Auto Pte Ltd

Ph	otos/Images			View in Brow	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per	1	~
1	23/05/19 12:59	General View	0	Thumbnail Load JPG	Print
2	23/05/19 12:59	General View	0	Load JPG	•
3	23/05/19 12:59	General View	0	Load JPG	•
4	23/05/19 12:59	General View	0	Load JPG	•
5	23/05/19 12:59	General View	0	Load JPG	2
6	23/05/19 12:59	General View	0	Load JPG	•
7	23/05/19 12:59	General View	0	Load JPG	•
8	23/05/19 12:59	General View	0	Load JPG	•
9	23/05/19 12:59	General View	0	Load JPG	•
10	23/05/19 12:59	General View	0	Load JPG	•
11	23/05/19 12:59	General View	0	Load JPG	•
12	23/05/19 12:59	General View	0	Load JPG	•
13	23/05/19 12:59	General View	0	Load JPG	•
14	23/05/19 12:59	General View	0	Load JPG	2
15	23/05/19 12:59	General View	0	Load JPG	3
16	23/05/19 12:59	General View	0	Load JPG	•
17	23/05/19 12:59	General View	0	Load JPG	•
18	23/05/19 12:59	General View	0	Load JPG	€
19	23/05/19 12:59	General View	0	Load JPG	•
20	23/05/19 12:59	General View	0	Load JPG	•
21	23/05/19 12:59	General View	0	Load JPG	•
22	23/05/19 12:59	General View	0	Load JPG	•
23	23/05/19 12:59	General View	0	Load JPG	•
24	23/05/19 12:59	General View	0	Load JPG	•
25	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
26	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
27	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
8	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
9	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
0	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
1	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
2	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
3	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
4	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
5	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•

Ph	otos/Images		3 per	page ▼	~
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
36	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	~
37	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
38	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
39	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
40	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
41	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
42	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
43	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	
44	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
45	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
46	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
47	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
48	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
49	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
50	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
51	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
52	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
53	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	S
54	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
55	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
56	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
57	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
58	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
59	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
60	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
61	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
62	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
63	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
64	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
65	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	
66	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
67	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
68	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
69	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
70	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
71	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
72	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
73	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
74	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
75	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
76	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
77	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
78	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
79	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
80	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	
31	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
32	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•
33	23/05/19 12:59	Photographs of Damaged Parts	0	Load JPG	•

9-114-	otos/Images		3 per page ▼		
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	il Print	
84	23/05/19 12:59	Photographs of Damaged Parts	1 Load JPG		
85	23/05/19 12:59	Photographs of Damaged Parts	⚠ Load JPG	-	
86	23/05/19 12:59	Photographs of Damaged Parts	⚠ Load JPG	-	
87	23/05/19 12:59	Photographs of Damaged Parts	Load JPG		
88	23/05/19 12:59	Photographs of Damaged Parts	Load JPG		
89	23/05/19 12:59	Photographs of Damaged Parts	■ Load JPG		
90	23/05/19 13:01	Photo After Spray	Load JPG	-	
91	23/05/19 13:01	Photo After Spray	1 Load JPG	-	
92	23/05/19 13:01	Photo After Spray	① Load JPG		
93	23/05/19 13:01	Photo After Spray	1 Load JPG	2	
94	23/05/19 13:01	Photo After Spray	Load JPG	2	
95	23/05/19 13:01	Photo After Spray	① Load JPG	•	
96	23/05/19 13:01	Photo After Spray	1 Load JPG	•	
97	23/05/19 13:01	Photo After Spray	1 Load JPG	(4)	
98	23/05/19 13:01	Photo After Spray	● Load JPG		
99	23/05/19 13:01	Photo After Spray	Load JPG	•	
100	23/05/19 13:01	Photo After Spray	1 Load JPG	•	
101	23/05/19 13:01	Photo After Spray	1 Load JPG	•	
102	23/05/19 13:01	Photo After Spray	1 Load JPG	•	
103	23/05/19 13:01	Photo After Spray	Load JPG Load JPG	•	
104	23/05/19 13:01	Photo After Spray	1 Load JPG	•	
105	23/05/19 13:01	Photo After Spray	1 Load JPG	•	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	Noset Save Frint
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/ICS19007925/ACD3S2

Date:

28/05/2019

REFERENCE

Handling Insurer:

ECICS Limited

Policy No:

Claimant Vehicle No:

SGD5507T

Insured Vehicle No:

SJL4854U

Date of Loss:

02/05/2019

Nature of Claim:

TP

Claim No:

DMPC1900122H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGD5507T

Make & Model:

TOYOTA WISH, 1.8 (A) 17/02/2006 (Man. Year: 2005)

Engine No: Chassis No:

Odometer:

1ZZ2479523 ZNE100290476

304367 km

Reg. Date: Colour:

Silver

Engine Capacity: Market Value/New Car Price:

1794 cc

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good Yes

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Front Right Side: Michelin 6 mm

Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

Michelin 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS Repairer's Adjuster's Difference Diff % Parts 0.00 0.00 0.00 Miscellaneous Items 0.00 0.00 0.00 Labour 0.00 0.00 0.00 Paintwork Labour 0.00 0.00 0.00 Towing 0.00 0.00 0.00 Nett Amount (S\$) 0.00 0.00 0.00

INSPECTION

Date Inspected:

Date of Assignment:

06/05/2019

06/05/2019 Inspected At:

Ms Car Auto Pte Ltd (HQ)

8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI

BUKIT

Singapore 415875

Estimated Period of Repair:

10.0 days

Adjuster: ADRIAN LING

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 - \$10,000.00

Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 28 May 2019)

Parts:

M1-MPV

TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGD5507T)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >