

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: AIG Asia Pacific Insurance Pte Ltd

Not Withheld
Lily 87
Rumay After Point
Today

Policy No: _____ Third Party

Date: 06.05.2019

Accident Date : 02.05.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mitsubishi Lancer Ex" Reg. No. SKU4373G Claiming Against Your Insured Reg. No. FBF886E			
1pc	Front Bumper		Bul 859.00 N ✓
10pcs	Front Bumper Clips	4.00	m 40.00 N ✓
1pc	Front Bumper Bracket		m 13.00 N ✓
1pc	Front Bumper Top Rubber Seal		m 28.00 N ✓
2pcs	Front Bumper Top Retainers	9.00	m 18.00 N ✓
8pcs	Front Bumper Top Retainer Rivets	2.00	m 16.00 N ✓
1pc	Front Bumper Side Air Grille		m 29.00 N ✓
2pcs	Front Bumper Corner Retainers	13.00	m 26.00 N ✓
1pc	Front Bumper Reinforcement		m 69.00 N X
1pc	Bonnet		m 622.00 N ✓
1pc	Bonnet Rubber Seal		m 15.00 N ✓
8pcs	Bonnet Insulator Clips	3.00	m 24.00 N ✓
2pcs	Headlamps	671.00	m 1,342.00 N ✓
1pc	Support Panel		m 376.00 N ✓
1pc	Wiper Tank		m 74.00 N ✓
1pc	Wiper Tank Motor		m 134.00 N ✓
2pcs	Front Fenders	496.00	m 992.00 N ✓
2pcs	Front Fender Chrome Moulding	59.00	m 118.00 N ✓
1pc	Front Fender Shield RH		m 105.00 N ✓
10pcs	Front Fender Shield Clips RH	3.00	m 30.00 N ✓
1pc	Front Wheel Rim RH		m 334.00 N X
1pc	Front Shock Absorber		m 427.00 N ✓
1pc	Front Shock Absorber Top Mounting		m 107.00 N ✓
1pc	Front Knuckle Arm RH		m 308.00 N ✓
1pc	Front Knuckle Arm RH Bearing		m 137.00 N ✓
1pc	Front Lower Arm		m 292.00 N ✓
			6,535.00
1pc	Front Number Plate		m 45.00 SN ✓
1pc	Front Number Plate Seal Pin		m 25.00 SN ✓
			6,605.00
			6,605.00

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Third Party

AIG Asia Pacific Insurance Pte Ltd

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: _____
Accident Date : 01.02.2019

Policy No: 06.05.2019

Date: _____

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	Estimate Cost Of Repair To "Mitsubishi Lancer Ex" Reg. No. SKU4373G Claiming Against Your Insured Reg. No. FBF886E DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
		B/F	6,605.00
	To Conduct Rear Electrical Check ,Focus Headlamp etc		30.00 201
	To Supply Off Peak Supplementary License,Transport and Services Charges for Plate Sealing		120.00 801
	To Provide Transportation (Towing)		80.00 501
	To Remove / Refill Air Con Gas		120.00 1001
	To Refit / Refill Radiator Coolant		60.00 301
	To Dismantle / Replace O/S Under Carriage		200.00 ?
	To Conduct Computerize Wheel Alignment Test		80.00 601
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		120.00 901
	Labour Charge - Panel Beating, Repairing Of Front Chassis Member, Fender Inner Panel etc.Cnt, Weld Support and Parts Replacement		950.00 7001
	To Respray Affected Areas		1,000.00 9001
		Total :	9,365.00