



# SMRT Accident Vehicle Repair Estimates

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer  
Signature:  
Date:

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
FAX Number : 63655582  
Estimator Telephone Number : 85662633  
Accident Reporting Number : 68662672

Date Generated : 23/09/2019  
User ID : PohSuan

## Section A - Accident Details

Registration Number	SHB5999E
Case Reference Number	TAX/05/19/2005
Registration Date	30/10/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	AHMAD ZAMANI BIN DAHLAN
Type of Accident	Head to Rear
Accident Date and Time	1/5/2019 4:15 AM
Accident Reported Date and Time	2/5/2019 1:22 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	1/5/2019 11:31 AM
Replacement Vehicle issued?	No
Job Card Number	24101316
Special Instruction to ARC, if any	TOWED \$60
Prepared Date and Time	2/5/2019 3:16 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



## Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,414.00	\$400.00
Total Spray Cost	\$1,694.00	\$500.00
Total Spare Part Cost	\$3,784.25	\$976.31
Total Other Cost	\$1,244.00	\$150.00
TOTAL COST	\$8,136.25	\$2,026.31
Lump Sum Total	\$8,150.00	\$2,050.00 (L/S)
Number of Repair Days	8.0	5.0
Prepared / Adjusted By	Kim Ming Chin	Naz (LKK) / LONPAC
ARC / Surveyor Sign Off Date	06/05/2019 5:05 PM	06/05/2019 3:29 PM
Signature		
Remarks	Supplementary = 2 days	LUMP SUM REPAIR 3 DAYS CHECK ITEMS PHOTOS AFTER REPAIR PHOTOS

Khanchana

Finalized.

- Naz.

24/9/19



# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
FAX Number 63665562  
Estimate Telephone Number 88662623  
Accident Reporting Number 64663672

Date Generated : 23/09/2019  
User ID : PohSuan

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0229	Invoice Number	
Quotation Date	16.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RR END PANEL	\$200.00	\$100.00
TO REPAIR REAR TAILGATE	\$200.00	\$100.00
TO REPAIR REAR PORTION	\$1,014.00	\$200.00
Total Labour	\$1,414.00	\$400.00

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$200.00	\$100.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,694.00	\$500.00

### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$84.00	\$60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO REMOVE / REFIT WINDSCREEN	\$240.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,244.00	\$150.00

### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given

CRK

SVC

SVC

SVC



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
FAX Number : 63655592  
Estimator Telephone Number : 88662623  
Accident Reporting Number : 88662672

Date Generated : 23/08/2019  
User ID : PohSuan

	76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X	SUL
	76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X	SUL
	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X	SUL
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	SUL
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	/	NN
	52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X	SUL
	52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X	SUL
	58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X	SUL
	58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	X	SUL
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	NN
	67005-47241	TAILGATE ASY	0.00	\$1,007.90	0.00	\$0.00	Replace	Not Given	X	SUL
	76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	X	SUL
	75310-47020	EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X	NN
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X	NN
	75442-47030	NAME PLATE (PRIUS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	X	NN
	75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X	NN
		STICKER SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X	NN
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X	NN
	75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X	NN
	75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X	NN
	75575-47030	MOULDING BACK WINDOW, LOWER NO.1	0.00	\$29.40	0.00	\$0.00	Replace	Not Given	X	NN
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	NN
	64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Check	X	SUL
	64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check	X	SUL
Total				\$5,005.40		\$463.95				

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
			ANTENNA, ELECTRICAL LOWER REAR	1.00	\$157.40	10.00	\$141.66	Replace	Replace
Total					917.10		756.44		

supplementary

BT  
CRK  
B&F  
BT  
BT  
CRK

1220.39  
- 20%

21/5 \$20.00 / 5 DAYS

976.31  
+ 400.00  
+ 650.00  
2026.31

10,344.50#

FINALIZED LUMP SUM REPAIR \$2,050.00 / 5 REPAIR DAYS