

ASS. REC. BY:

REF:

CS/AWA19007935/Avd3

n2

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

Wong Kin

of

AWAC

Date/Time:

6/5/19 @ 4:10pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJC 8998J

Insured:

GY 4651E

at Workshop n/s

New Huckle Teck

Tel:

6747 9241

of

1 kaki Bkt Ave 6 # 01-43

Policy No:

BVFCB0013241900

Claim No:

NSV1900223/SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

436pm @ 6/5/19

Person Contacted:

Sukyi

Vehicle

☒ IN

OUT

Date/Time

Action/Instruction (✓) Estimate

SJC 8998J - X

GY 4651E - CC3/41608023407/CDH

DUA: 10/08/2008

24/5/19

Adrian confirmed LS \$10000 (Real 13760.95, 5879)

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: _____Veh No: SJC8998J Yr Regn: 2007 / DecType: M. Cap / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camry c.c. 2362Colour: Black A/C: Insured / Std / Nil / NASp. Reading: 133599 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MR053BK4007020170Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 215/55R17R: 215/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 06/05/19Survey held at NHTDes. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

T? Exp. AWACOE Expiry: 30/11/22

RECEIVED 27 MAY 2019

MV: 28kPV: 17.9kNett: 10.1k

Date/Time, File Pass to?

Date/Time, File Return to?

1) 27/5 - typist

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, St

Photos

Others

TOTAL

350

Nivitha (LKK Auto)

From: Wong, Kin <Kin.Wong@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Monday, 6 May 2019 4:10 PM
To: 'assignments@lkkauto.com'; 'SUR'
Cc: 'Admin nht'
Subject: TP Survey assignment for SJC 8998 J DOA: 05/05/2019 Our ref: NSV1900223/SG

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of Mr Mohamad Taufikh as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SJC 8998 J
Insured Vehicle	:	GY 4651 E (Accident not Reported)
Policy Number	:	BVFCB0013241900
Name of Workshop	:	New Hock Teck Motor Pte Ltd
Contact Number	:	6747 9241
Person to Contact	:	Ms Sukyi Chong
Estimated Cost of repairs	:	\$ NA

Regards,
Claims Division

Copy to New Hock Teck Motor Pte Ltd (Your Ref:SJC 8998 J) via Email.

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group
Global Market

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

cee CONSUMER ELECTRONICS EXHIBITION

23-26 MAY SUNTEC SINGAPORE
LEVEL 3, 11AM-9PM LEVEL 4, 12-9PM



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 Post an Ad  Advertiser Login  Ways of Selling

2009 Subaru Forester 2.0X @ \$14.8K.



Cheapest In Market, Low
Mileage, Tip Top Condition,
Good For COE Renewal.
StarAd



PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.



Browse by Category

 Save Search

 Print

« Back (1 2) Next »

Sort by Date Posted

20 results/page

28 vehicles

Search camry

Advanced Search

Search

View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection camry Any Any > 10 year(s) old Any Any Any Available



☐ Toyota Camry 2.4A (COE till
01/2021)

\$16,500

\$9,730 /yr

16-Jan-2006

2,362 cc

304,000 km

Luxury

Available

Only \$26 Per Day For A Low Mileage COE Luxury Car, New Paint, Clean & Nice Interior, IROAD X9 Front & Rear Camera, 4 New Tyres, New Engine Mounting, Brake Pads, View To Appreciate, Reasonable Offer Wi...

Posted: 17-Apr-2019

Tags: 2006 Toyota Camry, 2006 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.0A (COE till
11/2021)

\$20,800

\$8,180 /yr

21-Nov-2006

1,998 cc

-

Luxury

Available

Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto Pte Ltd

Posted: 25-Apr-2019

Tags: 2006 Toyota Camry, 2006 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.4A (COE till
01/2027)

\$49,800

\$6,430 /yr

09-Feb-2007

2,362 cc

175,000 km

Luxury

Available

Very Well Maintained, Accident Free, Pearl White And Sporty, Original Paint And Like A New Car, Very Low Depreciation, Owner Relocate To Europe, Low Fuel Consumption, Most Reliable Japanese Model, No...

Posted: 04-Mar-2019

Tags: 2007 Toyota Camry, 2007 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota

DIRECT OWNER



☐ Toyota Camry 2.0A (COE till
02/2027)

\$48,800

\$6,280 /yr

13-Feb-2007

1,998 cc

-

Luxury

Available

Reliable Toyota Camry 2.0A. Spacious And Comfortable. View To Believe How Well This Car Is Taken Care Of, Interior Panels & Dashboard All In Good Original Condition. Spacious And Comfortable. View To ...

Posted: 26-Apr-2019

Tags: 2007 Toyota Camry, 2007 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ Toyota Camry 2.0A (COE till
03/2027)

\$48,800

\$6,240 /yr

02-Mar-2007

1,998 cc

90,000 km

Luxury

Available

1 Owner, Well Maintained, Cheap And Well Conditioned! Reliable 2.0L Japanese Sedan With Low Fuel Consumption/Maintenance Cost. Original Paintwork/Leather Interior! Accident Free. Easy And Flexible In...

Posted: 30-Apr-2019

Tags: 2007 Toyota Camry, 2007 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.0A (COE till
03/2022)

\$23,800

\$8,200 /yr

12-Apr-2007

1,998 cc

-

Luxury

Available

Many Wear And Tear Repaired With Receipts To Prove. Owner Believe In Preventive Maintenance. 100% Accident Free. Low Commitment But At Attractive Price.

Posted: 23-Mar-2018

Tags: 2007 Toyota Camry, 2007 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota

DIRECT OWNER

☐ Toyota Camry 2.0A (COE till
04/2027)

\$49,800

\$6,250 /yr

26-Apr-2007

1,998 cc

91,201 km

Luxury

Available

1 Owner Only. Very Nice Condition. All Parts Changed. New Paintwork Done. View To Believe.

SHORTLISTED HISTORY
Compare



★ Posted: 22-Apr-2019

Tags: 2007 Toyota Camry, 2007 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.0A (COE till 11/2027) \$51,888 \$6,050 /yr 28-Dec-2007 1,998 cc 113,500 km Luxury Available

Consignment Unit. Comes With Nice Car Plate 8618. Extremely Well Maintained Unit. New Alternator And Dashboard From Borneo Motor. Comes With All Around Security Cameras X4, 18" Limited Ed Rims, New Ba...

PREMIUM ED

★ Posted: 31-Mar-2019

Tags: 2007 Toyota Camry, 2007 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.0A (COE till 06/2028) \$54,888 \$6,010 /yr 24-Jun-2008 1,998 cc - Luxury Available

Camry 2.0A, At Affordable Depreciation. Fussy Owner. Regularly Serviced. Car Is A Definite Good To Go For Another 10 Years, As All Wear And Tear Been Replaced With Receipts To Prove. Probably The Most...

Prem Roy Motoring

★ Posted: 29-Mar-2019

Tags: 2008 Toyota Camry, 2008 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.0A (COE till 05/2023) \$33,800 \$8,310 /yr 27-Jun-2008 1,998 cc 158,000 km Luxury Available

Consignment Unit, Call Us For Non Obligation Viewing.

CONSIGNMENT

Car Search

★ Posted: 18-Apr-2019

Tags: 2008 Toyota Camry, 2008 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



Save on petrol with UOB One card!

Enjoy huge petrol savings of up to 24%, attractive cashback on your monthly spend, and 1-year annual fee waiver. Apply now and start enjoying today.

Find out more!



☐ Toyota Camry 2.4A (COE till 05/2023) \$35,800 \$8,800 /yr 02-Oct-2008 2,362 cc 87,058 km Luxury Available

View The Vehicle. Super Interior And Well Kept Internal And External. Regular Servicing Has Done. Just Renewed Road Tax For 6 Months.

DIRECT OWNER

★ Posted: 28-Apr-2019

Tags: 2008 Toyota Camry, 2008 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.0A (COE till 11/2028) \$55,800 \$5,850 /yr 17-Nov-2008 1,998 cc 117,000 km Luxury Available

2 Owners Car, Smooth And Silent Ride. Items Done Last 6 Mths Include New Paintwork, New Genuine Leather & Dashboard, 4 Brakepads, Battery Etc. Selling To Upgrade. Loan/Trade-In Avail.

DIRECT OWNER

★ Posted: 05-May-2019

Tags: 2008 Toyota Camry, 2008 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.0A (COE till 01/2024) \$39,800 \$8,480 /yr 15-Jan-2009 1,998 cc 100,000 km Luxury Available

100% Loan Available. Low Monthly Installment, Reliable And Excellent Fuel Efficiency, Bank And In House Loan Available, Well Maintained, Excellent Condition! Call For More Enquiries.

Motor Universe Credit Pte Ltd

★ Posted: 22-Mar-2019

Tags: 2009 Toyota Camry, 2009 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.0A (New 5-yr COE) \$40,800 \$8,150 /yr 11-Feb-2009 1,998 cc - Luxury Available

100% Loan Available! New Paintwork New Leather Seats, Best For Grab And Transportation Usages! Call Now!

PREMIUM ED

ABWIN (1994) Pte Ltd

★ Posted: 31-Mar-2019

Tags: 2009 Toyota Camry, 2009 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.4A G (COE till 01/2029) \$55,500 \$5,700 /yr 24-Feb-2009 2,362 cc 91,000 km Luxury Available

Vehicle Well Maintained! Original Paintwork And Interior! Reliable Engine! No Repairs Needed! Brand New Suspension And Tires. No Obligations! In-House And Bank Loans Available! Kindly Contact Our Sale...

★ Posted: 05-Apr-2019

Tags: 2009 Toyota Camry, 2009 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota



☐ Toyota Camry 2.0A (New 10-yr COE) \$59,800 \$5,980 /yr 25-Feb-2009 1,998 cc - Luxury Available

Open To Renew 5 Years COE At \$36800. Very Good Condition. Well Maintain By Previous Owner. Low-Interest Rate. Call/SMS For More Details.

★ Posted: 22-Apr-2019

Tags: 2009 Toyota Camry, 2009 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota

SHORTLISTED HISTORY

Compare

☐ Toyota Camry 2.0A (New 10-yr COE) \$59,777 \$5,970 /yr 24-Mar-2009 1,998 cc 125,797 km Luxury Available

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 4196J

Vehicle Details

Vehicle No.: SJC8998J

Vehicle to be Exported: No

Intended Deregistration Date: 06 May 2019

Vehicle Make: TOYOTA

Vehicle Model: CAMRY 2.4 AUTO ABS

AIRBAG

Primary Colour: Black

Manufacturing Year: 2007

Engine No.: 2AZE073037

Chassis No.: MR053BK4007020170

Maximum Power Output: 123.0 kW (164 bhp)

Open Market Value: \$28,797.00

Original Registration Date: 26 Dec 2007

First Registration Date: 26 Dec 2007

Transfer Count: 0

Actual ARF Paid: \$31,677.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Nov 2022

COE Category: E - Open Category

COE Period(Years): 5

PQP Paid: \$25,084.00

COE Rebate Amount: \$17,893.00

Total Rebate Amount: \$17,893.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 May 2019

OK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

WANG ANN

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

06/05/2019

TPAWA.

Veran,

Accident date: 05/05/2019

Estimated repair cost for vehicle no: SJC8998J TOYOTA CAMRY 2.4 A '07

CHASSIS: MR053BK4007020170

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Buckled</i>		\$980.20 ✓
2	2	Rear Boot Lid Hinge <i>Bent</i>	\$131.75	\$263.50 ✓
3	1	Rear Boot Lid Emblem Logo		\$76.10 ✓
4	1	Rear Boot Lid Camry Logo <i>new</i>		\$74.00 ✓
5	1	Rear Boot Lid 2.4 Logo		\$53.20 ✓
6	1	Rear Boot Lid Centre Chrome Moulding <i>cracked</i>		\$297.20 ✓
7	4	Rear Boot Lid Centre Chrome Moulding Clip <i>new</i>	\$6.50	\$26.00 ✓
8	1	Rear Boot Lid Number Plate <i>3rd</i>		\$50.00 ✓
9	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$83.10	\$166.20 ✓
10	2	Rear Boot Lid Side Reflector <i>cut</i>	\$387.00	\$774.00 ✓
11	1	Rear Boot Lid Inner Lock Assy <i>new</i>		\$429.30 ✓
12	1	Rear Boot Lid Inner Rubber <i>cut</i>		\$182.90 ✓
13	1	Rear Boot Lid Inner Trim Board <i>new</i>		\$561.20 ✓
14	8	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00 ✓
15	2	Rear Tail Lamp <i>cracked</i>	\$474.85	\$949.70 ✓
16	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 ✓
17	2	Rear Tail Lamp Lower Bracket <i>new</i>	\$43.75	\$87.50 ✓
18	2	Rear Tail Lamp Panel <i>RH Buckled</i>	\$193.20	\$386.40 ✓
19	1	Rear Bumper <i>Distorted</i>		\$546.20 ✓
20	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 ✓
21	2	Rear Bumper Side Retainer <i>new</i>	\$131.35	\$262.70 ✓
22	2	Rear Bumper Side Reflector (Special Nett) <i>new</i>	\$180.00	\$360.00 ✓
23	1	Rear Bumper Reinforcement <i>Bent</i>		\$531.50 ✓
24	2	Rear Bumper Reinforcement Bracket <i>new</i>	\$121.10	\$242.20 ✓
25	2	Rear Bumper Mud Shield <i>new</i>	\$93.10	\$186.20 ✓
26	1	Rear Bumper Reverse Sensor (Special Nett) <i>new</i>		\$380.00 ✓
27	2	Rear Fender <i>RH Buckled</i>	\$1,085.35	\$2,170.70 ✓
28	2	Rear Fender Air Duct <i>new</i>	\$112.00	\$224.00 ✓

29	2	Rear Fender Inner Trim Board	3 New	\$444.30	\$888.60	+
30	16	Rear Fender Inner Trim Board Clip	3 New	\$6.50	\$104.00	+
31	1	Rear End Panel	Distorted		\$659.25	+
32	1	Rear End Panel Top Garnish	Delid		\$381.40	+
33	1	Rear Spare Tyre Panel	Buckled		\$708.10	+
34	1	Rear Spare Tyre Panel Top Cover	Torn		\$281.90	+
35	1	Rear Spare Tyre Panel Top Sponge	See ~		\$268.20	+
36	1	Rear Spare Tyre Panel & End Panel Sealant	m		\$450.00	280 (SN)
37	2	Rear Spare Tyre Side Panel	Repair	\$232.30	\$464.60	+
38	1	Rear Exhaust	Best		\$981.85	+
39	1	Rear Exhaust Chrome Pipe	Best		\$160.00	100 (SN)
40	2	Rear Exhaust Mounting	3 New	\$65.90	\$131.80	+
41	1	Rear Center Exhaust			\$1,081.20	+
42	1	Rear Windscreen Moulding	3 New		\$181.25	+
43	1	Rear Windscreen Seal			\$95.00	+
44	1	Boothid Lock Sensor	used	168.90		
45	1	Boothid Lock Cover	used	28		
				Subtotal :-	\$17,234.05	

9995.50 SN 780
7496.62

Labour charges

To remove & refit cushion and res sent.	\$280.00	250
To remove & refit reverse sensor	\$100.00	60
To remove & refit rear & center exhaust	\$380.00	100
To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To check wiring	\$100.00	30
Tuff kote	\$150.00	✓
Towing Fee	\$150.00	60
Panel beating	\$2,600.00	1800
Spray painting	\$2,400.00	1600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$6,330.00

23,760.95

Total :- \$23,564.05

10k

total 1249662
A/C: 10K
12 Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA19007935/Avd3n2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLE TREE ANSON
SINGAPORE 079914

Date : 27-05-2019



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 4651E	Veh. Inspected	SJC 8998J
Policy No.	BVFCB0013241900	Coverage (\$)	0.00
Claim No.	NSV1900223/SG	Excess (\$)	0.00
Assign From	WONG KIN	Assign Date	06/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MR053BK4007020170	Colour	BLACK
Odometer	133599	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	BRIDGESTONE	6 mm
L/H Front Tyre	215/55 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	215/55 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	215/55 R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/05/2019	Inspection Date	06/05/2019
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 8998J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	BUCKLED	980.20	980.20
2	REAR BOOT LID HINGE @\$131.75	BENT	263.50	263.50
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	76.10	76.10
1	REAR BOOT LID CAMRY LOGO	NECESSARY	74.00	74.00
1	REAR BOOT LID 2.4 LOGO	NECESSARY	53.20	53.20
1	REAR BOOT LID CENTRE CHROME MOULDING	CRACKED	297.20	297.20
4	REAR BOOT LID CENTRE CHROME MOULDING CLIP @\$6.50	NECESSARY	26.00	26.00
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$83.10	NOT NECESSARY	166.20	-
2	REAR BOOT LID SIDE REFLECTOR @\$387.00	CUT	774.00	774.00
1	REAR BOOT LID INNER LOCK ASSY	DAMAGED	429.30	429.30
1	REAR BOOT LID INNER RUBBER	CUT	182.90	182.90
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	561.20	-
8	REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	52.00	-
2	REAR TAIL LAMP @\$474.85	CRACKED	949.70	949.70
4	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	32.00
2	REAR TAIL LAMP LOWER BRACKET @\$43.75	NOT NECESSARY	87.50	-
2	REAR TAIL LAMP PANEL @\$193.20	O/S BUCKLED	386.40	193.20
1	REAR BUMPER	DISTORTED	546.20	546.20
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER @\$131.35	NECESSARY	262.70	122.00
1	REAR BUMPER REINFORCEMENT	BENT	531.50	395.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$121.10	NOT NECESSARY	242.20	-
2	REAR BUMPER MUD SHIELD @\$93.10	NOT NECESSARY	186.20	-
2	REAR FENDER @\$1085.35	O/S BUCKLED	2,170.70	1,085.35
2	REAR FENDER AIR DUCT @\$112.00	NOT NECESSARY	224.00	-
2	REAR FENDER INNER TRIM BOARD @\$444.30	NOT NECESSARY	888.60	-
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	104.00	-
1	REAR END PANEL	DISTORTED	659.25	659.25
1	REAR END PANEL TOP GARNISH	DEFORMED	381.40	381.40
1	REAR SPARE TYRE PANEL	BUCKLED	708.10	708.10
1	REAR SPARE TYRE PANEL TOP COVER	TORN	281.90	281.90
1	REAR SPARE TYRE PANEL TOP SPONGE	NOT NECESSARY	268.20	-

Report Ref No. CS/AWA19007935/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR SPARE TYRE SIDE PANEL @\$232.30	TO REPAIR SEE LABOUR	464.60	-
1	REAR EXHAUST	BENT	981.85	981.85
2	REAR EXHAUST MOUNTING @\$65.90	NOT NECESSARY	131.80	-
1	REAR CENTER EXHAUST	NOT NECESSARY	1,081.20	-
1	REAR WINDSCREEN MOULDING	NECESSARY	181.25	181.25
1	REAR WINDSCREEN SEAL	NECESSARY	95.00	95.00
1	BOOTLID LOCK SENSOR	CRACKED	168.90	168.90
1	BOOTLID LOCK COVER	CRACKED	28.00	28.00
	LESS 25% DISCOUNT		-	-2,498.88
			16,080.95	7,496.62
	<u>SPECIAL NETT ITEMS</u>			
2	REAR BUMPER SIDE REFLECTOR @\$180.00 (SN)	DAMAGED	360.00	200.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	200.00
1	REAR SPARE TYRE PANEL & END PANEL SEALANT (SN)	NECESSARY	450.00	280.00
1	REAR EXHAUST CHROME PIPE (SN)	BENT	160.00	100.00
1	GUM (SN)	NECESSARY	50.00	50.00
			1,400.00	830.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION AND REAR SEAT.		280.00	250.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	60.00
	TO REMOVE & REFIT REAR & CENTER EXHAUST.		380.00	100.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	150.00
	TOWING FEE.		150.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE SIDE PANEL.		2,600.00	1,800.00
	SPRAY PAINTING.		2,400.00	1,600.00
	-		-	-
	-		-	-
	-		-	-
			6,280.00	4,170.00
GRAND TOTAL			23,760.95	12,496.62

Report Ref No. CS/AWA19007935/Avd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,000.00
---	--	--	-----------

Report Ref No. CS/AWA19007935/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.