

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 M/P: 9742 6003

REPAIR ESTIMATE FOR GX7603E

No.	Qty	List Items	
1	1	Front bumper	\$ 650.80 <i>ab</i>
2	1	Front bumper LH side retainer	\$ 91.70 <i>he</i>
3	1	Front LH step garnish	\$ 384.30 <i>de</i>
4	1	Front LH step panel	\$ 523.00 <i>R/bt</i>
5	1	Front LH door pillar	\$ 1,721.30 <i>Ry</i>
6	1	Front LH door	\$ 1,228.10 <i>bt</i>
7	1	Front LH door rubber	\$ 134.40 <i>ne</i>
8	2	Front LH door hinge (Top & bottom)	\$ 138.20 <i>bt</i>
			\$ 4,871.80
			Less 10% \$ 487.18
			Total : \$ 4,384.62

Special Nett Items

9	1	Front LH door company sticker	\$ 30.00 <i>ne</i>
---	---	-------------------------------	--------------------

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 800.00 <i>600</i>
2	To putty and spray Spray Paintings charges.	\$ 600.00 <i>500</i>
3	To conduct computerise wheel alignment test.	\$ 80.00 <i>60</i>
4	To supply and apply anti rust treatment	\$ 80.00 <i>30</i>
		Total : \$ 1,560.00

Total Parts and Labour : \$ 5,974.62

Tan Guan 97495749 / 67418434
WP

Lump sum
Resurvey after repair
sure/khaukuan
#days

14/5/19 22pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: