

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0565/2019/DY/TF
Date : 2-May-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. : **SKE 531 C**

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Ms. Xiao Liwen Karyn
Address : 114A Arthur Road
#06-05
Singapore 439826
Telephone : (HP)+65 81239973
Type of Claim : Third Party Claims
Policy No. : 1700020525-01
Vehicle No : **SLQ 2547 U**
Model Code : Q3 1.4 TFSI S TRONIC
Model / Year : Jun-17
Engine No : CZD 808131
Chassis No : WAUZZZ8U0HR091641
Mileage :
Date In : 2-May-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Apr-19
Place of Accident : ManuLife Tower Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLQ 2547 U

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /
2	To dismantle and renew front bumper and lhs headlight. Re-organize crash management components. Reinstall all parts removed.	\$ 1,600.00 800 1200
3	To respray front bumper.	\$ 1,200.00 800
4	To carry out diagnostic check.	S/N \$ 192.00 /
TOTAL LABOUR CHARGES		: \$ <u>3,472.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 2547 U

S/N	Parts Description	Damaged Parts & Prices S/Nett	
1	FRONT BUMPER / cut.	\$	1,888.00
2	FRONT BUMPER FIXING PARTS ?	\$	99.00
3	FRONT BUMPER AIR GUIDE GRILLE X NN	\$	163.00
4	FRONT BUMPER SENSOR BRACKET ?	2 \$	48.00
5	FRONT BUMPER GRILLE - LOWER CENTER X	\$	197.00
6	FRONT BUMPER CLOSING ELEMENT X } NN	\$	160.00
7	FRONT BUMPER SPOILER X	\$	349.00
8	RADIATOR GRILLE / cut.	\$	1,164.00
9	RADIATOR GRILLE SUPPORT ?	\$	111.00
10	FRONT BUMPER REINFORCEMENT ?	\$	770.00
11	FOAM FILLER PIECE ?	\$	93.00
12	FRONT BUMPER REINFORCEMENT COVER ?	\$	59.00
13	FRONT BUMPER TOP COVER ?	\$	112.00
14	CAUTION STICKER X NN	\$	13.00
15	FRONT BUMPER SENSOR ?	2 \$	462.00
16	FRONT BUMPER SENSOR SEAL RING / NCL.	\$	5.00
17	HORN - LOW TONE ?	\$	182.00
18	HEADLIGHT MOUNTING ?	\$	107.00
19	FRONT BUMPER SUPPORT - LH / RH ?	\$	46.00
20	FRONT BUMPER RETAINING PLATE ?	\$	79.00
SUB- TOTAL SPARE PARTS CHARGES		\$	6,107.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 2547 U

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>		<u>S/Nett</u>
21	HEADLIGHT - LH / <i>Act.</i>	\$	7,087.00
22	HEADLIGHT LIFT CYLINDER - LH ?	\$	192.00
23	WATER RESERVOIR ?	\$	200.00
24	FRONT WHEEL HOUSING LINER - LH X	\$	223.00
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS X } <i>mm</i>	\$	139.00
26	FRONT WHEEL SPOILER - LH X	\$	66.00
27	FRONT WHEEL ARCH TRIM - LH / RH / <i>mc</i>	\$	472.00
28	FRONT BUMPER AIR GUIDE - LH ?	\$	23.00
29	FRONT BUMPER SEALING STRIP - CENTER ?	\$	21.00
30	FRONT NO. PLATE / <i>Act.</i>	\$	40.00
31	SUNDRIES ?	\$	400.00
TOTAL SPARE PARTS CHARGES :		\$	14,970.00
TOTAL LABOUR CHARGES		\$	3,472.00
GRAND TOTAL		\$	18,442.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Guo Qiang - 82880282
Surveyed Date : 03/5/19.
Authorised Date :
Excess Cost :
Liability : 3 Days.
Remarks : before paint photos.

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant