

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

AWAHID LIMOUSINE

29/04/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAxA.

Vivian.

Accident date: 24/04/2018

Estimated repair cost for vehicle no: SKN8165B TOYOTA TOYOTA WISH 2.0 A '10

CHASSIS: JTDGJ20W005001700

S/n	Qty	Items	U/price	Amount
1	1	Front L/H Door <i>Dented</i>		\$980.20 <i>✓</i>
2	2	Front L/H Door Hinge <i>free</i>	\$132.00	\$264.00 <i>+</i>
3	1	Front L/H Door Inner Lock		\$578.20 <i>+</i>
4	1	Front L/H Door Inner Rubber <i>new</i>		\$272.60 <i>+</i>
5	1	Rear Bumper <i>torn</i>		\$625.20 <i>✓</i>
6	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 <i>30</i>
7	1	Rear L/H Bumper Side Retainer <i>new</i>		\$132.10 <i>✓</i>
8	1	Rear L/H Door <i>Dented Repair</i>		\$980.30 <i>+</i>
9	2	Rear L/H Door Hinge <i>free</i>	\$132.00	\$264.00 <i>+</i>
10	1	Rear L/H Door Inner Lock		\$578.20 <i>✓</i>
11	1	Rear L/H Door Inner Rubber		\$272.60 <i>+</i>
12	1	Rear L/H Fender <i>Repair</i>		\$972.45 <i>+</i>
13	1	Rear L/H Rim <i>at</i>		\$850.00 <i>450/sq</i>
14	1	Rear L/H Tyre <i>new</i>		\$350.00 <i>+</i>
15	1	L/H Rocker Panel Skirt <i>Repair</i>		\$850.00 <i>+</i>
16	10	L/H Rocker Panel Skirt Clip <i>new</i>	\$6.50	\$65.00 <i>+</i>

Door Frame Strip *new*

(50/sq) ✓
Subtotal:- \$8,086.85
90(su) .

17675

S.N: 540

132562

Labour charges

To check wiring

\$100.00 ~~20~~ 30

Tuff kote

\$150.00 +

Panel beating

\$1,600.00 ~~500~~ 500

Spray painting

\$1,800.00 ~~900~~ 900

Subtotal:- \$3,650.00

Total:- \$11,736.85

1430

Adrian Lj
L/S 07/03/19.
05 days.

total: 3255.62

L/S: 2-6K. ✓
05 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: