

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0588/2019/DY/TF  
**Date** : 8-May-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your insured vehicle no : SGD 1808 B**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Lim Yeow Choon  
**Address** : 495 Yio Chu Kang Road  
#11-06  
Singapore 787080  
**Telephone** : (HP)+65 96611918  
**Type of Claim** : Third Party Claim  
**Policy No.** : DMPPHQ18-004938  
**Vehicle No** : **SDQ 0880 P**  
**Model Code** : Q3 1.4 TFSI S tronic  
**Model / Year** : 16/8/2016  
**Engine No** : CZD 240305  
**Chassis No** : WAUZZZ8U8GR113304  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 26-Apr-19  
**Place of Accident** : CTE towards SLE after Braddell-

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SDQ 0880 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00	✓
2	To dismantle and renew rear bumper. To inspect lhs tail lamp panel and lhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00	500
3	To respray rear bumper.	\$ 1,200.00	550
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,872.00	

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SDQ 0880 P**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Distorted</i>	\$ 1,354.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 112.00	✓
3	REAR BUMPER SPOILER <i>distorted</i>	\$ 434.00	✓
4	REAR BUMPER TOWING COVER - LH / RH <i>new</i>	\$ 63.00	X
5	REAR BUMPER TAIL LIGHT - LH <i>cracked</i>	\$ 418.00	✓
6	REAR BUMPER CARRIER <i>Bent</i>	\$ 569.00	✓
7	FOAM FILLER PIECE <i>?</i>	\$ 78.00	?
8	REAR BUMPER GUIDE SECTION - LH <i>2nd</i>	\$ 91.00	✓
9	REAR BUMPER SENSOR <i>new</i>	2 \$ 462.00	+
10	REAR BUMPER SENSOR SEAL RING <i>new</i>	\$ 5.00	+
11	REAR WHEEL ARCH TRIM - LH / RH <i>new</i>	\$ 472.00	✓
12	SUNDRIES <i>?</i>	\$ 500.00	?
TOTAL SPARE PARTS		\$ 4,558.00	
TOTAL LABOUR CHARGES		\$ 2,872.00	
GRAND TOTAL		\$ 7,430.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lj  
Surveyed Date : 08/05/19.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 030 days.

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant