



CHEW MOTOR PTE. LTD.

Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

04/05/2019

Registration No: 201718369F

GST Reg No: 201718369R

01-43

Singapore 417883

Accident date: 03/05/2019

Estimated repair cost for vehicle no: SLR3672D HYUNDAI ELANTRA 1.6 A '17

CHASSIS: KMHD841CMJU507525

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Repair</i>		\$1,358.00 X
2	2	Rear Boot Lid Hinge <i>new</i>	\$84.30	\$168.60 X
3	1	Rear Boot Lid Emblem Logo <i>2</i>		\$28.80 ✓
4	1	Rear Boot Lid Elantra Logo <i>free</i>		\$38.50 ✓
5	1	Rear Boot Lid S Logo		\$22.80 ✓
6	2	Rear Boot Lid Side Reflector <i>cut LH</i>	\$168.80	\$337.60 168.80 X
7	1	Rear Boot Lid Inner Lock <i>new</i>		\$116.20 X
8	1	Rear Boot Lid Inner Rubber <i>new</i>		\$80.60 X
9	1	Rear Boot Lid Inner Trim Board <i>3M</i>		\$144.60 X
10	8	Rear Boot Lid Inner Trim Board Clip	\$6.50	\$52.00 X
11	1	Rear Boot Lid Number Plate <i>3M</i>		\$50.00 X
12	1	Rear Boot Lid Camera (Special Nett) <i>new</i>		\$680.00 X
13	2	Rear Tail Lamp <i>LH cut</i>	\$876.00	\$1,752.00 876 X
14	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 10 X
15	2	Rear Tail Lamp Lower Bracket <i>new</i>	\$28.00	\$56.00 X
16	1	Rear Bumper <i>Debond</i>		\$489.00 ✓
17	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30 X
18	2	Rear Bumper Side Retainer <i>new</i>	\$40.00	\$80.00 X
19	2	Rear Bumper Side Reflector <i>LH cut</i>	\$58.00	\$116.00 58 X
20	1	Rear Bumper Lower <i>Debond</i>		\$242.80 ✓
21	1	Rear Bumper Reinforcement <i>Best</i>		\$328.00 ✓
22	2	Rear Bumper Reinforcement Bracket <i>3M</i>	\$34.00	\$68.00 X
23	5	Rear Bumper Top & Lower Bracket <i>3M</i>	\$36.00	\$180.00 X
24	1	Rear Bumper Reverse Sensor (Special Nett) <i>200/m</i>		\$380.00 200/m X
25	1	Rear End Panel <i>Repair</i>		\$379.00 X
26	1	Rear End Panel Top Garnish <i>Debond</i>		\$105.00 ✓
27	2	Rear Fender Inner Trim Board <i>3M</i>	\$287.00	\$574.00 X
28	16	Rear Fender Inner Trim Board Clip <i>3M</i>	\$6.50	\$104.00 X
29	1	Rear Spare Tyre Panel Top Cover <i>3M</i>		\$225.00 X
30	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00 X

2477.70

1982.16

S.N: 200

Subtotal :- \$8,703.50Labour charges

To remove & refit cushion & trim board

~~\$280.00~~ 50

To remove & refit reverse sensor

~~\$180.00~~ 50

To remove & refit reverse camera

~~\$280.00~~ 50

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ X

Panel beating

~~\$1,400.00~~ 650

Spray painting

~~\$1,400.00~~ 600Subtotal :- \$3,790.00Total :- \$12,493.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3612.16

4/5: 2.9k

850 days

2.9k

Accident Photo

