

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0610/2019/TF
Date : 10-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no. : SLN 5167 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Seah Kiin Peng
Address : 39 Jalan Terang Bulan
Singapore 457316
Telephone : HP +65 83227920
Type of Claim : Third Party Claim
Policy No. : 2100377279-04
Vehicle No : **SKP 70 H**
Model Code : Audi A6 C7 2.0 TFSI MU
Model / Year : Jun-14
Engine No : CDN 397563
Chassis No : WAUZZZ4G7EN102024
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-May-19
Place of Accident : ECP 11KM

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 70 H

S/N	Nature of Jobs	Estimated Charges	
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$	360.00 ✓
2	To reinstall rear bumper sticker. (By owner)	S/N	TBC ✓
3	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$	1,200.00 500
4	To respray rear bumper.	\$	1,200.00 550
5	To carry out diagnostic check.	S/N \$	192.00 ✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 2,952.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 70 H .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>del</i>	\$ 2,343.00	✓
2	REAR BUMPER STICKY PAD <i>3 pieces</i>	\$ 21.00	✓
3	REAR BUMPER FIXING PARTS	\$ 249.00	✓
4	REAR BUMPER SPOILER <i>del</i>	\$ 316.00	✓
5	REAR BUMPER SECURING STRIP ?	\$ 157.00	?
6	REAR BUMPER CARRIER <i>2 pieces</i>	\$ 887.00	✓
7	REAR BUMPER CARRIER SEAL	2 \$ 26.00	✓
8	REAR BUMPER GUIDE SECTION - LH / RH	\$ 60.00	✓
9	REAR BUMPER CONNECTING PIECE	2 \$ 22.00	✓
10	REAR BUMPER GUIDE PROFILE - LH / RH	\$ 106.00	✓
11	REAR BUMPER GUIDE SECTION - CENTER	\$ 96.00	✓
12	REAR BUMPER CARRIER COVER	\$ 105.00	✓
13	REAR BUMPER SENSOR	2 \$ 462.00	✓
14	REAR BUMPER SENSOR SEAL	4 \$ 5.00	✓
15	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		\$ 5,255.00	
TOTAL LABOUR CHARGES		\$ 2,952.00	
GRAND TOTAL		\$ 8,207.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 13/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : We Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant