

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

: AXA INSURANCE S'PORE PTE LTD

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT19001911

Page

1

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

8 SHENTON WAY

Date Customer No.

: 2. May 2019 : WZA006

#27-01 AXA TOWER

Svc Advisor

: ANIKKA LAI SWEE KAM

Amount

SINGAPORE 068811

**Engine No** 

: L15B5671364

**Registration No** Chassis No

: SMK3932D

Qtv

Model

Item

Customer

: JHMRU1810JX201363

: SEOW JYH SENG

: HRV DX-SIN CVT YM 2018

Date | Time

)

Surveyor Name

2. May 2019 11:40:20 AM

Owner's Name

**Survey Date** 

Authorisation Date

Unit Price Disc %

**Total Amount** 

Total (Inclusive of GST)

7,448.01

521.35

7,969.36

7,969.36

Ins Policy No. **Date of Accident** 

: 29/4/2019

Description

**0% GST** 

**Amount** 

Amount incld GST

TP DIRECT SETTLEMENT (J/NO:

OWNER: SEOW JYH SENG

OWNER INSURER: TOKIO MARINE

ACC DATE: 29/04/2019

SURVEYED BY:

DATE:

REF NO:

TP INSURER: AXA

TP VEH: SGG7567R

04646-T7A-310ZZ	PANEL SET,L.RR.OUTSIDE	1	614.30	25	460.72	32.25	492.97
63720-T7A-300ZZ	GUTTER COMPL.RR.	1	76.80	25	57.60	4.03	61.63
74450-T7B-003	PROTECTOR,L.RR.WHEEL ARCH	1	175.50	25	131.62	9.21	140.83
75895-T7A-003	TAPEL.RR.DOOR PROTECTION	1	24.10	25	18.07	1.26	19.33
				Sum Item	668.01	46.75	<u>714.76</u>
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	1	3000.00		3000.00	210.00	3210.00
BKFE21R	CUT & RENEW RR L FENDER & DAMAGE PARTS.	1	3000.00		3000.00	210.00	3210.00
BML02I	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER	1	120.00	€	120.00	8.40	128.40
				Sum Labor	6780.00	<u>474.60</u>	7,254.60
Survey By							

## Printed on 2/5/2019 3:30:05 PM

Date & Time

Excess

Status

This is a computer generated invoice. No signature is required,

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53,50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000,00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.