

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM19007955/T1pa3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER			Date: 06-05-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SBN 9998P	Veh. Inspected	SLV 4196J	
	Policy No.	GA429847/1	Coverage (\$)	0.00	
	Claim No.	S9M01MAF	Excess (\$)	0.00	
	Assign From		Assign Date	06/05/2019	
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 5	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JM6CW1071H0127312	Colour	GREY	
	Odometer	30754	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	TOYO	6 mm	
	L/H Front Tyre	205/55 R16	тоуо	6 mm	
	R/H Rear Tyre	205/55 R16	TOYO	6 mm	
	L/H Rear Tyre	205/55 R16	тоуо	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	02/05/2019	Inspection Date	06/05/2019	
	Survey held at	5 SOON LEE ST #01-62			
	Repairer	Repairer CHENG AUTO BODYWORKS			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days				