

ATTN: MOTOR CLAIMS DEPARTMENT  
 OWNER: Leong Jenny  
 TP INSURER: AIG Asia Pacific Insurance Pte Ltd  
 POLICY NO: 5096108141-01  
 REFERENCE: TP CLAIM  
 DOA: 02/05/2019

*khachms*

**REPAIR ESTIMATE**

Est. No. : E19050003  
 Date : 06/05/2019  
 Vehicle Num. : SLT8450J  
 Make/Model : VOLKSWAGEN JETTA

| No                         | Description                             | Qty  | U/P    | Amt      |
|----------------------------|-----------------------------------------|------|--------|----------|
| <b>Section: LIST ITEMS</b> |                                         |      |        |          |
| 1                          | Front Bumper <i>Rebond</i>              | 1.00 | 775.00 | 775.00 ✓ |
| 2                          | Front Bumper Side Retainer <i>new</i>   | 1.00 | 35.00  | 35.00 ✓  |
| 3                          | RH Front Fender <i>Dented.</i>          | 1.00 | 380.00 | 380.00 ✓ |
| 4                          | RH Headlamp <i>lit</i>                  | 1.00 | 450.00 | 450.00 ✓ |
| 5                          | Front Grille <i>not on</i>              | 1.00 | 308.00 | 308.00 ✗ |
| 6                          | RH Front Bumper Cover <i>lit</i>        | 1.00 | 105.00 | 105.00 ✓ |
| 7                          | Front RH Fender Inner Shield <i>lit</i> | 1.00 | 120.00 | 120.00 ✓ |

Amt S\$ 2,173.00  
 Discount (10.00%) S\$ 217.30  
 Subtotal S\$ 1,955.70

|                        |                                        |      |        |                    |
|------------------------|----------------------------------------|------|--------|--------------------|
| <b>Section: LABOUR</b> |                                        |      |        |                    |
| 8                      | To Remove & Reinstall Front Bumper     | 1.00 | 100.00 | 100.00 ✓           |
| 9                      | To Remove & Reinstall Front Fender     | 1.00 | 100.00 | 100.00 ✓           |
| 10                     | To Remove & Reinstall Headlamp         | 1.00 | 80.00  | 80.00 <i>SD</i>    |
| 11                     | To Straighten Front Support Panel      | 1.00 | 100.00 | 100.00 ✗           |
| 12                     | To Straighten Front Fender Inner Panel | 1.00 | 120.00 | 120.00 ✗           |
| 13                     | To Sand Down, Primer & Spray Paint     | 1.00 | 750.00 | 750.00 <i>400.</i> |

Amt S\$ 1,250.00  
 Discount (0.00%) S\$ 0.00  
 Subtotal S\$ 1,250.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 1,955.70  
 LABOUR Subtotal S\$ 1,250.00  
**Total S\$ 3,205.70**

*total: 2328.50*  
*h/s: 1850*

*Adrian King*  
*h/s 07/05/19.*

*04 Days.*