

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 04/05/2019

INDIA INTERNATIONAL INSURANCE

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 30/04/2019 @ 21:30
VRN : SLE9938S
MODEL : TOYTA ALTIS 1.6
TP VRN : SH6765U

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 REAR BUMPER <i>rec</i>	1	\$ 486.50	\$ 486.50	
2 REAR BUMPER CLIP <i>rec</i>	10	\$ 5.00	\$ 50.00	
3 REAR BUMPER SIDE RETAINER R/L <i>X</i>	2	\$ 120.00	\$ 240.00	
4 REAR BUMPER REFLECTOR R/L <i>X (R) / 1 pc (L)</i>	2	\$ 58.00	\$ 116.00	
5 REVERSE SENSOR <i>?</i>	1	\$ 290.00	\$ 290.00 <i>200?</i>	
6 REAR BUMPER REINFORCEMENT <i>bt</i>	1	\$ 395.00	\$ 395.00	
7 REAR END PANEL <i>Repair</i>	1	\$ 590.00	\$ 590.00	
			\$ 2,167.50	
Discount -25%			\$ 541.88	
			\$ 1,625.63	
		PARTS TOTAL	\$ 1,625.63	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	\$ 1,250.00
Putty, Blend And Spray Paint on REAR Affected Area	\$ 1,000.00
Check Wiring and Ensure Proper Functioning	\$ 80.00
Remove and Refit Rear End Panel Lining and Garnish to Facilitate Repair	\$ 150.00
Remove and Reinstall Reverse Sensors	\$ 120.00
Remove and Reinstall Rear Reverse Camera	\$ X 120.00
Cavity Treatment on New Parts	\$ 20 80.00
Conduct Water Seepage Test	\$ X 120.00
LABOURS TOTAL	\$ 2,920.00

Rasul

Hp 90010068

3 days

P/P

14/05/19 @ 1100

Rasul by paint

No. of repair days: 7

CUSTOMER SIGNATURE



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Grand Total : \$ 4,545.63
Add 7% GST : \$ 318.19
Nett Total : \$ 4,863.82