

Asher
Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 04/05/2019

INDIA INTERNATIONAL INSURANCE

ACCIDENT DATE : 30/04/2019 @ 21:30

VRN : SLE9938S

ATTN: MOTOR CLAIMS DEPT

MODEL : TOYOTA ALTIS 1.6

TP VRN : SH6765U

	Qty	S\$ Unit	S\$ Amt	S\$ Labor
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 REAR BUMPER <i>VB</i>	1	\$ 486.50	\$ 486.50	
2 REAR BUMPER CLIP <i>acc</i>	10	\$ 5.00	\$ 50.00	
3 REAR BUMPER SIDE RETAINER R/L <i>xsu</i>	2	\$ 120.00	\$ 240.00	
4 REAR BUMPER REFLECTOR R/L <i>x (RA) / pcd</i>	2	\$ 58.00	\$ 116.00	
5 REVERSE SENSOR <i>? xsu</i>	1	\$ 290.00	\$ 290.00 <i>200?</i>	
6 REAR BUMPER REINFORCEMENT <i>bt</i>	1	\$ 395.00	\$ 395.00	
7 REAR END PANEL <i>Repair</i>	1	\$ 590.00	\$ 590.00	
			\$ 2,167.50	
Discount -25%			\$ 541.88	
			\$ 1,625.63	

PARTS TOTAL \$ 1,625.63

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	\$ 1,250.00
Putty, Blend And Spray Paint on REAR Affected Area	<i>500</i> \$ 1,000.00
Check Wiring and Ensure Proper Functioning	<i>60</i> \$ 80.00
Remove and Refit Rear End Panel Lining and Garnish to Facilitate Repair	<i>60</i> \$ 150.00
Remove and Reinstall Reverse Sensors	<i>60</i> \$ 120.00
Remove and Reinstall Rear Reverse Camera	<i>an</i> \$ 120.00
Cavity Treatment on New Parts	<i>\$ 20</i> 80.00
Conduct Water Seepage Test	<i>an</i> \$ 120.00

LABOURS TOTAL \$ 2,920.00

Rasul
Hp 90010068
Grand Total : \$ 4,545.63
Add 7% GST : \$ 318.19
Nett Total : \$ 4,863.82

No. of repair days: 7

3 days

P/P

14/05/19 @ 1100

Rasul bk paint

CUSTOMER SIGNATURE



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

SUPPLEMENTARY VEHICLE ESTIMATE dated 22/05/2019

INDIA INTERNATIONAL INSURANCE

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 30/04/2019 @ 21:30
VRN : SLE9938S
MODEL : TOYOTA ALTIS 1.6
TP VRN : SH6765U

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 BUMPER CLIP SCREW <i>nc ✓</i>	4	\$ 5.00	\$ 20.00	
			\$ 20.00	
Discount -25%			\$ 5.00	
			\$ 15.00	
		<i>PARTS TOTAL</i>	\$ 15.00	

P: 989.50
supp = 20.00
1009.50
- 25%
757.13
L: 1200.00
1957.13

Grand Total : \$ 15.00
Add 7% GST : \$ 1.05
Nett Total : \$ 16.05

No. of repair days: 7

CUSTOMER SIGNATURE



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)