

ASS. REC. BY:

REF: CS/FCI19007978/Ad3n2

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From Person: Gilen Lee

of FCI

Date/Time: 7.5.19 9.349.m

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 2361J

Insured: SHB 6378R

at Workshop m/s LC Auto motive

Tel: 92712214

of Block 25 Kaki Bukit Road 4 # 05-26

Policy No:

Claim No: D19002958MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 3.5.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 7.5.19 10.149.m

Person Contacted:

chris

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SKT 2361J-X	
	SHB 6378R- CC3/EQ3 19001604/K12A3	D.O.A - 22/01/2019
	lump sum \$11,000- Cred: 17989.35! 62%	

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKT2361J Yr Regn: 2011 AugustType: ☒ M/Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598Colour: Silver A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 262514 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: MR053RBE104122628Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☒ S/Rim / ☐ STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 07/05/19Survey held at LCDes. of Damages: ☒ Fnt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 17 JUN 2019

MV: 33.5K.PV: 20.3K.Nett: 13.2K.

Date/Time, File Pass to?

Date/Time, File Return to?

1) File Typist

3)

5)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date: 19/15 285

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

1704 285505017272758007/06/19

MOTOR SURVEY ASSIGNMENT

Date	06-05-2019	Our Ref No. D19002958MFSH
Accident Date	03-05-2019	Claim Type. Third Party
Insured Vehicle	SHB6378R	Third Party Vehicle. SKT2361J
Survey Location	BLOCK 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB	
Contact Person.	CHRIS CHAN PICK YUEN	
Contact No.	69664526/ 92712214	Fax No. 69664526
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LC AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



toyota altis

Price Range

Depreciation

2011

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Ideal Automobile Pte Ltd > Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price: \$33,800

Depreciation: \$12,040 /yr
View models with similar depreReg Date: 05-Jul-2011
(2yrs 2mths 1day COE left)

Mileage: 93,000 km (11.9k /yr)

Manufactured: 2011

Road Tax: \$742 /yr

Transmission: Auto

Dereg Value: \$17,607 as of today (change)

OMV: \$15,263

COE: \$38,889

ARF: \$15,263

Engine Cap: 1,598 cc

Power: 90.0 kW (120 bhp)

Curb Weight: 1,195 kg

No. of Owners: 1

Type of Vehicle: Mid-Sized Sedan

Features

Fuel Efficient And Powerful 1.6L 16 Valve DOHC VVTi Engine, Smooth Auto Transmission With Ect, Dual SRS Airbags, ABS, Digital Climate Control Aircon. View specs of the Toyota Corolla Altis (2006-2013)

Accessories

Leather Seats, Sports Rims, Toyota's Factory Audio Head Unit, Retractable Side Mirrors With Indicators, Reverse Sensors And Camera, Fog Lamps.

Description

1 Owner Only! Most Reliable And Economical Sedan! Great Condition! View To Believe! No Gimmicks! Trade In Welcome! Call Us For An Appointment Now!

Category

PART Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 12-Apr-2019 | Last Updated on: 03-May-2019

Upfront Payment


more Financial info



Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Ideal Automobile Pte Ltd

• dealer's pricelist

• 23 vehs sold | 16 vehs available

Address

210 Turf Club Road Lot A38

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CHEAPEST CAR INSURANCE RENEWAL

Choice of
\$0 excessOption of any
workshop

GET A CHEAPER QUOTE NOW!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Jitesh Gurnani.



BMW 420i M Sport Fully Loaded
Options. Extremely Well
Maintained. Mint Condition
Direct Owner StarAd



ABWIN

ONE-STOP

MOTORING SOLUTIONS



VIEW OUR PROFILE

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

6 vehicles

Search altis

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

altis

Any

Any

2011

Any

Any

Any

Available



Toyota Corolla Altis 1.6A

\$27,800

\$11,630 /yr

26-Jan-2011

1,598 cc

-

Sedan

Available

Brand New Coat Of Paintwork! Single Owner! Engine And Gearbox In Superb Condition 100% Problem Free, Best Fuel Efficient Car For Your A To B Transport! One Of The Most Reliable Vehicle With Low Maintenance...

Car (S) Pte Ltd



Posted: 06-May-2019

Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM AD



Toyota Corolla Altis 1.6A

\$27,800

\$11,270 /yr

15-Feb-2011

1,598 cc

-

Sedan

Available

New DOHC Dual VVT-I Engine. Well Maintained, Excellent Condition.



Posted: 04-May-2019

Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$28,800

\$11,670 /yr

24-Feb-2011

1,598 cc

-

Sedan

Available

1 Owner Car! Well Maintained, Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, Buy With Confidence! Call Us Now To M...

Car Search



Posted: 19-Apr-2019

Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

CONFIRMED



Toyota Corolla Altis 1.6A

\$50,000

\$20,100 /yr

13-Jun-2011

1,598 cc

130,000 km

Sedan

Available

Well Maintained And Excellent Condition. Direct Owner Sale With Low Genuine Mileage. Clean And Beautiful Interior, Washed And Vacuumed Weekly. Consignment Agents And Lowballers Don't Bother. Thank You...



Posted: 29-Apr-2019

Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

DIRECT OWNER

GET YOUR
COE
RENEWAL
LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Corolla Altis 1.6A

\$31,700

\$11,320 /yr

22-Jun-2011

1,598 cc

127,000 km

Sedan

Available

Well Maintained By 1 Careful Owner. Most Reliable And Economical Sedan. Mint Condition.



Posted: 24-Apr-2019

Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$37,800

\$12,050 /yr

14-Nov-2011

1,598 cc

122,000 km

Sedan

Available

1 Owner Only! Very Low Mileage! Most Reliable And Economical Sedan! Great Condition! View To Believe! No Gimmicks! Trade In Welcome! Call Us For An Appointment Now!



Posted: 12-Apr-2019

Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

SHORTLISTED HISTORY

Compare [4]

New Expired ads

20 results/page

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	4610H

Vehicle Details

Vehicle No.:	SKT2361J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	1ZRX121991
Chassis No.:	MR053REE104122628
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$14,797.00
Original Registration Date:	29 Aug 2011
First Registration Date:	29 Aug 2011
Transfer Count:	3
Actual ARF Paid:	\$14,797.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Aug 2021
PARF Rebate Amount:	\$8,878.00

Intended COE Rebate Details

COE Expiry Date:	28 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$49,301.00
COE Rebate Amount:	\$11,424.00
Total Rebate Amount:	\$20,302.00

The information contained herein is correct as at 03 May 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4610H
Vehicle Details	
Vehicle No.:	SKT2361J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	1ZR121991
Chassis No.:	MR053REE104122628
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$14,797.00
Original Registration Date:	29 Aug 2011
First Registration Date:	29 Aug 2011
Transfer Count:	3
Actual ARF Paid:	\$14,797.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Aug 2021
PARF Rebate Amount:	\$8,878.00
Intended COE Rebate Details	
COE Expiry Date:	28 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$49,301.00
COE Rebate Amount:	\$11,371.00
Total Rebate Amount:	\$20,249.00

The information contained herein is correct as at 07 May 2019

OK

LC AUTOMOTIVE

Block 25 KAKI BUKIT ROAD 4 #05-26 SYNERG @KB (S)417800

Tel : (65) 65250431 HP: 92712214

Email : chris_chanbebe@hotmail.com

SONG CUNFEI

Bk 25 Kaki Bukit Rd 4

05-26 SYNERGY @KB

Singapore 417800

06th MAY 2019

TP 1st Cop

Denise

MR053REF104122628.

Accident date: 03rd MAY 2019

Estimated repair cost for vehicle no: SKT2361J TOYOTA ALTIS 1.6A '11

S/n	Qty	Items	U/price	Amount
1	1	Rear boot lid <i>Distorted</i>		\$950.00 758
2	2	Rear boot lid hinges <i>new</i>	\$131.80	\$263.60 +
3	1	Rear boot lid ALTIS logo		\$54.10 ✓
4	1	Rear boot lid A1.6 logo		\$43.10 ✓
5	1	Rear boot lid emblem logo <i>new</i>		\$47.70 ✓
6	1	Rear boot lid VVTI logo		\$36.00 ✓
7	1	rear Boot Lid corolla logo		\$45.10 ✓
8	1	Rear boot lid chrome moulding clips <i>new</i>		\$15.00 ✓
9	1	Boot lid chrome moulding <i>new</i>		\$292.80 +
10	1	Rear boot lid inner lock <i>changed</i>		\$285.20 ✓
11	1	Rear Boot Lid Inner Trim board <i>new</i>		\$320.10 +
12	1	Rear Boot Lid Inner Trim board clips		\$50.00 +
13	1	Rear boot lid weatherstrip <i>at</i>		\$210.00 ✓
14	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$67.10	\$134.20 +
15	1	boot lid plate holder <i>del</i>		\$50.00 -30(SN)
16	2	boot lid lamp <i>crushed</i>	\$320.00	\$640.00 -435
17	2	Rear tail lamp <i>crushed</i>	\$425.00	\$850.00 -5700
18	4	Rear tail lamp clips <i>new</i>	\$8.00	\$32.00 20
19	2	Rear tail lamp panel <i>RH Buckled</i>	\$175.40	\$350.80 175.40
20	1	Rear bumper <i>Distorted</i>		\$850.00 482
21	2	Rear Bumper Side holder <i>new</i>	\$73.80	\$147.60 ✓
22	2	Rear bumper bracket <i>dent</i>	\$63.20	\$126.40 ✓
23	2	Rear bumper side reflector <i>new</i>	\$85.00	\$170.00 +
24	1	Rear bumper clips <i>new</i>		\$50.00 30
25	1	Rear end panel <i>Distorted</i>		\$560.00 ✓
26	1	Rear end panel top garnish <i>del</i>		\$265.00 ✓
27	1	rear end Panel sealant <i>new</i>		\$120.00 -60(SN)
28	1	Rear fender R/H <i>Buckled</i>		\$981.10 ✓

29	1	Rear fender L/H <i>Repis</i>		\$981.10	X
30	2	Rear fender inner shield		\$85.90	\$171.80 X
31	2	Rear fender inner trim board		\$389.10	\$778.20 X
32	1	rear fender inner shield clips			\$50.00 X
33	1	Rear fender inner trim board clips			\$60.00 X
34	1	Rear fender air duct <i>new</i>			\$156.70 X
35	1	rear windscreen moulding <i>new</i>			\$158.50 ✓
36	1	rear windscreen sealant			\$120.00 60(50)
37	1	Rear spare tire panel top cover <i>new</i>			\$292.80 X
38	2	Rear exhaust mounting <i>new</i>			\$56.30 X
39	1	Rear exhaust head shield <i>new</i>			\$165.30 X
40	1	Rear Exhaust <i>new</i>			\$998.10 X
41	1	Front bonnet <i>Buckled</i>			\$980.00 X 862
42	2	Front bonnet hinges		\$55.20	\$110.40 X
43	1	Front bonnet lock			\$155.10 X
44	1	Front bonnet inner rubber			\$160.10 X
45	6	Front bonnet inner rubber clips		\$12.90	\$77.40 X
46	1	Front bonnet inner sponge			\$184.20 X
47	1	Front bonnet lock panel <i>Bent</i>			\$161.20 ✓
48	2	Front headlamp <i>cracked</i>		\$1,350.00	\$2,700.00 ✓
49	1	Front grille <i>cracked</i>			\$290.00 -
50	1	Front grille emblem logo <i>new</i>			\$89.40 -
51	1	Front bumper <i>Distabed</i>			\$980.00 486
52	2	Front Bumper Side Bracket <i>new</i>		\$83.10	\$166.20 85
53	8	Front bumper clips <i>new</i>		\$12.90	\$103.20 20
54	1	Front bumper reinforcement <i>Bent</i>			\$480.10 327
55	2	front bumper reinforcement bracket <i>new</i>		\$131.10	\$262.20 +
56	2	Front bumper fog lamp cover <i>new</i>		\$131.10	\$262.20 +
57	2	front Bumper fog lamp		\$180.20	\$360.40 +
58	1	front Bumper lower grille <i>new</i>			\$280.00 +
59	1	front support panel <i>Buckled</i>			\$780.00 715
60	1	Front air-con condenser <i>Bent</i>			\$1,050.20 ✓
61	1	Front radiator <i>new</i>			\$1,150.20 X
62	1	Front radiator fan motor assy <i>new</i>			\$518.75 X

1224120 S.V. 1150
918090

Subtotal :-

\$23,229.85

S/n	Qty	Items/Nett	U/price	Amount
1	2	Rear bumper reverse sensor <i>Damaged</i>		\$280.00 200
2	1	rear camera <i>new</i>		\$480.00 +
3	1	Rear Boot Lid Number Plate <i>Bent</i>		\$50.00 -
4	1	Front bumper number plate <i>cracked</i>		\$50.00 -

Subtotal :-

\$860.00

Labour charges

To remove & re-fix cushion

~~\$120.00~~ 60

To remove & re-fix rear exhaust

~~\$250.00~~ X

To remove & re-fix rear windscreen

~~\$120.00~~ ✓

Gum

~~\$50.00~~ ✓

To remove & re-fix front windscreen

~~\$120.00~~ X

Gum

~~\$50.00~~ X

To remove & re-fix front air-con condenser, radiator
Fan-motor and top up gas

~~\$250.00~~ 120

Wheel alignment (computer)

~~\$120.00~~ X

To remove & re-fix petrol tank

~~\$120.00~~ 80

To remove & re-fix reverse sensor

~~\$100.00~~ 50

To Remove & install rear reverse camera

~~\$100.00~~ 50

Tuff kote

~~\$120.00~~ 80

Towing charges

~~\$100.00~~ 60

To Check Wiring System

~~\$80.00~~ 60

Panel beating

~~\$2,100.00~~ 1800

Spray painting

~~\$1,600.00~~ ✓

4/20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 432

subtotal:- \$4,900.00

Total:- \$28,989.85 29189.85

total 13750.90

HS

11K

15 days.

11K.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19007978/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6378R	Veh. Inspected	SKT 2361J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002958MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	07/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	MR053REE104122628	Colour	SILVER	
Odometer	262514	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/05/2019	Inspection Date	07/05/2019	
Survey held at	LC AUTOMOTIVE BLOCK 10 SIN MING IND.ESTATE , SECTOR C #01-20 SINGAPORE 575645			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 2361J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	DISTORTED	950.00	758.00
2	REAR BOOT LID HINGES @\$131.80	NOT NECESSARY	263.60	-
1	REAR BOOT LID ALTIS LOGO	NECESSARY	54.10	54.10
1	REAR BOOT LID A1.6 LOGO	NECESSARY	43.10	43.10
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	47.70	47.70
1	REAR BOOT LID VVTI LOGO	NECESSARY	36.00	36.00
1	REAR BOOT LID COROLLA LOGO	NECESSARY	45.10	45.10
1	REAR BOOT LID CHROME MOULDING CLIPS	NECESSARY	15.00	15.00
1	BOOT LID CHROME MOULDING	NOT NECESSARY	292.80	-
1	REAR BOOT LID INNER LOCK	DAMAGED	285.20	285.20
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	320.10	-
1	REAR BOOT LID INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
1	REAR BOOT LID WEATHERSTRIP	CUT	210.00	210.00
2	REAR BOOT LID NUMBER PLATE LAMP @\$67.10	NOT NECESSARY	134.20	-
2	BOOT LID LAMP @\$320.00	CRACKED	640.00	435.00
2	REAR TAIL LAMP @\$425.00	CRACKED	850.00	570.20
4	REAR TAIL LAMP CLIPS @\$8.00	NECESSARY	32.00	20.00
2	REAR TAIL LAMP PANEL @\$175.40	O/S BUCKLED	350.80	175.40
1	REAR BUMPER	DISTORTED	850.00	482.00
2	REAR BUMPER SIDE HOLDER @\$73.80	NECESSARY	147.60	147.60
2	REAR BUMPER BRACKET @\$63.20	DENTED	126.40	126.40
2	REAR BUMPER SIDE REFLECTOR @\$85.00	NOT NECESSARY	170.00	-
1	REAR BUMPER CLIPS	NECESSARY	50.00	30.00
1	REAR END PANEL	DISTORTED	560.00	560.00
1	REAR END PANEL TOP GARNISH	DEFORMED	265.00	265.00
1	REAR FENDER R/H	BUCKLED	981.10	981.10
1	REAR FENDER L/H	TO REPAIR SEE LABOUR	981.10	-
2	REAR FENDER INNER SHIELD @\$85.90	NOT NECESSARY	171.80	-
2	REAR FENDER INNER TRIM BOARD @\$389.10	NOT NECESSARY	778.20	-
1	REAR FENDER INNER SHIELD CLIPS	NOT NECESSARY	50.00	-

Report Ref No. CS/FCI19007978/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER TRIM BOARD CLIPS	NOT NECESSARY	60.00	-
1	REAR FENDER AIR DUCT	NOT NECESSARY	156.70	-
1	REAR WINDSCREEN MOULDING	NECESSARY	158.50	158.50
1	REAR SPARE TIRE PANEL TOP COVER	NOT NECESSARY	292.80	-
2	REAR EXHAUST MOUNTING	NOT NECESSARY	56.30	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	165.30	-
1	REAR EXHAUST	NOT NECESSARY	998.10	-
1	FRONT BONNET	BUCKLED	980.00	862.00
2	FRONT BONNET HINGES @\$55.20	NOT NECESSARY	110.40	-
1	FRONT BONNET LOCK	NOT NECESSARY	155.10	-
1	FRONT BONNET INNER RUBBER	NOT NECESSARY	160.10	-
6	FRONT BONNET INNER RUBBER CLIPS @\$12.90	NOT NECESSARY	77.40	-
1	FRONT BONNET INNER SPONGE	NOT NECESSARY	184.20	-
1	FRONT BONNET LOCK PANEL	BENT	161.20	161.20
2	FRONT HEADLAMP @\$1350.00	CRACKED	2,700.00	2,700.00
1	FRONT GRILLE	CRACKED	290.00	290.00
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	89.40	89.40
1	FRONT BUMPER	DISTORTED	980.00	486.00
2	FRONT BUMPER SIDE BRACKET @\$83.10	NECESSARY	166.20	85.00
8	FRONT BUMPER CLIPS @\$12.90	NECESSARY	103.20	30.00
1	FRONT BUMPER REINFORCEMENT	BENT	480.10	327.00
2	FRONT BUMPER REINFORCEMENT BRACKET @\$131.10	NOT NECESSARY	262.20	-
2	FRONT BUMPER FOG LAMP COVER @\$131.10	NOT NECESSARY	262.20	-
2	FRONT BUMPER FOG LAMP @\$180.20	NOT NECESSARY	360.40	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	280.00	-
1	FRONT SUPPORT PANEL	BUCKLED	780.00	715.00
1	FRONT AIR-CON CONDENSER	BENT	1,050.20	1,050.20
1	FRONT RADIATOR	NOT NECESSARY	1,150.20	-
1	FRONT RADIATOR FAN MOTOR ASSY	NOT NECESSARY	518.75	-
	LESS 25% DISCOUNT		-	-3,060.30
			22,939.85	9,180.90
	SPECIAL NETT ITEMS			
1	BOOT LID PLATE HOLDER (SN)	DEFORMED	50.00	30.00

Report Ref No. CS/FC119007978/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL SEALANT (SN)	NECESSARY	120.00	60.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
2	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR CAMERA (SN)	NOT NECESSARY	480.00	-
1	REAR BOOT LID NUMBER PLATE (SN)	BENT	50.00	50.00
1	FRONT BUMPER NUMBER PLATE (SN)	CRACKED	50.00	50.00
1	GUM (SN)	NECESSARY	100.00	50.00
			1,250.00	500.00
	LABOUR			
	TO REMOVE & RE-FIX CUSHION.		120.00	60.00
	TO REMOVE & RE-FIX REAR EXHAUST.	NOT NECESSARY	250.00	-
	TO REMOVE & RE-FIX REAR WINDSCREEN.		120.00	120.00
	TO REMOVE & RE-FIX FRONT WINDSCREEN.	NOT NECESSARY	120.00	-
	TO REMOVE & RE-FIX FRONT AIR-CON CONDENSER,RADIATOR FAN-MOTOR AND TOP UP GAS.		250.00	120.00
	WHEEL ALIGNMENT (COMPUTER).	NOT NECESSARY	120.00	-
	TO REMOVE & RE-FIX PETROL TANK.		120.00	80.00
	TO REMOVE & RE-FIX REVERSE SENSOR.		100.00	50.00
	TO REMOVE & INSTALL REAR REVERSE CAMERA.		100.00	50.00
	TUFF KOTE.		120.00	80.00
	TOWING CHARGES.		100.00	60.00
	TO CHECK WIRING SYSTEM.		80.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER L/H.		2,400.00	1,800.00
	SPRAY PAINTING.		1,600.00	1,600.00
			5,600.00	4,080.00
GRAND TOTAL			29,789.85	13,760.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CS/FCI19007978/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.