
**Accident Photo** 





### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process,
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT	
Date Of Report	12/10/2017 14:04	
Date Of Accident	11/10/2017 20:30	
Exact Location Of Accident	ALONG EVERITT ROAD NORTH	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	

	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGZ5309H	
Insured/Policyholder	General Control Control	
Name Of Registered Owner	TW PREMIUM AUTOMOBILE PTE LTD	
Co Reg No	-	
Email Address	NOEMAIL	
	(CASTELLA ME)	

Mobile Phone No. (LOCAL) +65-93831499 Alternative Phone No OFFICE-93831499 Vehicle Particulars

Manufacturer HONDA Model CIVIC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy NO for repair to your vehicle?

If No, Please state action to be taken REPORTING ONLY Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage THIRD PARTY

Fleet Policy NO

Policy Number DMHCSN1675381600

Cover Note Number

Driver

Name of Driver MUHAMMAD HAIRUL BIN HAMID

NRIC No S8731036A Date Of Birth 08/10/1987 Occupation OUTDOOR Date Of Driving Pass 29/08/2012

Driving Experience 5 YEARS AND 1 MONTH

Gender MALE

Mobile Number Fax Number Contact Number

EMail Address NOEMAIL Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured O

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

Ť

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes.Please state which Police Station

Police Station Name

MARINE PARADE NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 300 MARINE PARADE ROAD, POSTCODE: 449296, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-4428999 - FAX NO: 62447678

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

REFER ATTACHED POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number FW1737J
Vehicle Make/Model/Colour KAWASAKI

Details Of Properties

Name of Driver

MUHAMMAD MUSTAQIM BIN AZMAN

NRIC/Passport Number S9519269F Contact Number 91687412

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness** 

Name

Phone Number

### Email Address

# DETAILS OF INJURED PERSON 1

Name

MUHAMMAD MUSTAQIM BIN AZMAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FW1737J

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

WARK SEAR COMMENS

REM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Senature Name:

NRIC/FIN No.:

		an #2 Pg. 1		
SKETCH PLAN				
	T-MASS #-		& VERITT	ROAD MOR
A: SGZ53091		ô co		
B: FW17375				
DESCRIBE CIRCUMSTANCES				
REFER TO POUC	R KEPORT			
	September 1			
Armada A				
		19	1	
				-7
			NOT THE THE	
			1100000	
			1151 200 200 300 1151 200 201 (1991)	
		38		20 1800
DECLARATION	Constant			
We declare the top going particular	, _			1
olicyholder's Signature ate & Time:	Driver's Signature (If driver is not the policyhold	Re Na	porting Centre Personne me:	Signature





Police Station Of Origin: Marine Parade N.P.C 300 Marine Parade Road SINGAPORE 449296

1 of 3 Report No. T/20171011/2210

Tel No: 1800-4428999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/10/2017 23:37		Made:	Vide Report No.: G/20171011/0211	Station Diary No.:	
Litaria de la propia de la companya				AND AND DESCRIPTION OF THE PROPERTY OF THE PRO	
Name of Informant: MUHAMMAD HAIRUL BIN HAMID			Address: APT BLK 753 WOODLANDS 730753	CIRCLE #07-550 SINGAPORE	
ID Type / ID No.: NRIC NO / S8731036A Nationality: SINGAPORE CITIZEN		36A	Contact No.: - Home/Office: Mobile: 93831499		
		EN	Email:		
Sex: Age: Date of Birth: Male 30 08/10/1987		Date of Birth: 08/10/1987	Type of Informant:		
Race: Malay			Language: English	Institution / School Name:	
Occupation: AV TECHNICIAN		TOTAL NEWSCOOL	Driving Licence Information; Class: 3	Date of Expiry:	

Guiteral ketem					
Type of Accident:	Injury Conveyed By Ambula	ance	Drink Drive: No	Date/Time of Accident: 11/10/2017 20:30	Type of Location X-Junction
Location: Along Road 1 EVERITT RO  Everitt Road 1 Weather: Clear	AD NORTH  North junction of Langsat R	Road :	Surface:		Road Speed Limit:
Traffic Flow: Two Way			Control:		Traffic Volume:
Type of Collis Between Mov	ion: ing Vehicles - Head On				Anyone conveyed by ambulance: Yes

Lengths of w					
W1737J	Motorcycle	KAWASAKI	Green	AN AREADAN SEE	0
GZ5309H	Car	HONDA	White	Seriously Damaged	

Use of Pedestrian Crossing: NA





Police Station Of Origin: Marine Parade N.P.C. 300 Marine Parade Road SINGAPORE 449296

Report No. T/20171011/2210

2 of 3

Tel No: 1800-4428999

**CONTINUATION OF REPORT** 

Nome	AN ULANDAM DANIE	STATE STATE STATE STATE			经有价值 医	2017年1月1日中央公司的共享
Name	MUHAMMAD MUST	MUHAMMAD MUSTAQIM BIN AZMAN		ID No		S9519269F
Related Vehicle	FW1737J (Motorcycle)			Conta	ct No.	91687412
Hospital/Clinic	CHANGI GENERAL HOSPITAL .			Class Drivin Licend Expin	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Disc		NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of			
Daven 2. (U.)						
Name	MUHAMMAD HAIRU	L BIN HAM	IID	ID No	2	S8731036A
Related Vehicle	SGZ5309H (Car)			Conta	ct No.	93831499
Hospital/Clinic	NIL			Class Driving Licent Expiry	g ce &	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Disch		NIL	
No. of Days grant	ted Medical Leave	NIL	Degree of		NIL	

#### Brief Details.

On the abovementioned date, time and location, I was driving my Grab car, SGZ5309H, with a passenger sitting behind. I was driving along Langsat Rd turning right to Everitt Road North when suddenly a motorcycle came in the opposite direction. I did not see the motorcycle when I was turning. According to my passenger, the rider did not turn on his headlight. The motorcycle then knocked onto the front of my vehicle. The rider fell off from his motorcycle and I immediately went down to make a check. He was lying on the road but he was conscious. I called the ambulance and the ambulance came and conveyed the rider to CGH. I am not injured. The Traffic Police later came and gave me a report number and advised me to lodge an accident report. The investigation officer in charge is Clarence, 65476195





Police Station Of Origin: Marine Parade N.P.C 300 Marine Parade Road SINGAPORE 449296 Tel No: 1800-4428999

3 of 3 Report No. T/20171011/2210

CONTINUATION OF REPORT


### Sketch Plan


Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Staff Sgt NUR SAKINAH BINTE ABRAHIM	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 11/10/2017 23:37
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt RAZIZ BIN TAHAR Contact No.: 65476200	Classification Of Case:
Separate :	


## Sketch Plan #6 Pg. 1






## **Accident Photo**




















## PRUDENT ADJUSTORS SERVICES

3024 UBI ROAD 3 #02-65 SINGAPORE (408652) BUSINESS REGN. No. 53193457L Hp 96699986

#### VEHICLE DAMAGE INSPECTION REPORT

MR Muhammad Mustaagim Bin Azman

C/O Riaz LLC

133 New Bridge Road # 09-09

Chinatown Point Singapore 059413 Our Ref Date

: PA/FW1737/1117/tpw : 25 November 2017

REFERENCES

Claim Type Vehicle No.

Make

Model

: Third Party : FW 1737 J

: Kawasaki : KRRZX150

Reg. Date : 23 January 2003 Color : Blue Odometer : 16548

Date of Accident

Date of Assignment Date of Inspection

Date of Re-inspn Chassis No

Size

Engine No

: 11 October 2017

: 05 November 2017 : 06 November 2017 : 16 November 2017

: KR150KA55575 : Blocked

TYRE CONDITION

Front Rear

Make Swallow Viva

90/80-17 110/70-17 Thread Balance 6mm 4mm

# GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at rear and both side portion. Please refer to photographs and assessment of repairs for details

#### INSPECTION AND ADJUSTMENT

Original Quotation

: \$ 5,610.90

Revised Assessment

\$ 3,050.00 Lump sum

Survey conducted at OCCI SONO MOTOR

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately Seven (7) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

# PRUDENT ADJUSTORS SERVICES

Vehicle No: FW 1737 J

Our ref: PA/FW1737/1117/tpw

# ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

## ASSESSMENT FOR REPAIR: FW 1737 J

S/N	Description Material	(Oly	- Cohalliah	Onginal Revised Quotation Quotation
1	Top cowling	l pc	Cracked	195.00 Che 195.00
2	Cowling screen	1 pc	Cracked	82.50 Sca 82.50
3	Cowling stay	1 pc	Bent	60.50 8 60.50
4	Handle bar @ \$71.50/-	2 pcs	Bent RH	143.00 0654, 71.50 BC
5	Handle balancer	1 set	Grazed	40.00 gm 40.00 _
6	Brake lever	1 pc	Bent	20.00 500 20.00
7	Brake master pump	1 pc	Grazed	145.00 CM7 145.00 -
8	Head lamp assy	1 pc	Hdr cracked	160.00 cm 160.00
9	Mirror @ \$30/-	2 pcs	Broken	60.00 BN 60.00
10	Meter assy	1 pc	Usable	495.00 11 ~ *
11	Front signal @ \$30/-	2 pcs	Cracked	60.00 MSBN 60.00 /rc
12	Front fork assy @ \$350/-	2 pcs	Bent	700.00 2 700.00 X
13	Front fork under bracket	I pc	Distorted	160.00 8 ~ 160.00 2
14	Side fairing @ \$170/-	2 pcs	Not fitted	340.00 NF ~X
15	Front fender	1 pc	Cracked	85.00 647 85.00
16	Front rim	1 pc	Warped	320.00 A 320.00 X
17	Front disc plate	1 pc	Warped	155.00 bu 155.00 ×
18	Fuel tank	1 pc	Repair	R 460.00 S.N. 200.00/005. J
19	Air duct @ \$42/-	2 pcs	Not fitted	84.00 NN - X
20	Radiator assy	1 pc	Dented	210.00 <b>1</b> 0 210.00 X
21	Front footrest	1 pc	Bent	55.00 11 55.00 X
22	Front footrest bracket	1 pc	Bent	75.00 17 75.00 ×
23	Brake pedal	1 pc	Bent	58.00 3 - 58.00
24	Rear footrest	1 pc	Bent	35.00 5 35.00
25	Rear footrest bracket	l pc	Bent	65,00 21 65,00
26	Tail board	l pc	Repair	132.00 S.N.60.00 - S. W
27	Exhaust assy	l pc	Muffler only	506.00 Age 180.00
	Less 10%	1	,	4901.00 2992.50 490.10 299.25 4410.90 2693.25
				118871

# PRUDENT ADJUSTORS SERVICES

Vehicle No: FW 1737 J

Our ref: PA/FW1737/1117/tpw

## ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

	Add special nett from above				260.00
30	Front number plate	1 pc	Necessary	20.00 pu	15.00 /0
31	Front tyre - 50 %	l pc	Cut	120.00 11	60.00 ⊀
32	Steering cone / bearing	1 set	Necessary	140.00 ru	70.00/
			W 45	280.00	405.00
	Towing fee (2 trips)			120.00	100.00
	Chassis frame align			450.00	350.00 /
	Labour fee			350.00	280.00/
			1.7	920.00	730.00
	Total parts & labour comcluded			5610.90	3828.25
	Final lump sum repair adjustment				3050.00

1107.

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return

For Prudent Adjustors Services

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI17020720/URBS2

Date:

08/01/2018

REFERENCE

Handling Insurer: Pte. Ltd.

China Taiping Insurance (Singapore)

Policy No:

Nature of Claim: TP

DMHCSN1675381600

Claimant Vehicle

FW1737J

Insured Vehicle

SGZ5309H

No: Date of Loss:

11/10/2017

No:

Claim No:

SNM17D05972C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FW1737J

Make & Model:

KAWASAKI KRR ZX150, 148cc (M)

Engine No:

KR150EEA55575

Reg. Date:

23/01/2003 (Man. Year; 2002) Green

Chassis No:

KR150KA55575

Colour:

148 cc

Odometer:

16549 km

Engine Capacity: Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Engine Modification:

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

90-80-17

Rear Tyre Size:

110-70-17

Front Left Side:

Swallow 6 mm

Yes

Rear Left Side:

Swallow 6 mm

Front Right Side:

0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0,00	

INSPECTION

Date of Assignment:

30/10/2017

Date Inspected:

31/10/2017 Inspected At:

EROFIA MOTOR TRADING PTE LTD

1 KAKI BUKIT AVENUE 6 #02-62 AUTOBAY

SINGAPORE 417883

Estimated Period of Repair:

0.0 days

Adjuster:

MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

#### TOTAL LOSS ASPECT

Market Value: \$320.00

OMV: \$3,600.00

PARF Rebate (1): \$0.00

Quota Premium Paid: \$900.00

COE Rebate (2): \$105.00

Total Rebate (1) + (2) =: \$105.00

The total amount incurred will be Market Value \$320.00 minus Total Rebate \$105.00 = \$215.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

### REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 05 Jan 2018)

Parts:

N/A

KAWASAKI KRR ZX150 148cc (M) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Validity:

Print Code: LKK Auto Consultants Pte Ltd/FW1737J/08/01/2018 08:50 These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

There are no new parts selected.

LKK Auto Consultants Pte Ltd/FW1737J/08/01/2018 08:50. Not valid without Reference section.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/FW1737J/08/01/2018 08:50. Not valid without Reference section.

< END OF ESTIMATES >



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	ionale Des Experts En Auton	nobile		
CHI	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CS3/CTI17020	720/Utd3s2-1		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 14-05-2019 Code: CTI			
1.		Policy Particular	s :- THIRD PARTY CLA	IM		
	Insured Veh.	SGZ 5309H	Veh. Inspected	FW 1737J		
	Policy No.	DMHCSN1675381600	Coverage (\$)	0.00		
	Claim No.	SNM17D05972C02	Excess (\$)	0.00		
	Assign From	ALFRED TOH	Assign Date	07/05/2019		
2.		Vehicle Par	ticulars & Condition			
	Make & Model	KAWASAKI KRR ZX150	c.c	148		
	Engine No.	HIDDEN	Year of Reg.	2003		
	Chassis No.	KR150KA55575	Colour	GREEN		
	Odometer	16549	Steering	AFFECTED		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD	- ×			
3.		Condi	itions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	90-80-17	SWALLOW	6 mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre	110-70-17	SWALLOW	6 mm		
	L/H Rear Tyre			mm		
4.		The state of the s	tion of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE FF ETAILS.	RONT PORTION AND N/S	BODY.		
5.	General Information					
	Accident Date	11/10/2017	Inspection Date	31/10/2017		
	Survey held at	OCCI_SONO MOTOR.COM				
		225 KAKI BUKIT ROAD 4 #01-38 SYNERGY SINGAPORE 417800				
5a.	Remarks					
	A)THE INSPECTION B)IN ACCORDANG	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS, V	ITHOUT PREJUDICE" BAS WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.		
5b.		Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	5 Working Day	ys		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FW 1737J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS		l comment	Well -
1	TOP COWLING	CRACKED	195.00	195.00
1	COWLING SCREEN	SCRATCHED	82.50	82.50
1	COWLING STAY	BENT	60.50	60.50
2	HANDLE BAR @\$71.50	O/S BENT	143.00	71.50
1	SET HANDLE BALANCER	GRAZED	40.00	40.00
1	BRAKE LEVER	SCRATCHED	20.00	20.00
1	BRAKE MASTER PUMP	сит	145.00	145.00
1	HEAD LAMP ASSY	HDR CRACKED	160.00	160.00
2	MIRROR @ \$30.00	BROKEN	60.00	60.00
1	METER ASSY	NOT NECESSARY	495.00	
2	FRONT SIGNAL @ \$30.00	N/S BROKEN	60.00	30.00
2	FRONT FORK ASSY @ \$350.00	TO REPAIR SEE LABOUR	700.00	
1	FRONT FORK UNDER BRACKET	SERVICEABLE	160.00	
2	SIDE FAIRING @ \$170.00	NOT FITTED	340.00	
1	FRONT FENDER	сит	85.00	85.00
1	FRONT RIM	TO REPAIR SEE LABOUR	320.00	
1	FRONT DISC PLATE	SERVICEABLE	155.00	
2	AIR DUCT @ \$42.00	NOT NECESSARY	84.00	
1	RADIATOR ASSY	NOT NECESSARY	210.00	
1	FRONT FOOTREST	NOT NECESSARY	55.00	
1	FRONT FOOTREST BRACKET	NOT NECESSARY	75.00	
1	BRAKE PEDAL	BENT	58.00	58.00
1	REAR FOOTREST	BENT	35.00	35.00
1	REAR FOOTREST BRACKET	BENT	65.00	65.00
1	EXHAUST ASSY	DAMAGED	506.00	180.00
	LESS 10% DISCOUNT	Power and the contract of the	-430.90	-128.7
			3,878.10	1,158.7
1	FUEL TANK (SN)	TO REPAIR SEE LA	460.00	100.00

Report Ref No. CS3/CTI17020720/Utd3s2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
TAIL BOARD (SN)	TO REPAIR SEE LABOUR	132.00	60.00
LESS 10% DISCOUNT		-59.20	
		532.80	160.00
SPECIAL NETT ITEMS			7
FRONT NUMBER PLATE (SN)	NECESSARY	20.00	10.00
FRONT TYRE (SN)	NOT NECESSARY	120.00	
SET STEERING CONE / BEARING (SN)	NECESSARY	140.00	70.00
		280.00	80.00
LABOUR			
TOWING FEE (2 TRIPS)		120.00	100.00
CHASSIS FRAME ALIGN. INCLUSIVE OF THE REPAIR OF FRONT FORK ASSY, FRONT RIM, FUEL TANK AND TAIL BOARD.		450.00	350.00
LABOUR FEE.		350.00	280.00
		920.00	730.00
GRAND TOTAL		5,610.90	2,128.75
	TAIL BOARD (SN)  LESS 10% DISCOUNT  SPECIAL NETT ITEMS  FRONT NUMBER PLATE (SN)  FRONT TYRE (SN)  SET STEERING CONE / BEARING (SN)  LABOUR  TOWING FEE (2 TRIPS)  CHASSIS FRAME ALIGN. INCLUSIVE OF THE REPAIR OF FRONT FORK ASSY, FRONT RIM, FUEL TANK AND TAIL BOARD.  LABOUR FEE.	TAIL BOARD (SN)  LESS 10% DISCOUNT  SPECIAL NETT ITEMS  FRONT NUMBER PLATE (SN)  FRONT TYRE (SN)  SET STEERING CONE / BEARING (SN)  LABOUR  TO REPAIR SEE LABOUR  NECESSARY  NOT NECESSARY  NECESSARY  NECESSARY  NECESSARY  NECESSARY  NECESSARY  NECESSARY  NECESSARY  LABOUR  TOWING FEE (2 TRIPS)  CHASSIS FRAME ALIGN. INCLUSIVE OF THE REPAIR OF FRONT FORK ASSY, FRONT RIM, FUEL TANK AND TAIL BOARD.  LABOUR FEE.	TO REPAIR SEE   132.00   132

RECOMMENDED COST OF LUMP SUM REPAIRS	1,700,00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/CTI17020720/Utd3s2-1

NOTE: THIS MOTORCYCLE ONLY BALANCE 3 MONTHS PLUS AND CANNOT BE FURTHER RENEWAL.

MARKET VALUE: \$320.00 - \$500.00 (EST)

LTA: \$105.00

NETT VALUE: \$215.00 - \$395.00 (EST)

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.