

Stone (LKK)
8322 8813

Wing Airline 7/5/19 12.10pm
P/P 3 chys
Ry bpf spy

SERVICE ESTIMATE

67467 - C00001 SL: SERVICE SALES - PC
Ms Chella Ammall D/O Tanggarajo Pakri
16 Ladyhill Road

GST Reg.No:M28920628X
Inv.No. : B&P 0 Page 1
Inv.date. : 06/05/2019
WIP No. : 12885
Veh.In/Out:
*Tel.No. : Mobile: 93868397
Reg.No. : SKD1712X
Reg.date : 15/07/2011
Mileage : 0
Chassis No: SAJAC22F7BLV11653

Singapore 258681

Closed by : Patricia Kueh Anak S
Svc Consultant :
Remarks : Ms Chella Ammall D/O

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, HEADLAMP LH,ETC	0	1200.00	0		1,200.00	S /
800	TO PUTTY SPRAYPAINT ON FRT BUMPER,ETC	0	1000.00	0		1,000.00	S /
280	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S /
280	TO FOCUS HEADLAMP LH	0	162.00	0		162.00	S /
	BUMPER COVER FRT XJL X cut/Repair	1.0 EA	3010.90			3,010.90	S
	BUMPER BLIND RIVET X - MLC	10.0 EA	1.90			19.00	S
	POWERWASH COVER LH X ?	1.0 EA	61.50			61.50	S
	HEADLAMP LH XJL HID / BR	1.0 EA	3179.10			3,179.10	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Parts Total

Acknowledged by Repairer

Signature:

Date:

2,848.00
6,270.50
0.00

Gross Total. 9,118.50
Net..... 9,118.50
GST @ 7.0% 638.30
Total..... 9,756.80
Paid..... 0.00
Please Pay.. 9,756.80

GST: S=StdRated; O=OutOfScope; Z=ZeroRated