


**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S80FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD  
 8 SHENTON WAY  
 #27-01 AXA TOWER  
 SINGAPORE 068811  
 Registration No : SMH7178D  
 Chassis No : MRHFC1680GT000453  
 Model : CIVIC 1.5 TURBO VTIS YM2016  
 Owner's Name : TOH MENG LOONG SHAWN  
 Ins Policy No. :  
 Date of Accident : 4/5/2019

Document No. : SQT19001960  
 Date : 6. May 2019  
 Customer No. : WA008  
 Svc Advisor : LIEW THYE WEI  
 Engine No : L15B71629343  
 Date | Time : 6. May 2019 2:27:29 PM  
 Surveyor Name :  
 Survey Date :  
 Authorisation Date :

Page 1

| Item            | Description                      | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount Incl GST |
|-----------------|----------------------------------|-----|------------|--------|--------|---------------|-----------------|
|                 | OWN DAMAGE CLAIMS-J/NO:          |     |            |        |        |               |                 |
|                 | POLICY/CLAIMS NO: VA1 / GA449590 |     |            |        |        |               |                 |
|                 | OWNER: TOH MENG LOONG SHAWN      |     |            |        |        |               |                 |
|                 | ACC DATE: 04/05/19               |     |            |        |        |               |                 |
|                 | SURVEYED BY:                     |     |            |        |        |               |                 |
|                 | DATE:                            |     |            |        |        |               |                 |
|                 | AUTHORIZED ON:                   |     |            |        |        |               |                 |
|                 | REF NO:                          |     |            |        |        |               |                 |
| 71410-TEA-T01   | BULKHEAD ASSY.FR.                | 1   | 548.60     | 25     | 411.45 | 28.80         | 440.25          |
| 71430-TEA-T00   | BRACEBULKHEAD LOWER              | 1   | 15.50      | 25     | 11.62  | 0.81          | 12.43           |
| 71101-TEA-T00ZZ | FACEFR.BUMPER                    | 1   | 579.90     | 25     | 434.92 | 30.44         | 465.36          |
| 71102-TEA-A30   | GRILLE, FR.BUMPER LOWER          | 1   | 69.70      | 25     | 52.27  | 3.66          | 55.93           |
| 71203-TEA-T00   | PLATEFR.BUMPER LOWER INDUCTIO    | 1   | 72.70      | 25     | 54.52  | 3.82          | 58.34           |
| 71145-321-000   | BASEFR LIC PLATE                 | 1   | 37.80      | 25     | 28.35  | 1.98          | 30.33           |
| BO-NUM-COMP-L   | NUMBER PLATE WITH CASING-L(N)    | 1   | 45.00      |        | 45.00  | 3.15          | 48.15           |
| 71103-TEA-T10   | GARNISHR.FR.BUMPER SIDE          | 1   | 14.20      | 25     | 10.65  | 0.75          | 11.40           |
| 71108-TEA-T10   | GARNISHL.FR.BUMPER SIDE          | 1   | 14.20      | 25     | 10.65  | 0.75          | 11.40           |
| 71130-TEA-T00   | BEAM COMPFR.BUMPER               | 1   | 345.90     | 25     | 259.42 | 16.16         | 277.58          |
| 71202-TEA-T00   | PLATEFR.BUMPER.MIDDLE INDUCTN    | 1   | 57.30      | 25     | 42.97  | 3.01          | 45.98           |
| 71160-TEA-T00   | BEAM COMPFR.BUMPER CENTER UPP    | 1   | 214.80     | 25     | 161.10 | 11.28         | 172.38          |
| 71140-TEA-T00   | BEAMR.FR.BUMPER UPPER            | 1   | 26.70      | 25     | 20.02  | 1.40          | 21.42           |
| 71190-TEA-T00   | BEAML.FR.BUMPER UPPER            | 1   | 26.70      | 25     | 20.02  | 1.40          | 21.42           |
| 71193-TEA-T01   | SPACERR.FR.BUMPER SIDE           | 1   | 10.40      | 25     | 7.80   | 0.55          | 8.35            |
| 71193-TEA-T01   | SPACERL.FR.BUMPER SIDE           | 1   | 10.40      | 25     | 7.80   | 0.55          | 8.35            |
| 91506-TM8-033   | CLIP,BUMPER                      | 22  | 2.30       | 25     | 37.95  | 2.66          | 40.61           |
| 71121-TEA-T01   | BASE,FR.GRILLE CHROME            | 1   | 73.80      | 25     | 55.35  | 3.87          | 59.22           |
| 71125-TEA-T01   | MOLDINGFR.GRILLE                 | 1   | 100.40     | 25     | 75.30  | 5.27          | 80.57           |
| 71124-TEA-T01   | EXTENSION ASSYR.FR.GRILLE        | 1   | 85.60      | 25     | 64.20  | 4.49          | 68.69           |

Printed on 6/5/2019 4:56:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of S\$3,500 (incl GST) will be applicable for the request of the above quotation for estimates above S\$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6541 3638

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203538

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD  
 8 SHENTON WAY  
 #27-01 AXA TOWER  
 SINGAPORE 068811  
 Registration No : SMH7178D  
 Chassis No : MRHFC1660GT000453  
 Model : CIVIC 1.5 TURBO VTIS YM2016  
 Owner's Name : TOH MENG LOONG SHAWN  
 Ins Policy No. :  
 Date of Accident : 4/5/2019

Document No. : SQT19001960 Page 2  
 Date : 6. May 2019  
 Customer No. : WA006  
 Svc Advisor : LIEW THYE WEI  
 Engine No : L15B71629343  
 Date | Time : 6. May 2019 2:27:29 PM  
 Surveyor Name :  
 Survey Date :  
 Authorisation Date :

| Item           | Description                                        | Qty | Unit Price          | Disc % | Amount  | 0% GST Amount | Amount Incl GST |
|----------------|----------------------------------------------------|-----|---------------------|--------|---------|---------------|-----------------|
| 74129-TEA-T01  | EXTENSION ASSYL.FR.GRILLE                          | 1   | 65.60 ?             | 25     | 64.20   | 4.49          | 68.69           |
| 74146-TEA-T00  | RUBBERHOOD SEAL                                    | 1   | 27.60 ✓             | 25     | 20.70   | 1.45          | 22.15           |
| 75700-TBA-A00  | EMBLEM                                             | 1   | 15.00 ✓             | 25     | 11.25   | 0.79          | 12.04           |
| 90301-ST0-003  | NUTPUSH 3MM                                        | 2   | 2.10 ?              | 25     | 3.15    | 0.22          | 3.37            |
| 74127-TEA-T00  | COVERFR.BULKHEAD                                   | 1   | 18.20 X             | 25     | 13.65   | 0.96          | 14.61           |
| 33900-TBA-A01  | LIGHT ASSYL.FR.FOG                                 | 1   | 305.90 ?            | 25     | 228.42  | 16.06         | 244.48          |
| 33950-TBA-A01  | LIGHT ASSYL.FR.FOG                                 | 1   | 305.90 ?            | 25     | 228.42  | 16.06         | 244.48          |
| 33100-TEA-T11  | HEADLIGHT ASSY.R.                                  | 1   | 1189.70 ✓           | 25     | 892.27  | 62.46         | 954.73          |
| 33150-TEA-T11  | HEADLIGHT ASSYL                                    | 1   | 1189.70 ?           | 25     | 892.27  | 62.46         | 954.73          |
| 18010-SAA-A01  | RADIATOR COMP                                      | 1   | 1100.50 ?           | 25     | 825.37  | 57.78         | 883.15          |
| 08CLA-P9911LK8 | COOLANT ANTI-FREEZE TYPE 2                         | 3   | 23.20 ?             | 25     | 52.20   | 3.65          | 55.85           |
| 80100-TEIC-A01 | CONDENSER ASSY                                     | 1   | 704.40 ✓            | 25     | 528.30  | 36.98         | 565.28          |
| 80525-TBA-A01  | SENSOR ASSYAMBIENT                                 | 1   | 40.10 ?             | 25     | 30.07   | 2.10          | 32.17           |
| 91565-TBA-K01  | CLIPAMBIENT SENSOR                                 | 1   | 5.40 ?              | 25     | 4.05    | 0.28          | 4.33            |
| Sum Item       |                                                    |     |                     |        | 5607.68 | 392.64        | 6,000.22        |
| B08UN          | SUNDRIES                                           | 1   | 30.00 ✓             |        | 30.00   | 2.10          | 32.10           |
| BML011         | INSPECT FR LIGHTING MECHANISMS & FOCUS             | 1   | 80.00 ✓             |        | 80.00   | 5.80          | 85.80           |
| BMA01D         | REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.      | 1   | 230.00 ✓            |        | 230.00  | 16.10         | 246.10          |
| BMC01D         | REMOVE & INSTALL RADIATOR WITH FITTINGS.           | 1   | 180.00 ✓            |        | 180.00  | 12.60         | 192.60          |
| BKBH01M        | REMOVE & RENEW BULKHEAD. STRAIGHTEN                | 1   | 2200.00 1120? 1180? |        | 2200.00 | 154.00        | 2354.00         |
| BP02R          | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P) | 1   | 1300.00 700         |        | 1300.00 | 91.00         | 1391.00         |
| Sum Labor      |                                                    |     |                     |        | 4020.00 | 281.40        | 4,301.40        |

Survey By : merous rhr 5-7 dy.  
 Date & Time : 7/5/19 @ 11.30  
 Excess : 500  
 Status : Authorised Theng Sheng Behn jony

Total Amount 9,627.68 673.94 10,301.62  
 Total (Inclusive of GST) 10,301.62

Printed on 6/5/2019 4:03:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$55.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# **QUOTATION**

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

|                         |                                |                           |                         |             |   |
|-------------------------|--------------------------------|---------------------------|-------------------------|-------------|---|
| <b>Customer</b>         | : AXA INSURANCE S'PORE PTE LTD | <b>Document No.</b>       | : SQT19001960           | <b>Page</b> | 3 |
|                         | : 8 SHENTON WAY                | <b>Date</b>               | : 6 May 2019            |             |   |
|                         | : #27-01 AXA TOWER             | <b>Customer No.</b>       | : WA006                 |             |   |
|                         | : SINGAPORE 068811             | <b>Svc Advisor</b>        | : LIEW THYE WEI         |             |   |
| <b>Registration No</b>  | : SMH7178D                     | <b>Engine No</b>          | : L15B71629343          |             |   |
| <b>Chassis No</b>       | : MRHFC1660GT000463            | <b>Date / Time</b>        | : 6 May 2019 2:27:29 PM |             |   |
| <b>Model</b>            | : CIVIC 1.5 TURBO VTIS YM2018  | <b>Surveyor Name</b>      | :                       |             |   |
| <b>Owner's Name</b>     | : TOH MENG LOONG SHAWN         | <b>Survey Date</b>        | :                       |             |   |
| <b>Ins Policy No.</b>   | :                              | <b>Authorisation Date</b> | :                       |             |   |
| <b>Date of Accident</b> | : 4/5/2019                     |                           |                         |             |   |

| Item      | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incl GST |
|-----------|-------------|-----|------------|--------|--------|---------------|-----------------|
| Signature | _____       |     |            |        |        |               |                 |

Printed on 5/5/2019 4:58:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.